

2/20/2002

ASS. REC. BY:

REF: CS/FWD19003629/Ksd3 Special Instruction

Surveyor:
meimen

lcmth
lionel fun

ASSIGNMENT (Office)

FWD

Date/Time: 26/2/19 @ 4:05pm

Estimated Cost:

OD / TP / FWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKL 4555X

Insured:

at Workshop m/s:

Ah Lim Motor

Tel:

64563637

of

176 Sin Ming Drive # 05-12

Policy No:

PNPV2017-00007666-01

Claim No:

1201900005016

Sum Insured:

Excess:

\$500.00

Make of Veh:

D.O.A. 21/2/19

(Client's Record)

27/2/19

H.O.D. Endorsement:

CA / (REV) / REP. / REV 24 HRS

Date/Time:

4:13pm @ 26/2/19

Person Contacted:

Mei li

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SKL 4555X - CS3/FWD19003556/Ecd3 D.O.A. 21/2/19

CS/FWD/19003629/KSD3

REF: FWD

ASSIGNMENT

Date: 27/2/19

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKL 4555X

at Workshop no: Ah Kim Motor

at 176 Sin Ming Drive # 05-12

Insured

Policy No

Claims No

Sum Insured: Excess: \$500.00

(Client's Record)

Make of Veh: Moming

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bat. or Market Value: \$56k

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP: / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SKL 4555X Regn: 11: 13

Type: ☒ M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Maruti 5 Wagon 1994

Colour: M. Grey A/C Insured / Std / Nil / NA

Sp Reading: 73083 I/Radio: Insured / Std / Nil / NA

Eng/No: JN 8CW10F150 116853

C/Ho

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modt: Nil / ☒ Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Mathis

Front: 7 mm Rear: 7 mm

R/Bal: 7 mm L/Bal: 7 mm

D.O.A: 21/2/19 D.O.I: 27/2/19

Survey held at

Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 01 MAR 2019

Date/Time: 01/03/19 @ 10:19 a.m. Action/Instruction: instruction from Level Tan, Vehicle Tow to another workshop for repair. Submit B.I to them.

Date/Time: File Pass to: 01/03/19 Typist

☒ : Preli. Report

☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech Insp (\$)

☐ Weekend (\$)

Survey Fee:

Transportation

Other

200

150

10

TOTAL

Report Format: Preli

Lump Sum / L.B.E: 13

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Feb 2019 15:09 Sendback Est	26 Feb 2019 15:17 S\$7,911.00	26 Feb 2019 16:05 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	NG WILLIAM, ID: S1802651A			
Vehicle Reg. No.:	SKL4555X	Date of Loss:	21/02/2019 00:00 - :59 [63 Months and 7 Days From LTA Reg Date (Man Yr)]	
Claim Type:	OD / 1201900005016	Policy/Cover Note No.:	PNPV2017-00007666-01 (Comprehensive)	
		Excess:	S\$500.00	
Repairer:	Ah Lim Motor Company (Sin Ming) 176 Sin Ming Drive #05-12, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64563637			
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/03/2019]			
Driver/Custodian:	CHANG YOKE FONG (47 / Female) , NRIC: S7172720C, Tel: +6591190401 Email: changyf26@gmail.com			

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

SKL4555X (1201900005016)

OD

Feb 21 2019 12:00AM

[NG WILLIAM]

Ah Lim Motor Company

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 01/03/2019 10:19 AM.
To LKK_HQ
Subject Alert - Adj Mandate Maintained - SKL4555X - Claim Handler: Lionel Tan

Maintained:Tow to another workshop for repair.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan

Date: 27 Feb 2019

Preliminary Advice

Vehicle No	: SKL4555X	Accident Date	: 21/02/2019
Make	: MAZDA 5	Policy No.	: PNPV2017-00007666-01
Assignment Date	: 26/02/2019	Excess	: S\$500.00
Date of Inspection	: 27/02/2019	Est. Duration of Repair	: 5 days
Inspection At	: Ah Lim Motor Company (Sin Ming) 176 Sin Ming Drive #05-12, Sin Ming AutoCare Singapore 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,911.00
Revised Amount	:S\$	5,403.00
Check Items (Estimated)	:S\$	1,578.00
Total	:S\$	6,981.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	56,000.00
COE / PARF Rebate	:S\$	53,777.00
Salvage Value	:S\$	
Margin for Repair	:S\$	2,223.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Repairer proposed \$ 5,500.00 to repair the vehicle on part by part basis.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan

Date: 27 Feb 2019

Preliminary Advice

Vehicle No	: SKL4555X	Accident Date	: 21/02/2019
Make	: MAZDA 5	Policy No.	: PNPV2017-00007666-01
Assignment Date	: 26/02/2019	Excess	: S\$500.00
Date of Inspection	: 27/02/2019	Est. Duration of Repair	: 5 days
Inspection At	: Ah Lim Motor Company (Sin Ming) 176 Sin Ming Drive #05-12, Sin Ming AutoCare Singapore 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,911.00
Revised Amount	:S\$	5,403.00
Check Items (Estimated)	:S\$	1,578.00
Total	:S\$	6,981.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	56,000.00
COE / PARF Rebate	:S\$	53,777.00
Salvage Value	:S\$	
Margin for Repair	:S\$	2,223.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We are pending repair cost from repairer

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/02/2019 17:55
Date Of Accident	21/02/2019 08:50
Exact Location Of Accident	SLIP RD FRM SLE/BKE INTO WOODLANDS AVE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKL4555X
Insured/Policyholder	
Name Of Registered Owner	NG WILLIAM
NRIC No	S1802651A
Email Address	NG_WILLIAM_NG@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-96565970
Alternative Phone No	OTHERS-91190401

Vehicle Particulars

Manufacturer	MAZDA
Model	5 2.0
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2017-00007666-01
Cover Note Number	14/11/2018 TO 13/11/2019

Driver

Name of Driver	CHANG YOKE FONG
NRIC No	S7172720C
Date Of Birth	26/07/1971
Occupation	INDOOR
Date Of Driving Pass	01/12/1995
Driving Experience	23 YEARS AND 2 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91190401
Fax Number	
Contact Number	
E-Mail Address	CHANGYF26@GMAIL.COM

Sketch Plan Pg. 1
SKETCH PLAN


IMPORTANT NOTICE



1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow Insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 21/2/2019
2:30pm


Reporting Centre Person's Signature
Name: 
NRIC/FIN No.: 21/02/19

GIA/MA/SG/001-1 (Rev. 03)



CERTIFICATE OF INSURANCE

Please call +65-6322-2072 for FWD Emergency Assistance
if Your Car breaks down or is involved in an accident.

All accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

POLICY NUMBER: PNPV2017-00007666-01 (Comprehensive - Classic Plan)

Car plate number: SKL4555X

Your name (As the policyholder): NG WILLIAM

Coverage start date: 14/11/2018

Coverage end date: 13/11/2019

Covered geographical area: Singapore, West Malaysia and Southern Thailand

Who is insured to drive:

(a) You; and

(b) Anyone with a valid driving license who You give permission to drive Your Car.

Important things to know:

Your Policy comprises this Certificate of Insurance, the Contract, the Car Insurance Summary and any Endorsements attached by Us. These documents should be read together as one. You must make sure that any person You give permission to drive Your Car understands Your duties under this Policy and complies with its conditions.

Your Policy is only valid if Your Car is being used for non-commercial activities in accordance with Your contract.

Finance company: Hong Leong Finance Limited

We confirm that this Policy complies with the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).

Issued on: 21/10/2018

Abhishek Bhatia
Chief Executive Officer
FWD Singapore Pte Ltd

Please immediately inform us at +65-6820-8888
or email us at contact.sg@fwd.com if any details
in this Certificate of Insurance need to be changed.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2651A
Vehicle Details	
Vehicle No.:	SKL4555X
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Feb 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA5 2.0L SP 5EAT ABS D/AB 2WD 5DR SR
Primary Colour:	Grey
Manufacturing Year:	2013
Engine No.:	LF11562475
Chassis No.:	JM6CW10F1E0116853
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$19,873.00
Original Registration Date:	14 Nov 2013
First Registration Date:	14 Nov 2013
Transfer Count:	0
Actual ARF Paid:	\$19,873.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Nov 2023
PARF Rebate Amount:	\$13,911.00
Intended COE Rebate Details	
COE Expiry Date:	13 Nov 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$84,578.00
COE Rebate Amount:	\$39,866.00
Total Rebate Amount:	\$53,777.00

The information contained herein is correct as at 27 Feb 2019

OK

AH LIM MOTOR COMPANY

176 SIN MING DRIVE #05-12
 SIN MING AUTOCARE Singapore 575721
 Tel: 64563637 Fax: Email:
 GST Reg No: M9-0009639-E

SURVEYOR COPY

INSURER: FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/FWD
Policy No:	PNPV2017-00007666-01	Date of Loss:	21/02/2019
Vehicle Reg. No.:	SKL4555X	Driveable?	
Driver Age/Info:	47 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NG WILLIAM		
Driver:	CHANG YOKE FONG		

Make/Model:	MAZDA 5, 2.0 (A)	Vehicle Reg. Date:	14/11/2013
Vehicle Colour:	GREY		
Engine No:	LF11562475	Chassis No:	JM6CW10F1E0116853
Odometer:	0 KM		

Paint Type: NO
 Total Loss? NO
 Est. Duration of Repair (day) 8 5 days

MV-561
18
Not with hand
Recovery by paint
Ex @ 5000
Ref: 62564315

Description of Accident/Loss	REFER TO SKETCH PLAN
------------------------------	----------------------

Remarks: WORKSHOP HANDLER : MEILI TAN - TEL: 6456 3637 EMAIL : MEILI@ALMSM.COM.SG VEHICLE IS IN OUR SIN MING BRANCH WORKSHOP. PLEASE ARRANGE FOR SURVEY URGENTLY IF POSSIBLE.

Present Location: AH LIM MOTOR COMPANY (SIN MING)

COST OF CLAIMS

	Amount
Parts	5,961.00
Miscellaneous Items	0.00
Labour	1,950.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	7,911.00
+ GST 7.00% (\$\$)	553.77
Nett Amount (\$\$)	8,464.77

This claim is handled by: MEILI TAN-SIN MING BRANCH

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Feb 2019)
 Parts: M1-MPV MAZDA 5 2.0 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SKL4555X)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BONNET	B ₁	0.00	0.00	*900.00 F ✓
2	10		*FRONT BONNET INSULATOR CLIPS	me	0.00	0.00	*30.00 F ✓
3	2		*FRONT BONNET HINGE LH / RH	R	0.00	0.00	*60.00 F X
4	2		*HEADLAMP RH / LH	mye m	0.00	0.00	*2,440.00 F ✓
5	2		*HEADLAMP LOWER BRACKET LH / RH		0.00	0.00	*40.00 F ?
6	1		*FRONT BUMPER	Bu	0.00	0.00	*420.00 F ✓
7	1		*FRONT BUMPER REINFORCEMENT		0.00	0.00	*285.00 F ?
8	2		*FRONT BUMPER SIDE RETAINER LH / RH	D/S	0.00	0.00	*16.00 F ✓
9	20		*FRONT BUMPER CLIPS	me	0.00	0.00	*40.00 F ✓
10	1		*FRONT BUMPER SPONGE		0.00	0.00	*45.00 F ?
11	1		*FRONT BUMPER CENTER LOGO	me	0.00	0.00	*18.00 F ✓
12	1		*FRONT BUMPER CENTER LOWER GRILLE	C/R	0.00	0.00	*300.00 F ✓
13	1		*TOWING COVER	R	0.00	0.00	*30.00 F ✓
14	1		*FRONT BUMPER TOP COVER		0.00	0.00	*160.00 F ?
15	6		*FRONT BUMPER TOP COVER RIVETS	me	0.00	0.00	*24.00 F ✓
16	1		*FOGLAMP COVER RH		0.00	0.00	*45.00 F ?
17	1		*ENGINE LOWER COVER-CHECK PRICE	me	0.00	0.00	*160.00 F X
18	1		*RADIATOR SUPPORT PANEL		0.00	0.00	*200.00 F ?
19	1		*RADIATOR		0.00	0.00	*320.00 F ?
20	1		*AIR CON CONDENSER		0.00	0.00	*300.00 F ?
21	1		*FRONT BONNET RUBBER SEAL	my	0.00	0.00	*30.00 F ✓
22	1		*BRACE PANEL		0.00	0.00	*28.00 F ?
23	1		*RADIATOR COOLANT		0	0.00	*35.00 FS ?
24	1		*NUMBER PLATE	B ₁	0	0.00	*35.00 FS ✓
Total Parts (S\$)						5,961.00	

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	20/ 30.00
2	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES; RADIATOR AND HOSES; VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	New	120.00 ?
3	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD FRONT SUPPORT PANEL; TO KNOCK & REPAIR AFFECTED AREAS; INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	500/ 900.00
4	TO SPRAY BONNET; FRONT BUMPER; FRONT FENDER LH / RH ; FRONT DOOR LH / RH	New	600/ 900.00
Gross Labour Cost (S\$)			1,950.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AH LIM MOTOR COMPANY

176 SIN MING DRIVE #05-12
 SIN MING AUTOCARE Singapore 575721
 Tel: 64563637 Fax: Email:
 GST Reg No: M9-0009639-E

SURVEYOR COPY

INSURER: FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/FWD
Policy No:	PNPV2017-00007666-01	Date of Loss:	21/02/2019
Vehicle Reg. No.:	SKL4555X	Driveable?	
Driver Age/Info:	47 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NG WILLIAM		
Driver:	CHANG YOKE FONG		

Make/Model:	MAZDA 5, 2.0 (A)	Vehicle Reg. Date:	14/11/2013
Vehicle Colour:	GREY		
Engine No:	LF11562475	Chassis No:	JM6CW10F1E0116853
Odometer:	0 KM		

Paint Type:
 Total Loss? **NO**
 Est. Duration of Repair (day) *8 5 days*

Not with work
Re-spray B4 paint
Ex @ 500dp
Fax: 62564315

Description of Accident/Loss: REFER TO SKETCH PLAN

Remarks: WORKSHOP HANDLER : MEILI TAN - TEL: 6456 3637 EMAIL : MEILI@ALMSM.COM.SG VEHICLE IS IN OUR SIN MING BRANCH WORKSHOP. PLEASE ARRANGE FOR SURVEY URGENTLY IF POSSIBLE.

Present Location: AH LIM MOTOR COMPANY (SIN MING)

COST OF CLAIMS

	Amount
Parts	5,961.00
Miscellaneous Items	0.00
Labour	1,950.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	7,911.00
+ GST 7.00% (\$\$)	553.77
Nett Amount (\$\$)	8,464.77

This claim is handled by: MEILI TAN-SIN MING BRANCH

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Feb 2019)

Parts: M1-MPV MAZDA 5 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKL4555X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BONNET	Bz 0.00	0.00	*900.00 F	✓
2	10		*FRONT BONNET INSULATOR CLIPS	me 0.00	0.00	*30.00 F	✓
3	2		*FRONT BONNET HINGE LH / RH	R 0.00	0.00	*60.00 F	X
4	2		*HEADLAMP RH / LH	mg, M 0.00	0.00	*2,440.00 F	✓
5	2		*HEADLAMP LOWER BRACKET LH / RH	0.00	0.00	*40.00 F	?
6	1		*FRONT BUMPER	Bu 0.00	0.00	*420.00 F	✓
7	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	*285.00 F	?
8	2		*FRONT BUMPER SIDE RETAINER LH / RH	D/S 0.00	0.00	*16.00 F	✓
9	20		*FRONT BUMPER CLIPS	me 0.00	0.00	*40.00 F	✓
10	1		*FRONT BUMPER SPONGE	0.00	0.00	*45.00 F	?
11	1		*FRONT BUMPER CENTER LOGO	me 0.00	0.00	*18.00 F	✓
12	1		*FRONT BUMPER CENTER LOWER GRILLE	C/R 0.00	0.00	*300.00 F	✓
13	1		*TOWING COVER	nd 0.00	0.00	*30.00 F	✓
14	1		*FRONT BUMPER TOP COVER	0.00	0.00	*160.00 F	?
15	6		*FRONT BUMPER TOP COVER RIVETS	me 0.00	0.00	*24.00 F	✓
16	1		*FOGLAMP COVER RH	0.00	0.00	*45.00 F	?
17	1		*ENGINE LOWER COVER-CHECK PRICE	Sm 0.00	0.00	*160.00 F	X
18	1		*RADIATOR SUPPORT PANEL	0.00	0.00	*200.00 F	?
19	1		*RADIATOR	0.00	0.00	*320.00 F	?
20	1		*AIR CON CONDENSER	0.00	0.00	*300.00 F	?
21	1		*FRONT BONNET RUBBER SEAL	cm 0.00	0.00	*30.00 F	✓
22	1		*BRACE PANEL	0.00	0.00	*28.00 F	?
23	1		*RADIATOR COOLANT	0	0.00	*35.00 FS	?
24	1		*NUMBER PLATE	Bz 0	0.00	*35.00 FS	✓

F=Franchise part. S=SpcNett.

Total Parts (S\$)

5,961.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			<i>200</i>
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	30.00
2	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES; RADIATOR AND HOSES; VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	New	120.00 ?
3	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD FRONT SUPPORT PANEL; TO KNOCK & REPAIR AFFECTYED AREAS; INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	<i>500</i> 900.00
4	TO SPRAY BONNET; FRONT BUMPER; FRONT FENDER LH / RH ; FRONT DOOR LH / RH	New	<i>600</i> 900.00
Gross Labour Cost (S\$)			1,950.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Feb 2019 15:09 Sendback Est	26 Feb 2019 15:17 S\$7,911.00	26 Feb 2019 16:05 Edit Adj Rpt	S\$5,403.00 Edit Estimates	S\$5,403.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	NG WILLIAM , ID: S1802651A		
Vehicle Reg. No.:	SKL4555X	Date of Loss:	21/02/2019 00:00 - :59 [63 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201900005016	Policy/Cover Note No.:	PNPV2017-00007666-01 (Comprehensive)
		Excess:	S\$500.00
Repairer:	Ah Lim Motor Company (Sin Ming) 176 Sin Ming Drive #05-12, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64563637		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 07/03/2019]		
Driver/Custodian:	CHANG YOKE FONG (47 / Female) , NRIC: S7172720C, Tel: +6591190401 Email: changyf26@gmail.com		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- FWD_SG (01/03/2019): Alert - Adj Mandate Maintained - SKL4555X - Claim Handler: Lionel Tan

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKL4555X (1201900005016)

OD

Feb 21 2019 12:00AM




[NG WILLIAM]

Ah Lim Motor Company

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[View](#)
[View in Browser ▼](#)





















Assessment Reports

1 per page ▼ ☒

No	Finalized On	Ah Lim Motor Company (Sin Ming)	Thumbnail	Print
1	26/02/19 15:17	Repairer Estimates	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/02/19 14:01	Adjuster Immediate Advice	 Load HTM	
2	27/02/19 15:05	Adjuster Immediate Advice	 Load HTM	






Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/03/19 12:21	General View	 Load JPG <input checked="" type="checkbox"/>	
2	01/03/19 12:21	General View	 Load JPG <input checked="" type="checkbox"/>	
3	01/03/19 12:21	General View	 Load JPG <input checked="" type="checkbox"/>	
4	01/03/19 12:21	General View	 Load JPG <input checked="" type="checkbox"/>	
5	01/03/19 12:21	General View	 Load JPG <input checked="" type="checkbox"/>	
6	01/03/19 12:21	General View	 Load JPG <input checked="" type="checkbox"/>	
7	01/03/19 12:21	General View	 Load JPG <input checked="" type="checkbox"/>	
8	01/03/19 12:21	General View	 Load JPG <input checked="" type="checkbox"/>	
9	01/03/19 12:21	General View	 Load JPG <input checked="" type="checkbox"/>	
10	01/03/19 12:21	General View	 Load JPG <input checked="" type="checkbox"/>	
11	01/03/19 12:21	General View	 Load JPG <input checked="" type="checkbox"/>	
12	01/03/19 12:21	General View	 Load JPG <input checked="" type="checkbox"/>	
13	01/03/19 12:21	General View	 Load JPG <input checked="" type="checkbox"/>	
14	01/03/19 12:21	General View	 Load JPG <input checked="" type="checkbox"/>	
15	01/03/19 12:21	General View	 Load JPG <input checked="" type="checkbox"/>	
16	01/03/19 12:21	General View	 Load JPG <input checked="" type="checkbox"/>	
17	01/03/19 12:21	General View	 Load JPG <input checked="" type="checkbox"/>	
18	01/03/19 12:21	Chassis Number	 Load JPG <input checked="" type="checkbox"/>	
19	01/03/19 12:21	Odometer Reading	 Load JPG <input checked="" type="checkbox"/>	
20	01/03/19 12:21	General View	 Load JPG <input checked="" type="checkbox"/>	


































Documentation

1 per page ▼ ☒

No	Finalized On	Ah Lim Motor Company (Sin Ming)	Thumbnail	Print
1	26/02/19 15:12	E-filed GIA report	 Load PDF	
2	26/02/19 15:12	Certificate of Insurance	 Load PDF	
3	26/02/19 15:12	Driver's Particulars	 Load PDF	
4	26/02/19 15:12	Log card (if available)	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/02/19 15:28	ESTIMATE.pdf	 Load PDF	

Linked Accident Report Documents

View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (Sin Ming)	Thumbnail	Print
1	21/02/19 18:09	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (Sin Ming)	Thumbnail	Print
1	21/02/19 18:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	21/02/19 18:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	21/02/19 18:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	21/02/19 18:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	21/02/19 18:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	21/02/19 18:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	21/02/19 18:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	21/02/19 18:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	21/02/19 18:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	21/02/19 18:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	21/02/19 18:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	21/02/19 18:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	21/02/19 18:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	21/02/19 18:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
15	21/02/19 18:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
16	21/02/19 18:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
17	21/02/19 18:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
18	21/02/19 18:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
19	21/02/19 18:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
20	21/02/19 18:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
21	21/02/19 18:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
22	21/02/19 18:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
23	21/02/19 18:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
24	21/02/19 18:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
25	21/02/19 18:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
26	21/02/19 18:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
27	21/02/19 18:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
28	21/02/19 18:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
29	21/02/19 18:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
30	21/02/19 18:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (Sin Ming)	Thumbnail	Print
1	21/02/19 18:06	Sketch Plan	 Load TIF	
2	21/02/19 18:06	Driver's Particulars	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD19003629/KSD3S2
Date: 07/03/2019

REFERENCE

Insured/Claimant:	NG WILLIAM	Policy No:	PNPV2017-00007666-01	
Date of Loss:	21/02/2019	Nature of Claim:	OD	Claim No: 1201900005016

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKL4555X	Engine No:	LF11562475
Make & Model:	MAZDA 5, 2.0 (A)	Chassis No:	JM6CW10F1E0116853
Reg. Date:	14/11/2013 (Man. Year: 2013)	Odometer:	73063 km
Colour:	Metallic Grey		
Engine Capacity:	1999 cc		
Market Value/New Car Price:	S\$56,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Maxxis 7 mm	Rear Left Side:	Maxxis 7 mm
Front Right Side:	Maxxis 7 mm	Rear Right Side:	Maxxis 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,961.00	4,283.00	1,678.00	28.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,950.00	1,120.00	830.00	42.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,911.00	5,403.00	2,508.00	31.70
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	7,911.00	4,903.00	3,008.00	38.02
+ GST 7.00/7.00% (S\$)	553.77	343.21	210.56	38.02
Nett Amount (S\$)	8,464.77	5,246.21	3,218.56	38.02

INSPECTION

Date of Assignment:	26/02/2019	Present Location:	Ah Lim Motor Company (Sin Ming)
Date Inspected:	27/02/2019	Inspected At:	Ah Lim Motor Company (Sin Ming) 176 Sin Ming Drive #05-12, Sin Ming AutoCare Singapore 575721
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1,578.00 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Mar 2019)
Parts:	M1-MPV	MAZDA 5 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKL4555X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	900.00 F	*900.00 F
2	10		*FRONT BONNET INSULATOR CLIPS	Necessary	30.00 F	*30.00 F
3	2		*FRONT BONNET HINGE LH /RH	Repair	60.00 F	*- F
4	2		*HEADLAMP RH / LH	Mtg Cracked	2,440.00 F	*2,440.00 F
5	2		*HEADLAMP LOWER BRACKET LH / RH	*Check	40.00 F	*- F
6	1		*FRONT BUMPER	Buckled	420.00 F	*420.00 F
7	1		*FRONT BUMPER REINFORCEMENT	*Check	285.00 F	*- F
8	2		*FRONT BUMPER SIDE RETAINER LH / RH	Distorted	16.00 F	*16.00 F
9	20		*FRONT BUMPER CLIPS	Necessary	40.00 F	*40.00 F
10	1		*FRONT BUMPER SPONGE	*Check	45.00 F	*- F
11	1		*FRONT BUMPER CENTER LOGO	Necessary	18.00 F	*18.00 F
12	1		*FRONT BUMPER CENTER LOWER GRILLE	Cracked	300.00 F	*300.00 F
13	1		*TOWING COVER	Dented	30.00 F	*30.00 F
14	1		*FRONT BUMPER TOP COVER	*Check	160.00 F	*- F
15	6		*FRONT BUMPER TOP COVER RIVETS	Necessary	24.00 F	*24.00 F
16	1		*FOGLAMP COVER RH	*Check	45.00 F	*- F
17	1		*ENGINE LOWER COVER-CHECK PRICE	Serviceable	160.00 F	*- F
18	1		*RADIATOR SUPPORT PANEL	*Check	200.00 F	*- F
19	1		*RADIATOR	*Check	320.00 F	*- F
20	1		*AIR CON CONDENSER	*Check	300.00 F	*- F
21	1		*FRONT BONNET RUBBER SEAL	Cut	30.00 F	*30.00 F
22	1		*BRACE PANEL	*Check	28.00 F	*- F
23	1		*RADIATOR COOLANT	*Check	35.00 FS	*- FS
24	1		*NUMBER PLATE	Bent	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	5,961.00	4,283.00
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	30.00	20.00
2	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES; RADIATOR AND HOSES; VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS. (*Check)	New	120.00	0.00
3	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD FRONT SUPPORT PANEL; TO KNOCK & REPAIR AFFECTYED AREAS; INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	900.00	500.00
4	TO SPRAY BONNET; FRONT BUMPER; FRONT FENDER LH / RH ; FRONT DOOR LH / RH	New	900.00	600.00
Gross Labour Cost (\$\$)			1,950.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >