

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan

Date: 27 Feb 2019

Preliminary Advice

Vehicle No	: SKL4555X	Accident Date	: 21/02/2019
Make	: MAZDA 5	Policy No.	: PNPV2017-00007666-01
Assignment Date	: 26/02/2019	Excess	: S\$500.00
Date of Inspection	: 27/02/2019	Est. Duration of Repair	: 5 days
Inspection At	: Ah Lim Motor Company (Sin Ming) 176 Sin Ming Drive #05-12, Sin Ming AutoCare Singapore 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,911.00
Revised Amount	:S\$	5,403.00
Check Items (Estimated)	:S\$	1,578.00
Total	:S\$	6,981.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	56,000.00
COE / PARF Rebate	:S\$	53,777.00
Salvage Value	:S\$	
Margin for Repair	:S\$	2,223.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Repairer proposed \$ 5,500.00 to repair the vehicle on part by part basis.