

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan

Date: 27 Feb 2019

Preliminary Advice

| | | | |
|--------------------|---|-------------------------|------------------------|
| Vehicle No | : SKL4555X | Accident Date | : 21/02/2019 |
| Make | : MAZDA 5 | Policy No. | : PNPV2017-00007666-01 |
| Assignment Date | : 26/02/2019 | Excess | : S\$500.00 |
| Date of Inspection | : 27/02/2019 | Est. Duration of Repair | : 5 days |
| Inspection At | : Ah Lim Motor Company (Sin Ming) 176 Sin Ming Drive #05-12, Sin Ming AutoCare Singapore 575721 | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 7,911.00 |
| Revised Amount | :S\$ | 5,403.00 |
| Check Items (Estimated) | :S\$ | 1,578.00 |
| Total | :S\$ | 6,981.00 |

| | | |
|-----------------|------|--|
| Lump Sum Repair | :S\$ | |
|-----------------|------|--|

Total Loss Consideration

| | | |
|--------------------|------|-----------|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | 56,000.00 |
| COE / PARF Rebate | :S\$ | 53,777.00 |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | 2,223.00 |

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We are pending repair cost from repairer