

2007/08

ASS. REC. BY

REF: 08/FCI19003631/Krd3

02
Special Instruction

Surveyor
CWS

ASSIGNMENT (Office)

From (Person): Kelvin Tan

of FCI

Date/Time: 2:54pm 26/2/19

Estimated Cost: Bill to:

OD (IT) WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No. 8KS3858S

Insured: SH 6976C

at Workshop n/s Complete VMS

Tel: 61550012

of 176 Sin Ming Drive #03-14

Policy No. Claim No. D19001390MFSH

Sum Insured: Excess:

Make of Vch: (Client's Record) D.O.A. 24/2/2019

CA / REV / REP. / REV 24 HRS lup
H.O.D. Endorsement: 27/2/19

Date/Time: 5:25pm 26/2/19 Person Contacted: Ji Hui Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	8KS3858S-X
	SH 6976C - CS3/FCI 6005477/Ugh 3c2 DOA: 22/3/16
1/3/19	Email preli revised to FCI
14/3	11pm 8200d email & confirm (Ref 3452.92, 6890)

REF: FCI

INSURANCE

Form Date: 27/12/19

Estimated Cost

OD: WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKS 3858S

at Workshop: Complete VMS
176 Sin Ming Drive #03-14

Insured

Policy No

Claim No

Sum Insured


Excess

(Client's Record)

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 857k

IDAC Accident Report Consistent? Yes or No

GIA / PR Seen Consistent? Yes or No

Est. Repairs: 04 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKS 3858S Regn: 04 15

Type: Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: (Honda Vezel) CC: 1496

Colour: M.P. White AC: Insured / Std / Nil / NA

Sp Reading: 70883 T/Radio: Insured / Std / Nil / NA

Eng No

Chassis No: R41 1017505

Gen Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / SRim / STD / RRim or

Tyre Size: F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 9 mm

R/Bal: 9 mm

L/Bal: 9 mm

L/Bal: 9 mm

D.O.A: 24/12/19

D.O.I: 27/12/19

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 14 MAR 2019

Date/Time, File Pass to?

Prel. Report

1)

Final Report

Date/Time, File Return to?

2) 143 - typist

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation

1) 50

2) 50

3) 12

4) 12

TOTAL

Report Format: CWS

Lump Sum / LB: 2000k

Add Fee:

Site Insp (\$)

Interview (\$)

Tech Invs (\$)

Week-end (\$)

140
50
50
12
12
252



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19001390MFSH

Our ref: CS/FCI19003631/Kvd3

Date : 1/3/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKS 3858S


We thank for your instruction on 26/2/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 27/2/2019 at the premises of M/s COMPLETE VMS PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$5,452.92
Revised Estimate Amount	: S\$2,855.52
"Check" Items Amount	: S\$280.00
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	26-02-2019	Our Ref No. D19001390MFSH
Accident Date	24-02-2019	Claim Type. Third Party
Insured Vehicle	SH6976C	Third Party Vehicle. SKS3858S
Survey Location	176 SIN MING DRIVE #03-14SIN MING AUTOCARE COMPLEX	
Contact Person.	LILY/LI HUI (TEL: 64539622)	
Contact No.	64550012/ 0	Fax No. 65540012
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	COMPLETE VMS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Gan Li Hui <lihui@completevms.com.sg>
Sent: Thursday, 14 March 2019 11:52 AM
To: Kenneth Kong (LKKAuto)
Subject: Re: SKS3858S DOA: 24/2/2019

Without Prejudice

Dear Mr Kenneth,

L/S \$2000.00 before GST (OK)

Thank you & Best Regards,

Gan Li Hui (Ms)

Complete VMS PTE LTD

Block 176 Sin Ming Drive, #03-14

Sin Ming Autocare Complex, Singapore 575721

Tel: 6455 0012 Fax: 6554 0012

On Thu, 14 Mar 2019 at 10:35, Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com> wrote:

Attach finalised for SKS 3858S. Kenneth

From: Gan Li Hui [mailto:lihui@completevms.com.sg]

Sent: Wednesday, 13 March, 2019 2:30 PM

To: Kenneth Kong (LKKAuto)

Subject: SKS3858S DOA: 24/2/2019

Without Prejudice

Dear Mr Kenneth,

Please finalize.

Thank you & Best Regards,
Gan Li Hui (Ms)

Complete VMS PTE LTD

Block 176 Sin Ming Drive, #03-14

Sin Ming Autocare Complex, Singapore 575721

Tel: 6455 0012 Fax: 6554 0012

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 1 March 2019 3:34 PM
To: 'CWS Motor Claims'
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001390MFSH/1, SKS 3858S
Attachments: SKS 3858S PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SKS 3858S
Date of survey: 27/2/2019
Number of days : 4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 26 February 2019 5:27 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001390MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer agreed survey on 27/02/2019.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 26 February 2019 2:54 PM
To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19001390MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9801E
Vehicle Details	
Vehicle No.:	SKS38585
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X AUTO
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	L15B3517501
Chassis No.:	RU11017505
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$18,556.00
Original Registration Date:	13 Apr 2015
First Registration Date:	13 Apr 2015
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Apr 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	12 Apr 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,199.00
COE Rebate Amount:	\$34,970.00
Total Rebate Amount:	\$38,720.00

The information contained herein is correct as at 01 Mar 2019

OK



*Not Authored
 11 Sep @ 2000hr
 Resurvey After Paint
 4 days*

Email : darren@completevms.com.sg ()
 lily@completevms.com.sg ()
 lihui@completevms.com.sg ()

TAN KUOK CHIANG
 BLK 272C PUNGGOL WALK #04-583
 SINGAPORE 823272

Attention : THE OWNER
 Contact : 92282417

Estimate : ES006611

Date : 25/02/2019
 Vehicle Num. : SKS3858S
 Make/Model : HONDA VEZEL 1.5X A-2015
 Chassis/Eng# : RU11017505/L15B3517501
 Accident Date : 24/02/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		LIST ITEMS :		
1.	1	TAIL GATE <i>1100.90</i>	<i>Bu</i> 1,260.00	✓
2.	1	TAIL GATE LOCK	<i>R</i> 198.00	X
3.	1	REAR W/SCREEN MOULDING TOP	<i>nn</i> 56.20	—
4.	1	REAR W/SCREEN MOULDING LOWER	<i>nn</i> 68.00	—
5.	2	REAR W/SCREEN MOULDING SIDE	35.00 <i>nn</i> 70.00	—
6.	1	REAR END PANEL	<i>R</i> 638.00	X
7.	1	REAR BUMPER <i>610.20</i>	<i>Bu</i> 880.00	✓
8.	6	REAR BUMPER CLIP	4.20 <i>nn</i> 25.20	✓
9.	2	REAR BUMPER BRACKET	121.00 <i>R</i> 242.00	X
		List TotalS\$:		3,437.40
		20.00% Discount S\$:		687.48
				2,749.92
		SPECIAL NETT ITEMS :		
1.	1	VEZEL EMBLEM	<i>nn</i> 68.00	✓
2.	1	H LOGO	<i>nn</i> 60.00	X
3.	1	REAR W/SCREEN SEALANT	<i>nn</i> 65.00	405m
4.	1	REVERSE SENSOR	<i>nn</i> 280.00	X
		Special Nett Total S\$:		473.00
		LABOUR :		
		REMOVE & REINSTALL REAR W/SCREEN GLASS	<i>120l</i> 180.00	
		TRANSFER TAILGATE COMPONENT TO NEW GATE	150.00	<i>60l</i>
		RUST PROOFING TREATMENT	100.00	<i>30l</i>
		SPRAY PAINT DAMAGED AREA AFFECTED	<i>250l</i> 900.00	<i>400l</i>
		TO CUT OFF REAR END PANEL, KNOCK AND STRAIGHTEN REAR		

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



COMPLETE VMS PTE LTD *The Premier One-Stop Vehicle Accident Claims Centre*
 176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
 (Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
 lily@completevms.com.sg ()
 lihui@completevms.com.sg ()

TAN KUOK CHIANG
 BLK 272C PUNGGOL WALK #04-583
 SINGAPORE 823272

Attention : THE OWNER
 Contact : 92282417

Estimate : ES006611

Date : 25/02/2019
 Vehicle Num. : SKS3858S
 Make/Model : HONDA VEZEL 1.5X A-2015
 Chassis/Eng# : RU11017505/L15B3517501
 Accident Date : 24/02/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS		900.00
		Labour Total S\$:		2,230.00

4000 Total

SingDollars : Five Thousand Four Hundred Fifty-Two & Cents Ninety-Two Only

Total S\$: 5,452.92

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19003631/Kvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 14-03-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 6976C	Veh. Inspected	SKS 3858S
Policy No.		Coverage (\$)	0.00
Claim No.	D19001390MFSH	Excess (\$)	0.00
Assign From	KARENT	Assign Date	26/02/2019
2. Vehicle Particulars & Condition			
Make & Model	HONDA VEZEL (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	RU11017505	Colour	METALLIC PEARL WHITE
Odometer	70883	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	MICHELIN	9 mm
L/H Front Tyre	215/60 R16	MICHELIN	9 mm
R/H Rear Tyre	215/60 R16	MICHELIN	9 mm
L/H Rear Tyre	215/60 R16	MICHELIN	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	24/02/2019	Inspection Date	27/02/2019
Survey held at	COMPLETE VMS PTE LTD BLK 176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX SINGAPORE 575721		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 3858S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAIL GATE	BENT	1,260.00	1,100.90
1	TAIL GATE LOCK	TO REPAIR SEE LABOUR	198.00	-
1	REAR W/SCREEN MOULDING TOP	NECESSARY	56.20	56.20
1	REAR W/SCREEN MOULDING LOWER	NECESSARY	68.00	68.00
2	REAR W/SCREEN MOULDING SIDE @\$35.00	NECESSARY	70.00	70.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	638.00	-
1	REAR BUMPER	BUCKLED	880.00	610.20
6	REAR BUMPER CLIP @\$4.20	NECESSARY	25.20	25.20
2	REAR BUMPER BRACKET @\$121.00	TO REPAIR SEE LABOUR	242.00	-
	LESS 20% DISCOUNT		-687.48	-386.10
			2,749.92	1,544.40
SPECIAL NETT ITEMS				
1	VEZEL EMBLEM (SN)	NECESSARY	68.00	68.00
1	H LOGO (SN)	NOT NECESSARY	60.00	-
1	REAR W/SCREEN SEALANT (SN)	NECESSARY	65.00	40.00
1	REVERSE SENSOR (SN)	SERVICEABLE	280.00	-
			473.00	108.00
LABOUR				
	REMOVE & REINSTALL REAR W/SCREEN GLASS.		180.00	120.00
	TRANSFER TAILGATE COMPONENT TO NEW GATE.		150.00	60.00
	RUST PROOFING TREATMENT.		100.00	30.00
	SPRAY PAINT DAMAGED AREA AFFECTED.		900.00	250.00
	TO CUT OFF REAR END PANEL,KNOCK AND STRAIGHTEN REAR CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS.INCLUSIVE OF THE REPAIR OF TAIL GATE LOCK,REAR END PANEL AND REAR BUMPER BRACKET.		900.00	400.00
			2,230.00	860.00
GRAND TOTAL			5,452.92	2,512.40



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,000.00
---	--	--	----------

Report Ref No. CS/FCI19003631/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.