

AGS, REC BY:

REP

08/FCI19003636/UtD3

Special Instruction

Surveyor

ASSIGNMENT (Office)

CWS

Mening Chig

of

FCI

Date/Time

3:05pm 26/2/19

Estimated Cost

Bill to:

OD / (1) / WS / TP RES / OD RES / EVA / INV / MVTCS

To Inspect Vehicle No.

SLA 97202

Insured

SHA 9711X

at Workshop m/s

Progressive

Tel

67415336

of

BLK 3022A Ubi Rd 1 # 01-45/46

Policy No.

Claim No.

D19001341MP84

Sum Insured

Excess:

Make of Veh:

D.O.A

24/2/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

(DS)

27/2/19 @ after 10:30am

H.O.D. Endorsement

Date/Time:

5:01pm 26/2/19

Person Contacted:

pei wen

Vehicle

(OUT)

Date/Time

Action/Instruction

(✓)

Estimate

SLA 97202-X

SHA 9711X-NA/EQT18COS180/14

D.O.A: 17/3/18

28/2@2:43pm- revised via email preli advise.

REF: FCI


ASSIGNMENT

Date: 27/2/19
 Estimated Cost:
 ON ☒ WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: 3LA 97202
 at Work shop no: progressive
 of: BLK 3022A, Ubi Rd 1 # 01-45/46
 Insured:
 Policy No:
 Claims No:
 Sum Insured:
 (Client's Record)
 Make of Veh:

After 1030am

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value:

60k.

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days: Res.: Yes or No

Lump Sum:

13%

3 Val.: Yes or No

CA / REV / REP: / 24 HRS '052

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: 3LA97202
 Type: ☒ M Car / ☐ M Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or (A/

Make: Toyota Sienta

C.C. 1496

Colour: white

Insured / Std / NI / NA

Sp. Reading: 95215

T/Radio: Insured / Std / NI / NA

Eng No:

C/Ro:

NSP 170 70 10 638

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modt: Nil / STD A/Rim or

Tyre Size:

F:

185/60 R15

R:

BS / DUN / EXNOVA / GY / ES / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

7

mm

R/Bal:

7

mm

L/Bal:

7

mm

L/Bal:

7

mm

D.O.A:

24/2/19

D.O.I:

27/2/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/2/19

14/3/19 confirmed final f & 6044.58 with Ray.
 (Red: 3700, 38%)

RECEIVED 15 MAR 2019

Date/Time, File Pass to?

15/3 Typist



Date/Time, File Return to?

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation

) S + PC

) Photo

) Other

TOTAL

Report Format:

Lump Sum / I.R. /

TP

6044.58

Add Fee:



Site Insp (\$)



Interview (\$)



Tech Insp (\$)



Week-end (\$)

170

50

50

76

346



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001391MFSH

Date: 28/2/2019

Our Ref: CS/FCI19003635/Utd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLA 9720Z

Please be informed that we had conducted the inspection of the abovementioned vehicle 27/2/2019 at the premises of M/s progressive have the following to report: -

Workshop Estimate Amount	: S\$	<u>9,285.33</u>
Revised Estimate Amount	: S\$	<u>5,530.32</u>
"Check" Items Amount	: S\$	<u>2,010.13</u>
Market Value	: S\$	<u> </u>
LTA Reimbursement Value	: S\$	<u> </u>
Nett Value	: S\$	<u> </u>

Description of Damage:
The vehicle sustained damages at the rear portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
Marcus
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	26-02-2019	Our Ref No. D19001391MFSH
Accident Date	24-02-2019	Claim Type. Third Party
Insured Vehicle	SHA9711Y	Third Party Vehicle. SLA9720Z
Survey Location	BLK 3022A UBI ROAD #01-45/46	
Contact Person.	LILY LIM	
Contact No.	67415336/ 0	Fax No. 67417208
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PROGRESSIVE CAR CARE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MERINA CHIA SAN SAN	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Thursday, 28 February 2019 2:43 PM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Merina Chia San San'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001391MFSH/1
Attachments: PRELI ADVISED SLZ 9720Z.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLA 9720Z**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 26 February 2019 5:40 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Merina Chia San San' <MerinaChia@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001391MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer arrange on 27/02/2019.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 26 February 2019 3:05 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Merina Chia San San <MerinaChia@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19001391MFSH/1

Dear Sir/Mdm,

Denise Tay (LKKAUTO)

From: Ray <ray@procarcare.com.sg>
Sent: Thursday, 14 March 2019 1:02 PM
To: Marcus Chua (LKKAUTO)
Cc: Wayne; Peiwen; Chermaine
Subject: SLA9720Z - TO FINALIZE
Attachments: REPORT .pdf

Hi Marcus,

Please refer to finalize

Supp	\$464.25
Parts	\$3095.33
Sn	\$295.00
Lab	\$2190.00
Total	\$6044.58

Regards,

Ray LIN

Damage Assessment

Progressive Automotive Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

T: +65 6741 5336 | F: +65 6741 7208

E: claims@procarcare.com.sg

W: www.procarcare.com.sg

With effect from 1 Sep 2018, **Progressive Automotive Pte Ltd will be rebranded as **Progressive Car Care Pte Ltd**. You may now reach us at our new email addresses (@procarcare.com.sg) and our old email addresses (@progauto.com.sg) shall cease to function with effect from 1 Sep 2018. We look forward to your continued support.*

CHEAPEST CAR INSURANCE RENEWAL



Compare
10+ Insurers

GET A CHEAPER QUOTE NOW!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 10 Years Coe Renewal Toyota Estima 2.4A



2.38%P.A Low Interest@GV
Finance. \$0 Admin Fees. \$4800
Downpayment Monthly \$988
GV Credit Pte Ltd StarAd



VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND

HOTLINE: 6741 9997

VIEW OUR CARS

Browse by Category

Sort by Date Posted 20 results/page

10 vehicles

Sienta

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Sienta		Any	Any	2016	Any	Any	Any	Available
	Toyota	Sienta 1.5A X	\$64,800	\$8,150 /yr	28-Jul-2016	1,496 cc	42,000 km	MPV	Available
1 Owner. Well Maintained. Pristine Pearl White Paintwork, Fitted With Black Leather With Orange Trims. Most Economical MPV In The Market Right Now. Enough Seats For Your Children, Parents And Helper! ... Auto Zoom Enterprise Pte Ltd Posted: 27-Feb-2019 Tags: 2016 Toyota Sienta, 2016 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota									
	Toyota	Sienta 1.5A X	\$69,888	\$8,790 /yr	22-Jul-2016	1,496 cc	41,000 km	MPV	Available
Full Service Record Warranty Until July 2019 New Front Tires (Feb 2019). Posted: 24-Feb-2019 Tags: 2016 Toyota Sienta, 2016 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota									
	Toyota	Sienta 1.5A G	\$65,800	\$8,490 /yr	04-Feb-2016	1,496 cc	43,900 km	MPV	Available
1 Single Owner, Not Those Usual Grab/Uber/Gojek Vehicle! Made In Japan, Best Selling Small/Mid Size MPV With 20.2km/L Impressive Fuel Consumption. Higher Spec And A Lot More Feature Than x Model But Wi... Posted: 23-Feb-2019 Tags: 2016 Toyota Sienta, 2016 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota									
	Toyota	Sienta 1.5A G	\$68,998	\$8,110 /yr	22-Nov-2016	1,496 cc	-	MPV	Available
Be Our Next Lucky Client To Own This Impressive Grade-A Pre-Owned Vehicle At Most Reasonable And Affordable Price! Still Under Warranty With 2 Free Servicing. Exterior In Nearly Mint Condition, Extrem... Posted: 23-Feb-2019 Tags: 2016 Toyota Sienta, 2016 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota									
	Sprint Booster Throttle Controller 3 Drive Latest For TOYOTA. Electronic Throttle Special Harness & Cable Type Throttle Controller.Guaranty Pickup Response More info about this product								
	Toyota	Sienta 1.5A G	\$63,800	\$8,060 /yr	30-Jun-2016	1,496 cc	79,000 km	MPV	Available
1 Careful Owner Upgraded To New Car. Very Well-Kept. Lowest Depreciation. High Loan Available. Don't Miss! Car Times Automobile Pte Ltd Posted: 22-Feb-2019 Tags: 2016 Toyota Sienta, 2016 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota									
	Toyota	Sienta 1.5A G (OPC)	\$59,800	\$7,160 /yr	25-Aug-2016	1,496 cc	34,000 km	MPV	Available
Tip Top Condition! Rare OPC Unit For Sale! Made In Japan. Loads Of Additional Accessories To Go With. Easy Finance. Most Sought After 7 Seaters MPV! Trade In Welcome. Must View To Appreciate. Selling ... Don Motoring Posted: 19-Feb-2019 Tags: 2016 Toyota Sienta, 2016 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota									
Compare	Toyota	Sienta 1.5A G	\$65,800	\$8,400 /yr	26-May-2016	1,496 cc	52,047 km	MPV	Available

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 4375J

Vehicle Details

Vehicle No.: SLA9720Z
Vehicle to be Exported: No
Intended Deregistration Date: 27 Feb 2019
Vehicle Make: TOYOTA
Vehicle Model: SIENTA 1.5G A
Primary Colour: White
Manufacturing Year: 2015
Engine No.: 2NR8543816
Chassis No.: NSP1707010638
Maximum Power Output: 80.0 kW (107 bhp)
Open Market Value: \$19,042.00
Original Registration Date: 23 Mar 2016
First Registration Date: 23 Mar 2016
Transfer Count: 0
Actual ARF Paid: \$14,042.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 22 Mar 2026
PARF Rebate Amount: \$10,531.00

Intended COE Rebate Details

COE Expiry Date: 22 Mar 2026
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$43,000.00
COE Rebate Amount: \$30,367.00
Total Rebate Amount: \$40,898.00

The information contained herein is correct as at 27 Feb 2019

OK

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
 GST:201006949C RCB NO:201006949C

Not Authorized
27/2/19
Take photo before repairing
2/2K
Take photo before
body

M/S : GOH XIANG DA
 BLK 740 PASIR RIS ST 71 #07-49
 SINGAPORE 510740

Estimate No: EST1504611
 Date: 25 Feb 2019
 Policy No: D28913975QMY
 Veh Reg No: SLA9720Z
 Make/Model: TOYOTA SIENTA 1.5G A
 Chassis No: NSP1707010638
 Engine No: 2NR8543816
 Reg. Date: 23/03/2016

ATTN:
 Your Ref No: TP 0219-5416
 Claim Type: Third Party
 Accident Date: 24/02/2019
 TP Veh Reg No: SHA 9711 Y

Estimate Repair Cost to Vehicle No :SLA9720Z

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 REAR BOOT <i>Body</i>	1,086.100	1 PCS	1,086.10	—
2 REAR BOOT RUBBER <i>TVI</i>	357.0000	1 PC	357.00	—
3 REAR BOOT TOP LOCK <i>MBM</i>	448.0000	1 PC	448.00	—
4 REAR BOOT BOTTOM LOCK <i>11</i>	55.1000	1 PC	55.10	X
5 REAR BOOT GLASS MOULDING <i>neu</i>	130.0000	2 PCS	260.00	—
6 REAR BOOT TOYOTA LOGO <i>neu</i>	58.3000	1 PC	58.30	—
7 REAR BOOT OUTER GARNISH <i>11</i>	278.0000	1 PCS	278.00	—
8 REAR BOOT REFLECTOR - LH <i>11</i>	178.3000	1 PC	178.30	—
9 REAR BOOT REFLECTOR - RH <i>11</i>	178.3000	1 PCS	178.30	—
10 REAR BOOT WIPER MOTOR <i>11</i>	575.0000	1 PCS	575.00	X
11 REAR BUMPER TOP PAD, BLACK - CENTRE <i>D.S</i>	182.0000	1 PCS	182.00	—
12 REAR BUMPER, LH PAD, BLACK - LH <i>CU?</i>	124.0000	1 PCS	124.00	—
13 REAR BUMPER, RH PAD, BLACK - RH <i>11</i>	124.0000	1 PCS	124.00	X
14 REAR BUMPER LOWER, WHITE <i>D.S</i>	360.4000	1 PC	360.40	—
15 REAR BUMPER CLIPS <i>neu</i>	8.9000	10 PC	89.00	—
16 REAR BUMPER SIDE HOLDER - LH <i>11</i>	68.1000	1 PCS	68.10	X
17 REAR BUMPER SIDE HOLDER - RH <i>11</i>	68.1000	1 PCS	68.10	X
18 REAR BUMPER BRACKETS - LH <i>11</i>	78.0000	1 PC	78.00	X
19 REAR BUMPER BRACKETS - RH <i>11</i>	78.0000	1 PC	78.00	X
20 REAR BUMPER REFLECTORS - LH <i>11</i>	52.1000	1 PC	52.10	X
21 REAR BUMPER REFLECTORS - RH <i>11</i>	52.1000	1 PC	52.10	X
22 REAR BUMPER SENSOR - LH <i>should</i>	410.6000	1 PC	410.60	220 S.W
23 REAR BUMPER SENSOR - RH <i>11</i>	410.6000	1 PC	410.60	X
24 REAR TAILLAMP - LH <i>11</i>	350.0000	1 PC	350.00	X
25 REAR TAILLAMP - RH <i>11</i>	350.0000	1 PC	350.00	X
26 REAR PANEL <i>Body</i>	609.7000	1 PCS	609.70	—
27 REAR PANEL TOP GARNISH <i>D.S</i>	142.1000	1 PCS	142.10	—
28 REAR SPARE TYRE BOARD <i>11</i>	513.7000	1 PC	513.70	X
29 REAR PANEL - OUTER <i>Body</i>	410.5000	1 PCS	410.50	—
			7,947.10	
Less 25%			1,986.78	5,960.33

Special Net

30 REAR BUMPER SENSOR <i>Repair</i>	220.0000	1 SET	220.00	X
31 REAR BOOT CAMERA <i>neu</i>	350.0000	1 SET	350.00	X
32 REAR NUMBER PLATE WITH CASING <i>neu</i>	35.0000	1 SET	35.00	—
33 SPONGE TAPE <i>neu</i>	20.0000	1 PCS	20.00	—
34 SEALANT <i>neu w/brush</i>	20.0000	2 PC	40.00	—

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : GOH XIANG DA
BLK 740 PASIR RIS ST 71 #07-49
SINGAPORE 510740

Estimate No: EST1504611
Date: 25 Feb 2019
Policy No: D28913975QMY
Veh Reg No: SLA9720Z
Make/Model: TOYOTA SIENTA 1.5G A
Chassis No: NSP1707010638
Engine No: 2NR8543816
Reg. Date: 23/03/2016

ATTN:
Your Ref No: TP 0219-5416
Claim Type: Third Party
Accident Date: 24/02/2019
TP Veh Reg No: SHA 9711 Y

Estimate Repair Cost to Vehicle No :SLA9720Z

Description	U/Price	Quantity	Price SS	Amount SS
			665.00	665.00
Labour				
35 TO KNOCK OUT DENTS, CUT/WELD, REAR PANEL, REAR SPARE TYRE FLOOR PANEL, REMOVE, REPLACE ACCIDENT PARTS	1,000.000	1 JOB	1,000.00	900
36 TO RESPRAY PAINT ON ACCIDENT PORTIONS	1,000.000	1 JOB	1,000.00	900
37 TO TUFF-KOTE	100.0000	1 JOB	100.00	60
38 TO CHECK WIRING	50.0000	1 JOB	50.00	20
39 TO REMOVE, REFIX REAR GARNISH, CARPET & RELATED PARTS	150.0000	1 JOB	150.00	80
40 TO TRANSFER REAR BUMPER SENSOR	100.0000	1 JOB	100.00	50
41 TO REMOVE, REPAIR REAR EXHAUST PIPE	80.0000	1 JOB	1180.00	X
42 TO REMOVE, REFIT REAR BOOT GLASS	120.0000	1 JOB	120.00	✓
43 TO TRANSFER REAR BOOT	60.0000	1 JOB	60.00	✓
			2,660.00	2,660.00
Total				SS 9,285.33
Add GST @ 7%				649.97
Total Amount Payable				SS 9,935.30

TOTAL: SINGAPORE DOLLAR NINE THOUSAND NINE HUNDRED THIRTY FIVE AND CENTS THIRTY ONLY

For Progressive Car Care Pte Ltd



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before respray painting
- To clarify damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental estimate must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer
Signature:
Date:

7-4746-1
252
353957
604458

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccare.com.sg
GST:201006949C RCB NO:201006949C

M/S : GOH XIANG DA
BLK 740 PASIR RIS ST 71 #07-49
SINGAPORE 510740

Estimate No: **EST1504611**
Date: 01 Mar 2019
Policy No: D28913975QMY
Veh Reg No: **SLA9720Z**
Make/Model: TOYOTA SIENTA 1.5G A
Chassis No: NSP1707010638
Engine No: 2NR8543816
Reg. Date: 23/03/2016

ATTN:
Your Ref No: TP 0219-5416
Claim Type: Third Party
Accident Date: 24/02/2019
TP Veh Reg No: SHA 9711 Y

Estimate Repair Cost to Vehicle No :SLA9720Z

Description	U/Price	Quantity	Price SS	Amount SS
Supplementary Parts to Repair				
List Price				
1 REAR TRAY LUGGAGE COMPARTMENT <i>one</i>	419.8000	1 PC	419.80	
2 REAR BOOT INNER HANDLE, SMALL - RH <i>one</i>	68.7000	1 PC	68.70	
3 ANTENNA KEY SENSOR <i>one</i>	130.5000	1 PC	130.50	
			619.00	
		Less 25%	154.75	464.25
			Total	SS 464.25
			GST Amount	SS 32.50
			Total Amount Payable	SS 496.75

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19003635/Utd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 18-03-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9711Y	Veh. Inspected	SLA 9720Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19001391MFSH	Excess (\$)	0.00	
Assign From	MERINA CHIA	Assign Date	26/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA SIENTA (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	NSP1707010638	Colour	WHITE	
Odometer	95215	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	YOKOHAMA	7 mm	
L/H Front Tyre	185/60 R15	YOKOHAMA	7 mm	
R/H Rear Tyre	185/60 R15	YOKOHAMA	7 mm	
L/H Rear Tyre	185/60 R15	YOKOHAMA	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/02/2019	Inspection Date	27/02/2019	
Survey held at	PROGRESSIVE CAR CARE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 9720Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT	BADLY DENTED	1,086.10	1,086.10
1	REAR BOOT RUBBER	TWISTED	357.00	357.00
1	REAR BOOT TOP LOCK	DENTED / JAMMED	448.00	448.00
1	REAR BOOT BOTTOM LOCK	NOT NECESSARY	55.10	-
2	REAR BOOT GLASS MOULDING @\$130.00	NECESSARY	260.00	260.00
1	REAR BOOT TOYOTA LOGO	NECESSARY	58.30	58.30
1	REAR BOOT OUTER GARNISH	NOT NECESSARY	278.00	-
1	REAR BOOT REFLECTOR-LH	NOT NECESSARY	178.30	-
1	REAR BOOT REFLECTOR-RH	NOT NECESSARY	178.30	-
1	REAR BOOT WIPER MOTOR	NOT NECESSARY	575.00	-
1	REAR BUMPER TOP PAD,BLACK-CENTRE	DISTORTED	182.00	182.00
1	REAR BUMPER LH PAD,BLACK-LH	CUT	124.00	124.00
1	REAR BUMPER RH PAD,BLACK-RH	NOT NECESSARY	124.00	-
1	REAR BUMPER LOWER,WHITE	DISTORTED	360.40	360.40
10	REAR BUMPER CLIPS @\$8.90	NECESSARY	89.00	89.00
1	REAR BUMPER SIDE HOLDER-LH	NOT NECESSARY	68.10	-
1	REAR BUMPER SIDE HOLDER-RH	NOT NECESSARY	68.10	-
1	REAR BUMPER BRACKETS-LH	NOT NECESSARY	78.00	-
1	REAR BUMPER BRACKETS-RH	NOT NECESSARY	78.00	-
1	REAR BUMPER REFLECTORS-LH	NOT NECESSARY	52.10	-
1	REAR BUMPER REFLECTORS-RH	NOT NECESSARY	52.10	-
1	REAR BUMPER SENSOR-RH	NOT NECESSARY	410.60	-
1	REAR TAILLAMP-LH	NOT NECESSARY	350.00	-
1	REAR TAILLAMP-RH	NOT NECESSARY	350.00	-
1	REAR PANEL	BADLY DENTED	609.70	609.70
1	REAR PANEL TOP GARNISH	DISTORTED	142.10	142.10
1	REAR SPARE TYRE BOARD	NOT NECESSARY	513.70	-
1	REAR PANEL-OUTER	BADLY DENTED	410.50	410.50
1	REAR TRAY LUGGAGE COMPARTMENT (ADDITIONAL)	CRACKED	419.80	419.80
1	REAR BOOT INNER HANDLE,SMALL-RH (ADDITIONAL)	TWISTED	68.70	68.70
1	ANTENNA KEY SENSOR (ADDITIONAL)	CRACKED	130.50	130.50

Report Ref No. CS/FCI19003635/Utd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-2,038.87	-1,186.52
			6,116.63	3,559.58
1	REAR BUMPER SENSOR-LH (SN)	SHORTED	410.60	200.00
	LESS 25% DISCOUNT		-102.65	-
			307.95	200.00
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER SENSOR (SN)	REPEATED	220.00	-
1	SET REAR BOOT CAMERA (SN)	SERVICEABLE	350.00	-
1	SET REAR NUMBER PLATE WITH CASING (SN)	SCRATCHED	35.00	35.00
1	SPONGE TAPE (SN)	NECESSARY	20.00	20.00
2	REAR W/SCREEN SEALANT @\$20.00 (SN)	NECESSARY	40.00	40.00
			665.00	95.00
	LABOUR			
	TO KNOCK OUT DENTS,CUT/WELD,REAR PANEL,REAR SPARE TYRE FLOOR PANEL,REMOVE,REPLACE ACCIDENT PARTS.		1,000.00	900.00
	TO RESPRAY PAINT ON ACCIDENT PORTIONS.		1,000.00	900.00
	TO TUFF-KOTE.		100.00	60.00
	TO CHECK WIRING.		50.00	20.00
	TO REMOVE,REFIX REAR GARNISH,CARPET & RELATED PARTS.		150.00	80.00
	TO TRANSFER REAR BUMPER SENSOR.		100.00	50.00
	TO REMOVE,REPAIR REAR EXHAUST PIPE.	NOT NECESSARY	80.00	-
	TO REMOVE,REFIT REAR BOOT GLASS.		120.00	120.00
	TO TRANSFER REAR BOOT.		60.00	60.00
	-		-	-
	-		-	-
	-		-	-
			2,660.00	2,190.00
	GRAND TOTAL		9,749.58	6,044.58
RECOMMENDED COST OF REPAIRS				6,044.58

Report Ref No. CS/FCI19003635/Utd3n2



Report Ref No. CS/FCI19003635/Utd3n2

A handwritten signature in black ink, appearing to be 'Ch' followed by a stylized flourish.

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.