

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccare.com.sg
GST:201006949C RCB NO:201006949C

M/S : GOH XIANG DA
BLK 740 PASIR RIS ST 71 #07-49
SINGAPORE 510740

Estimate No: **EST1504611**
Date: 01 Mar 2019
Policy No: D28913975QMY
Veh Reg No: **SLA9720Z**
Make/Model: TOYOTA SIENTA 1.5G A
Chassis No: NSP1707010638
Engine No: 2NR8543816
Reg. Date: 23/03/2016

ATTN:
Your Ref No: TP 0219-5416
Claim Type: Third Party
Accident Date: 24/02/2019
TP Veh Reg No: SHA 9711 Y

Estimate Repair Cost to Vehicle No :SLA9720Z

Description	U/Price	Quantity	Price S\$	Amount S\$
Supplementary Parts to Repair				
List Price				
1 REAR TRAY LUGGAGE COMPARTMENT <i>cm</i>	419.8000	1 PC	419.80	
2 REAR BOOT INNER HANDLE, SMALL - RH <i>rw</i>	68.7000	1 PC	68.70	
3 ANTENNA KEY SENSOR <i>cm</i>	130.5000	1 PC	130.50	
			619.00	
		Less 25%	154.75	464.25
			Total	S\$ 464.25
			GST Amount	S\$ 32.50
			Total Amount Payable	S\$ 496.75

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE