

Autowerkz Remanufacturing Pte Ltd

4, Defu Lane 1
Singapore 539479
GST No: 201209464R

Tel : 6468 5335
Fax : 6281 5008
website : www.autowerkz.sg

To : AIG Asia Pacific Insurance Pte Ltd
Date : 20.02.2019

Particulars of vehicle

Reg No.	SJR7516U	Make & Model	: Honda Jazz 1.3L AT
Engine No	L13Z11021457	Chassis No	: JHMGE68509S221451
Year	2008	Registration Date	: 13.07.2009

Accident Detail

Date Of Accident : 18.02.2019
Time Of accident : 7.20am
Place Of Accident : SLE toward BKE after Woodlands Ave 2

Estimated Cost of repair for vehicle No SJR7516U

Item	QTY	U/Price	Amount
1 Rear Boot Door <i>BA</i>	1	\$ 771	\$ 771
2 Rear Bumper <i>DE</i>	1	\$ 497	\$ 497
3 Windscreen Moulding <i>AM</i>	2	\$ 54.42	\$ 108.84

Sub Total: \$ 1376.84

Labour Charge

1) To dismantle damage parts, replace recommended parts and repair of tail lamp panel	\$ 550 <i>400</i>
2) Spray painting on rear boot door, rear bumper and tail lamp panel	\$ 550 <i>400</i>
3) Dismantle and install existing windscreen, windscreen moulding and sealant on new rear boot door	\$ 230 <i>120</i>
4) To remove rear bumper parking sensor	\$ 100 <i>60</i>
5) Check electrical wiring	\$ 100 <i>X</i>

Sub Total: \$ 1530

Grand Total: \$ 2,906.84



Autowerkz Remanufacturing Pte Ltd
Jonathan HP: 98315151

Rasul
Hp 90010068
4 days
4/3
26/02/19 @ 1515
Rasul after repair
email: rasul@1kkauto.com
office: 62563561