

INSURANCE CASE OWNER: CC6 / AIG1900 2643, 4263 | LKK: IDAC:

Surveyor: cks DOI: ASSIGNMENT 27/1/19 Date/Time: 26/1/19  
 Registered in Merimen: 26/1/19

Pre-assign / CCU / FTR  
 Insured Vehicle No.: SMG 34L Claim No.: 40162300555  
 Name of Insured: SIM CHIN HWA Policy No.:  
 Insured Tel No.: HP: 27/1/19 Make / Model: BMW  
 Excess Sec II :SS D.O.A.: 27/1/19 Place of Accident: JUNC of STADIUM WALK  
 Is driver the owner? (YES / NO) Nature of Accident:  
 If NO Driver Name / Age: OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO  
 Driver Tel No.: (V/L) (YES / NO) Insured Liability: % Final? Yes / No

SLC9775M → → → →  
 INSRs WSP: help motor INSRs WSP: INSRs WSP: INSRs WSP:  
 Tel: Tel: Tel: Tel:  
 Liability: Liability: Liability: Liability:  
 RMKS: RMKS: RMKS: RMKS:

Date/Time	STAGE	DATE / PIC
	Non-Reporting Itr (1st):	
	Non-Reporting Itr (2nd):	
	Non-Reporting Itr (Final):	
05-03-19 11:20	Notification Itr (if non-pickup):	
	Call OE: <u>26/1/19 05-03-19</u>	
	After call Itr to OE:	
	Documentation Check List: Handler Typist	
	Notification Itr (if non-pickup)	<input type="checkbox"/>
	After call Itr to OE:	<input checked="" type="checkbox"/>
18-03-19	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD:	<input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by: cks

Repair Cost: 43 \$5,000 ( days) Reduction: 48 % Email  Call

FINAL SETTLEMENT Date/Time: 11-04-19 Confirm with: DPND Email  Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 4b  
 Repair Cost: \$5,000 OI TRAVEL STRAIGHT ON MINDE ROAD. (OI TRAVEL AGAINST TRAFFIC D48)  
 Loss of Rental (LOR): \$5 - ( days)  
 Loss of Use (LOU): \$5 500.00 (50) x 10 days  
 Loss of Income (LOI): \$5 - (5 x days)  
 LOR only  LOU only  LOR + LOU  LOR + LO  (Tick only one)  
 GIATA Search: \$52.00  
 Medical: \$5 -  
 Disbursement: \$5 - (e.g. Tow/ Independent)  
 Legal Cost: \$5 -  
 Total: \$5,522.00 Global Sum \$5:  
 1) Claim status: Normal/Reject/Private Settle  
 2) Report Format: TP  
 3) Survey fee: 7500

FINAL PAYMENT Date/Time: 11-04-19 Confirm with: DPND Email  Call

Payee 1: \$5,522.00 Name 1: TRAVEL STRAIGHT ON MINDE ROAD  
 Payee 2: (Strike if N.A.) \$5 Name 2:  
 Payee 3: (Strike if N.A.) \$5 Name 3:

(08/11/13) wef  
ASS. REC. BY: Marius

REF: A166/ e

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: SLC9354  
at Workshop m/s: My motor  
of \_\_\_\_\_  
Insured: SM9342  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

Veh No: SLC9354 Yr Regn: 25/7/10  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or CA  
Make: mit herer c.c 1499  
Colour: silver A/C: Insured / Std / NI / NA  
Sp. Reading: 146864 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: JM4SR4Y2AAU000764  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or  
Brake: In order / Jammed / Leaked / Burnt or  
Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)  
Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Tyre Size: F: 205/60R16  
R: \_\_\_\_\_  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or  
Front: 6 mm Rear: 6 mm  
R/Bal. \_\_\_\_\_ mm R/Bal. \_\_\_\_\_ mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. 22/2/19 D.O.I. 27/2/19  
Survey held at \_\_\_\_\_

Bal. or Market Value: 23k.  
IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: 7 days Res.: Yes or No  
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 6424F  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT  
1495 End.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Rear  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
LTA 13.849 have video of fold  
net 9151  
1/2: 18,000 (Red: 7,299.65 48%)

Date/Time, File Pass to?  : Prel. Report  
 : Final Report

Days Of Repair: \_\_\_\_\_  
Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_  
Transportation: \_\_\_\_\_  
TOTAL

Add Fee:  : Site Insp (\$ \_\_\_\_\_) ) \$ + RS \_\_\_\_\$  
 : Interview (\$ \_\_\_\_\_) ) Photos  
 : Tech. Invs (\$ \_\_\_\_\_) ) Others  
 : Weekend (\$ \_\_\_\_\_)

Report Format : \_\_\_\_\_  
Lump Sum / I.B.I: (\$ \_\_\_\_\_)

# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 37809100W

NOT A/c  
27/2/19  
7-ly

Our Ref: TP 2938/02/19

Your Ref:

Date: 27th FEB 2019

L/S # 8000

MS GOH TIEW KEAK MELISSA  
BLK 604C, #11-738,  
FUNGGOLO RD, S (823604)

ELEGANCE Saloon

Estimate cost of repair to MITSUBISHI LANCER 1.5 (A) MIVEC - SLC 935 U

1 pc front bonnet		Buc	809.00	Nett	✓
2 pcs front bonnet o/s & n/s hinge	€ \$ 58.00	N	116.00	"	X
1 pc front bonnet lock		Tim	52.00	"	✓
12 pcs front bonnet insulator & rubber clips	€ \$ 3.50	N	42.00	"	✓
2 pcs o/s & n/s head lamp assy	€ \$ 698.00	N	1,396.00	"	✓
2 pcs o/s & n/s head lamp rubber	€ \$ 18.00	N	36.00	"	1pc
2 pcs o/s & n/s head lamp bracket	€ \$ 78.00	N	156.00	"	1pc
2 pcs front o/s & n/s fender	€ \$ 588.00	N	1,176.00	"	1pc
2 pcs front o/s & n/s fender inner shield	€ \$ 110.00	N	220.00	"	1pc
16 pcs front o/s & n/s fender inner shield clips	€ \$ 3.50	N	56.00	"	✓
1 pc front bumper		D.S	847.00	"	✓
1 pc front bumper reinforcement		bul	393.00	"	✓
1 pc front bumper top retainer		bul	78.00	"	✓
8 pcs front bumper top retainer rivets	€ \$ 5.50	N	44.00	"	✓
1 pc front bumper top rubber		ser	30.00	"	✓
8 pcs front bumper top rubber clips	€ \$ 3.50	N	28.00	"	✓
1 pc front bumper top grille		Tim	107.00	"	✓
1 set front bumper top grille chrome moulding		om	307.00	"	✓
1 pc front bumper top grille logo emblem		om	38.00	"	✓
1 pc front bumper lower grille		om	87.00	"	✓
1 set front bumper lower grille chrome moulding		om	335.00	"	✓
1 pc front bumper o/s fog lamp garnish		om	38.00	"	✓
8 pcs front bumper clips	€ \$ 3.50	N	28.00	"	✓
2 pcs front bumper reinforcement o/s & n/s stay	€ \$ 58.00	N	116.00	"	✓
1 pc front number plate & holder		bul	60.00	"	400.00
1 pc front support panel		senton	882.00	"	✓
1 pc washer tank		11	81.00	"	✓
1 pc radiator		holder om	1,161.00	"	✓
1 pc radiator auto fan comp		11	733.00	"	✓
2 pcs radiator o/s & n/s top bracket	€ \$ 28.00	N	56.00	"	✓
1 pc air cond condenser		Tim/Pur	1,023.00	"	✓
1 pc air cond condenser auto fan comp		11	733.00	"	✓
1 pc air cond condenser liquice pipe		11	319.00	"	✓
1 pc front support panel top cover garnish		Tim	64.00	"	✓
8 pcs front support top garnish clips	€ \$ 3.50	N	28.00	"	✓
1 pc air intake hose		11	147.00	"	✓
3 pcs air intake hose clips	€ \$ 5.50	N	16.50	"	✓
			\$ 11,838.50	Nett	850
	Less 10%		\$ 1,183.85		772
			\$ 10,654.65		
Towing charge			50.00		✓
			\$ 10,704.65		
Balance C/P.....					

# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2938/02/19 Your Ref: \_\_\_\_\_ Date: 27th FEB 2019

MS GOH TIEW KEAK MELISSA.,

Balance B/F..... \$ 10,704.65

To wiring check up & adjust headlight alignment.	40.00	30
To remove & refix air cond parts & refill R134 gas.	150.00	100
To jack, straighten & knocking out front o/s & n/s chassis frame member.	500.00	X
To check & adjust front wheel alignment & balancing.	120.00	X
To respray Tuff-Kote on all affected accident parts.	180.00	h
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front o/s & n/s wheel house panel, front o/s & n/s door pillar panel & necessary parts, to weld, renew & align above parts.	1,700.00	850
To putty & respray painting on all affected accident parts.	1,900.00	1200

\$ 15,294.65  
-----

10032

Dollars : Fifteen Thousand Two Hundred Ninety Four And Cents Sixty Five Only.

HUP MOTOR TRADING & SERVICE

\_\_\_\_\_

LES Auto Consultants hereby notify

the signatory of the following:

- To use only authorised spare parts
- To use only authorised spare labour
- Parts to be used must be of the highest quality
- To use only authorised "Genuine Products" base
- To use only authorised "Genuine Products" base
- To use only authorised "Genuine Products" base
- To use only authorised "Genuine Products" base

Authorised by Repairer:

Signature:

Date:

# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Not Held  
27/2/19  
7 July

Our Ref: TP 2938/02/19 Your Ref: \_\_\_\_\_ Date: 27th FEB 2019

MS GOH TIEW KEAK MELISSA  
BLK 604C, #11-738,  
FUNGOL RD, S (823604)

ELEGANCE Saloon

Estimate cost of repair to MITSUBISHI LANCER 1.5 (A) MIVEC - SLC 935 U

		Sub \$		809.00	Nett ✓
1 pc front bonnet					
2 pcs front bonnet o/s & n/s hinge	€ \$	58.00 N		116.00	" ?
1 pc front bonnet lock			7m	52.00	"
12 pcs front bonnet insulator & rubber clips	€ \$	3.50 N	Am	42.00	"
2 pcs o/s & n/s head lamp assy	€ \$	698.00 N		1,396.00	" 12C
2 pcs o/s & n/s head lamp rubber	€ \$	18.00 N		36.00	" 12C
2 pcs o/s & n/s head lamp bracket	€ \$	78.00 N		156.00	" 12C
2 pcs front o/s & n/s fender	€ \$	588.00 N		1,176.00	" 12C
2 pcs front o/s & n/s fender inner shield	€ \$	110.00 N		220.00	" 12C
16 pcs front o/s & n/s fender inner shield clips	€ \$	3.50 N	Am	56.00	"
1 pc front bumper			2-5	847.00	"
1 pc front bumper reinforcement			bul	393.00	"
1 pc front bumper top retainer			bul	78.00	"
8 pcs front bumper top retainer rivets	€ \$	5.50 N	Am	44.00	"
1 pc front bumper top rubber			Am	30.00	"
8 pcs front bumper top rubber clips	€ \$	3.50 N	Am	28.00	"
1 pc front bumper top grille			Am	107.00	"
1 set front bumper top grille chrome moulding			Am	307.00	"
1 pc front bumper top grille logo emblem			Am	38.00	"
1 pc front bumper lower grille				87.00	" ?
1 set front bumper lower grille chrome moulding				335.00	" ?
1 pc front bumper o/s fog lamp garnish			Am	38.00	"
8 pcs front bumper clips	€ \$	3.50 N	Am	28.00	" ?
2 pcs front bumper reinforcement o/s & n/s stay	€ \$	58.00 N		116.00	" ?
1 pc front number plate & holder			bul	60.00	" 405.00
1 pc front support panel				882.00	" ?
1 pc washer tank				81.00	" ?
1 pc radiator				1,161.00	" ?
1 pc radiator auto fan comp				733.00	" ?
2 pcs radiator o/s & n/s top bracket	€ \$	28.00 N		56.00	" ?
1 pc air cond condenser				1,023.00	" ?
1 pc air cond condenser auto fan comp				733.00	" ?
1 pc air cond condenser liquice pipe				319.00	" ?
1 pc front support panel top cover garnish				64.00	" ?
8 pcs front support top garnish clips	€ \$	3.50 N		28.00	" ?
1 pc air intake hose				147.00	" ?
3 pcs air intake hose clips	€ \$	5.50		16.50	" ?
				\$ 11,838.50	Nett
				Less 10%	\$ 1,183.85
					\$ 10,654.65
Towing charge					50.00 ✓
					\$ 10,704.65
					Balance C/F.....

# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2938/02/19 Your Ref: \_\_\_\_\_ Date: 27th FEB 2019

MS GOH TIEW KEAK MELISSA.,	Balance B/P.....	\$ 10,704.65
To wiring check up & adjust headlight alignment.	40.00	30
To remove & refix air cond parts & refill Ra134 gas.	150.00	100
To jack, straighten & knocking out front o/s & n/s chassis frame member.	500.00	?
To check & adjust front wheel alignment & balancing.	11 120.00	X
To respray Tuff-Kote on all affected accident parts.	180.00	80
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front o/s & n/s wheel house panel, front o/s & n/s door pillar panel & necessary parts, to weld, renew & align above parts.	1,700.00	?
To putty & respray painting on all affected accident parts.	1,900.00	1200
	<u>\$ 15,294.65</u>	<u>=====</u>

Dollars : Fifteen Thousand Two Hundred Ninety Four And Cents Sixty Five Only.

HUP MOTOR TRADING & SERVICE  


**Auto Centre** is proudly  
the Singaporean branch of:

- The most advanced & spacious garage
- The most convenient & safe drive-inway
- Fully equipped with latest tools
- The most experienced & professional staff
- The most competitive & reasonable prices
- Staffed with highly trained & experienced and  
certified technicians from the insurance company

Auto Centre by Hupmotor  
Singapore  
2019

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6424F
Vehicle Details	
Vehicle No.:	SLC935U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	26 Feb 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.5EX MIVEC A/T ELEGANCE 2WD 4DR
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	4A910128492
Chassis No.:	JMYSRCY2AAU000764
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,035.00
Original Registration Date:	29 Jul 2010
First Registration Date:	29 Jul 2010
Transfer Count:	2
Actual ARF Paid:	\$17,035.00 <i>2517</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jul 2020
PARF Rebate Amount:	\$9,369.00
Intended COE Rebate Details	
COE Expiry Date:	28 Jul 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$31,510.00
COE Rebate Amount:	\$4,480.00
<b>Total Rebate Amount:</b>	<b>\$13,849.00</b>

The information contained herein is correct as at 26 Feb 2019

OK



Mitsubishi Lancer Price Range Depreciation 2010 Vehicle Type Submit Advanced Search

Home > Used Cars > A1 Motoring Pte Ltd > Mitsubishi Lancer EX 1.5A Sports

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Vehicle Number Plates

**BUY & SELL**  
Your AUSPICIOUS & UNIQUE Vehicle No.  
Do you know? We are Singapore's **BIGGEST PLAYER** with the most vehicle plate numbers for sale?  
[Click here to view our Auctioneers' Motoring!](#)

Mitsubishi Lancer EX 1.5A Sports

Overview Financial Insurance Accessories Similar Research Photos Map

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

<b>Price</b>	<b>\$19,000</b>	
<b>Depreciation</b>	\$11,050 /yr	<a href="#">View models with similar depreciation</a>
<b>Reg Date</b>	07-Jan-2010 (10mths 10days COE left)	
<b>Manufactured</b>	2009	
<b>Mileage</b>	150,000 km (16.4k /yr)	
<b>Transmission</b>	Auto	
<b>Engine Cap</b>	1,499 cc	
<b>Road Tax</b>	\$684 /yr	
<b>Power</b>	80.0 kW (107 bhp)	<a href="#">View specs of the Mitsubishi Lancer EX (2008-2017)</a>
<b>Curb Weight</b>	1,313 kg	
<b>Features</b>	1.5L 16 Valves DOHC Engine. Dual SRS Airbags. ABS. Auto Climatic Aircon. 4 Speed Auto Transmissions.	
<b>Accessories</b>	Sports Rims. Leather Seats. Factory Fitted Audio System. Retractable Side Mirrors With Indicators. Solar Film.	
<b>Description</b>	Balloon Scheme Available. Regular Servicing. Well Maintained.	
<b>COE</b>	\$15,792	
<b>OMV</b>	\$19,039	
<b>ARF</b>	\$19,039	
<b>Dereg Value</b>	\$10,674 as of today (change)	
<b>No. of Owners</b>	3	
<b>Type of Veh</b>	Mid-Sized Sedan	
<b>Category</b>	PARF Car	
<b>Availability</b>	Available	

Add to Shortlist Add to Compare Add a Note

Posted on: 07-Jan-2019 | Last Updated on: 28-Jan-2019

Tags: Mitsubishi Lancer, mitsubishi lancer, 2010 Mitsubishi Lancer, 2010 mitsubishi lancer, Mitsubishi, Lancer, lancer, Used Mitsubishi

Upfront Payment [+ more Financial info](#)

<b>Transfer Fee</b>	\$25	
<b>Down Payment</b>	\$5,700 (change)	Maximum 70% Loan



Seller Information

<b>Company</b>	A1 Motoring Pte Ltd + dealer's prolist + 15 vehs sold   11 vehs available	
<b>Address</b>	48 Toh Guan Road East #01-116 <a href="#">Search cars nearby this location</a>	
<b>Location</b>	Enterprise Hub	
<b>Contact Person(s)</b>	Rosli	93678860
	Roy	87999711
	Leon	82288105

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.  
**Vehicle Evaluation**



Find out the market value for your car. Get a free Car Valuation.  
**Free Valuation**

Compare



**Post FREE Ad to Sell Your Used Items!**

Have preloved items cluttering around your house?  
Sell it on Marketplace. Posting an advertisement is FREE!

Mitsubishi Lancer Price Range Depreciation 2010 Vehicle Type Submit

Advanced Search

Home > Used Cars > Cars 19 > Mitsubishi Lancer EX 1.5A Sports

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Commercial Vehicle

BRAND NEW FLEET AVAILABLE FOR RENT / LEASE  
CALL: 8482 3003

Mitsubishi Lancer EX 1.5A Sports

Overview Financial Insurance Accessories Similar Research Photos Map

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

<b>Price</b>	<b>\$25,800</b>	
<b>Depreciation</b>	\$10,590 /yr	<a href="#">View models with similar depreciation</a>
<b>Reg Date</b>	30-Sep-2010	(1yr 7mths 2days COE left)
<b>Manufactured</b>	2010	
<b>Mileage</b>	113,000 km (13.4k /yr)	
<b>Transmission</b>	Auto	
<b>Engine Cap</b>	1,499 cc	
<b>Road Tax</b>	\$684 /yr	
<b>Power</b>	80.0 kW (107 bhp)	<a href="#">View specs of the Mitsubishi Lancer EX (2008-2017)</a>
<b>Curb Weight</b>	1,313 kg	
<b>Features</b>	-	
<b>Accessories</b>	-	
<b>Description</b>	Low Mileage Of 113,000km. Keyless, Sports Model. High Trade In. Bank Loan/In House Loan Available.	
<b>COE</b>	\$30,001	
<b>OMV</b>	\$17,949	
<b>ARF</b>	\$17,949	
<b>Dereg Value</b>	\$14,639 as of today (change)	
<b>No. of Owners</b>	3	
<b>Type of Veh</b>	Mid-Sized Sedan	
<b>Category</b>	MPV Car	
<b>Availability</b>	Available	

Add to Shortlist Add to Compare Add a Note

Posted on: 24-Feb-2019 | Last Updated on: 25-Feb-2019

Tags: Mitsubishi Lancer, mitsubishi lancer, 2010 Mitsubishi Lancer, 2010 mitsubishi lancer, Mitsubishi, Lancer, lancer, Used Mitsubishi

Upfront Payment [= more Financial Info](#)

<b>Transfer Fee</b>	\$25	
<b>Down Payment</b>	\$7,740 (change)	Maximum 70% Loan
<b>1st Instalment</b>	\$995	
	\$1,070 onwards	
	Not at fault? No upfront payment required!	



Seller Information

<b>Company</b>	Cars 19	
	= dealer's prelist = 4 vehs sold   2 vehs available	
<b>Address</b>	210 Turf Club Road Lot B19 <a href="#">Search cars nearby this location</a>	
<b>Location</b>	Car Mall @ The Grandstand	
<b>Office No</b>	63385723	
<b>Contact Person(s)</b>	Brandon Wilson	90034566 90067020

Useful Services

AFRAID OF LEMONS? Request to have this car evaluated professionally.  
**Vehicle Evaluation**

Find out the market value for your car. Get a free Car Valuation.  
**Free Valuation**



## Asher Sng (LKKAuto)

---

**From:** Asher Sng (LKKAuto)  
**Sent:** Monday, 25 March 2019 2:53 PM  
**To:** 'Tan, Bennie-WZ'  
**Subject:** [MANDATE REQUEST] Your ref : 4616213005SG, ACCIDENT ON 22/02/2019 INVOLVING SMG 34L (OI) & SLC 935U (TP)

Your ref : **4616213005SG**  
Our ref : CC6/AIG19003643/Ueb3

Dear Sirs,

### **ACCIDENT ON 22/02/2019 INVOLVING SMG 34L (OI) & SLC 935U (TP)**

We refer to the above matter.

The accident occurred when our insured travel straight on minor road hit third party vehicle (Insured travel against the traffic rule).

Basing on the reports of the circumstance of the accident, we propose to settle third-party claim at 100% liability.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer repairer "**HUP MOTOR TRADING & SERVICE**" at **\$ 8,602.00 (all-in)**.

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repairs (with GST)	\$ 15,294.65	\$ 8,000.00
2. Loss of Use (10days x \$70)	\$ 700.00	\$ 600.00 (10days x \$60)
3. LTA Search Fee	\$ 2.00	\$ 2.00
<b>Total</b>	<b>\$ 15,996.65</b>	<b>\$ 8,602.00</b>

**For your approval in merimen please.**

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Print Received Message

This mail is associated with :

**\*SLC935U (4616213005SG)**  
**[SMG34L]**

TP

GOH TIEW KEAK MELISSA  
Feb 22 2019 6:00PM  
[Sim Chin Hwa]  
Hup Motor Trading & Service

**From** AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 04/04/2019 15:55 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$8540.00) - SLC935U - Claim Handler: Tan, Bennie-WZ

Approved:8540.00:Pls do your utmost to negotiate settlement: \$8400-8540 (All-in).

# 哈 汽 車 貿 易 服 務

**HUP MOTOR TRADING & SERVICE** Email : hupmotor@gmail.com

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 WEB SITE: http://hupmotor.com.sg Reg. No. 378091/00W

Our Ref: TP 2938/02/19

Your Ref:

Date: 12th March 2019

The Claim's Manager  
Motor Claims Dept.  
AIG Asia Pacific Insurance Pte. Ltd.  
78, Shenton Way, #07-16, Chartis Bldg.  
Singapore 079120

Dear Sirs,

RE : ACCIDENT ON 22/02/19 ALONG SINGAPORE INDOOR STADIUM  
INVOLVING : SLC 935 U & YOUR INSURED : SMG 34 L

We act for Ms Goh Tiew Keak, Melissa., NRIC No : S7906424F  
Who is the registered owner of Veh. No : SLC 935 U Which was involved  
in the above accident with Veh. No : SMG 34 L Which we understand  
is insured with you.

Your appointed surveyor had surveyed our client's damaged vehicle and  
we had repaired the vehicle.

The accident was clearly caused by your insured's negligence, I am,  
therefore, seeking compensation from you for my financial losses as  
itemised below : -

Cost of repair	₹ 8,000.00
Loss of Use : 10 days ( 1 day X ₹ 70.00 )	700.00 (Includ PRI)
LTA Search Fee & GIA-RMC Search Fee	2.00
Survey Fee	0.00

₹ 8,702.00  
=====

We have enclosed copies of relevant documents to support my client's  
claim, There was no receipt enclosed, as my client's did not pay us  
any single amount.

Your prompt settlement of our claim would be much appreciated.

Yours faithfully,

HUP MOTOR TRADING & SERVICE

Important Note: This Settlement only valid for property claims.  
Not include injury claims.

Mr David Ang B. Y.

Encl : Final Bill, ~~Car Rental Bill~~, LTA Search Fee, Owner Authorisation  
Letter, GIA Report, ~~Survey Report & Ins. Cert.~~

Remark : Kindly acknowledge receipt.

**Asher Sng (LKKAuto)**

---

**From:** Asher Sng (LKKAuto)  
**Sent:** Tuesday, 5 March 2019 11:28 AM  
**To:** 'JOESIM@SHOW-COMPANY.COM'  
**Subject:** ACCIDENT INVOLVING SMG 34L AND SLC 935U ON 22/02/2019

**Our Ref: CC6/AIG19003643/Ueb3**

05 MAR 2019

**SIM CHIN HWA**

Dear Sir/Madam,

**ACCIDENT INVOLVING SMG 34L AND SLC 935U ON 22/02/2019**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Asher  
*Case Handler*  
DID: 6841 6051  
FAX: 6741 4108  
Email: [Ashersng@lkkauto.com](mailto:Ashersng@lkkauto.com)

*c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)*

TO : AIG ASIA PACIFIC INSURANCE PTE. LTD.

## AUTHORIZATION TO ACT

I, GOH TIEW KEAK MELISSA (S7906424F) ("the third party claimant")

of BLK 604C, #11-73B, PUNGGOL RD, S (823604) (address),

owner of SLC 935 U (vehicle no.) hereby authorize

Hup Motor Trading & Service,

("The workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my

Vehicle No. SLC 935 U that was damaged pursuant to the

accident which occurred on 22/02/19 (date) along Singapore

Indoor Stadium (location)

involving Vehicle No/s SMG 34 L

("The accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 26th day of February (month) 20 19 (year)



Owner Of SLC 935 U (S7906424F)  
Signed by "the third party claimant"

HUP MOTOR TRADING & SERVICE



Signed by "the workshop"

Important Note: The Settlement only value for property claims.  
Not include injury claims.

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, **HUP MOTOR TRADING & SERVICE** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$8,000.00** (Repair Cost), **S\$500.00** (Loss of Use/Rental), **S\$2.00** (Disbursement) for vehicle no. **SLC 935U** that was damaged pursuant to the accident which occurred on **22/02/2019** (date) along **SINGAPORE INDOOR STADIUM** (location) involving vehicle no/s **SMG 34L**.

This is pursuant to the inspection conducted on **27/2/2019** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **GOH TIEW KEAK MELISSA** ("the third party claimant") of vehicle no. **SLC 935U** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SLC 935U** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 11 (day) of 04 (month) 2019 (year)



**CKS**

Signed by appointed surveyor

**HUP MOTOR TRADING & SERVICE**

Signed by "the workshop" (with chop)

# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2938/02/19

Your Ref:

Date: 12th March 2019

MS GOH TIEW KEAK MELISSA (INVOICE)

BLK 604C, #11-738,

FUNGGOL RD, S (823604)

Cost of repair to MITSUBISHI LANCER 1.5 (A) MIVEC Saloon - SLC 935 U

To supply front bonnet, lock, hinge, insulator clips, head lamp assy, retainer, rubber, fender, inner shield, clips, front bumper, reinforcement, clips, top grille, lower grille, moulding, aircoop grille, top retainer, top cover garnish, clips, rivets, front support panel, radiator, air cond condenser, auto fan motor, intake hose, clips, front number plate & necessary parts.

To remove & refix air cond parts & refill R4134 gas, including wiring check up & adjust headlight alignment, includ Towing charge.

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front o/s & n/s chassis frame member, door pillar panel, wheel house panel, front fender & necessary parts, to weld, renew & align above parts.

To putty & respray painting on all affected accident parts, including respray Tuff-Kote on all affected parts.

Lump Sum Repair : \$ 8,000.00

\*\*\*\*\*

Dollars : Eight Thousand Only.

HUP MOTOR TRADING & SERVICE

.....  






RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-19-030682  
Date of Request: 26/02/2019

Your Ref No: Online Purchase

Hup Motor Trading & Service  
Blk 9004 Tampines Street 93  
#01-120  
Singapore 528838

Dear Sir/Madam,

Enquiry Date 26/02/2019  
Enquiry By David Ang Beng Yeow  
TP Vehicle No. SMG34L  
Accident Date 22/02/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

---

For GIARMC Official use:

Date:

GIRO  Cash  Cheque

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Feb 2019 <a href="#">Edit Reg</a>		27 Feb 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$8,000.00</b> <a href="#">Edit Estimates</a>	<b>S\$8,000.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>Sim Chin Hwa</b> , ID: S1490953B								
Main Claimant:	<b>GOH TIEW KEAK MELISSA</b> , ID: S7906424F								
Vehicle Reg. No.:	<b>SLC935U</b>	Date of Loss:	22/02/2019 18:00 - :59 [102 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 4616213005SG</b>	Policy/Cover Note No.:	1800094208 (Comprehensive) Coverage: 04/08/2018 - 03/08/2019						
Vehicle Reg. No. (Insured):	<b>SMG34L</b>	Policy No. (Claimant):	MT/00508543						
Repairer:	<b>Hup Motor Trading &amp; Service (HQ)</b> Blk 9004 Tampines Street 93, #01-120, 528838 Tampines - Tel: 67840039/98154655								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Tan, Bennie-WZ</b> - 6419 1718] Bennie-WZ.Tan@aig.com								
Claimant's Insurer:	<b>Direct Asia Insurance (Singapore) Pte Ltd (HQ)</b> - Tel: 65322888								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 07/03/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
• AIG_SG_EXPRESS (04/04/2019): Alert - Adj Mandate Approved (S\$8540.00) - SLC935U - Claim Handler: Tan, Bennie-...									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*SLC935U (4616213005SG)  
[SMG34L]

TP

GOH TIEW KEAK MELISSA



















































Feb 22 2019 6:00PM

[Sim Chin Hwa]

Hup Motor Trading & Service

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View <span style="float: right;">View in Browser</span>	
<b>Video</b>														1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	05/03/19 11:20	TP VIDEO											Load MP4			
2	05/03/19 11:20	TP WITNESS VIDEO											Load MP4			
<b>Letters/Correspondences</b>														1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	(Draft)	Third Party Express Settlement - Payment Breakdown											Edit			
<b>Photos/Images</b>														3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	27/02/19 15:57	Chassis Number											Load JPG <input checked="" type="checkbox"/>			
2	27/02/19 15:57	Odometer Reading											Load JPG <input checked="" type="checkbox"/>			
3	27/02/19 15:57	General View											Load JPG <input checked="" type="checkbox"/>			
4	27/02/19 15:57	General View											Load JPG <input checked="" type="checkbox"/>			
5	27/02/19 15:57	General View											Load JPG <input checked="" type="checkbox"/>			
6	27/02/19 15:57	General View											Load JPG <input checked="" type="checkbox"/>			
7	27/02/19 15:57	General View											Load JPG <input checked="" type="checkbox"/>			
8	27/02/19 15:57	General View											Load JPG <input checked="" type="checkbox"/>			
9	27/02/19 15:57	General View											Load JPG <input checked="" type="checkbox"/>			
10	27/02/19 15:57	General View											Load JPG <input checked="" type="checkbox"/>			
11	27/02/19 15:57	General View											Load JPG <input checked="" type="checkbox"/>			
12	27/02/19 15:57	General View											Load JPG <input checked="" type="checkbox"/>			
13	27/02/19 15:57	General View											Load JPG <input checked="" type="checkbox"/>			
14	27/02/19 15:57	General View											Load JPG <input checked="" type="checkbox"/>			
15	27/02/19 15:58	General View											Load JPG <input checked="" type="checkbox"/>			
16	27/02/19 15:58	General View											Load JPG <input checked="" type="checkbox"/>			
17	27/02/19 15:58	General View											Load JPG <input checked="" type="checkbox"/>			
18	27/02/19 15:58	General View											Load JPG <input checked="" type="checkbox"/>			
19	27/02/19 15:58	General View											Load JPG <input checked="" type="checkbox"/>			
20	27/02/19 15:58	General View											Load JPG <input checked="" type="checkbox"/>			
21	27/02/19 15:58	General View											Load JPG <input checked="" type="checkbox"/>			
22	27/02/19 15:58	General View											Load JPG <input checked="" type="checkbox"/>			
23	27/02/19 15:58	General View											Load JPG <input checked="" type="checkbox"/>			
24	27/02/19 15:58	General View											Load JPG <input checked="" type="checkbox"/>			
25	27/02/19 15:58	General View											Load JPG <input checked="" type="checkbox"/>			
26	27/02/19 15:58	General View											Load JPG <input checked="" type="checkbox"/>			
27	27/02/19 15:58	General View											Load JPG <input checked="" type="checkbox"/>			
28	27/02/19 15:58	General View											Load JPG <input checked="" type="checkbox"/>			
29	27/02/19 15:58	General View											Load JPG <input checked="" type="checkbox"/>			
30	27/02/19 15:58	General View											Load JPG <input checked="" type="checkbox"/>			

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
31	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
32	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
33	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
34	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
35	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
36	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
37	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
38	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
39	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
40	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
41	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
42	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
43	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
44	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
45	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
46	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
47	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
48	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
49	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
50	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
51	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
52	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
53	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
54	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
55	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
56	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
57	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
58	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
59	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
60	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
61	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
62	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
63	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
64	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
65	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
66	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
67	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
68	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
69	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
70	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
71	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
72	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
73	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
74	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
75	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
76	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
77	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
78	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>
79	27/02/19 15:58	General View	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
80	27/02/19 15:58	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
81	27/02/19 15:58	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
82	27/02/19 15:58	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
83	27/02/19 15:58	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
84	27/02/19 15:58	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
85	27/02/19 15:58	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
86	27/02/19 15:58	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
87	27/02/19 15:58	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
88	27/02/19 15:58	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
89	27/02/19 15:58	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
90	27/02/19 15:58	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
91	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
92	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
93	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
94	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
95	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
96	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
97	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
98	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
99	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
100	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
101	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
102	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
103	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
104	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
105	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
106	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
107	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
108	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
109	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
110	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
111	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
112	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
113	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
114	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
115	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
116	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
117	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
118	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
119	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
120	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
121	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
122	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
123	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
124	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
125	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
126	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
127	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
128	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
129	05/03/19 18:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
130	05/03/19 18:13	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
131	05/03/19 18:13	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
132	05/03/19 18:13	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
133	05/03/19 18:13	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
134	05/03/19 18:13	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
135	05/03/19 18:13	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
136	05/03/19 18:13	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
137	05/03/19 18:13	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
138	05/03/19 18:13	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
139	05/03/19 18:13	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
140	05/03/19 18:13	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
141	05/03/19 18:13	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
142	05/03/19 18:13	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
143	05/03/19 18:13	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
144	05/03/19 18:13	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
145	05/03/19 18:13	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
146	05/03/19 18:13	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
147	05/03/19 18:13	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/02/19 18:52	TP EST & GIA REPORT		Load PDF
2	05/03/19 11:29	LETTER TO OI		Load PDF
3	22/03/19 08:37	GIA SEARCH		Load PDF
4	17/04/19 11:42	WORKSHOP INVOICE		Load PDF
5	17/04/19 11:42	AUTHORISATION TO ACT FORM		Load PDF
6	17/04/19 11:42	Release Voucher		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	27/02/19 12:36	OI GIA REPORT		Load PDF

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

Vehicle No:	SMG34L (Insd veh)	Model:	MITSUBISHI LANCER 1.5 MIVEC (A)
	SLC935U (TP veh)		
Date of Accident:	22/02/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	15,294.65	
Final Repair Cost	:	\$	8,000.00	
Loss of Use	:	\$	500.00	10.00 days at \$50.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	2.00	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	8,502.00	
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)				
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability ___ 100 ___ (%)		
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No:		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	Hup Motor Trading & Service	:	\$ 8,502.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

17 Apr  
2019

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19003643/UEB3Q2

Date: 17/04/2019

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 1800094208	
Claimant Vehicle No: SLC935U	Insured Vehicle No: SMG34L	
Date of Loss: 22/02/2019	Nature of Claim: TP	Claim No: 4616213005SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: <b>SLC935U</b>		
Make & Model: MITSUBISHI LANCER, 1.5 MIVEC (A)	Engine No: 4A910128492	
Reg. Date: 29/07/2010 (Man. Year: 2009)	Chassis No: JMYSRCY2AAU000764	
Colour: Silver	Odometer: 146864 km	
Engine Capacity: 1499 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): <b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

#### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,654.65	7,762.00	2,892.65	27.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,640.00	2,310.00	2,330.00	50.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,294.65</b>	<b>10,072.00</b>	<b>5,222.65</b>	<b>34.15</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>8,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>15,294.65</b>	<b>8,000.00</b>	<b>7,294.65</b>	<b>47.69</b>
<b>+ Loss of Use (10.0 x S\$50.00/day) (S\$)</b>		500.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>8,502.00</b>		

#### INSPECTION

Date of Assignment:	27/02/2019	
Date Inspected:	27/02/2019	Inspected At: Hup Motor Trading & Service (HQ) Blk 9004 Tampines Street 93, #01-120 Singapore 528838
Estimated Period of Repair:	7.0 days	



---

**Adjuster:** MARCUS CHUA

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Buckled	809.00 FN	*809.00 FN
2	2		*FRONT BONNET O/S & N/S HINGE	Repair	116.00 FN	*- FN
3	1		*FRONT BONNET LOCK	Twisted	52.00 FN	*52.00 FN
4	12		*FRONT BONNET INSULATOR & RUBBER CLIPS	Necessary	42.00 FN	*42.00 FN
5	2		*O/S & N/S HEAD LAMP ASSY	Cracked	1,396.00 FN	*1,396.00 FN
6	1		*O/S & N/S HEAD LAMP RUBBER	O/S Torn	36.00 FN	*18.00 FN
7	1		*O/S & N/S HEAD LAMP BRACKET	O/S Bent	156.00 FN	*78.00 FN
8	1		*FRONT O/S & N/S FENDER	N/S Repair / O/S Dented	1,176.00 FN	*588.00 FN
9	1		*FRONT O/S & N/S FENDER INNER SHIELD	O/S Torn	220.00 FN	*110.00 FN
10	16		*FRONT O/S & N/S FENDER INNER SHIELD CLIPS	Necessary	56.00 FN	*56.00 FN
11	1		*FRONT BUMPER	Distorted	847.00 FN	*847.00 FN
12	1		*FRONT BUMPER REINFORCEMENT	Bent	393.00 FN	*393.00 FN
13	1		*FRONT BUMPER TOP RETAINER	Bent	78.00 FN	*78.00 FN
14	8		*FRONT BUMPER TOP RETAINER RIVETS	Necessary	44.00 FN	*44.00 FN
15	1		*FRONT BUMPER TOP RUBBER	Necessary	30.00 FN	*30.00 FN
16	8		*FRONT BUMPER TOP RUBBER CLIPS	Necessary	28.00 FN	*28.00 FN
17	1		*FRONT BUMPER TOP GRILLE	Twisted	107.00 FN	*107.00 FN
18	1		*SET FRONT BUMPER TOP GRILLE CHROME MOULDING	Cracked	307.00 FN	*307.00 FN
19	1		*FRONT BUMPER TOP GRILLE LOGO EMBLEM	Necessary	38.00 FN	*38.00 FN
20	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	87.00 FN	*- FN
21	1		*FRONT BUMPER LOWER GRILLE CHROME MOULDING	Cracked	335.00 FN	*335.00 FN
22	1		*FRONT BUMPER O/S FOG LAMP GARNISH	Missing	38.00 FN	*38.00 FN
23	8		*FRONT BUMPER CLIPS	Necessary	28.00 FN	*28.00 FN
24	2		*FRONT BUMPER REINFORCEMENT O/S & N/S STAY	Not Necessary	116.00 FN	*- FN
25	1		*FRONT NUMBER PLATE & HOLDER	Bent	54.00 FS	*40.00 FS
26	1		*FRONT SUPPORT PANEL	Bent / Twisted	882.00 FN	*882.00 FN
27	1		*WASHER TANK	Not Necessary	81.00 FN	*- FN
28	1		*RADIATOR	Holder Cracked	1,161.00 FN	*1,161.00 FN
29	1		*RADIATOR AUTO FAN COMP	Not Necessary	733.00 FN	*- FN
30	2		*RADIATOR O/S & N/S TOP BRACKET	Not Necessary	56.00 FN	*- FN
31	1		*AIR COND CONDENSER	Twisted / Punctured	1,023.00 FN	*1,023.00 FN
32	1		*AIR COND CONDENSER AUTO FAN COMP	Not Necessary	733.00 FN	*- FN
33	1		*AIR COND CONDENSER LIQUICE PIPE	Not Necessary	319.00 FN	*- FN
34	1		*FRONT SUPPORT PANEL TOP COVER GARNISH	Torn	64.00 FN	*64.00 FN
35	8		*FRONT SUPPORT TOP GARNISH CLIPS	Necessary	28.00 FN	*28.00 FN
36	1		*AIR INTAKE HOSE	Not Necessary	147.00 FN	*- FN
37	3		*AIR INTAKE HOSE CLIPS	Not Necessary	16.50 FN	*- FN

F=Franchise part. S=SpcNett. N=NetItemDisc.

Sub Total (S\$) **11,832.50**      **8,620.00**  
 - Nett Item Discount on N Items 10.00/10.00% (S\$)      1,177.85      858.00

**Total Parts (S\$) 10,654.65      7,762.00**

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOWING CHARGE	New	50.00	50.00
2	TO WIRING CHECK UP & ADJUST HEADLIGHT ALIGNMENT	New	40.00	30.00
3	TO REMOVE & REFIX AIR COND PARTS & REFILL RA134 GAS	New	150.00	100.00
4	TO JACK,STRAIGHTEN & KNOCKING OUT FRONT O/S & N/S CHASSIS FRAME MEMBER	New	500.00	0.00
5	TO CHECK & ADJUST FRONT WHEEL ALIGNMENT & BALANCING	New	120.00	0.00
6	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS	New	180.00	80.00
7	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS ,TO JACK,STRAIGHTEN & KNOCKING OUT FRONT O/S & N/S WHEEL HOUSE PANEL,FRONT O/S & N/S DOOR PILLAR PANEL & NECESSARY PARTS,TO WELD,RENEW & ALIGN ABOVE PARTS	New	1,700.00	850.00
8	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	1,900.00	1,200.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,640.00</b>	<b>2,310.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >