

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2938/02/19

Your Ref:

Date: 27th FEB 2019

MS GOH TIEW KEAK MELISSA
BLK 604C, #11-738,
PUNGGOL RD, S (823604)

ELEGANCE Saloon

Estimate cost of repair to MITSUBISHI LANCER 1.5 (A) MIVEC - SLC 935 U

1 pc front bonnet		Buc \$	809.00	Nett	✓
2 pcs front bonnet o/s & n/s hinge	@ \$ 58.00 N		116.00	" ?	
1 pc front bonnet lock		7m	52.00	"	✓
12 pcs front bonnet insulator & rubber clips	@ \$ 3.50 N	7m	42.00	"	✓
2 pcs o/s & n/s head lamp assy	@ \$ 698.00 N	MS? o/s	1,396.00	" 12C	
2 pcs o/s & n/s head lamp rubber	@ \$ 18.00 N	o/s 7m	36.00	" 12C	
2 pcs o/s & n/s head lamp bracket	@ \$ 78.00 N	o/s 7m	156.00	" 12C	
2 pcs front o/s & n/s fender	@ \$ 588.00 N	MS? o/s	1,176.00	" 12C	
2 pcs front o/s & n/s fender inner shield	@ \$ 110.00 N	o/s 7m	220.00	" 12C	
16 pcs front o/s & n/s fender inner shield clips	@ \$ 3.50 N	7m	56.00	"	✓
1 pc front bumper		7-5	847.00	"	✓
1 pc front bumper reinforcement		7m	393.00	"	✓
1 pc front bumper top retainer		7m	78.00	"	✓
8 pcs front bumper top retainer rivets	@ \$ 5.50 N	7m	44.00	"	✓
1 pc front bumper top rubber		7m	30.00	"	✓
8 pcs front bumper top rubber clips	@ \$ 3.50 N	7m	28.00	"	✓
1 pc front bumper top grille		7m	107.00	"	✓
1 set front bumper top grille chrome moulding		7m	307.00	"	✓
1 pc front bumper top grille logo emblem		7m	38.00	"	✓
1 pc front bumper lower grille			87.00	" ?	
1 set front bumper lower grille chrome moulding			335.00	" ?	
1 pc front bumper o/s fog lamp garnish		MS-5	38.00	"	✓
8 pcs front bumper clips	@ \$ 3.50 N	7m	28.00	"	✓
2 pcs front bumper reinforcement o/s & n/s stay	@ \$ 58.00 N		116.00	" ?	
1 pc front number plate & holder		7m	60.00	" 405.00	
1 pc front support panel			882.00	" ?	
1 pc washer tank			81.00	" ?	
1 pc radiator			1,161.00	" ?	
1 pc radiator auto fan comp			733.00	" ?	
2 pcs radiator o/s & n/s top bracket	@ \$ 28.00 N		56.00	" ?	
1 pc air cond condenser			1,023.00	" ?	
1 pc air cond condenser auto fan comp			733.00	" ?	
1 pc air cond condenser liquice pipe			319.00	" ?	
1 pc front support panel top cover garnish			64.00	" ?	
8 pcs front support top garnish clips	@ \$ 3.50 N		28.00	" ?	
1 pc air intake hose			147.00	" ?	
3 pcs air intake hose clips	@ \$ 5.50		16.50	" ?	

\$ 11,838.50 Nett

Less 10% \$ 1,183.85

\$ 10,654.65

Towing charge

50.00 ✓

\$ 10,704.65

Balance C/F.....

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2938/02/19

Your Ref: _____

Date: 27th FEB 2019

MS GOH TIEW KEAK MELISSA.,

Balance B/F..... \$ 10,704.65

To wiring check up & adjust headlight alignment.	40.00	30
To remove & refix air cond parts & refill Ra134 gas.	150.00	100
To jack, straighten & knocking out front o/s & n/s chassis frame member.	500.00	?
To check & adjust front wheel alignment & balancing.	11 120.00	x
To respray Tuff-Kote on all affected accident parts.	180.00	80
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front o/s & n/s wheel house panel, front o/s & n/s door pillar panel & necessary parts, to weld, renew & align above parts.	1,700.00	7
To putty & respray painting on all affected accident parts.	1,900.00	1200
	<u>\$ 15,294.65</u>	
	=====	

Dollars : Fifteen Thousand Two Hundred Ninety Four And Cents Sixty Five Only.

HUP MOTOR TRADING & SERVICE

.....

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts, prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: