哈汽車貿易服務

HUP MOTOR TRADING & SERVICE Email : hupmotor@gmail.com

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 WEB SITE: http://hupmotor.com.sg Reg. No. 378091/00W

TP 2938/02/19

Your Ref:

Date: 12th March 2019



The Claim's Manager Motor Claims Dept. AIG Asia Pacific Insurance Pte. Ltd. 78, Shenton Way, #07-16, Chartis Bldg. Singapore 079120 -

Dear Sirs,

RE : ACCIDENT ON 22/02/19 ALONG SINGAPORE INDOOR STADIUM INVOLVING : SLC 935 U & YOUR INSURED : SMG 34 L

We act for Ms Goh Tiew Keak, Melissa., NRIC No : S7906424F Who is the registered owner of Veh. No : SLC 935 U Which was involved in the above accident with Veh. No : SMG 34 L Which we understand is insured with you.

Your appointed surveyor had surveyed our client's damaged vehicle and we had repaired the vehicle.

The accident was clearly caused by your insured's negligence, I am, therefore, seeking compensation from you for my financial losses as itemised below : -

> Cost of repair Loss of Use : 40 days (1 day X \$ 70.00) LTA Search Fee & GIA-RMC Search Fee Survey Fee

700.00 (Includ PRI) 2.00 0.00

\$ 8,702.00

We have enclosed copies of relevant documents to support my client's claim, There was no receipt enclosed, as my client's did not pay us any single amount.

Your prompt settlement of our claim would be much appreciated.

Yours faithfully.

HUP MOTOR TRAPING & SERVICE

Important Note: The Settlement only value for property claims, Not include injury claims.

Mr David Ang B. Y.

Encl : Final Bill, Car Rental Bill, LTA Search Fee, Owner Authorisation Letter, GIA Report, Survey Report & Ins. Cert.

Remark : Kindly acknowledge receipt.

哈汽車貿易服務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2938/02/19

Your Ref:

Date: 12th March 2019

MS GOH TIEW KEAK MELISSA (INVOICE) BLK 604C, #11-738, FUNGGOL RD, S (823604)

Cost of repair to MITSUBISHI LANCER 1.5 (A) MIVEC Saloon - SLC 935 U

To supply front bonnet, lock, hinge, insulator clips, head lamp assy, retainer, rubber, fender, inner shield, clips, front bumper, reinforcement, clips, top grille, lower grille, moulding, airscoop grille, top retainer, top cover garnish, clips, rivets, front support panel, radiator, air cond condenser, auto fan motor, intake hose, clips, front number plate & necessary parts.

To remove & refix air cond parts & refill Ra134 gas, including wiring check up & adjust headlight alignment, includ Towing charge.

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front o/s & n/s chassis frame member, door pillar panel, wheel house panel, front fender & necessary parts, to weld, renew & align above parts.

To putty & respray painting on all affected accident parts, including respray Tuff-Kote on all affected parts.

Lump Sum Repair : \$ 8,000.00

Dollars : Eight Thousand Only.

HUP MOTOR TRADUIG & SERVICE



RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No:

GR-19-030682

Date of Request:

26/02/2019

Your Ref No:

Online Purchase

Hup Motor Trading & Service Blk 9004 Tampines Street 93

#01-120

Singapore 528838

Dear Sir/Madam,

Enquiry Date

26/02/2019

Enquiry By

David Ang Beng Yeow

TP Vehicle No.

SMG34L

Accident Date

22/02/2019

Enquiry Result

Enquiry Result			I Tol No
TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
	AIG Asia Pacific Insurance Pte. Ltd.	04/08/2018-03/08/2019	65-6419-3000
SMG34L	AIG Asia I dellie modranoe i te. zita		

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

AUTHORIZATION TO ACT

of bin boto, #11-130, FUNGGUL	
	RD, S (823604) (address),
owner of SLC 935 U	(vehicle no.) hereby authorize
Hup Motor Trading & Service,	
("The workshop") to act for me	with respect to my claim for
repair costs and/or rental and	d/or loss of use ("claim") for my
Vehicle No. <u>SLC 935 U</u> that	at was damaged pursuant to the
accident which occurred on $22/$	/02/19 (date) along <u>Singapore</u>
Indoor Stadium	(location)
involving Vehicle No/s <u>SMG 34</u> ("The accident"),	L.
I further authorize the worksh	nop to settle my above mentioned
claim in a manner that they de authorized to receive payment	eem fit and the workshop is further further to settlement of my claim
claim in a manner that they de authorized to receive payment with payment cheque/s being ma I further acknowledge that any on my behalf is on a without p	eem fit and the workshop is further further to settlement of my claim
claim in a manner that they de authorized to receive payment with payment cheque/s being ma I further acknowledge that any on my behalf is on a without p liability basis insofar as the other vehicle/s is concerned.	eem fit and the workshop is further further to settlement of my claim ade in favour of the workshop. The settlement the workshop may reach prejudice and without admission of
claim in a manner that they de authorized to receive payment with payment cheque/s being ma I further acknowledge that any on my behalf is on a without p liability basis insofar as the other vehicle/s is concerned.	eem fit and the workshop is further further to settlement of my claim ade in favour of the workshop. y settlement the workshop may reach prejudice and without admission of a driver/owner/insurers of the