

INS. CASE OWNER:

CC

Y, Asm

1900

3645, Rha352

LKK:
IDAC:

100847

Surveyor:

DOI:

ASSIGNMENT

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

Nature of Accident:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher: DO FORM

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

3,750.00

(6 days)

Reduction:

43 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

8-7-19

Confirm with

JOHNSON

Email ☒ Call ☐

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

4,012.50

Loss of Rental (LOR):

S\$

800

(\$100 x 8 days)

Loss of Use (LOU):

S\$

-

(\$ x days)

Loss of Income (LOI):

S\$

-

(\$ x days)

LOR only ☐ LOU only ☒

LOR + LOU

☐

LOR + LOI

☐

[Tick only one]

GIA/LTA Search

S\$

7.49

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

Total:

S\$

4,819.99

Global Sum S\$:

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

4360.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$

4,819.99

Name 1:

TAN LIM MOTOR PTE LTD

Payee 2: (Strike if N.A.)

S\$

-

Name 2:

-

Payee 3: (Strike if N.A.)

S\$

-

Name 3:

-

31543
COE SPRING, 31/12/2023

\$ 3,750

Cost: \$2,031.45 (43%)

Lump Sum / I.B.A. (%)

FOIA



陳林摩哆私人有限公司

TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

NTUC Insured's Veh No : SLU1308D

Date of Accident : 25 February 2019

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date : 25 February 2019

Mr Fadzli Nizam Bin Morsed

LKK - Rasul

Estimate To Repair SJP7082P - Toyota PICNIC AUTO W/O ROOF RACK

Chassis No : JTEGH23B700026462

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	tailgate lid <i>BT</i> ✓	\$ 1,307.00
02	1 pc	tailgate lid toyota badge <i>nee</i> ✓	\$ 48.00
03	1 pc	tailgate lid picnic badge <i>ne</i> ✓	\$ 55.00
04	1 pc	tailgate lid centre logo badge <i>ne</i> ✓	\$ 80.00
05	1 pc	tailgate lid outer lock garnish <i>X 3/4 ne</i>	\$ 99.60
06	1 pc	tailgate lid lock top <i>X</i>	\$ 235.00
07	1 pc	o/s tailgate lid inner trim board <i>2RA</i> ✓	\$ 360.00
08	1 pc	tailgate lid weatherstrip <i>ne</i> ✓	\$ 315.10
09	1 pc	rear end panel <i>BT</i> ✓	\$ 428.00
10	1 pc	rear end panel inner trim <i>DE</i> ✓	\$ 245.00
11	1 pc	rear bumper <i>DE</i> ✓	\$ 520.00
12	2 pc	rear bumper side retainer @ \$45.00 <i>X ne</i>	\$ 90.00
13	6 pc	rear bumper fastener clips @ \$4.30 <i>ne</i> ✓	\$ 25.80
14	2 pc	rear bumper side holder @ \$25.00 <i>X ne</i>	\$ 50.00
15	2 pc	rear bumper end splashshield cover @ \$67.55 <i>X ne</i>	\$ 135.10
16	1 pc	rear lamp <i>X ne</i>	\$ 250.00
17	1 pc	rear luggage floor panel inner trim <i>at</i> ✓	\$ 785.00
18	1 pc	rear luggage floor partition garnish <i>X ne</i>	\$ 320.00
Less 25 %			\$ 5,348.60
			\$ 1,337.15
			\$ 4,011.45
<u>SPECIAL NETT ITEMS</u>			
19	1 pc	rear bumper parking sensor <i>ne</i> ✓	\$ 220 <i>ne</i> 350.00
20	1 pc	rear license plate <i>X ne</i>	\$ 50.00
			\$ 400.00
<u>LABOUR & MISC. CHARGES</u>			
01		To rust-proofing of the affected areas.	\$ 60 <i>120.00</i>
02		To check electrical lighting concerned.	\$ X 50.00
03		To reinstall of rear bumper parking sensor.	\$ 60 <i>80.00</i>
04		To remove and refit rear windscreen glass.	\$ 120.00
05		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 600 <i>900.00</i>
06		Putty and spray painting of the affected portion.	\$ 600 <i>900.00</i>
			\$ 2,170.00
Total			\$ 6,581.45

Rasul
Hp 90010068

6 days

HS

26/02/19 @ 1545

Resurvey

after repair

 MANDATE IA - (TAN LIM - SJP 7082P)

Type

 Question

Message

Please proceed

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 190607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 28/2/2019

Survey Details:

Date of loss	25-Feb-19
Date of appointment	26-Feb-19
Date of survey	26-Feb-19
Location of survey	TAN LIM MOTOR PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SJP 7082P
Make and Model	TOYOTA PICNIC AUTO - 1998cc
Date of registration	1/4/2009 // COE Renew, expiry-31/12/2023
Parf Rebate	
Market Value	\$ 34,000.00
Parf Rebate	\$ 27,056.00
Nett Loss	\$ 6,944.00

Repair details:

Initial Estimate	6,581.45
------------------	----------

Proposed/Revised repair cost:

Parts	\$ 3,346.68
Check items (estimate)	\$ -
Labour	\$ 1,320.00
Total	\$ 4,666.68
Lump Sum(if applicable)	\$ 3,750.00

Number of days for repair	<u>6 days</u>
---------------------------	---------------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

HEAD TO REA- BOLA 27

Mandate:

Liability(TP)		100%	
Proposed repair cost	\$	4,012.50	
Loss of use	\$	800.00	\$100 x 8 days
LTA search fees	\$	7.49	
Proposed Total	\$	4,819.99	



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Address: 1 Defu Lane 6 Singapore 539365

Tel: 6858 5151 Fax: 6858 0877

Our Ref : TP021022019

Date : 08/05/2019

Your Ref : SLU1308D

AXA INSURANCE

Attn: CLK / Motor Claims Department

Dear Sir/Madam,

ACCIDENT INVOLVING STP 7082P & SLU1308D ON 25.02.2019

We refer to the above accident.

It appears that your insured is the proximate cause of the accident.

We herewith enclose the relevant supporting documents to substantiate our client's property damage claim as our client has authorized us to quantify, to act and to reach settlement on their behalf.

☐ Original survey report/ _____ copies of photographs

☐ Original Tax-invoice number

☐ Original rental invoice number

☒ SAS / AS & IS / police report

☐ police result

☐ Certificate Of Insurance

☒ Vehicle search result

☒ Authorisation To Act

☐ _____

The quantification of our client's property damage claim is as follows:-

a)	Cost of repair (inclusive GST)	\$	4,012.50
b)	Survey fees / Photographs as per request	\$	
c)	Vehicle Search fees / GIA fees / Police Report fees / Reporting fees	\$	7.49
d)	Loss of hire / use / rental / earnings / rental fees [4100 x 9 days]	\$	900.00
e)	Scene photographs	\$	
f)	Admin fee	\$	
g)		\$	
Total		\$	4,919.99

* Driver's injury and other losses exclude in this claim.

Please acknowledge receipt of this Letter of Demand within fourteen (14) days.

If you are agreeable to the above, please forward discharge voucher for our client's signature and payment issued directly to "Tan Lim Motor Pte Ltd" within 28 days.

Yours faithfully,

Johnson Chua

Email: johnson.chua@tlmotor.com.sg



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19003645/R1ha3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 15-07-2019



ATTN: PETER WANG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLU 1308D	Veh. Inspected	SJP 7082P
Policy No.	GA437202/1	Coverage (\$)	0.00
Claim No.	S9M01F3U	Excess (\$)	0.00
Assign From	PETER WANG	Assign Date	26/02/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PICNIC AUTO	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JTEGH23B700026462	Colour	BLUE
Odometer	123465	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60R16	ROADSTONE	6 mm
L/H Front Tyre	205/60R16	ROADSTONE	6 mm
R/H Rear Tyre	205/60R16	ROADSTONE	6 mm
L/H Rear Tyre	205/60R16	ROADSTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	25/02/2019	Inspection Date	26/02/2019
Survey held at	1 DEFU LANE 6		
Repairer	TAN LIM MOTOR PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJP 7082P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE LID (CONSISTENT)	BENT	1,307.00	1,307.00
1	TAILGATE LID TOYOTA BADGE (CONSISTENT)	NECESSARY	48.00	48.00
1	TAILGATE LID PINIC BADGE (CONSISTENT)	NECESSARY	55.00	55.00
1	TAILGATE LID CENTRE LOGO BADGE (CONSISTENT)	NECESSARY	80.00	80.00
1	TAILGATE LID OUTER LOCK GARNISH (CONSISTENT)	SERVICEABLE	99.60	-
1	TAILGATE LID LOCK TOP (CONSISTENT)	SERVICEABLE	235.00	-
1	O/S TAILGATE LID INNER TRIM BOARD (CONSISTENT)	CRACKED	360.00	360.00
1	TAILGATE LID WEATHERSTRIP (CONSISTENT)	NECESSARY	315.10	315.10
1	REAR END PANEL (CONSISTENT)	BENT	428.00	428.00
1	REAR END PANEL INNER TRIM (CONSISTENT)	DEFORMED	245.00	245.00
1	REAR BUMPER (CONSISTENT)	DEFORMED	520.00	520.00
2	REAR BUMPER SIDE RETAINER @ \$45.00 (CONSISTENT)	SERVICEABLE	90.00	-
6	REAR BUMPER FASTENER CLIPS @ \$4.30 (CONSISTENT)	NECESSARY	25.80	25.80
2	REAR BUMPER SIDE HOLDER @ \$25.00 (CONSISTENT)	SERVICEABLE	50.00	-
2	REAR BUMPER END SPLASHIELD COVER @ \$67.55 (CONSISTENT)	SERVICEABLE	135.10	-
1	REAR LAMP (CONSISTENT)	SERVICEABLE	250.00	-
1	REAR LUGGAGE FLOOR PANEL INNER TRIM (CONSISTENT)	CUT	785.00	785.00
1	REAR LUGGAGE FLOOR PARTITION GARNISH (CONSISTENT)	SERVICEABLE	320.00	-
	LESS 25% DISCOUNT		-1,337.15	-1,042.23
			4,011.45	3,126.67
SPECIAL NETT ITEMS				
1	REAR BUMPER PARKING SENSOR (SN) (CONSISTENT)	NECESSARY	350.00	220.00
1	REAR LICENCE PLATE (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
			400.00	220.00
LABOUR				
	TO RUST-PROOFING OF THE AFFECTED AREAS.		120.00	60.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	50.00	-

Report Ref No. CC4/ASM19003645/R1ha3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No..2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.		80.00	60.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		120.00	120.00
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.		900.00	600.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		900.00	600.00
			2,170.00	1,440.00
GRAND TOTAL			6,581.45	4,786.67
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,750.00

Report Ref No. CC4/ASM19003645/R1ha3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.