



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19003645/R1ha3s2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 15-07-2019



ATTN: YVONNE ANG

Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SLU 1308D	<b>Veh. Inspected</b>	SJP 7082P
<b>Policy No.</b>	GA437202/1	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S9M01F3U	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	YVONNE ANG	<b>Assign Date</b>	26/02/2019

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA PICNIC AUTO	<b>c.c</b>	1998
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2009
<b>Chassis No.</b>	JTEGH23B700026462	<b>Colour</b>	BLUE
<b>Odometer</b>	123465	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	205/60R16	ROADSTONE	6 mm
<b>L/H Front Tyre</b>	205/60R16	ROADSTONE	6 mm
<b>R/H Rear Tyre</b>	205/60R16	ROADSTONE	6 mm
<b>L/H Rear Tyre</b>	205/60R16	ROADSTONE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

<b>Accident Date</b>	25/02/2019	<b>Inspection Date</b>	26/02/2019
<b>Survey held at</b>	1 DEFU LANE 6		
<b>Repairer</b>	TAN LIM MOTOR PTE LTD		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>6 Working Days</b>
-------------------------------------	-----------------------