

ESTIMATE

| Invoice Name & Address | | Owner Name & Vehicle Info | |
|-----------------------------|--|---------------------------|-----------------------------------|
| Kee Kia Kian | | Cust No/Name | /Kee Kia Kian |
| BLK 286C TOH GUAN RD | | Reg No/Reg Date | SLC6168C / 22/04/2016 |
| #06-16 | | Date In/Mileage | / 0 |
| SINGAPORE 603286 | | Chassis No | VF73ABHZTFJ870927 |
| Contact No Mobile: 97419727 | | Engine No | 10JBHD3028399 |
| | | Make/Model | CIT/GC4P 1.6 BLUEHDI EAT6 CONFORT |
| | | Colour/Trim | T6M / 8MF |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | | |
|---|-------|-------------------|-----|--------------|--------|------------|-------|------------|
| CSM00073 | Cash | 25/02/2019/ 12:31 | TLC | 442 / CocoLu | 14154 | | | |
| Description of Goods / Services | | | | | Qty | Unit Price | Disc% | Amount |
| E PNT88000 | | | | | | | | ✓ 600.00 |
| RENEW REAR BUMPER | | | | | | | | ✓ 420.00 |
| E PNT98000 | | | | | | | | 60 100.00 |
| SPRAY PAINT FOR REAR BUMPER | | | | | | | | ✓ 50.00 |
| E PNT88000 | | | | | | | | ✓ 300.00 |
| REMOVE & INSTALL PARKING SENSOR | | | | | | | | ✓ 20.00 |
| A 54900099 | | | | | | | | ✓ 858.00 |
| CHECK WIRING & ELECTRICAL SYSTEM | | | | | | | | ✓ 313.00 |
| A 54900099 | | | | | | | | ✓ 296.00 |
| CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM | | | | | | | | ✓ 258.00 |
| M SUNDRY | | | | | | | | |
| Sundry | | | | | 1.00 | 858.00 | 0.00 | de 858.00 |
| M REAR BUMPER | | | | | 1.00 | 313.00 | 0.00 | ant 313.00 |
| M BUMPER SKIRT | | | | | 1.00 | 296.00 | 0.00 | ? 296.00 |
| M BUMPER BRACKET | | | | | 1.00 | 258.00 | 0.00 | ? 258.00 |
| M BUMPER BRACKET | | | | | | | | |

Estimate

SURVEYOR NAME: Taufik 97495749
 SURVEYOR SIGNATURE: [Signature]
 DATE: 24/11/2015 WP
 REMARKS: Resurvey before paint
save 3 days

LKK Auto Consultants hence notify

Confirm & accept by the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplement items must be resurveyed and

Authorized signatory and company stamp

Validity of this estimate is 10 days from date of quotation. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

| | |
|------------------------|-----------------|
| Parts | 1,725.00 |
| Labour | 1,470.00 |
| Standard Menu | 0.00 |
| Specialist Job | 0.00 |
| Diagnostics Job | 0.00 |
| Sundry/Others | 20.00 |
| Total (w/o GST) | 3,215.00 |