



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



CITROËN

ESTIMATE

Company Reg No. 200609327M
GST Reg No. MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
Kee Kia Kian		Cust No/Name /Kee Kia Kian	
BLK 286C TOH GUAN RD		Reg No/Reg Date SLC6168C / 22/04/2016	
#06-16		Date In/Mileage / 0	
SINGAPORE 603286		Chassis No VF73ABHZTFJ870927	
Contact No Mobile: 97419727		Engine No 10JBHD3028399	
		Make/Model CIT/GC4P 1.6 BLUEHDI EAT6 CONFORT	
		Colour/Trim T6M / 8MF	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	25/02/2019/ 12:31	TLC	442 / CocoLu	14154

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR BUMPER				✓ 600.00 ✓
E PNT98000 SPRAY PAINT FOR REAR BUMPER				✓ 420.00 ✓
E PNT88000 REMOVE & INSTALL PARKING SENSOR				60 100.00 ✓
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				✓ 50.00 ✓
A 54900099 CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM				✓ 300.00 ✓
M SUNDRY Sundry				✓ 20.00 ✓
M REAR BUMPER	1.00	858.00	0.00	de 858.00 910
M BUMPER SKIRT	1.00	313.00	0.00	art 313.00 331
M BUMPER BRACKET	1.00	296.00	0.00	ref 296.00
M BUMPER BRACKET	1.00	258.00	0.00	ref 258.00

Estimate

SURVEYOR NAME: Taufik 97495749

SURVEYOR SIGNATURE: [Signature]

DATE: 24/11/2015 WP

REMARKS: Repair before paint

over 10 days work.

03 days

LKK Auto Consultants hence notify

Confirm & accept number of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

- No illegal or excessive charges is allowed
- Supplement items must be resurveyed and

Parts	1,725.00
Labour	1,470.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	20.00
Total (w/o GST)	3,215.00

Validity of this estimate is 10 days from date of issuance. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.