

INS. CASE OWNER:

CC 6, 201 1900 5649, KEASY

IDAC:

**ASSIGNMENT**

Surveyor:

KSC

DOI:

5/2/19

Date / Time:

26/2/19

Registered in Merimex:

Pre-assign / CCU / FTE



Insured Vehicle No. :

S6L5718J

Claim No. :

Name of Insured :

Whe Auto/Ins

Policy No. :

Insured Tel No. :

HP:

Make / Model :

Excess Sec II :SS

D.O.A:

25/2/19

Place of Accident :

P16

Is driver the owner? ( YES / NO )

( YES / NO )

Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability : %

Final ? Yes / No

S6L5028E



INSRS:

WSP:

Tel:

Liability:

RMKS:

BH Auto



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

S6L5028E - cur/Asm190028631/Ph3 : 007-5/2/19

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OE: 18-03-19 Email:

After call ltr to OE:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OE:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PER:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

9.03.19 4:30pm

CAUSED AND CONFIRMED ACCIDENT. DID INVOLVED 5 VEH DID WAS THE 5TH PART. INFORM TP CLAIM AND AGREED TO STATE AND PROGR ABOUT NO ISSUE.

15.05.19

FILE PASS TO TYPIST TO PREPARE REPORT.

17/1/19

File -> MK to close

TP to attached.

**PRELIMINARY ADVICE**

Date/Time:

Sent By:

**FINALIZATION**

Date/Time:

Confirm with:

Confirm by: KSC

Repair Cost: R/S \$515,500

( 21 days) Reduction: 63 %

**FINAL SETTLEMENT**

Date/Time:

29/6/19

Confirm with: Yun Shi

Email: Call:

Final Liability:

% 100

(Agreed / Assesed) BOLA S/N No.: 28

IF NO or B 28, Ass. Lia: 0%

Repair Cost:

W/L 29

\$511,585.00

5 VEH DID 4TH

Loss of Rental (LOR): nil

\$5338.40

( 26 days) x 200

Loss of Use (LOU):

\$5 -

(\$ x days)

Loss of Income (LOI):

\$5 -

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search:

\$531.00

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tow/ Independent)

Legal Cost:

\$5 -

1) Claim status: No / Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

\$519954.40

Global Sum \$5: 199500

**FINAL PAYMENT**

Date/Time:

Confirm with:

Email: Call:

Payee 1:

\$5 199500

Name 1:

BH Auto Services Pte Ltd.

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

COMPLIMENT 29/6/19

du 4/7/19 on

ASSIGNMENT

From: \_\_\_\_\_ Date: 05/3/19

Estimated Cost: \_\_\_\_\_

OO/TP/WS/TP RES/OD RES/EVA/INV/ MV

To inspect Vehicle No: SLV 5028E

at Workshop no: BH AUTO

of BIK 1 Sector C, s/m Ind. Est #01-115/

Insured: 113/115/17

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

Veh No: SLV 5028E Yr Reg: \_\_\_\_\_

Type:  M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: M (A) C200 CGI 1796

Colour: M Black A/C Insured / Std / NI / NA

Sp. Bonding: 183611 T/Excl: Insured / Std / NI / NA

Eng No: \_\_\_\_\_

C/No: W00 2040482A 520589

Gen. Cond:  Good / Fair / Poor / Burnt

Steering:  In order? / Jammed / Leaked / Burnt or

Brake:  In order? / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD /  M or

(Policy Condition)

Remarks: The veh had commenced its repair at the time of inspection.


Est. Repairs: 21 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT



Tyre Size: F: 225/45R17

R: \_\_\_\_\_

BS / DUN / EXNOVA /  GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R/Bal: 8 mm R/Bal: 8 mm

L/Bal: 8 mm L/Bal: 8 mm

D.O.A: 25/2/19 D.O.L: 5/3/19

Survey held at: \_\_\_\_\_

Des. of Damages: Fnt /  Rear / O/S / N/S / UIC / Rooftop or

& P/W

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Call by 8/15, 500 not more than??
	(RED -> 26.821 637)
	21 + 3 day Sunday + 2hrs =

Cost/Time: File Parts list?  : Prel. Report

File  : Final Report

Date/Time: File Return to?

Report Format:

Lump Sum / I.B.U. IS

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:  Site Insp. (\$)

Interview. (\$)

Tech. Insp. (\$)

W/O - Road. (\$)

# BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

## EQ Insurance Company Ltd

22 Gemmill Lane

Singapore 069257

Tel: 6223 9433 Fax: 6223 4190

ATTN: MOTOR CLAIM DEPARTMENT

Tel: 6338 7288 Fax: 6880 4838

DEAR SIR / MADAM :

*Not Notified  
1/1/19?  
Previous After Paint*

### ACCIDENT REPAIR ON: SLV5028E

MODEL : MERCEDES C200 CGI

POLICY NO : GA410430

CHASSIS NO : WDD2040482A520589

YEAR OF MANUFACTURE : 2011

DATE / TIME OF ACCIDENT: 25/02/2019 Time: 1535Hrs at PIE EUNOS TOWARDS CHANGI.

THIRD PARTY VEHICLE NO: SGL5718J

Date: 04/03/2019

Page : 1 of 3

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

<u>Replacement Of Parts</u>		Quantity	Unit Price	Condition	Amount	
S/N			SS		SS	
1	Bootlid	1	1,660.00	Dented	1,660.00	✓
2	Bootlid hinge LH	1	155.00	Bented	155.00	✓
3	Bootlid hinge RH	1	155.00	Bented	155.00	✓
4	Bootlid hinge cover LH	1	20.00	Kinked	20.00	? x 1/19
5	Bootlid hinge cover RH	1	20.00	Kinked	20.00	? x 1/19
6	Bootlid weatherstrip	1	175.00	Cut	175.00	50/19
7	Bootlid stopper LH	1	13.00	Necessary	13.00	? x 1/19
8	Bootlid stopper RH	1	13.00	Necessary	13.00	? x 1/19
9	Bootlid lock assy	1	90.00	Bented	90.00	✓
10	Bootlid lock striker	1		Bented		? x 1/19
11	Bootlid emblem	1	55.00	Necessary	55.00	✓
12	Bootlid lettering "C200"	1	80.00	Necessary	80.00	✓
13	Bootlid lettering "CGI"	1	80.00	Necessary	80.00	✓
14	Bootlid moulding chrome	1	210.00	Cracked	210.00	✓
15	Bootlid inner trim board	1	235.00	Kinked	235.00	? x 1/19
16	Bootlid inner trim board clips	12	5.00	Necessary	60.00	? x 1/19
17	Rear tail lamp assy LH	1	560.00	Broken	560.00	✓
18	Rear tail lamp assy RH	1	560.00	Broken	560.00	✓
19	Rear tail lamp garnish LH	1	50.00	Kinked	50.00	? x 1/19
20	Rear tail lamp garnish RH	1	50.00	Kinked	50.00	✓
21	Rear tail lamp lower bracket LH	1	75.00	Broken	75.00	✓
22	Rear tail lamp lower bracket RH	1	75.00	Broken	75.00	✓
23	Rear tail lamp panel LH	1	1,280.00	Bented	1,280.00	? x 1/19
24	Rear tail lamp panel RH	1	1,280.00	Bented	1,280.00	✓
25	Rear bumper	1	1,460.00	Broken	1,460.00	✓
26	Rear bumper reinforcement	1	695.00	Dented	695.00	✓
27	Rear bumper side bracket LH	1	45.00	Broken	45.00	✓
28	Rear bumper side bracket RH	1	45.00	Broken	45.00	✓
29	Rear bumper lower bracket LH	1	98.00	Broken	98.00	✓
30	Rear bumper lower bracket RH	1	98.00	Broken	98.00	✓
31	Rear bumper clips	10	5.00	Necessary	50.00	✓
32	Rear bumper rivet	10	5.00	Necessary	50.00	✓
33	Rear bumper side moulding LH	1	110.00	Necessary	110.00	✓
34	Rear bumper side moulding RH	1	110.00	Necessary	110.00	✓

35	Rear bumper centre moulding	1	120.00	Necessary	Me	120.00	✓
36	Rear bumper under cover	1	290.00	Broken	CM	290.00	✓
37	Rear bumper sensor	4	290.00	Malfunction		1,160.00	✓
38	Rear bumper sensor ring	4	10.00	Necessary	Me	40.00	✓
39	Rear bumper sensor wiring harness	1	155.00	Cut		155.00	7 x H/24
40	Rear bumper centre bracket	1	175.00	Broken		175.00	7 x H/24
41	Rear chassis member bracket LH	1		Bented			7 x H/24
42	Rear chassis member bracket RH	1		Bented			7 x H/24
43	Rear end panel	1	2,150.00	Dented	B	2,150.00	✓
44	Rear end panel top garnish	1	198.00	Kinked		198.00	7 x H/24
45	Rear floor panel	1		Bented	7 x H/24		
46	Rear floor panel cover board	1		Kinked	7 x H/24		
47	Seat rear back assembly	1		Bented	7 x H/24		
48	Seat rear bottom back assembly	1		Bented	7 x H/24		
49	Rear fender LH	1	2,090.00	Dented	R	2,090.00	X
50	Rear fender RH	1	2,090.00	Dented	Bu	2,090.00	✓
51	Rear fender inner shield LH	1	320.00	Cut	Sm	320.00	X
52	Rear fender inner shield RH	1	320.00	Cut		320.00	7 x H/24
53	Rear fender inner lower air vent RH	1	160.00	Kinked	R	160.00	7 x H/24
54	Rear exhaust silencer assy box	1	1,695.00	Bented	R	1,695.00	X
55	Rear exhaust silencer mounting	2	96.00	Necessary	Sm	192.00	X
56	Rear exhaust silencer rubber	2	70.00	Necessary	Sm	140.00	X
57	Bonnet	1	1,720.00	Dented	R	1,720.00	X
58	Bonnet emblem	1	80.00	Necessary	Me	80.00	✓
59	Bonnet hinge LH	1	110.00	Bented	H	110.00	} X
60	Bonnet hinge RH	1	110.00	Bented	H	110.00	
61	Bonnet insulator	1	255.00	Kinked	Sm	255.00	
62	Bonnet insulator clips	12	5.00	Necessary	Sm	60.00	
63	Bonnet spring LH	1	18.00	Necessary	Sm	18.00	
64	Bonnet spring RH	1	18.00	Necessary	Sm	18.00	
65	Bonnet lock LH	1	265.00	Bented	R	265.00	
66	Bonnet lock RH	1	265.00	Bented	H	265.00	
67	Bonnet lock top catch LH	1	65.00	Bented	H	65.00	
68	Bonnet lock top catch RH	1	65.00	Bented	H	65.00	
69	Bonnet lock catch	1	300.00	Bented	R	300.00	
70	Front grille	1	700.00	Broken	CM	700.00	✓
71	Front grille emblem	1	130.00	Necessary	Me	130.00	✓
72	Front bumper	1	1,515.00	Broken	CM	1,515.00	✓
73	Front bumper number plate garnish	1	135.00	Kinked	Sm	135.00	✓
74	Front bumper tow cover	1	54.00	Scratches	Sm	54.00	X
75	Front bumper sensor	6	288.00	Malfunction		1,728.00	7 x H/24
76	Front bumper sensor ring	6	10.00	Necessary		60.00	7 x H/24
77	Front bumper lower side moulding LH	1	90.00	Necessary	Me	90.00	✓
78	Front bumper lower side moulding RH	1	90.00	Necessary	Me	90.00	✓
79	Front bumper lower grille	1	90.00	Torn	Me	90.00	✓
80	Front bumper sponge	1	170.00	Broken		170.00	7 x H/24
81	Front bumper reinforcement	1	350.00	Dented	B	350.00	✓
82	Front bumper fog lamp LH	1	290.00	To Check	Sm	290.00	X
83	Front bumper fog lamp RH	1	290.00	To Check	Sm	290.00	X
84	Front bumper fog lamp cover LH	1	45.00	Scratches	Sm	45.00	X
85	Front bumper fog lamp cover RH	1	45.00	Scratches	Sm	45.00	X
86	Front bumper fog lamp lining chrome RH	1	105.00	Scratches	Sm	105.00	X
87	Front bumper fog lamp lining chrome LH	1	105.00	Scratches	Sm	105.00	X
88	Headlamp assy LH	1	1,030.00	Cut		1,030.00	7 x H/24
89	Headlamp assy RH	1	1,030.00	Cut		1,030.00	7 x H/24
90	Headlamp lower bracket LH	1	150.00	Torn	H	150.00	X
91	Headlamp lower bracket RH	1	150.00	Torn	H	150.00	X
92	Headlamp top garnish LH	1	215.00	Kinked	Sm	215.00	X
93	Headlamp top garnish RH	1	215.00	Kinked	Sm	215.00	X
94	Headlamp top panel LH	1	310.00	Bented	H	310.00	X
95	Headlamp top panel RH	1	310.00	Bented	H	310.00	X
96	Front support top panel	1	1,950.00	Bented		1,950.00	7 x H/24

97	Front support top panel garnish	1		Sm	Kinked	X		
98	Front air guide	1			Kinked	2	NH	
99	Front brace panel	1			Bented	2	NH	
100	Intecooler	1	1,300.00		Torn			1,300.00 7 NH
							Sub-Total:	36,990.00
							Less: 10% discount -	3,699.00
<b>Total Parts after 10% discount:</b>								<b>33,291.00</b>

**Special Nett Items**

1	Anti-rust coating	5	80.00					400.00 90l
2	Front number plate with casing	1	100.00			CM		100.00 451a
3	Rear number plate with casing	1	100.00			nu		100.00 451a
4	Rear windscreen sealant	1	120.00			nu		120.00 401nd
5	Rear end panel seal	1	100.00			nu		100.00 301a
6	Rear fender seal	1	100.00			nu		100.00 301a
								920.00
<b>Total Parts:</b>								<b>34,211.00</b>

**Labour Charges For Front and Rear Portion**

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.							2600l 4,000.00
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities							1980l 2,500.00
3	Provide skill labour to disconnect and check electrical wiring							60.00 40l
4	Remove and reinstall cushions, seats, backrest, inner trim, garnish, roof lining and or upholstery to facilitate repairs							150.00 120l
5	Dismantle and transfer bootlid fittings and mechanism to new/facilitate repair							80.00 60l
6	Provide skill labour to remove and replace bumper sensors							160.00 60l
7	Provide skill labour to remove and refit rear windscreen							200.00 120l
8	Provide skill labour to check and readjust wheel alignment					nu		80.00 X
9	Provide skill labour to remove and replace exhaust pipe/system to facilitate repair							120.00 80l
10	Provide skill labour to remove and refit fuel tank fixture and attachment							80.00 60l
11	Provide skill labour to mount vehicle onto chassis alignment bench							350.00 250l
12	Provide skill labour to remove and replace intercooler and related part							80.00 7x
13	Towing charges							(Bill) 250.00 7x
<b>Total Labour:</b>								<b>8,110.00</b>
<b>Total Parts &amp; Labour:</b>								<b>42,321.00</b>
<b>GST 7%</b>								<b>2,962.47</b>
<b>Grand Total:</b>								<b>45,283.47</b>

Estimate Repair Duration 26 days

ACCIDENT VEHICLE OF : SLV 5028E

Page : 3 of 3

21 days

**Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.**

Yours sincerely,

the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice"
- No legal modification(s) is allowed
- Supplementary items must be reviewed and is subject to final approval from insurance Co.

Authorised by Repairer

Survey attended by:

Name : Kenroth  
 Company : CIC  
 Date : 3/3/18  
 Time : 1.10pm  
 Contact No : 96910883  
 Email : \_\_\_\_\_

ESTIMATOR: WEN ZHENG

> [Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 2574Z

### Vehicle Details

Vehicle No.: SLV5028E  
Vehicle to be Exported: No  
Intended Deregistration Date: 26 Feb 2019  
Vehicle Make: MERCEDES BENZ  
Vehicle Model: C 200 CGI  
Primary Colour: Black  
Manufacturing Year: 2011  
Engine No.: 27186030212105  
Chassis No.: WDD2040482A520589  
Maximum Power Output: 135.0 kW (181 bhp)  
Open Market Value: \$42,402.00  
Original Registration Date: 29 Apr 2011  
First Registration Date: 29 Apr 2011  
Transfer Count: 1  
Actual ARF Paid: \$42,402.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 28 Apr 2021  
PARF Rebate Amount: \$25,441.00

### Intended COE Rebate Details

COE Expiry Date: 28 Apr 2021  
COE Category: B - Car (1601cc & above)  
COE Period(Years): 10  
QP Paid: \$55,001.00  
COE Rebate Amount: \$11,947.00  
**Total Rebate Amount: \$37,388.00**

The information contained herein is correct as at 26 Feb 2019

OK

Google AdSense

Post an Advertisement  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

Ford 5- Max (4) Eco Boost 2.0i - 230 BHP:



Run Like A Max 230 BHP  
Outstanding Performance  
Direct Owner 51,400



Browse by Category

Sort by Date Posted 20 results/page

4 vehicles

Mercedes Benz c200

Advanced Search

Image	Title	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
	<b>Search Selection</b>	Mercedes Benz c200	Any	Any	2011	Any	Any	Any	Available
	<b>Mercedes-Benz C-Class C200 CGI Avantgarde</b>	Mercedes-Benz C-Class C200 CGI Avantgarde	\$51,800	\$13,570 /yr	21-Apr-2011	1,796 cc	149,776 km	Luxury	Available
	1 Owner. Full C&C Maintenance. Excellent Condition. Accident Free. Flexible Loan Options With Promo Rate 2.18%. Please Call Us For A Test Drive Appointment!								
	Posted: 24-Feb-2019	Tags: 2011 Mercedes-Benz C200, 2011 mercedes-benz c200, Mercedes-Benz C200, mercedes-benz c200, Mercedes-Benz, C200, c200, Used Mercedes-Benz							
	<b>Mercedes-Benz C-Class C200</b>	Mercedes-Benz C-Class C200	\$64,998	\$14,730 /yr	14-Dec-2011	1,796 cc	-	Luxury	Available
	Be Our Next Lucky Client To Own This Impressive Grade-A Pre-Owned Vehicle At Most Reasonable And Affordable Price! Beautifully Hop Up With Expensive Wheels & Carbon Fibre Parts. Engine And Gearbox In ...								
	Posted: 22-Feb-2019	Tags: 2011 Mercedes-Benz C200, 2011 mercedes-benz c200, Mercedes-Benz C200, mercedes-benz c200, Mercedes-Benz, C200, c200, Used Mercedes-Benz							
	<b>Mercedes-Benz C-Class C200 CGI Avantgarde</b>	Mercedes-Benz C-Class C200 CGI Avantgarde	\$53,800	\$14,420 /yr	01-Jun-2011	1,796 cc	179,000 km	Luxury	Available
	Superb Condition CGI Avantgarde. Lady Owner. Well Kept Condition. 1 Year Extended Warranty From Reputable Workshop. Call For Appointment. Call Now!								
	Posted: 16-Feb-2019	Tags: 2011 Mercedes-Benz C200, 2011 mercedes-benz c200, Mercedes-Benz C200, mercedes-benz c200, Mercedes-Benz, C200, c200, Used Mercedes-Benz							
	<b>Mercedes-Benz C-Class C200 CGI Estate</b>	Mercedes-Benz C-Class C200 CGI Estate	\$57,800	\$15,200 /yr	01-Jul-2011	1,796 cc	-	Stationwagon	Available
	70% Loan Available, Low Mileage Done 18000Km Annually, No Repairs Needed, Well Maintained, From Cycle And Carriage, Sporty Black In Colour, Please Call For Viewing And Enquiry.								
	Posted: 10-Feb-2019	Tags: 2011 Mercedes-Benz C200, 2011 mercedes-benz c200, Mercedes-Benz C200, mercedes-benz c200, Mercedes-Benz, C200, c200, Used Mercedes-Benz							

Save this search criteria, to get email alerts whenever a match is found.

Title	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
-------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classified for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to CDE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Mercedes Benz c200, Mercedes Benz c200 Singapore, used Mercedes Benz c200 Singapore, used Mercedes Benz c200, used vehicles Singapore or even buy used Mercedes Benz c200 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, hover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & CDE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

Compare

about Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement



Auto  
Consultants  
Pte Ltd

Company Registration No. 19007199R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 4366501 FAX : (065) 43562913

Your ref: TBA  
Our ref: CC6/EQ119003649/K063

Date: 15/03/2019

The Motor Claims Department  
M/s EQ INSURANCE COMPANY LTD

**PRELIMINARY ADVICE OF VEHICLE NO. SLV 5028C**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 05/03/2019 at the premises of M/s BH Auto Services Pte Ltd (Sin Ming) - Sin Ming and have the following to report:-

Workshop Estimate Amount	: SS	42,321.00
Revised Estimate Amount	: SS	20,925.00
"Check" Items Amount	: SS	9,300.00
Total (Including Check Items)	: SS	30,226.00
Market Value	: SS	53,000.00
LTA Reimbursement Value	: SS	37,388.00
Nett Value	: S	2,012.00

Description of Damages:  
The vehicle sustained damages at the Front & Rear Panel



Comments/Present Status:  
Damages Considered  
Estimated normal repair cost/expense: S\$ 30,226.00

Yours faithfully,

KENNETH K...  
Licensed Appraiser

**Asher Sng (LKKAuto)**

---

**From:** Asher Sng (LKKAuto)  
**Sent:** Tuesday, 19 March 2019 4:56 PM  
**To:** 'SANDRA.WEE@LIVE.COM.SG'  
**Subject:** ACCIDENT INVOLVING SGL 5718J AND SLV 5028E ON 05/02/2019

Our Ref: CC6/EQI19003649/Kea3

19 MAR 2019

**WEE GEOK JOO / WEE YEN LING SANDRA**

Dear Sir/Madam,

**ACCIDENT INVOLVING SGL 5718J AND SLV 5028E ON 05/02/2019**

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal EQ INSURANCE COMPANY LIMITED.

Please call us if you have further queries.

Yours faithfully,

Asher  
Case Handler  
DID: 6841 6051  
FAX: 6741 4108  
Email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com)

c.c. *EQ INSURANCE COMPANY LIMITED*  
*(Motor Claims Dept)*

## AUTHORISATION

Name of owner of m/vehicle: Toh Jui Hui Sharlene  
Address: 415B Fernvale Link #17-50 S(792405)  
NRIC No: S8912574Z  
RE: ACCIDENT ON 25/12/2019 ALONG PTE Eunos Twos Changi  
INVOLVING SLV5028E vs SGL576J

In consideration of **BH AUTO SERVICES PTE LTD** ("the Workshop") repairing my/our vehicle no. SLV5028E at my/our request, I/We the abovenamed owner of motor vehicle no. SLV5028E hereby authorise the Workshop to demand claim, negotiate, settle my/our claim for cost of repairs loss of use and all other expenses and damages arising out of the above accident.

I/We further authorise the Workshop to appoint solicitors to demand, claim, negotiate, settle and/or commence legal proceedings in my/our name for the above purpose and at the sole discretion of the Workshop. All sums recovered therefrom shall belong to the Workshop absolutely and I/We further authorise the Workshop to give absolute discharge on my/our behalf and to sign all discharge vouchers and other documents in relation to the same on my/our behalf. I/We further agree to fully co-operate with the solicitors appointed by the Workshop on my/our behalf and attend all Court hearings that are necessary to prosecute the claims maintained by the Workshop.

I/We agree that in the event that the claim is rejected for whatsoever reason or the Workshop decides not to proceed with legal proceedings or for whatsoever reason the Workshop is unable to recover all of the repair costs or are only able to recover a portion of the same I/we hereby undertake to pay them the full repair costs and or any portion thereof that cannot be recovered and all expenses including legal costs that they may have incurred in pursuing the claim within 7 days from the date of the written notice for payment by them to my/our last known address.


I/We hereby declare that I/we will always remain and be liable to the Workshop for the cost of repair to my/our motor vehicle and expenses incurred on my/our behalf. In the event that Workshop has to issue any notice or commence legal proceedings against me/us to enforce this undertaking against me/us, I/we shall be liable for the Workshop's expenses and legal cost (including solicitor and client cost) on an indemnity basis.

I/We further authorise the Workshop to give to the other party/parties absolute discharge in respect of any liability and any sum, whether agreed or not made the Workshop or to the law firm appointed by the Workshop towards full settlement of my/our claim it shall be regarded as full and final discharge of the claim.

I/We further authorise the Workshop to settle the above mentioned claim in a manner that they deem fit and the Workshop is further authorised to receive payment further to settlement of my claim with payment cheque/s being made in favour of the Workshop.

Date this 26 (day) of 03 (month) 19 (year)

Signed:



Owner of m/vehicle: Toh Jui Hui Sharlene

HP: 90686734

Witnessed:

# BH AUTO SERVICES PTE LTD

BLK 1 SIN MING INDUSTRIAL ESTATE  
SECTOR C #01-115 SINGAPORE 575636

Tel: 6743 3494

Fax: 6269 2404

CO. REG. NO. 201006106C

GST REG NO. 201006106C

## TAX INVOICE

### Final Repair Bill

Our Ref: SLV5028E

Date: 02/05/2019

M/s EQ Insurance Company Limited  
5 Maxwell Road  
#17-00 Tower Block  
MND Complex Singapore 069110

Vehicle No : SLV5028E  
Make/ Model : MERCEDES C200CGI  
Year of Manufacture : 2011  
Chassis No. : WDD2040482A520589  
Colour : BLACK  
D.O.A : 25/02/2019

QTY	ITEM/PARTICULARS	AMOUNT (S\$)
-----	------------------	--------------

1. Repair Cost for Motor Vehicle No. SLV5028E  
Type of repair: LUMP SUM :S\$ 15,500.00

GST @ 7% : S\$ 1085.00

**GRAND TOTAL:S\$ 16,585.00**

**Total : Singapore Dollars Sixteen Thousand Five Hundred and Eighty-Five Dollars Only.**

  
Company's Stamp & Signature



明輝汽車服務私人有限公司  
BH AUTO SERVICES PTE LTD

NO. 213, KRANJI ROAD, SINGAPORE 739465 TEL: (65) 6558 8944  
FAX: (65) 6515 3144 CO. REG. NO. 200817512K GST REG. NO. 200817512K

Reference No.: CS 04035

Invoice No.: \_\_\_\_\_

Customer Name: Toh Jin Hui

Date/ Time: \_\_\_\_\_

Address: \_\_\_\_\_

Mobile Number: 90686734

Car Make & Model: Mercedes C200

Car Plate No: \_\_\_\_\_

SN	Services Provided	Brand	Qty	Unit Price	Amount
1	Towing Service				S\$
2	Battery				S\$
3	Tyres				S\$
4	Others: <u>Rental</u>	<u>SLM 3/60R</u>	<u>45</u>	<u>\$120.00</u>	<u>S\$ 5400.00</u>
Total Amount (inclusive of GST):					<u>S\$ 5778.00</u>

Special Remarks

26/02/2019 - 10/04/19

Service Done by:

Sales Person Name & Signature

Acknowledged by:

Customer Name & Signature

Received by:

Finance Department



# BH AUTO SERVICES PTE LTD

BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-111/113/115/117  
SINGAPORE 575636 TEL: (65) 6559 8944 FAX (65) 6269 2404  
CO. REG. NO.: 200917512K GST REG. NO.: 200917512K

## VEHICLE RENTAL AGREEMENT

Owner: BH AUTO SERVICES PTE LTD ("the owner") Date: \_\_\_\_\_

Hirer: Toh Jin Hui Sharlene Tel / HP: 90686734

NRIC / Co. Reg No: S89125742 FAX: \_\_\_\_\_

Address: \_\_\_\_\_

Owner and Hirer have agreed to this Vehicle Rental Agreement for the motor vehicle described below and upon the Terms and Conditions contained on both sides of this document. Hirer acknowledges having read and understood all the Terms and Conditions and signifies acceptance upon signing.

Owner Vehicle No.	<u>SLV 5028 E</u>	<u>Mercedes Benz C200</u>
Vehicle Reg. No.	<u>SLM 3160 R</u>	Rental:
Odometer:	<u>188590</u>	
Date & Time Out:	<u>26/02/2019</u>	Hirer's Signature: <u>[Signature]</u>
Date & Time In:	<u>10/4/19 - 6:45pm.</u>	Hirer's Signature: <u>[Signature]</u>

### Third Party Claim

In respect of each third party insurance claim arising from the date of hire to date of return of the vehicle (both dates inclusive). Hirer unconditionally agrees to pay Owner S\$ 3,500/- comprising excess payable and compensation to Owner for impact of claim on future motor insurance premiums.

### Own Vehicle Damage

Hirer is responsible for the first S\$ 3,500/- excess for collision or damage to first party (owner) and shall pay additional plus loss of earnings while damaged vehicle is under repair.

### BH AUTO SERVICES PTE LTD

[Signature]  
Authorised Signature



[Signature]  
Hirer's Signature



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

 6 Raffles Quay #18-00, Singapore 048580  
 Phone: +65 6224 0010 Fax: +65 6224 0030  
 Operating Hours: Monday to Friday 9am to 5pm  
 GST Registration No: M400017735

## Third Party Insurer Enquiry

Our Ref No: GR-19-030637

Date of Request: 26/02/2019

Your Ref No:

Online Purchase

 BH Auto Services Pte Ltd  
 Blk 1 Sin Ming Industrial Estate Sector C  
 #01/111/113/115/117  
 Singapore 575636

Dear Sir/Madam,

 Enquiry Date 26/02/2019  
 Enquiry By Jacelyn Loh Cai Ling  
 TP Vehicle No. SGL5718J  
 Accident Date 25/02/2019
**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SGL5718J	EQ Insurance Company Ltd	21/09/2018-20/09/2019	6223 9433

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
 Phone: +65 6224 0010 Fax: +65 6224 0030  
 Operating Hours: Monday to Friday 9am to 5pm  
 GST Registration No: M400017735

## TAX INVOICE

Our Ref No: GR-19-030637  
 Date of Request: 26/02/2019

Your Ref No: Online Purchase

BH Auto Services Pte Ltd  
 Blk 1 Sin Ming Industrial Estate Sector C  
 #01/111/113/115/117  
 Singapore 575636

Dear Sir/Madam,

Enquiry Date: 26/02/2019  
 Enquiry By: Jacelyn Loh Cai Ling  
 TP Vehicle No: SGL5718J  
 Accident Date: 25/02/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

 GIRO  Cash  Cheque



**GENERAL  
INSURANCE  
ASSOCIATION**

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**SEARCH RESULTS**

Our Ref No: GR-19-039943  
Date of Request: 13/03/2019

Your Ref No: Online Purchase

BH Auto Services Pte Ltd  
Blk 1 Sin Ming Industrial Estate Sector C  
#01/111/113/115/117  
Singapore 575636

Dear Sir/Madam,

**Your Search Criteria:**

Date of Accident: 25/02/2019  
Place of Accident: PIE EUNOS TWDS CHANGI  
Client Vehicle No: SLV5028E

With reference to your search criteria for the accident report, the following documents were found to closely match your search criteria:

REQ. VEHICLE	ACCIDENT LOCATION	ACCIDENT DATE
SGL5718J	PIE TWDS CHANGI NEAR JALAN EUNOS	25/02/2019 15:35

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

 6 Raffles Quay #18-00, Singapore 048580  
 Phone: +65 6224 0010 Fax: +65 6224 0030  
 Operating Hours: Monday to Friday 9am to 5pm  
 GST Registration No: M400017735

## TAX INVOICE

Our Ref No: GR-19-039948

Date of Request: 13/03/2019

Your Ref No:

Online Purchase

 BH Auto Services Pte Ltd  
 Blk 1 Sin Ming Industrial Estate Sector C  
 #01/111/113/115/117  
 Singapore 575636

Dear Sir/Madam,

 Date of Accident: 25/02/2019  
 Vehicle No: SLV5028E  
 Place of Accident: PIE EUNOS TWDS CHANGI  
 Involving Vehicle No: SGL5718J

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SGL5718J	PIE EUNOS TWDS CHANGI	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You,

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[X] GIRO [ ] Cash [ ] Cheque



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

 6 Raffles Quay #18-00, Singapore 048580  
 Phone: +65 6224 0010 Fax: +65 6224 0030  
 Operating Hours: Monday to Friday 9am to 5pm  
 GST Registration No: M400017735

## TAX INVOICE

 Our Ref No: GR-19-039943  
 Date of Request: 13/03/2019

Your Ref No: Online Purchase

 BH Auto Services Pte Ltd  
 Blk 1 Sin Ming Industrial Estate Sector C  
 #01/111/113/115/117  
 Singapore 575636

Dear Sir/Madam,

**Your Search Criteria:**
 Date of Accident: 25/02/2019  
 Place of Accident: PIE EUNOS TWDS CHANGI  
 Client Vehicle No: SLV5028E

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

 GIRO  Cash  Cheque

## Hsiao Tong (LKKAuto)

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Saturday, 29 June 2019 3:08 PM  
**To:** Janet Tan  
**Cc:** Tan Wei Yin; Admin A  
**Subject:** RE: <SEEK MANDATE> EQ ref : TBA \*LKK ref : CC6/EQI19003649/Kpa3q2 [ACCIDENT INVOLVING SGL5718J(EQ-DM19HO00601/JT) AND SLV5028E(TP) ON 05/02/2019]

Dear Sirs/Madam,

We refer to the above matter.

Case has been settled at a global sum of **\$19,950.00(all-in)** with Third Party repairer.

We will proceed to close file and submit all the relevant documents to your good office soon.

Thank you.

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Janet Tan <[janet.tan@eqinsurance.com.sg](mailto:janet.tan@eqinsurance.com.sg)>  
**Sent:** Wednesday, 26 June 2019 1:58 PM  
**To:** Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>  
**Cc:** Tan Wei Yin <[weiyin.tan@eqinsurance.com.sg](mailto:weiyin.tan@eqinsurance.com.sg)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
**Subject:** FW: <SEEK MANDATE> EQ ref : TBA \*LKK ref : CC6/EQI19003649/Kpa3q2 [ACCIDENT INVOLVING SGL5718J(EQ-DM19HO00601/JT) AND SLV5028E(TP) ON 05/02/2019]

Dear Hsiao Tong

Please proceed to offer up to \$19,954.40.

Regards,

**Janet Tan**

Senior Executive | Claims



EQ Insurance Company Limited



*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.*

**From:** Hsiao Tong (LKKAuto) [<mailto:chewht@lkkauto.com>]  
**Sent:** Wednesday, June 26, 2019 12:09 PM  
**To:** Janet Tan <[janet.tan@eqinsurance.com.sg](mailto:janet.tan@eqinsurance.com.sg)>  
**Cc:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
**Subject:** <SEEK MANDATE> EQ ref : TBA \*LKK ref : CC6/EQI19003649/Kpa3q2 [ACCIDENT INVOLVING SGL5718J(EQ-OI) AND SLV5028E(TP) ON 05/02/2019]

EQ ref : **TBA**  
LKK ref : CC6/EQI19003649/Kpa3q2

Dear Sirs/Madam,

**ACCIDENT INVOLVING SGL5718J(EQ-OI) AND SLV5028E(TP) ON 05/02/2019**

We refer to the above matter.

The said chain collision involved 5 vehicles whereby our insured was the 4th vehicle.  
In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%.  
We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer Third Party repairer "**BH AUTO SERVICES PTE LTD**" at **\$19,954.40(all-in)**.

The summary is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 45,283.47	\$ 16,585.00
2. Loss of Rental (32days x \$120.00)(w/GST)	\$ 4,108.80	\$ 3,338.40 (26days x \$120.00)(w/GST)
3. LTA/ GIA Search Fee	\$ 31.00	\$ 31.00
Total	\$ 49,423.27	<b>\$ 19,954.40</b>

\*\*21days recommendation for repair + 3Sunday + 2PRS = 26days.

Enclosed here with all the relevant documents for your perusal.

**Kindly let us have your approval/instruction.**

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

# BH AUTO SERVICES PTE LTD

fshey

BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636

Tel: 6559 8944 Fax: 6269 2404

CO. REG. NO. 200917512K

GST REG NO. 200917512K

**PLEASE QUOTE OUR FILE REFERENCE WHEN REPLYING**

Your Reference: SGL5718J

Our Reference: SLV5028E

Date: 02/05/2019

M/s EQ Insurance Company Limited  
5 Maxwell Road  
#17-00 Tower Block  
MND Complex Singapore 069110

BY POST & EMAIL

Attention: Claims Department

CLAIMANT: TOH JIN HUI SHALENE

**PROPERTY DAMAGED CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 25/02/2019 ALONG PIE EUNOS TWDS CHANGI INVOLVING VEHICLE NO SLV5028E & SGL5718J**

We act for TOH JIN HUI SHALENE who was the owner of motor vehicle no. SLV5028E.

We are instructed by the above named to claim damages against you/your insured in connection with a road traffic accident on 25/02/2019 involving our client's vehicle registration number SLV5028E and vehicle registration number SGL5718J, driven by you/your insured at the material time.

We are instructed that the accident was caused by you/your insured's negligent driving and /or management of your/you insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

1	Cost of Repair (Included 7% GST)	\$ 16,585.00
2	Loss of Rental (\$ 120.00 x 32days) (Included 7% GST) Surveyor recommended repair 21 days, 2days PRI, 1days survey, 2 days resurvey and 6 days sunday	\$ 4108.80
3	LTA Search Fee	\$ 31.00
	<b>Total :</b>	<b>\$ 20724.80</b>

We enclose a copy of each of the following documents for your consideration:-

- GIA/ Police report lodged by driver of ;
- Final Repair Bill
- Rental Invoice / Loss Of Use
- LTA Search Fee Invoice
- Letter Of Authorization

Kindly revert to our client's claim within the next 7 days.

Yours faithfully,



Yun Shi

(O): 6559 8944 (F): 6269 2404

Email: yunshi.chan@bhauto.com.sg



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 17/07/2019

**THIRD PARTY DIRECT SETTLEMENT**

Vehicle No.	SGL 5718J (Insd Veh)	Your Ref. No. : DM19HO00601/JT
	SLV 5028E (TP Veh)	Our Ref. No. : CC6/EQ19003649/Kpa3q2
Date of Accident	25/2/2019	

Liability	100%	
Final Repair Cost	: \$ 16,585.00	
Loss of Use	: \$	days
Rental (If any)	: \$ 3,338.40	26 days
Others:	: \$ 31.00	
	: \$	
	19,954.40	
Final Settlement Sum	: \$ 19,950.00	GLOBAL SUM
Remarks	:	

**Payment Instruction: Payee's Breakdown**

1)	BH AUTO SERVICES PTE LTD	: \$ 19,950.00
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC6/EQ19003649/Kpa3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 17-07-2019	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGL 5718J	Veh. Inspected	SLV 5028E
Policy No.	DMPPHQ18-006338	Coverage (\$)	0.00
Claim No.	DM19HO00601/JT	Excess (\$)	0.00
Assign From		Assign Date	05/03/2019
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ C 200 CGI (A)	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WDD2040482A520589	Colour	METALLIC BLACK
Odometer	183611	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45 R17	GOODYEAR	8 mm
L/H Front Tyre	225/45 R17	GOODYEAR	8 mm
R/H Rear Tyre	225/45 R17	GOODYEAR	8 mm
L/H Rear Tyre	225/45 R17	GOODYEAR	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	25/02/2019	Inspection Date	05/03/2019
Survey held at	BH AUTO SERVICES PTE LTD BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575638		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		21 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 6

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 5028E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BOOTLID	BENT	1,660.00	1,660.00
1	BOOTLID HINGE LH	BENT	155.00	155.00
1	BOOTLID HINGE RH	BENT	155.00	155.00
1	BOOTLID HINGE COVER LH	NOT NECESSARY	20.00	-
1	BOOTLID HINGE COVER RH	NOT NECESSARY	20.00	-
1	BOOTLID STOPPER LH	NOT NECESSARY	13.00	-
1	BOOTLID STOPPER RH	NOT NECESSARY	13.00	-
1	BOOTLID LOCK ASSY	JAMMED	90.00	90.00
1	BOOTLID LOCK STRIKER (NPA)	NOT NECESSARY	-	-
1	BOOTLID EMBLEM	NECESSARY	55.00	55.00
1	BOOTLID LETTERING "C200"	NECESSARY	80.00	80.00
1	BOOTLID LETTERING "CGI"	NECESSARY	80.00	80.00
1	BOOTLID MOULDING CHROME	WARPED	210.00	210.00
1	BOOTLID INNER TRIM BOARD	NOT NECESSARY	235.00	-
12	BOOTLID INNER TRIM BOARD CLIPS @\$5.00	NOT NECESSARY	60.00	-
1	REAR TAIL LAMP ASSY LH	CRACKED	560.00	560.00
1	REAR TAIL LAMP ASSY RH	BROKEN	560.00	560.00
1	REAR TAIL LAMP GARNISH LH	NOT NECESSARY	50.00	-
1	REAR TAIL LAMP GARNISH RH	DISTORTED	50.00	50.00
1	REAR TAIL LAMP LOWER BRACKET LH	DISTORTED	75.00	75.00
1	REAR TAIL LAMP LOWER BRACKET RH	BENT	75.00	75.00
1	REAR TAIL LAMP PANEL LH	NOT NECESSARY	1,280.00	-
1	REAR TAIL LAMP PANEL RH	BENT	1,280.00	1,280.00
1	REAR BUMPER	BENT	1,460.00	1,460.00
1	REAR BUMPER REINFORCEMENT	BENT	695.00	695.00
1	REAR BUMPER SIDE BRACKET LH	DISTORTED	45.00	45.00
1	REAR BUMPER SIDE BRACKET RH	DISTORTED	45.00	45.00
1	REAR BUMPER LOWER BRACKET LH	CRACKED	98.00	98.00
1	REAR BUMPER LOWER BRACKET RH	CRACKED	98.00	98.00
10	REAR BUMPER CLIPS @\$5.00	NECESSARY	50.00	50.00
10	REAR BUMPER RIVET @\$5.00	NECESSARY	50.00	50.00

Report Ref No. CC6/EQ19003649/Kpa3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER SIDE MOULDING LH	NECESSARY	110.00	110.00
1	REAR BUMPER SIDE MOULDING RH	NECESSARY	110.00	110.00
1	REAR BUMPER CENTRE MOULDING	NECESSARY	120.00	120.00
1	REAR BUMPER UNDER COVER	CRACKED	290.00	290.00
4	REAR BUMPER SENSOR @\$290.00	SHORTED	1,160.00	1,160.00
4	REAR BUMPER SENSOR RING @\$10.00	NECESSARY	40.00	40.00
1	REAR BUMPER SENSOR WIRING HARNESS	NOT NECESSARY	155.00	-
1	REAR BUMPER CENTRE BRACKET	NOT NECESSARY	175.00	-
1	REAR CHASSIS MEMBER BRACKET LH (NPA)	NOT NECESSARY	-	-
1	REAR CHASSIS MEMBER BRACKET RH (NPA)	NOT NECESSARY	-	-
1	REAR END PANEL	BENT	2,150.00	2,150.00
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	198.00	-
1	REAR FLOOR PANEL (NPA)	NOT NECESSARY	-	-
1	REAR FLOOR PANEL COVER BOARD (NPA)	NOT NECESSARY	-	-
1	SEAT REAR BACK ASSEMBLY (NPA)	NOT NECESSARY	-	-
1	SEAT REAR BOTTOM BACK ASSEMBLY (NPA)	NOT NECESSARY	-	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR	2,090.00	-
1	REAR FENDER RH	BUCKLED	2,090.00	2,090.00
1	REAR FENDER INNER SHIELD LH	SERVICEABLE	320.00	-
1	REAR FENDER INNER SHIELD RH	NOT NECESSARY	320.00	-
1	REAR FENDER INNER LOWER AIR VENT RH	NOT NECESSARY	160.00	-
1	REAR EXHAUST SILENCER ASSY BOX	TO REPAIR SEE LABOUR	1,695.00	-
2	REAR EXHAUST SILENCER MOUNTING @\$96.00	SERVICEABLE	192.00	-
2	REAR EXHAUST SILENCER RUBBER @\$70.00	SERVICEABLE	140.00	-
1	BONNET	TO REPAIR SEE LABOUR	1,720.00	-
1	BONNET EMBLEM	NECESSARY	80.00	80.00
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	110.00	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	110.00	-
1	BONNET INSULATOR	SERVICEABLE	255.00	-
12	BONNET INSULATOR CLIPS @\$5.00	NOT NECESSARY	60.00	-

Report Ref No. CC6/EQ119003649/Kpa3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 3 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET SPRING LH	SERVICEABLE	18.00	-
1	BONNET SPRING RH	SERVICEABLE	18.00	-
1	BONNET LOCK LH	TO REPAIR SEE LABOUR	265.00	-
1	BONNET LOCK RH	TO REPAIR SEE LABOUR	265.00	-
1	BONNET LOCK TOP CATCH LH	TO REPAIR SEE LABOUR	65.00	-
1	BONNET LOCK TOP CATCH RH	TO REPAIR SEE LABOUR	65.00	-
1	BONNET LOCK CATCH	TO REPAIR SEE LABOUR	300.00	-
1	FRONT GRILLE	CRACKED	700.00	700.00
1	FRONT GRILLE EMBLEM	NECESSARY	130.00	130.00
1	FRONT BUMPER	CRACKED	1,515.00	1,515.00
1	FRONT BUMPER NUMBER PLATE GARNISH	DENTED	135.00	135.00
1	FRONT BUMPER TOW COVER	SERVICEABLE	54.00	-
8	FRONT BUMPER SENSOR @\$288.00	NOT NECESSARY	1,728.00	-
6	FRONT BUMPER SENSOR RING @\$10.00	NOT NECESSARY	60.00	-
1	FRONT BUMPER LOWER SIDE MOULDING LH	NECESSARY	90.00	90.00
1	FRONT BUMPER LOWER SIDE MOULDING RH	NECESSARY	90.00	90.00
1	FRONT BUMPER LOWER GRILLE	DENTED	90.00	90.00
1	FRONT BUMPER SPONGE	NOT NECESSARY	170.00	-
1	FRONT BUMPER REINFORCEMENT	BENT	350.00	350.00
1	FRONT BUMPER FOG LAMP LH	SERVICEABLE	290.00	-
1	FRONT BUMPER FOG LAMP RH	SERVICEABLE	290.00	-
1	FRONT BUMPER FOG LAMP COVER LH	SERVICEABLE	45.00	-
1	FRONT BUMPER FOG LAMP COVER RH	SERVICEABLE	45.00	-
1	FRONT BUMPER FOG LAMP LINING CHROME RH	SERVICEABLE	105.00	-
1	FRONT BUMPER FOG LAMP LINING CHROME LH	SERVICEABLE	105.00	-
1	HEADLAMP ASSY LH	NOT NECESSARY	1,030.00	-
1	HEADLAMP ASSY RH	NOT NECESSARY	1,030.00	-
1	HEADLAMP LOWER BRACKET LH	TO REPAIR SEE LABOUR	150.00	-

Report Ref No. CC6/EQ119003649/Kpa3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 4 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	HEADLAMP LOWER BRACKET RH	TO REPAIR SEE LABOUR	150.00	-
1	HEADLAMP TOP GARNISH LH	SERVICEABLE	215.00	-
1	HEADLAMP TOP GARNISH RH	SERVICEABLE	215.00	-
1	HEADLAMP TOP PANEL LH	TO REPAIR SEE LABOUR	310.00	-
1	HEADLAMP TOP PANEL RH	TO REPAIR SEE LABOUR	310.00	-
1	FRONT SUPPORT TOP PANEL	NOT NECESSARY	1,950.00	-
1	FRONT SUPPORT TOP PANEL GARNISH (NPA)	SERVICEABLE	-	-
1	FRONT AIR GUIDE (NPA)	NOT NECESSARY	-	-
1	FRONT BRACE PANEL (NPA)	NOT NECESSARY	-	-
1	INTERCOOLER	NOT NECESSARY	1,300.00	-
	LESS 10% DISCOUNT		-3,681.50	-1,687.60
			33,133.50	15,188.40
1	BOOTLID WEATHERSTRIP (SN) (50%)	DISTORTED / CUT	175.00	87.50
	LESS 10% DISCOUNT		-17.50	-
			157.50	87.50
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT NUMBER PLATE WITH CASING (SN)	CRACKED	100.00	45.00
1	REAR NUMBER PLATE WITH CASING (SN)	DENTED	100.00	45.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	120.00	40.00
1	REAR END PANEL SEAL (SN)	NECESSARY	100.00	30.00
1	REAR FENDER SEAL (SN)	NECESSARY	100.00	30.00
			520.00	190.00
	<b><u>LABOUR</u></b>			
	ANTI-RUST COATING.		400.00	90.00

Report Ref No. CC6/EQI19003649/Kpa3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 5 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT, CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER LH, REAR EXHAUST SILENCER ASSY BOX, BONNET, BONNET HINGE LH, BONNET HINGE RH, BONNET LOCK LH, BONNET LOCK RH, BONNET LOCK TOP CATCH LH, BONNET LOCK TOP CATCH RH. )		4,000.00	2,600.00
	BONNET LOCK CATCH, HEADLAMP LOWER BRACKET LH, HEADLAMP LOWER BRACKET RH, HEADLAMP TOP PANEL LH AND HEADLAMP TOP PANEL RH. )		-	-
	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES.		2,500.00	1,980.00
	PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING.		60.00	40.00
	REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING AND OR UPHOLSTERY TO FACILITATE REPAIRS.		150.00	120.00
	DISMANTLE AND TRANSFER BOOTLID FITTINGS AND MECHANISM TO NEW / FACILITATE REPAIR.		80.00	60.00
	PROVIDE SKILL LABOUR TO REMOVE AND REPLACE BUMPER SENSORS.		160.00	60.00
	PROVIDE SKILL LABOUR TO REMOVE AND REFIT REAR WINDSCREEN.		200.00	120.00
	PROVIDE SKILL LABOUR TO CHECK AND READJUST WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	PROVIDE SKILL LABOUR TO REMOVE AND REPLACE EXHAUST PIPE / SYSTEM TO FACILITATE REPAIR.		120.00	80.00
	PROVIDE SKILL LABOUR TO REMOVE AND REFIT FUEL TANK FIXTURE AND ATTACHMENT.		80.00	60.00
	PROVIDE SKILL LABOUR TO MOUNT VEHICLE ONTO CHASSIS ALIGNMENT BENCH.		350.00	250.00
	PROVIDE SKILL LABOUR TO REMOVE AND REPLACE INTERCOOLER AND RELATED PART.	NOT NECESSARY	80.00	-
	TOWING CHARGES.	NOT NECESSARY	250.00	-
			8,510.00	5,460.00
	<b>GRAND TOTAL</b>		<b>42,321.00</b>	<b>20,925.90</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>15,500.00</b>

Report Ref No. CC6/EQ119003649/Kpa3q2



Report Ref No. CC6/EQ119003649/Kpa3q2

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**

## Joanne Lee (LKK Auto)

---

**From:** Joanne Lee (LKK Auto) <report@lkkauto.com>  
**Sent:** Thursday, 18 July 2019 3:57 PM  
**To:** 'eqiprs@eqinsurance.com.sg'  
**Cc:** 'chewht@lkkauto.com'  
**Subject:** TP Direct Settlement - Accident Involving SGL 5718J (OI) and SLV 5028E (TP) on 25/02/2019  
**Attachments:** LKK REPORT & PHOTO.pdf; TP DS SUPPORTING DOCUMENT.pdf

Dear Sir/Madam,

Please be informed that the above-mentioned case had been settled.

Enclose herewith final report & relevant documents for your necessary action please.

Thank you.

Best Regards,

JOANNE | Reports

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: [report@lkkauto.com](mailto:report@lkkauto.com)

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 Singapore 408933