

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5689P**AAD1902-215***Not Notwithstanding**Resumy B4 paint**82254.58*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 5689P

JTDKB3FU703074450

RENAULT

LATITUDE

24.2.2019

EQ

26/10/2018

PART**LIST**

1	1 FRONT BUMPER	\$	<i>Buckler</i>	499.90	✓
2	1 BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$	<i>SL</i>	101.20	} X
3	1 REINFORCEMENT, FRONT BUMPER	\$	<i>N</i>	696.40	
4	1 ABSORBER, FRONT BUMPER, LOWER	\$	<i>SL</i>	130.20	
5	1 ABSORBER, FRONT BUMPER ENERGY	\$	<i>SL</i>	78.10	
6	1 FRONT BUMPER SIDE RETAINER RH	\$	<i>SL</i>	78.00	
7	1 FRONT BUMPER SIDE RETAINER LH	\$	<i>SL</i>	78.00	
8	1 FRONT BUMPER SUPPORT	\$	<i>SL</i>	81.70	
9	1 EXTENSION, FRONT BUMPER, RH	\$	<i>SL</i>	117.80	
10	1 EXTENSION, FRONT BUMPER, LH	\$	<i>SL</i>	117.80	
11	1 FRONT LED LAMP (LOWER) RH	\$	<i>SL</i>	907.75	} X
12	1 FRONT LED LAMP (LOWER) LH	\$	<i>SL</i>	907.75	
13	1 FRONT HEADLAMP RH	\$	<i>SL</i>	2,909.04	
14	1 COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	<i>SL</i>	492.30	
15	1 MOTOR, HEADLAMP LEVELING, RH	\$	<i>SL</i>	413.10	
16	1 FRONT HEADLAMP LH	\$	<i>SL</i>	2,909.04	
17	1 COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	<i>SL</i>	492.30	
18	1 MOTOR, HEADLAMP LEVELING, RH	\$	<i>SL</i>	413.10	
19	1 FRONT FENDER <i>RH</i>	\$	<i>SL</i>	945.30	✓
20	1 EXTENSION, FRONT FENDER, <i>RH</i>	\$	<i>N</i>	48.80	X
21	1 COVER SUB-ASSY, FRONT PILLAR, UPR <i>RH</i>	\$	<i>SL</i>	98.30	X
22	1 LINER, FRONT FENDER, RH	\$	<i>SL</i>	200.70	X
23	1 FRONT FENDER EMBLEM <i>RH</i>	\$	<i>N</i>	86.50	✓
24	1 SEAL, FENDER APRON MUDGUARD, <i>RH</i>	\$	<i>SL</i>	50.90	X
25	1 FRONT BONNET	\$	<i>N</i>	950.50	X
26	1 FRONT LOWER ARM	\$	<i>SL</i>	631.90	X
27	1 FRONT SHOCK ABSORBER	\$	<i>SL</i>	398.20	X
28	1 SHAFT ASSY, FRONT DRIVE, RH	\$	<i>N</i>	1,186.20	X
29	1 ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 RH	\$	<i>SL</i>	637.50	X

Trans-cab Auto Services Pte Ltd**AAD1902-215**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5689P

30	1 KNUCKLE, STEERING, RH	\$	<i>Sn</i>	562.30	}	<i>X</i>
31	1 LINK ASSY, FRONT STABILIZER, RH	\$	<i>Sn</i>	199.00		
32	1 BAR, STABILIZER, FRONT	\$	<i>Sn</i>	360.30		
33	1 SUPPORT SUB-ASSY, FRONT SUSPENSION, RH	\$	<i>Sn</i>	200.60		
34	1 ABSORBER ASSY, SHOCK, FRONT RH	\$	<i>Sn</i>	401.80		
35	1 COCK ASSY, RESERVE TANK	\$	<i>Sn</i>	117.80		
36	1 PANEL SUB-ASSY, FRONT DOOR, LH	\$	<i>n</i>	1,264.00		
		\$		19,764.08		
		25% \$		4,941.02		
		\$		14,823.06		

Special Nett

1	1 FRONT WHEEL RIM	\$	<i>Sn</i>	1,570.55	<i>X</i>
2	1 FRONT WHEEL RIM COVER	\$	<i>n</i>	175.80	✓
3	1 CLIP, FRONT FENDER LINER	\$	<i>n</i>	22.00	<i>X</i>
		TOTAL \$		1,768.35	

TOTAL PARTS \$ 16,591.41**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	4,200.00	<i>4401</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	<i>4001</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>301</i>
To transfer of Fender fittings, attachments and perform water seepage test.	\$	<i>n</i> 170.00	<i>X</i>
To transfer of Front Bumper fittings, attachments and perform water seepage test.	\$	<i>n</i> 170.00	<i>X</i>

Trans-cab Auto Services Pte Ltd**AAD1902-215**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5689P

To transfer of front windscreen fittings and conduct water seepage test.	\$	nn 170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	601
To vacuum, replace, refix and recharge air condenser	\$	nn 380.00	X
To replace, refix and top up coolant for radiator	\$	4 170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	4 170.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	4 380.00	X
TOTAL	\$	10,400.00	

Over All Total \$ 41,814.47**(PART-BY-PART) Repair Days**~~14 days~~

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: