



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

*Not Allowed
Main
The/He Survey
3dy.
28/2/19
1/7/8*

EQ INSURANCE

5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEX
SINGAPORE 069110

DATE : 19-02-2019

VEHICLE NO. : SKZ7209C

ACCIDENT DATE : 14-02-2019 19:15

THIRD PARTY REF. : YN3113T

ATTN: EQ INSURANCE

ESTIMATE COST OF REPAIR TO VEHICLE SKZ7209C MAZDA 6-2.0 4-DOOR SEDAN 2.0L SP.6

QTY PARTS DESCRIPTION

1	1	FRONT HEADLAMP LH
2	1	FRONT FENDER LH
3	1	FRONT FENDER SHIELD LH
4	10	FRONT FENDER SHIELD CLIP@\$2.00
5	1	FRONT BUMPER
6	1	FRONT BUMPER SIDE RETAINER LH
7	10	FRONT BUMPER CLIP@\$2.00

AMOUNT (SG\$)

<i>320</i>	1250.00	—
<i>300</i>	120.00	—
	89.00	?
<i>neu</i>	20.00	—
<i>2</i>	550.00	α
<i>300</i>	8.00	—
<i>neu</i>	20.00	—
	2,057.00	
	ADD 20 %	
	411.40	
	TOTAL (A)	
	2,468.40	

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM	30.00	<i>20</i>
2	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	480.00	<i>300</i>
3	1	SPRAYPAINTING CHARGES	620.00	<i>600</i>

TOTAL (D)

1,130.00

ESTIMATE TOTAL

3,598.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: