

# PEOPLE'S VEHICLE RECOVERY SERVICE

BLK 3023-A UBI ROAD 1 #01-60 SINGAPORE 408717

Tel No. : 67433246/ 67438552 Fax No. : 67430013

E-Mail : peoplevehicle@gmail.com

Tax Reg. No. : M90001895E Buss. Reg. No. : 31800200X

CHINA TAI PING INSURANCE (S) PTE LTD  
105 CECIL STREET #19-00  
THE OCTAGON (S) 069534

Attention : Motor Claim Department

Contact : 6389 6111 Fax No. : 6222 1033

Estimate : ES19003

Date : 19/02/2019

Vehicle Num. : GBE 6599 A

Make/Model : TOYOTA HIACE

Chassis/Eng# :

Accident Date : 19/02/2019

Claim No. : TT 337-19

Reference : YP 3481 U

Policy No. : NTUC 5101145685

JTFHT02P700190665

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

|     |   |                             |        |          |
|-----|---|-----------------------------|--------|----------|
| 1.  | 1 | DOOR L/H FRT Distorted      | 115    | 1,710.20 |
| 2.  | 2 | DOOR HINGE L/H FRT Bent     | 278.20 | 556.40   |
| 3.  | 1 | DOOR RUBBER L/H FRT         |        | 285.30   |
| 4.  | 1 | DOOR OUTER HANDLE L/H FRT   |        | 278.20   |
| 5.  | 1 | DOOR OUTER MOULDING L/H FRT |        | 231.10   |
| 6.  | 1 | DOOR BOARD L/H FRT          |        | 678.10   |
| 7.  | 1 | DOOR INNER LOCK L/H FRT     |        | 578.20   |
| 8.  | 1 | DOOR PILLAR L/H FRT         |        | 781.20   |
| 9.  | 1 | SIDE PANEL L/H              |        | 231.20   |
| 10. | 1 | HEAD LAMP L/H               |        | 789.20   |

List TotalS\$ :

25.00% Discount S\$ :

6,127.10

1,531.78

4,595.32

|    |   |                      |    |       |
|----|---|----------------------|----|-------|
| 1. | 1 | SPECIAL NETT ITEMS : |    |       |
| 2. | 1 | WINDSCREEN GUM       | 20 | 40.00 |
|    |   | BODY LETTERING       |    | 20.00 |

Special Nett Total S\$ :

60.00

CONTINUE / ...

# PEOPLE'S VEHICLE RECOVERY SERVICE

BLK 3023-A UBI ROAD 1 #01-60 SINGAPORE 408717

Tel No. : 67433246/ 67438552 Fax No. : 67430013

E-Mail : peoplevehicle@gmail.com

Tax Reg. No. : M90001895E Buss. Reg. No. : 31800200X

CHINA TAI PING INSURANCE (S) PTE LTD  
105 CECIL STREET #19-00  
THE OCTAGON (S) 069534

Attention : Motor Claim Department

Contact : 6389 6111 Fax No. : 6222 1033

Estimate : ES19003

Date : 19/02/2019

Vehicle Num. : GBE 6599 A

Make/Model : TOYOTA HIACE

Chassis/Eng# :

Accident Date : 19/02/2019

Claim No. : TT 337-19

Reference : YP 3481 U

Policy No. : NTUC 5101145685

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

## LABOUR :

SPRAY PAINTING ACCIDENT EFFECT PARTS  
REMOVE AND REFIX FRT WINDSCREEN  
REMOVE & REFIX DASHBOARD & CHECK WIREING  
UNDERCOAT  
ROOF HEADLINING, CARPET, SEAT & GARNISH  
REMOVE AND REFIX FUEL TANK  
REMOVE & REPLACE ACCIDENT DAMAGED PARTS  
TOREPAIR AND KNOCK DOOR SIDE PANEL L/H

1100

~~900.00~~ 500  
120.00 x  
280.00 x  
120.00 x  
180.00 x  
100.00 x  
~~1,800.00~~ 600

Labour Total S\$ :

3,500.00

SingDollars : Eight Thousand One Hundred Fifty-Five & Cents Thirty-Two Only

E. & O.E.

Total S\$ : 8,155.32

for PEOPLE'S VEHICLE RECOVERY SERVICE

Computer Generated Invoice. No Signature Required.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 4089.10

L/S: 3250

OS Pays.