

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

27/2/2019

M/S AIG

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR SLH7287J

TO SUPPLY :

List Items

- | | | |
|-----|------|------------------------|
| 01) | 1 PC | REAR BUMPER |
| 02) | 1 PC | REAR BUMPER BRACKET |
| 03) | 1 PC | REAR BUMPER RETAINER |
| 04) | 1 PC | REAR BUMPER SPONGE |
| 05) | 1 PC | REAR RH LAMP |
| 06) | 1 PC | NOTE EMBLEM |
| 07) | 1 PC | NISSAN EMBLEM |
| 08) | 1 PC | DIG.S EMBLEM |
| 09) | 1 PC | REAR END PANEL |
| | 1 PC | REAR END PANEL GARNISH |

01)	\$	414.00	✓
02)	\$	86.60	X
03)	\$	47.10	✓
04)	\$	111.90	X
05)	\$	293.70	X
06)	\$	73.60	✓
07)	\$	59.70	✓
08)	\$	59.70	✓
09)	\$	552.80	X
	\$	63.50	X
	\$	1,762.60	
LESS 10%	\$	(176.26)	
	\$	1,586.34	

SPECIAL NETT

- | | | |
|-----|---------------------|-------------------|
| 10) | 1 PC set | PARKING SENSOR |
| 11) | 1 PC | SEALANT |
| 12) | 1 SET | REAR BUMPER CLIPS |

10)	\$	280.00	200
11)	\$	60.00	X
12)	\$	40.00	✓

Labour Charge

- | | |
|-----|----------------------|
| 13) | SENSOR LABOUR |
| 14) | REMOVE INNER GARNISH |
| 15) | SPRAY PAINTING |
| 16) | LABOUR CHARGE |
| 17) | TUFF COAT |
| 18) | WIRING CHECK |

13)	\$	80.00	-50
14)	\$	60.00	✓
15)	\$	750.00	-500
16)	\$	600.00	-400
17)	\$	90.00	X
18)	\$	30.00	20
	\$	3,576.34	

19) Bootlid Rubber.

7m 96.90 N 102

P-751
18%
P-675.90
S.N 240.00
Ink 1110.00
2025.90

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Nat Allwood

4/3/19

Take the before party.
3 dy.