

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel : 64663022 Fax : 68966591
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE dated 26/02/2019

AXA

ATTN: MOTOR CLAIMS DEPT

ACCIDENT DATE : 24/02/2019 @ 10:45
 VRN : SKZ5230C
 MODEL : HONDA VEZEL 1.5X
 TP VRN : SBK38K

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 FRONT LH DOOR	1	\$ 845.00	\$ 845.00 <i>Ry</i>	
2 FRONT LH DOOR STICKER	1	\$ 45.00	\$ 45.00 <i>x</i>	
3 FRONT LH WEATHERSTRIP	3	\$ 58.00	\$ 174.00 <i>x</i>	
4 REAR LH DOOR	1	\$ 880.00	\$ 880.00 <i>hb</i>	
5 REAR LH DOOR STICKER	1	\$ 42.00	\$ 42.00 <i>new</i>	
6 REAR LH DOOR WEATHERSTRIP	3	\$ 38.00	\$ 114.00 <i>?</i>	
7 LH SIDE SKIRT	1	\$ 363.00	\$ 363.00 <i>?</i>	
8 REAR LH DOOR CORNER STICKER	1	\$ 28.00	\$ 28.00 <i>new</i>	
9 REAR LH DOOR WINDOW REGULATOR	1	\$ 455.00	\$ 455.00 <i>?</i>	
10 REAR FENDER WHEELARCH LH	1	\$ 172.00	\$ 172.00 <i>ant</i>	
11 REAR LH RIM	1	\$ 813.00	\$ 813.00 <i>Ry</i>	
12 REAR LH DOOR TOP RUBBER	1	\$ 171.00	\$ 171.00 <i>new</i>	
			\$ 4,102.00	
Discount -20%			\$ 820.40	
			\$ 3,281.60	
<u>Special Nett</u>				
59 FRONT LH DOOR CHROME	1	\$ 185.00	\$ 185.00 <i>ant</i>	
60 REAR LH DOOR CHROME	1	\$ 185.00	\$ 185.00 <i>ant</i>	
61 LH SIDE SKIRT CHROME	1	\$ 205.00	\$ 205.00 <i>?</i>	
62 REAR LH TYRE	1	\$ 103.00	\$ 103.00 <i>x</i>	
			\$ 678.00	
63 REAR BUMPER	Repair			
64 REAR FENDER LH	Repair			
PARTS TOTAL			\$ 3,959.60	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to the insurance Company

Acknowledged
 Signature
 Date

2. Labour Charges

Panel Beat, Cut, Weld, Re-align & Replace Damaged Parts Of Affected Area
Putty, Blend And Spray Paint on Affected Area
Check Wiring and Ensure Proper Functioning
Remove and Replace 2 Door window Glasses to Facilitate Repair
Dismantle and Transfer 2 Doors Fittings & Mechanisms to New Doors
Check, Re-adjust and Computerise Wheel Alignment / Side Slip Test
Remove, Replace and Balance Rim / Tyre
Conduct Water Seepage Test

750 \$ 1,500.00
750 \$ 1,500.00
\$ 30 80.00
\$ 60 200.00
\$ 60 360.00
\$ 60 180.00
\$ 30 40.00
\$ 60 120.00

LABOURS TOTAL

\$ 3,980.00

Grand Total : \$ 7,939.60
Add 7% GST : \$ 555.77
Nett Total : \$ 8,495.37

No. of repair days: 9



CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

Tan Jia Hui 17/11/19
WP
4/11/19 430pm
5 days
Tan Jia Hui 17/11/19
Resing before point