



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD**  
**EUNOS LINK SERVICE CENTRE**

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info														
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept.  Contact No 63896111	<table> <tr> <td>Cust No/Name</td><td>/Mr Heng Chong Ming</td></tr> <tr> <td>Reg No/Reg Date</td><td>SGH8021L / 23/06/2006</td></tr> <tr> <td>Date In/Mileage</td><td>22/02/2019/ 0</td></tr> <tr> <td>Chassis No</td><td>KNADE241266118048</td></tr> <tr> <td>Engine No</td><td>G4EE6H038388</td></tr> <tr> <td>Make/Model</td><td>KIA/RIO 1.4 M HB</td></tr> <tr> <td>Colour/Trim</td><td>J4 / RU(</td></tr> </table>	Cust No/Name	/Mr Heng Chong Ming	Reg No/Reg Date	SGH8021L / 23/06/2006	Date In/Mileage	22/02/2019/ 0	Chassis No	KNADE241266118048	Engine No	G4EE6H038388	Make/Model	KIA/RIO 1.4 M HB	Colour/Trim	J4 / RU(
Cust No/Name	/Mr Heng Chong Ming														
Reg No/Reg Date	SGH8021L / 23/06/2006														
Date In/Mileage	22/02/2019/ 0														
Chassis No	KNADE241266118048														
Engine No	G4EE6H038388														
Make/Model	KIA/RIO 1.4 M HB														
Colour/Trim	J4 / RU(														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000018	Credit	27/02/2019/ 14:38	DS	218 / MarsLer	19334

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S MIPNT88088 DIAGNOSTIC / SCANNING		11		250.00
S MIPNT88088 TO REMOVE AND RE-INSTALL TRIMMING TO GIVE WAY ACCESS REPAIR ON LHS ACCIDENT AFFECTED AREAS		11		600.00
S MIPNT88088 TO TRANSFER LHF DOOR COMPONENT & MECHANISM PARTS		300		600.00
S MIPNT88088 TO REPLACE LHF DOOR, ETC		900		1800.00
S MIPNT88088 -TO REPAIR LHS PILLAR ACCIDENT AFFECTED AREAS STRAIGHTEN, REFORM, ALIGN ON LHS ACCIDENT AFFECTED AREAS		100		200.00
S MIPNT88088 TO APPLY SEALANT KIT ON NEW PANEL		840		1260.00
S MIPNT98088 SPRAY PAINTING ON LHS ACCIDENT AFFECTED AREAS				
M KS 76003 1G 010 LHF DOOR PANEL ASSY	1.00	648.00	0.00	648.00
M KS 79310 1G 000 UPR LH HINGE	1.00	27.00	0.00	27.00
M KS 79320 1G 000 LWR LH HINGE	1.00	27.00	0.00	27.00
M KS 82210 1G 001 W/STRIP ASSY-FR DR B	1.00	43.00	0.00	43.00
M KS 87721 1G 010 LHF DR W/LINE MOULDI	1.00	47.00	0.00	47.00
M KS 82650 1G 050 LHF DOOR O/SIDE HAND	1.00	80.00	0.00	80.00
M KS 81312 1G 000 LHF DOOR LATCH ASSY	1.00	238.00	0.00	238.00
M KS 82401 1G 010 REGULATOR ASSY-FR DR	1.00	249.00	0.00	249.00
M KS 82530 1G 000 LHF DR WDO GLASS RUN	1.00	105.00	0.00	105.00
Z NOTES ACCIDENT ON 18/02/2019 ALONG VEERASAMY ROAD OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT CAR TP # GV5229B TP INS : CHINA TAIPING				
<p><b>Confirm &amp; accepted by</b> To display damaged part(s) during resurvey</p> <p>• Parts prices are subject to confirmation</p> <p>• Third party survey is on a "Without Prejudice" basis</p> <p>• No illegal modification(s) is allowed</p> <p>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</p>				<p>2536</p> <p>Parts 1,464.00</p> <p>Labour 0.00</p> <p>Standard Menu 0.00</p> <p>Specialist Job 4,710.00</p> <p>Others(Lub,etc) 0.00</p> <p>Sundry 0.00</p> <p>Total(w/o GST) 6,174.00</p>

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.