72/03/2002 ASC. REC. BY:	REF: es/Msg190	Makar Au	dank	Instruction	
Surveyor: Tausikh	ASSTONM	ENT (Office)	/	instruction:	
Merimin Journ To	of of	MSIG	De	10/Firms: 02/s	19010.08cm
Estimated Cost:	9 "	Bill to:		127 I III.C 071	2101010000
OD THE WS ! TP RES ! OD	RES/EVA/INV/MV7	CS			
To Inspect Vehicle No:	FBM 686	D	_ Insured;	SKB34	41A
at Workshop m/s	A.S. phoon		Tel:	6515 077	O
of Blk 36 76h (nuch red East 9	#01-35			
Policy No: 271200	82	Claim No: _	5841	93	
Sum Insured:		Excess:			
Make of Veh:(Client's Record)			D.0	D.A. 29/91	12019
CA / REV / REP. / REV 2	4 HRS		1	I.O.D. Endorsement:	
Date/Time: 11:44ama 25		Mr.Ke			
Date/Time Action/Instructi	ion () Estimate	Estimate	not wet	done : Once	done
27/2/19 - Whelp wil	I call to amonge. A	or finite.	1-101		
FBM 686	D-X	· · · · · · · · · · · · · · · · · · ·			
	ALA-NA/MSGI7	0/30/18/13		BOH : 21/2	7/12
12/4/190 12,03m re	used to Jowyn	They V9K U	Neiner	. Corneit	re to vigent, 1/
	Uniage Total L				. '

Date/Time, Life Pass to? Days Of Repair: Preli. Report 190 Survey Fee: Resurvey No. of Trip: Final Report Transportation Oale/Time File Roturn to? Add Fee: Site Insp. (\$) 5. 45 51 Intersteys (\$ 1 I body butte-TP /74 unsafe. teen toy: (\$ r dhair Report Format Westernel 15 Lump Sum/LB !: (3 160


...CLAIM SUBFOLDER...(New Assignment)

LAIM SUBF	OLDER TRA	CKING							
Case 1	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Sub	mitted	Ins Auth'ed	Status	
Main	26 Feb 2019		27 Feb 2019 10:08 Assign					New Assignation Cancel Case	ment
М	ain	Re	erence	C	laim Details	\Box	Documer	nts	Show All
CLAIM SUB	FOLDER DE	TAILS				[Create	d by insurer]		
Insured:		AD SALMAN BIN @GMAIL.COM	ABDULLAH TA	N @ TAN GR	EGORY, ID: S	1467785B	, Tel: +659180	1588, Email:	
Main Claimant:	AHMAD S	HAHRUL BIN SAI	HAD, ID: S86	10590Z					
Vehicle Reg. No.:	FBM686D				Date of Loss:	29/01/2019 23:00 - :59 [19 Months and 6 Days From LTA Reg Date (Man Yr)]			
Claim Type:	TP / 584	193			Policy/Cover Note No.:		2 (Comprehensiv e: 20/05/2018 - 1		
Vehicle Reg. No. (Insured):	SKB3441	A			Policy No. (Claimant):				
					Excess:	S\$500.00			10000
Repairer:	A S Phoo	n Pte Ltd (toh Gu	an) (HQ) BLK	36 TOH GUAN	ROAD EAST E	NTERPRISE	E HUB #01-35, 4	08701 Jurong Isla	and - Tel:
Handling Insurer:		urance (Singapo					**	lei Ling - 6643 1	307]
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	. [Imm.Adv	ice due 2	28/02/2019]		
Driver/Custo dian (Insured):	минамма	AD AFIQ BIN MUHA							
Adj Asg. Remarks:	on WP. SJI arrange fo	E :AGREED / LIABI or survey .	LITY UNCLEAR F	Please appoint	LKK AUTO to c	onduct the	survey . Kindly	contact MR KEE (6515 0770 to
ASSOCIAT	ED MAIL RE	CEIVED						View All Com	pose Case Mail
There are no	mail for this	case.							
ALL ASSO	CIATED TAS	SKS [□]				View Al	I Search Tasks	Create New Ta	sk Complete
Dun Date	Priority	Tyne Tack	Group Sub	iect Hand	ller Assinn	ned By	Completed O	n Created	On Done?

No results.

TAN CHIN HOE & CO

ADVOCATES & SOLICITORS GST No. & UEN: 53131160X



24 Reffles Place #24-01 Clifford Centre Singapore 048621 Tel: 6538 2687 Facsimile: 6538 0287

Email: Info@tanchinhoe.com.ag

Your Ref:

Our Ref:

RT/68/2019/sn

25 February 2019

MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #23-01 SGX Centre 2 Singapore 068807 PROPERTY DAMAGE CLAIM INJURY CLAIM FAX NO: 68277800

Attn: Claims Department

Dear Sirs

ACCIDENT INVOLVING FBM686D AND SKB3441A ON 30 JANUARY 2019

- We act for Mr Ahmad Shahrul Bin Sahad who was involved in an accident caused solely by the negligence of your insured, the driver of SKB3441A. Our client was injured as a result of the accident.
- We will revert with our client's quantification shortly.
- 3. In the meantime, our client's motorcycle is at the premises of A S Phoon Pte Ltd at Blk 36 Toh Guan Road East #01-35 Singapore 608580. Please contact Mr Kee at 65150770 for an appointment to survey the motorcycle within 2 days, falling which A S Phoon Pte Ltd will proceed to carry out the repairs.
- 4. We also enclose a copy of our client's traffic police report for your attention.

Yours faithfully

2.

CC

Muhammad Salman Bin Abdullah Tan @ Tan Gregory Blk 148 Simei Street 1

#02-117

client

Singapore 520148

A S Phoon Pte Ltd Fax No: 65150779

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Jowyn Tay Mei Ling

Date:

12 Apr 2019

Preliminary Advice

Insured Vehicle No : SKB3441A

TP Vehicle No

: FBM686D

Accident Date

: 29/01/2019

Make

: YAMAHA XABRE

Assignment Date

: 27/02/2019

Date of Inspection

: 09/04/2019

Est. Duration of Repair

: 6.00

Inspection At

: A S PHOON PTE LTD (TOH GUAN) (HQ)

BLK 36 TOH GUAN ROAD EAST ENTERPRISE HUB #01-35

SINGAPORE 408701

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion, o/s body and parts claimed are consistent to the accident. The chassis frame affected due to collision.

Repairer's Estimate (Gross)	:S\$	6,665.00
Revised Amount	:S\$	4,624.20
Check Items (Estimated)	:S\$	906.30
Total	:S\$	5,530.50
Lump Sum Repair	:S\$	

Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	9,800.00
COE / PARF Rebate	:S\$	4,920.00
Salvage Value	:S\$	
Margin for Repair	:S\$	4,880.00

Remarks

The vehicle is economical/not economical for repair.

The above survey was conducted on a 'without prejudice' basis. PLEASE BE INFORMED THAT THE MOTORBIKE UNSAFE TO REPAIR DUE TO CHASSIS FRAME AFFECTED. THEREFORE, WE ARE RECOMMEND IT AS TOTAL LOSS.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Singapore NRIC	
Owner ID:	0590Z	
Vehicle Details		
Vehicle No.:	FBM686D	
Vehicle to be Exported:	No	
Intended Deregistration Date:	10 Apr 2019	
Vehicle Make:	YAMAHA	
Vehicle Model:	XABRE TFX150	
Primary Colour:	Silver	
Manufacturing Year:	2017	
Engine No.:	G3G8E0031227	
Chassis No.:	MH3RG3710HK024625	
Maximum Power Output:	-	
Open Market Value:	\$2,683.00	
Original Registration Date:	23 Jun 2017	
First Registration Date:	23 Jun 2017	
Transfer Count:	1	
Actual ARF Paid:	\$403.00	
Intended PARF Rebate Details		
PARF Eligibility:	No	
PARF Eligibility Expiry Date:	7.6.7	
PARF Rebate Amount:	\$0.00	
Intended COE Rebate Details		
COE Expiry Date:	22 Jun 2027	
COE Category:	D - Motorcycle	
COE Period(Years):	10	
QP Paid:	\$6,001.00	
COE Rebate Amount:	\$4,920.00	
Total Rebate Amount:	\$4,920.00	

The information contained herein is correct as at 10 Apr 2019





Police Station Of Origin: Punggol N.P.C 21A Tebing Lane SINGAPORE 828837 Tel No: 1800-6049999

1 of 3 Report No. T/20190201/2001

Date/Time 01/02/2019		ade:		Vide R	eport No.:	0.00	V	Stat 1	ion Diary No.
Utifotone (A.)	application	伯洛尔公							
Name of In	formant:		AD	Addres APT BI 821664	K 664A PUN	GGOL DR	ive #17-2	206 SIN	IGAPORE
ID Type / ID NRIC NO /		0Z		Contac Home/			Mobile:	811806	68
Nationality:	•			Email:					
Sex: Male	Age: 32	Date of 16/04/1		Type o Rider	f Informant:				
Race: Javanese				Langua English	1	3.40	Institutio	n / Sch	iool Name:
Occupation					Licence Infor 2B,2A,2,3	rmation:	Date of	Explry:	
Generating Type of Accident:	l Ir	njury Attended k		i ili	Drink Drive: No	Date/Tim Accident 30/01/20		100	Type of Locati I-Junction
Location: Junction of BEDOK RI JALAN EU	ESERVO INOS	IR ROAD				1 20181163			,
Along Bed	<u>ok Reser</u>	voir Road	towards	Eunos L	ink: Surface:			Road	Speed Limit:
Weather: Clear				Dry	Guriado.			,,,,,,	-p
Traffic Flo	w:	·		Traffic	Control: Light - Work	ing		Traffic Light	: Volume:
Type of Construction	ollision: Moving V	ehicles - l	ļead To S					Anyor ambu Yes	ne conveyed blance:
			E- 0207 \$66-0	N. Periodo		a Sivier and	17 (\$2.55km)	Kassyssa	
escondinal men	SALINIES CO	12 14 20 14 16 16 16 16 16 16 16 16 16 16 16 16 16	A 7-20, 40 10 14 14 15 16.						
Détails o	Vehicle	Involved	Make	355 ve ()	Moděl - 3	Color	TO CO	ndition	No of Passe
Vehicle N	о Турв	Involved rcycle	Make ,		Model XABRE	Color Silver	Se	riously	No of Passe
Details of Vehicle N FBM686D	Moto		Make			2.4.110214	Se		0

Détails of Ve	hicle involved	48.23				
Vehicle No	Type	Make	Model 1	Color	Condition.	No of Passenger
FBM686D	Motorcycle	YAMAHA	XABRE TFX150	Silver	Seriously Damaged	0
SKB3441A	Car		2.*2			0

Postails of Ve	hicle insurance			
Vehicle No.	nsurance Company	Insurance No.	Effective	主郊的Dafe
FBM686D	AXA INSURANCE SINGAPORE PTE	P2171407	24/06/2018	23/06/2019
	LTD	<u> </u>		·





Police Station Of Origin: Punggol N.P.C 21A Tebing Lane SINGAPORE 828837 Tel No: 1800-6049999 2 of 3 Report No, T/20190201/2001

CONTINUATION OF REPORT

STREET, STREET	er av en	orden en e		W. BELLEVIN	MINRITYE	ก็ไข่สามารถใช้เลยเก็บเก็บเก็บเก็บเก็บเก็บเก็บเก็บเก็บเก็บ
Any Pedestrian Ir		MERCEN.				AND THE PROPERTY OF THE PARTY O
No. of Pedestrian			Use of Peo	lestrian	Cross	ing: NA
Ricer			コープレイン マーラング・アンドー	Carried attack	IS YEAR A WAY	
Name	AHMAD SHAHRUL BIN SAI	HAD	i w	ID No.		S8610590Z
Related Vehicle	FBM686D (Motorcycle)			Conta	ct No.	81180668
Hospital/Clinic	NATIONAL UNIVERSITY HOSPITAL			Class of Driving Licence & Expiry Date		Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	30/01/2019		Date Disc	harge	30/01	/2019
No. of Days grant	ted Medical Leave 04		Degree of	Injury	Slight	t
IDING BURNERS			問題如此	網牌游	域期	的 學是一個學學的學學學
Name	MUHAMMAD AFIQ BIN MU SALMAN TAN	HAM	//AD	ID No.		S3543649H
Related Vehicle	NİL .			Conta	ct No.	97806210
Hospital/Clinic	NIL		1/4 / · ·	Class Driving Licent Expiry	g ce &	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Disc			
No. of Days gran	ted Medical Leave NIL		Degree of	Injury	NIL	

Brief Details.

On the 30th January 2019 at about 12am, I was riding my motorcycle FBM 686D along Bedok Reservoir Road towards Eunos Link. I was approaching the junction of Bedok Reservoir Road and Jalan Eunos when I noticed one vehicle SKB 3441A from the opposite direction. I observed that the traffic lights were green and carried on riding. Suddenly, the said vehicle turned to the right into Jalan Eunos and I applied my brakes. However, my motorcycle hit the side portion of the said vehicle. Due to the impact, I flew over the said vehicle and landed on the ground. Subsequently, the ambulance arrived and rendered first aid to me. I was not conveyed to the hospital. My motorcycle had damages on the front.

On the same day at about 1815hrs, I went to National University Hospital as I had difficulties in walking. I was given 4 days medical leave.





Police Station Of Origin: Punggol N.P.C 21A Tebing Lane SINGAPORE 828837 Tel No: 1800-6049999 3 of 3 Report No. T/20190201/2001

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Staff Sgt ZAKI FAHMY RAZAL!	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 01/02/2019 00:04
Officer In Charge Of Case: TP / GIT / SI THABAGESH JEYATHESH Contact No.: 65476232 Authentication Stamp	Classification Of Case:
NP168 Signature:_ Singapore Police F	rere



潘發展私人有限公司

A. S. PHOON PTE LTD

Head Off

: 399, Changi Road S'pore 419846. Tel: (65) 6747 0770 Fax: (65) 6841 1263

Ubi : Blk 3007 #01-432/436 Ubi Road 1, S'pore 408701. Tel: (65) 6744 0770 Fax: (65) 6742 0250
Toh Guan : Blk 36 Toh Guan Road East #01-35 S'pore 608580 Tel: (65) 6515 0770 Fax: (65) 6515 0779
Website : www.asphoon.com Email: Enquiry@asphoon.com Co Reg No: 197701213H

FBM686D YAMAHA MT15 REPAIR LIST

ITEM	DESCRIPTION	
1	FRONT FENDER	PRICE (SGD)
2	FRONT WHEEL ASSY	\$48.00
3	VALVE RIM	\$350.00
4	FRONT WHEEL AXLE	\$10.00
5	FRONT WHEEL BEARING X2	\$25.00
6	DUST COVER	\$40.00
7	FRONT TYRE	\$12.00
8	FRONT FORK RH & LH @ \$580	\$120.00 Pols.
9	STEM .STEERING	\$1,160.00
10	CONE BEARING SET	\$185.00
11	FRONT FORK TOP BRIDGE	- \$60.00
12	HANDLE BAR	\$215.00
13	HANDLE GRIP	\$75.00
14	BRAKE LEVER	\$40.00
15	HEADLAMP COMP	\$22.00
16	STAY HEADLAMP	\$320.00
17	HEADLAMP COVER	\$120.00
18	FRONT LICENCE PLATE	\$60.00
19	STAY. LICENCE PLATE	\$15.00
20	METER ASSY	\$20.00
21	RADIATOR	\$400.00
22	FAN RADIATOR	\$295.00
23	COOLANT	\$155.00
24	GRILLE	φ40.00
25	ENGINE GUARD	bt = \$120.00 bt = \$350.00
26	BRAKE PEDAL	51/\$350.00 but \$48.00
27	FRONT FOOTREST COMPLETE	\$60.00
28	EXHAUST ASSY	de/ \$780.00
29	EXHAUST GASKET	\$10.00
30	HEAT PROTECTION	h / \$75.00
31	LOWER SPOILER RH & LH @ \$55	\$110.00
32	REAR FAIRING . RH	\$85.00
33	WORKMANSHIP	25 \$450.00
34	TRANSPORTATION TP-IDAC-WORKSHOP	\$120.00
35	BODY CHASSIS REPAIR	2 5 \$550.00
36	TRANSPORTATION 2 WAY TO REPAIR CHASSIS .	\$ \$120.00
		0 4120.00

TOTAL

\$6,665.00



潘發展私人有限公司

A. S. PHOON PTE LTD

Head Off

: 399, Changi Road S'pore 419846. Tel: (65) 6747 0770 Fax: (65) 6841 1263

: Blk 3007 #01-432/436 Ubi Road 1, S'pore 408701. Tel: (65) 6744 0770 Fax: (65) 6742 0250 Toh Guan : Blk 36 Toh Guan Road East #01-35 S'pore 608580 Tel: (65) 6515 0770 Fax: (65) 6515 0779

: www.asphoon.com Email: Enquiry@asphoon.com Co Reg No: 197701213H

FBM686D YAMAHA MT15 REPAIR LIST

CHASSIS DAMAGED LTA NOT ALLOW TO REPLACE CHASSIS SO, WE RECOMMENDED FOR TOTAL LOSS.

MARKET VALUE \$9800

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged ! Repaire

Signature:

Date:

Tayth 9749749

april 19 1645

To check repair bout.

Gdays.

Swellmant.com

...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUB	FOLDER TRA	CKING							
Case Main	Notified 26 Feb 2019	27 Feb 2019			.20	S\$4,624.20 View Rpt	Ins Auth'ed	Pending for Report Cancel Case	
	Main	R	eference	CI	aim Deta	ils	Docume	nts	Show All
CLAIM SU	JBFOLDER DE	TAILS				[Created	by insurer]		
Insured:		AD SALMAN BIN @GMAIL.COM	ABDULLAH TAN @	TAN GRE	GORY, II	D: S1467785B,	Tel: +659180	1588, Email:	
Main Claimant:	AHMAD S	HAHRUL BIN SA	HAD, ID: S86105	90Z					
Vehicle Re	g. FBM686	D			Date of Lo		19 23:00 - :59 ns and 6 Days Fr	rom LTA Reg Date (Man Yr)]
Claim Type	TP / 584	TP / 584193					(Comprehensive 20/05/2018 - 1		
Vehicle Re No. (Insured):	SKB3441	A			Policy No. (Claimant	S			
Sec. 1881					Excess:	S\$500.00			
Repairer: Handling Insurer:			uan) (HQ) BLK 36 ore) Pte. Ltd. (HQ)						
Adjuster:	LKK Auto 29/03/20		e Ltd (HQ) - Tel: 62	56-3561	[Handled	by MOHD TAU	FIKH BIN HAM	ID] [Final Rp	t due
Driver/Cus dian (Insured):	MUHAMMA		AMMAD SALMAN TAN	(23 / Male), NRIC	: S9543649H,	Tel: +6597806	210 Email:	
Adj Asg. Remarks:	on WP. SJ arrange fo		SILITY UNCLEAR Plea	se appoint l	KK AUTO	to conduct the	survey . Kindly c	ontact MR KEE @ 6	515 0770 to
ASSOCIA	TED MAIL RE	CEIVED						View All Compo	se Case Mail
There are	no mail for this	case.							
ALL ASS	OCIATED TAS	SKS⊟				View All	Search Tasks	Create New Task	Complete
Due Da		Type Tasl	Group Subjec	t Handl	er As	signed By	Completed O	n Created O	n Done?

Claim Documents

*FBM686D (584193) [SKB3441A]

AHMAD SHAHRUL BIN SAHAD Jan 29 2019 11:00PM [MUHAMMAD SALMAN BIN ABDULLAH TAN @ TAN GREGORY] A S Phoon Pte Ltd (toh Guan)

No 1	E: 11 1.0	Assessment Reports			
1	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
	26/02/19 14:23	Accident Statement From:SC - Reg. No: SKB3441A, Claimant: TAN GREGORY @ MUHAMMAD SALMAN BIN ABDULLAH TAN	0	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	12/04/19 12:03	Adjuster Immediate Advice	0	Load HTM	
Pho	tos/Images		3 per p	page 🔻	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	-	Thumbnail	Prin
1	12/04/19 11:49	General View	0	Load JPG	~
2	12/04/19 11:49	General View	0	Load JPG	V
3	12/04/19 11:49	General View	0	Load JPG	✓
4	12/04/19 11:49	General View	0	Load JPG	~
5	12/04/19 11:49	General View	Ð	Load JPG	✓
6	12/04/19 11:49	General View	Ð	Load JPG	✓
7	12/04/19 11:49	General View	0	Load JPG	✓
8	12/04/19 11:49	General View	Ð	Load JPG	✓
9	12/04/19 11:49	General View	0	Load JPG	✓
10	12/04/19 11:49	General View	0	Load JPG	✓
11	12/04/19 11:49	General View	0	Load JPG	~
12	12/04/19 11:49	General View	0	Load JPG	V
13	12/04/19 11:49	General View	0	Load JPG	V
14	12/04/19 11:49	General View	O	Load JPG	~
15	12/04/19 11:49	General View	Ø	Load JPG	V
16	12/04/19 11:49	General View	0	Load JPG	✓
17	12/04/19 11:49	General View	0	Load JPG	V
18	12/04/19 11:49	General View	0	Load JPG	V
19	12/04/19 11:49	General View	0	Load JPG	✓
20	12/04/19 11:49	General View	0	Load JPG	V
21	12/04/19 11:49	General View	O	Load JPG	✓
22	12/04/19 11:49	Chassis Number	0	Load JPG	V
23	12/04/19 11:49	General View	0	Load JPG	~
24	12/04/19 11:49	General View	0	Load JPG	V
25	12/04/19 11:49	General View	0	Load JPG	V
26	12/04/19 11:49	General View	0	Load JPG	V
27	12/04/19 11:49	General View	0	Load JPG	✓
28	12/04/19 11:49	General View	0	Load JPG	✓
29	12/04/19 11:49	General View	0	Load JPG	V
30	12/04/19 11:49	General View	0	Load JPG	₹
31	12/04/19 11:49	General View	0	Load JPG	V

Ass	Assessment Reports		1 per page	V
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbna	-
			0	✓
33	12/04/19 11:49	General View	1 Load JPG	✓
34	12/04/19 11:49	General View	1 Load JPG	▼
35	12/04/19 11:49	General View	1 Load JPG	~
36	12/04/19 11:49	General View	1 Load JPG	V
37	12/04/19 11:49	General View	1 Load JPG	✓
38	12/04/19 11:49	General View	♠ Load JPG	V
39	12/04/19 11:49	General View	1 Load JPG	V
40	12/04/19 11:49	General View	♠ Load JPG	V
41	12/04/19 11:49	General View	1 Load JPG	_
42	12/04/19 11:49	General View	1 Load JPG	
43	12/04/19 11:49	General View	1 Load JPG	
17/24			1 Load JPG	
44	12/04/19 11:49	General View		
45	12/04/19 11:49	General View		
46	12/04/19 11:49	General View	1 Load JPG	
47	12/04/19 11:49	General View	1 Load JPG	
48	12/04/19 11:49	General View	1 Load JPG	
49	12/04/19 11:49	General View	1 Load JPG	
50	12/04/19 11:49	General View	1 Load JPG	V
51	12/04/19 11:49	General View	1 Load JPG	✓
52	12/04/19 11:49	General View	■ Load JPG	✓
53	12/04/19 11:49	General View	Load JPG	V
54	12/04/19 11:49	General View	■ Load JPG	~
55	12/04/19 11:49	General View	Load JPG	✓
56	12/04/19 11:49	General View	Load JPG	V
57	12/04/19 11:49	General View	Load JPG	V
58	12/04/19 11:49	General View	1 Load JPG	V
59	12/04/19 11:49	General View	Load JPG	
60	12/04/19 11:49	General View	1 Load JPG	
0.0	To the second se	General View	1 Load JPG	-
61	12/04/19 11:49	General View	1 Load JPG	-
62	12/04/19 11:49		■ Load JPG	
63	12/04/19 11:49	General View	1 Load JPG	+=
64	12/04/19 11:49	General View		
65	12/04/19 11:49	General View	Load JPG	_
66	12/04/19 11:49	General View	Load JPG	
67	12/04/19 11:49	General View	1 Load JPG	_
68	12/04/19 11:49	General View	1 Load JPG	
69	12/04/19 11:49	General View	1 Load JPG	_
70	12/04/19 11:49	General View	1 Load JPG	_
71	12/04/19 11:49	General View	Load JPG	V
72	12/04/19 11:49	General View	1 Load JPG	
				-
Dog	cumentation		1 per page	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbna Load PD	-
1	26/02/19 14:30	TPD FBM686D - PRI & POLICE REPORT	1 Load PDI	
2	26/02/19 15:41	Reply email from TP Lawyer & appoint LKK AUTO	1 Load PDI	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Our Checkist Remarks - ERR Auto Consultants File Eta (11g)	
	^
	~

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG19003694/T1QD3E2

Date:

26/04/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

27120082

Claimant Vehicle FBM686D

Insured Vehicle No:

SKB3441A

No: Date of Loss:

29/01/2019

Nature of Claim:

TP

Claim No: 584193

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

FBM686D

Make & Model:

YAMAHA XABRE, 150cc TFX150

Engine No:

G3G8E0031227

Reg. Date: Colour:

23/06/2017 (Man. Year: 2017)

Chassis No: Odometer:

MH3RG3710HK024625

Engine Capacity:

Black 150 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

4.60-17

0 mm

Rear Tyre Size:

4.60-17

Front Left Side:

Dunlop 5 mm

Rear Left Side: Rear Right Side: Dunlop 5 mm 0 mm

0 km

Front Right Side:

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,425.00	3,964.20	1,460.80	26.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,240.00	660.00	580.00	46.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,665.00	4,624.20	2,040.80	30.62
+ GST 7.00/7.00% (S\$)	466.55	323.69	142.86	30.62
Nett Amount (S\$)	7,131.55	4,947.89	2,183.66	30.62

INSPECTION

Date of Assignment:

27/02/2019

Date Inspected:

09/04/2019 Inspected At:

A S Phoon Pte Ltd (toh Guan) (HQ) BLK 36 TOH GUAN ROAD EAST

ENTERPRISE HUB #01-35

Singapore 408701

Estimated Period of Repair:

0.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(EXCLUDE CHECK ITEMS \$\$906.30 NETT)

MARKET VALUE: \$9,800.00 (estimate)

LTA REBATE: \$4,920.00 NETT VALUE: \$4,880.00

REPAIR DETAILS

Referen Part Source		(Last Synchronised: 26 Apr 2019)		
Parts:	N/A	YAMAHA XABRE 150cc TFX150 (Model not available in database)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	(Unsubmitted, no print-code for FBM686D)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info	: Items/values no	ot in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty Pa	rt No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Missing	48.00 F	*48.00 FL
2	1		*FRONT WHEEL ASSY	Cracked	350.00 F	*350.00 FL
3	1		*VALVE RIM	Necessary	10.00 F	*10.00 FL
1	1		*FRONT WHEEL AXLE	Bent	25.00 F	*25.00 FL
5	2		*FRONT WHEEL BEARING	Necessary	40.00 F	*40.00 FL
3	1		*DUST COVER	* Check	12.00 F	*-FL
7	1		*FRONT TYRE (80%)	Punctured	120.00 FS	*96.00 FS
3	2		*FRONT FORK RH & LH	Bent	1,160.00 F	*1,160.00 FL
9	1		*STEM STEERING	Bent	185.00 F	*185.00 FL
10	1		*SET CONE BEARING	Necessary	60.00 F	*60.00 FL
11	1		*FRONT FORK TOP BRIDGE	Cracked	215.00 F	*215.00 FL
12	1		*HANDLE BAR	Bent	75.00 F	*75.00 FL
13	1		*HANDLE GRIP	Cut	40.00 F	*40.00 FL
14	1		*BRAKE LEVER	Cut	22.00 F	*22.00 FL
15	1		*HEADLAMP COMP	* Check	320.00 F	*- FL
16	1		*STAY HEADLAMP	* Check	120.00 F	*-FL
17	1		*HEADLAMP COVER	Cut	60.00 F	*60.00 FL
18	1		*FRONT LICENCE PLATE	Bent	15.00 F	*15.00 FL
19	1		*STAY LICENCE PLATE	Bent	20.00 F	*20.00 FL
20	1		*METER ASSY	* Check	400.00 F	*- FL
21	1		*RADIATOR	Dented	295.00 F	*295.00 FL
22	1		*FAN RADIATOR	* Check	155.00 F	*- FL
23	1		*COOLANT	Necessary	40.00 F	*40.00 FL
24	1		*GRILLE	Bent	120.00 F	*120.00 FL
25	1		*ENGINE GUARD	Bent	350.00 F	*350.00 FL
26	1		*BRAKE PEDAL	Bent	48.00 F	*48.00 FL
27	1		*FRONT FOOTREST COMPLETE	Broken	60.00 F	*60.00 FL
28	1		*EXHAUST ASSY	Dented	780.00 F	*780.00 FL
29	1		*EXHAUST GASKET	Necessary	10.00 F	*10.00 FL
30	1		*HEAT PROTECTION	Bent	75.00 F	*75.00 FL
31	2		*LOWER SPOILER RH & LH	Cut	110.00 F	*110.00 FL
32	1		*REAR FAIRING RH	Cut	85.00 F	*85.00 FL
	anchise part	. S=SpcN	ett. L=ListItemDisc.	-	5 S S S S	
				Sub Total (S\$)	5,425.00	4,394.00
			- List Item Discount on L It	ems 0.00/10.00% (S\$) _	0.00	429.80
				Total Parts (S\$)	5,425.00	3,964.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
our Items			
WORKMANSHIP	New	450.00	250.00
TRANSPORTATION TP-IDAC-WORKSHOP	New	120.00	80.00
BODY CHASSIS REPAIR	New	550.00	250.00
TRANSPORTATION 2 WAY TO REPAIR CHASSIS	New	120.00	80.00
Gross	Labour Cost (S\$)	1,240.00	660.00
Penort was unsubmitted	during this print-out		
	OUR Items WORKMANSHIP TRANSPORTATION TP-IDAC-WORKSHOP BODY CHASSIS REPAIR TRANSPORTATION 2 WAY TO REPAIR CHASSIS Gross	OUR Items WORKMANSHIP TRANSPORTATION TP-IDAC-WORKSHOP BODY CHASSIS REPAIR New	Dur Items WORKMANSHIP New 450.00 TRANSPORTATION TP-IDAC-WORKSHOP New 120.00 BODY CHASSIS REPAIR New 550.00 TRANSPORTATION 2 WAY TO REPAIR CHASSIS New 120.00 Gross Labour Cost (\$\$) 1,240.00

< END OF ESTIMATES >