



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

To: Janet Tan
6496 9032
Tel: 62239433

Customer : EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLK MND BUILDING
SINGAPORE 069110

Registration No : SLK452D

Chassis No : JHMRC1890GC207564

Model : ODYSSEY 2.4 EXV-S 16YM

Owner's Name : PUA TEE WEE

Ins Policy No. : SD18V14371/MPC2/R01

Date of Accident : 26/2/2019

Document No. : SQT19000909 Page 1

Date : 26. Feb 2019

Customer No. : WZE011

Svc Advisor : ARY CHUA WAI NGEE

Engine No : K24W72013339

Date | Time : 26. Feb 2019 9:45:10 AM

Surveyor Name : DID : +65 6846 5673
HP : +65 8100 6306
Email : arychua@honda.com.sg

Survey Date :

Authorisation Date :

Fax No EQ = 62234190 26 FEB 2019

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 72241) OWNER: PUA TEE WEE OWNER INSURER: LIBERTY INSURANCE PTE LTD ACC DATE: 26-02-2019@07.20AM ACC: KPE TUNNEL SURVEYED BY: REF NO: TP INSURER: EQ INSURANCE COMPANY LTD TP VEH: SKF9503U - AUDI/A4/BLACK						
66100-T6A-Q00ZZ	PANEL COMP,REAR <i>Red SD</i>	1	460.80	25	345.60	24.19	369.79
04656-T6A-310ZZ	PAN SET,3RD SEAT	1	337.90	25	253.42	17.74	271.16
68100-T6A-Q10ZZ	TAILGATE COMP <i>Red SD</i>	1	1070.80	25	803.10	56.22	859.32
74440-T6A-003	WEATHERSTRIPTAILGATE <i>Red SD</i>	1	117.40	25	88.05	6.16	94.21
74800-TF0-J02	LOCKTAILGATE <i>Red SD</i>	1	185.40	25	139.05	9.73	148.78
74890-T6A-J01	GARNISH ASSYRR.LICENSE	1	230.40	25	172.80	12.10	184.90
74891-T6A-003	MOLDING ASSYRR.LICENSE GARN	1	175.50	25	131.62	9.21	140.83
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE <i>Red SD</i>	2	18.00	25	27.00	1.89	28.89
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER <i>Red SD</i>	1	16.90	25	12.67	0.89	13.56
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER <i>Red SD</i>	1	16.90	25	12.67	0.89	13.56
73221-SR4-000	SPACERRR.W/SHIELD <i>Red SD</i>	4	3.90	25	11.70	0.82	12.52
73226-SZW-000	DAMPERSTD 5X5 <i>Red SD</i>	2	8.50	25	12.75	0.89	13.64
76711-T6A-003	CAPPVOT <i>Red SD</i>	1	4.80	25	3.60	0.25	3.85
33550-T6A-003	TAILLIGHT ASSYL.	1	838.10	25	628.57	44.00	672.57
34150-T6A-003	LIGHT ASSYR.LID <i>Red SD</i>	1	386.20	25	289.65	20.28	309.93
34155-T6A-003	LIGHT ASSYL.LID <i>Red SD</i>	1	386.20	25	289.65	20.28	309.93
38387-SLE-003	ANTENNA ASSY,L.RR. <i>Red SD</i>	1	60.60	25	45.45	3.18	48.63
74940-TR0-003	BUZZER ASSYSMART <i>Red SD</i>	1	60.10	25	45.07	3.15	48.22
75701-T6A-000	EMBLEMH <i>Red SD</i>	1	26.30	25	19.72	1.38	21.10

16:48pm

Printed on 26/2/2019 4:11:05 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLK MND BUILDING
SINGAPORE 069110

Registration No : SLK452D
Chassis No : JHMRC1890GC207564
Model : ODYSSEY 2.4 EXV-S 16YM
Owner's Name : PUA TEE WEE
Ins Policy No. : SD18V14371/PC2/R01
Date of Accident : 26/2/2019

Document No. : SQT19000909 Page 2
Date : 26. Feb 2019
Customer No. : WZE011
Svc Advisor : ARY CHUA WAI NGEE
Engine No : K24W72013339
Date | Time : 26. Feb 2019 9:45:10 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
84640-T6A-003ZA	LINING ASSYRR.PANEL <i>D13</i>	1	103.60	✓ 25	77.70	5.44	83.14
84665-T6A-N71ZD	LINING COMPL.RR.SIDE	1	763.60	? 25	572.70	40.09	612.79
84431-T6A-J01ZA	LINING ASSYTAILGATE LOWER <i>26/2/19</i>	1	206.30	✓ 25	154.72	10.83	165.55
84441-T6A-J01ZA	POCKETTAILGATE LINING PULL	1	10.70	? 25	8.02	0.56	8.58
04715-T6A-900ZZ	FACERR.BUMPER <i>D.S</i>	1	568.30	✓ 25	426.22	29.84	456.06
33555-SLJ-013	REFLECTOR ASSYL.RR.	1	45.40	? 25	34.05	2.38	36.43
71507-T6A-003ZH	FACE,L.RR.BUMPER <i>DD PR</i>	1	76.80	✓ 25	57.60	4.03	61.63
71517-T6A-921ZB	SPOILER ASSYL.RR.SIDE <i>CU?</i>	1	114.10	✓ 25	85.57	5.99	91.56
71593-T6A-003	SPACERR.RR.BUMPER SIDE <i>ru</i>	1	19.10	✓ 25	14.32	1.00	15.32
71598-T6A-003	SPACERL.RR.BUMPER SIDE <i>ru</i>	1	19.10	✓ 25	14.32	1.00	15.32
91505-TM8-003	CLIP,BUMPER <i>ru</i>	7	2.30	✓ 25	12.07	0.84	12.91
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR <i>smhd</i>	1	320.00	✓	320.00	22.40	342.40
72841-SH3-315	OILSHEET	1	40.70	? 25	30.52	2.14	32.66
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>ru</i>	1	60.00	✓	60.00	4.20	64.20
Sum Item					5199.95	363.99	5,563.94
BOSUN	SUNDRIES <i>ru</i>	1	100.00	20	100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00	✓	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	100.00	80	100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	160.00	100	160.00	11.20	171.20
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00	130	180.00	12.60	192.60
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	180	250.00	17.50	267.50
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	350.00	280? ph.	350.00	24.50	374.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	350.00	300	350.00	24.50	374.50
BOMISC1	RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM (N)	1	450.00	320	450.00	31.50	481.50
BOMISC1	REMOVE & INSTALL REVERSE CAMERA & CALIBRATION (N)	1	450.00	320	450.00	31.50	481.50
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	550.00	220?	550.00	38.50	588.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	550.00	300	550.00	38.50	588.50

Printed on 26/2/2019 4:11:05 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair

Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : EQ INSURANCE COMPANY LTD
 5 MAXWELL ROAD
 #17-00 TOWER BLK MND BUILDING
 SINGAPORE 069110

Registration No : SLK452D

Chassis No : JHMRC1890GC207564

Model : ODYSSEY 2.4 EXV-S 16YM

Owner's Name : PUA TEE WEE

Ins Policy No. : SD18V14371/PC2/R01

Date of Accident : 26/2/2019

Document No. : SQT19000909 Page 3

Date : 26. Feb 2019

Customer No. : WZE011

Svc Advisor : ARY CHUA WAI NGEE

Engine No : K24W72013339

Date | Time : 26. Feb 2019 9:45:10 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00	380	650.00	45.50	695.50
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2800.00	2500	2800.00	196.00	2996.00
BKRP22M	CUT RR FLOOR PANEL,RR END PANEL ETC... STRAIGHTEN	1	4800.00	2800! 3820	4800.00	336.00	5136.00
Sum Labor					11840.00	828.80	12,668.80

Survey By: Marcus Hala

Date & Time: 27/2/19 @ 2pm

Excess: Not Applicable

Status: Not Applicable

Signature: Take photo before repair. 10-12 days.

Total Amount 17,039.95 1,192.79 18,232.74

Total (Inclusive of GST) 18,232.74

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Printed on 26/2/2019 4:11:05 PM
 This is a computer generated invoice. No signature is required.
 Part prices are subjected to change without notice.
 The above estimated cost of repair do not include any unforeseen damages.
 GST Amount is calculated from individual line(s).
 An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.
 However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.