



**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

Service and Body Repair  
Tel +65 6841 3838 Website: www.honda.com.sg  
For 24-hours Roadside Assistance, Call 98203838

# QUOTATION

GST Reg No: M200050223  
Company Ref. No. S60FC1380G

To: Janet Tan  
6496 9032  
Tel: 62239433

**Customer** : EQ INSURANCE COMPANY LTD  
5 MAXWELL ROAD  
#17-00 TOWER BLK MND BUILDING  
SINGAPORE 069110

**Registration No** : SLK452D

**Chassis No** : JHMRC1890GC207564

**Model** : ODYSSEY 2.4 EXV-S 16YM

**Owner's Name** : PUA TEE WEE

**Ins Policy No.** : SD18V14371/MPC2/R01

**Date of Accident** : 26/2/2019

**Document No.** : SQT19000909 Page 1

**Date** : 26. Feb 2019

**Customer No.** : WZE011

**Svc Advisor** : ARY CHUA WAI NGEE

**Engine No** : K24W72013339

**Date | Time** : 26. Feb 2019 9:45:10 AM

**Surveyor Name** : DID : +65 6846 5673

**Survey Date** : HP : +65 8100 5300

**Authorisation Date** : Email : arychua@honda.com.sg

Fax No EQ = 62234190 26 FEB 2019

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO. 72241) OWNER: PUA TEE WEE OWNER INSURER: LIBERTY INSURANCE PTE LTD ACC DATE: 26-02-2019@07:20AM ACC: KPE TUNNEL SURVEYED BY: REF NO: TP INSURER: EQ INSURANCE COMPANY LTD TP VEH: SKF9503U - AUDI/A4/BLACK						
66100-T6A-Q00ZZ	PANEL COMP. REAR <i>Body</i>	1	460.80	25	345.60	24.19	369.79
04656-T6A-310ZZ	PAN SET. 3RD SEAT <i>Body</i>	1	337.90	25	253.42	17.74	271.16
68100-T6A-Q10ZZ	TAILGATE COMP <i>Body</i>	1	1070.80	25	803.10	56.22	859.32
74440-T6A-003	WEATHERSTRIPTAILGATE <i>Tru</i>	1	117.40	25	88.05	6.16	94.21
74800-TF0-J02	LOCKTAILGATE <i>Body</i>	1	185.40	25	139.05	9.73	148.78
74890-T6A-J01	GARNISH ASSYRR. LICENSE <i>CN</i>	1	230.40	25	172.80	12.10	184.90
74891-T6A-003	MOLDING ASSYRR. LICENSE GARN <i>CN</i>	1	175.50	25	131.62	9.21	140.83
73214-T6A-003	MOLDINGRR. WINDSHIELD SIDE <i>NR</i>	2	18.00	25	27.00	1.89	28.89
73215-T6A-003	MOLDINGR. RR WINDSHIELD CORNER <i>NR</i>	1	16.90	25	12.67	0.89	13.56
73216-T6A-003	MOLDINGL. RR WINDSHIELD CORNER <i>NR</i>	1	16.90	25	12.67	0.89	13.56
73221-SR4-000	SPACERRR. W/SHIELD <i>NR</i>	4	3.90	25	11.70	0.82	12.52
73226-SZW-000	DAMPERSTD 5X5 <i>NR</i>	2	8.50	25	12.75	0.89	13.64
76711-T6A-003	CAPPIVOT <i>NR</i>	1	4.80	25	3.60	0.25	3.85
33550-T6A-003	TAILLIGHT ASSYL <i>CN</i>	1	838.10	25	628.57	44.00	672.57
34150-T6A-003	LIGHT ASSYR. LID <i>NR</i>	1	386.20	25	289.65	20.28	309.93
34155-T6A-003	LIGHT ASSYL. LID <i>NR</i>	1	386.20	25	289.65	20.28	309.93
38387-SLE-003	ANTENNA ASSY. L. RR <i>CN</i>	1	60.60	25	45.45	3.18	48.63
74940-TR0-003	BUZZER ASSYSMART <i>CN</i>	1	60.10	25	45.07	3.15	48.22
75701-T6A-000	EMBLEM.H <i>NR</i>	1	26.30	25	19.72	1.38	21.10

16:48pm

Printed on 26/2/2019 4:11:05 PM

This is a computer generated invoice. No signature is required.  
Part prices are subjected to change without notice.  
The above estimated cost of repair do not include any unforeseen damages.  
GST Amount is calculated from individual line(s).  
An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.  
However, if the repairs are subsequently done at Kah Motor Co. Sdn Bhd, it will be refunded.



# QUOTATION

## KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No: M200050223

Company Ref. No: S60FC1380G

Customer : EQ INSURANCE COMPANY LTD  
 5 MAXWELL ROAD  
 #17-00 TOWER BLK MND BUILDING  
 SINGAPORE 069110

Registration No : SLK452D  
 Chassis No : JHMRC1890GC207564  
 Model : ODYSSEY 2.4 EXV-S 16YM  
 Owner's Name : PUA TEE WEE  
 Ins Policy No. : SD18V14371/VPC2/R01  
 Date of Accident : 26/2/2019

Document No. : SQT19000909  
 Date : 26. Feb 2019  
 Customer No. : WZE011  
 Svc Advisor : ARY CHUA WAI NGEN  
 Engine No : K24W72013339  
 Date | Time : 26. Feb 2019 9:45:10 AM  
 Surveyor Name :  
 Survey Date :  
 Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
84640-T6A-003ZA	LINING ASSYRR.PANEL	1	103.60	25	77.70	5.44	83.14
84665-T6A-N71ZD	LINING COMPL.RR SIDE	1	763.60	25	572.70	40.09	612.79
84431-T6A-J01ZA	LINING ASSYTAILGATE LOWER	1	206.30	25	154.72	10.83	165.55
84441-T6A-J01ZA	POCKETTAILGATE LINING PULL	1	10.70	25	8.02	0.56	8.58
04715-T6A-900ZZ	FACERR.BUMPER	1	568.30	25	426.22	29.84	456.06
33555-SLJ-013	REFLECTOR ASSYL.RR	1	45.40	25	34.05	2.38	36.43
71507-T6A-003ZH	FACE.L.RR.BUMPER	1	76.80	25	57.60	4.03	61.63
71517-T6A-921ZB	SPOILER ASSYL.RR.SIDE	1	114.10	25	85.57	5.99	91.56
71593-T6A-003	SPACERR.RR.BUMPER.SIDE	1	19.10	25	14.32	1.00	15.32
71598-T6A-003	SPACERL.RR.BUMPER.SIDE	1	19.10	25	14.32	1.00	15.32
91505-TM8-003	CLIP.BUMPER	7	2.30	25	12.07	0.84	12.91
NMRS-4P-TM3040L	4PCS ACT.RR.SENSOR	1	320.00		320.00	22.40	342.40
72841-SH3-315	OILSHEET	1	40.70	25	30.52	2.14	32.66
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
<b>Sum Item</b>					<b>5199.95</b>	<b>363.99</b>	<b>5,563.94</b>
BOSUN	SUNDRIES	1	100.00	20	100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT	1	100.00		100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	160.00		160.00	11.20	171.20
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BP00R	APPLY BODY UNDERSIDE COATING (N)	1	250.00		250.00	17.50	267.50
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	350.00		350.00	24.50	374.50
BG02D	REMOVE & INSTALL RR WINDSCREEN (N)	1	350.00		350.00	24.50	374.50
BOMISC1	RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM (N)	1	450.00		450.00	31.50	481.50
BOMISC1	REMOVE & INSTALL REVERSE CAMERA & CALIBRATION (N)	1	450.00		450.00	31.50	481.50
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR (N)	1	550.00		550.00	38.50	588.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	550.00		550.00	38.50	588.50

Printed on 26/2/2019 4:11:05 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

Service and Body Repair  
Tel: +65 6841 3838 Website: www.honda.com.sg  
For 24-hours Roadside Assistance, Call 98203838

# QUOTATION

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

Customer : EQ INSURANCE COMPANY LTD  
5 MAXWELL ROAD  
#17-00 TOWER BLK MND BUILDING  
SINGAPORE 069110  
Registration No : SLK452D  
Chassis No : JHMRC1890GC207564  
Model : ODYSSEY 2.4 EXV-S 16YM  
Owner's Name : PUA TEE WEE  
Ins Policy No. : SD18V14371/VPC2/R01  
Date of Accident : 26/2/2019

Document No. : SQT19000909 Page 3  
Date : 26 Feb 2019  
Customer No. : WZE011  
Svc Advisor : ARY CHUA WAI NGEE  
Engine No : K24W72013339  
Date | Time : 26 Feb 2019 9:45:10 AM  
Surveyor Name :  
Survey Date :  
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00	380	650.00	45.50	695.50
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P)	1	2800.00	2500	2800.00	196.00	2996.00
BKRP22M	CUT RR FLOOR PANEL, RR END PANEL ETC... STRAIGHTEN	1	4800.00	3920	4800.00	336.00	5136.00
<b>Sum Labor</b>					<b>11840.00</b>	<b>828.80</b>	<b>12,668.80</b>

Survey By : Marcus Hui  
Date & Time : 27/2/19 @ 2pm  
Excess : \_\_\_\_\_  
Status : Not Applicable  
Signature : Take photo before repair. 10-1207.

**Total Amount** 17,039.95 1,192.79 **18,232.74**  
**Total (Inclusive of GST)** **18,232.74**

9/19 = 14307.88

**WPS Auto Consultancy** hereby notifies the Receiver of the following:

- To include labour and spray painting
- To include damaged parts during survey
- Receiver is subject to confirmation
- This quote is on a "without prejudice" basis
- No single part estimate is allowed
- Supplementary items must be submitted and subject to final approval from Insurance Company

Acknowledged by Receiver  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

Printed on 26/2/2019 4:11:05 PM

This is a computer generated invoice. No signature is required.  
Part prices are subjected to change without notice.  
The above estimated cost of repair do not include any unforeseen damages.  
GST Amount is calculated from individual line(s).  
An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.  
However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded.



# SERVICE PRE-INVOICE

**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022  
255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

<b>Customer:</b>	WZE011 / EQ INSURANCE	<b>Document No:</b>	SVO19012923
<b>Chassis No:</b>	JHMRC1890GC207564	<b>Printed By:</b>	ARYCHUA
<b>License No:</b>	SLK452D	<b>Order Date:</b>	27. February 2019
<b>Mileage:</b>	61777	<b>Order Time:</b>	4:10:22 PM
<b>Engine No:</b>	K24W72013339	<b>Service Advisor:</b>	ARY CHUA WAI NGREE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 72241) OWNER: PUA TEE WEE OWNER INSURER: LIBERTY INSURANCE PTE LTD ACC DATE: 26-02-2019@07.20AM ACC: KPE TUNNEL SURVEYED BY: MARCUS CHUA(LKK) 27-02-2019@13.13PM REF NO: TP INSURER: EQ INSURANCE COMPANY LTD TP VEH: SKF9503U - AUDI/A4/BLACK						
66100-T6A-Q00ZZ	PANEL COMP,REAR	1	460.80	25	345.60	24.19	369.79
04656-T6A-310ZZ	PAN SET,3RD SEAT	1	337.90	25	253.42	17.74	271.16
68100-T6A-Q10ZZ	TAILGATE COMP	1	1,070.80	25	803.10	56.22	859.32
74440-T6A-003	WEATHERSTRIPTAILGATE	1	117.40	25	88.05	6.16	94.21
74800-TF0-J02	LOCKTAILGATE	1	185.40	25	139.05	9.73	148.78
74890-T6A-J01	GARNISH ASSYRR.LICENSE	1	230.40	25	172.80	12.10	184.90
74891-T6A-003	MOLDING ASSYRR.LICENSE GARN	1	175.50	25	131.62	9.21	140.83
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	18.00	25	27.00	1.89	28.89
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER	1	16.90	25	12.67	0.89	13.56
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	16.90	25	12.67	0.89	13.56
73221-SR4-000	SPACERRR.W/SHIELD	4	3.90	25	11.70	0.82	12.52
73226-SZW-000	DAMPERSTD 5X5	2	8.50	25	12.75	0.89	13.64
76711-T6A-003	CAPPIVOT	1	4.80	25	3.60	0.25	3.85
33550-T6A-003	TAILLIGHT ASSYL.	1	838.10	25	628.57	44.00	672.57
34150-T6A-003	LIGHT ASSYR.LID	1	386.20	25	289.65	20.28	309.93
34155-T6A-003	LIGHT ASSYL.LID	1	386.20	25	289.65	20.28	309.93
38387-SLE-003	ANTENNA ASSY,L.RR.	1	60.60	25	45.45	3.18	48.63
74940-TR0-003	BUZZER ASSYSMART	1	60.10	25	45.07	3.15	48.22
75701-T6A-000	EMBLEMH	1	26.30	25	19.72	1.38	21.10
84640-T6A-003ZA	LINING ASSYRR.PANEL	1	103.60	25	77.70	5.44	83.14
84665-T6A-N71ZD	LINING COMPL.RR.SIDE	1	763.60	25	572.70	40.09	612.79
84431-T6A-J01ZA	LINING ASSYTAILGATE LOWER	1	206.30	25	154.72	10.83	165.55
04715-T6A-900ZZ	FACERR.BUMPER	1	568.30	25	426.22	29.84	456.06
71507-T6A-003ZH	FACE,L.RR.BUMPER	1	76.80	25	57.60	4.03	61.63
71517-T6A-921ZB	SPOILER ASSYL.RR.SIDE	1	114.10	25	85.57	5.99	91.56
71593-T6A-003	SPACERR.RR.BUMPER SIDE	1	19.10	25	14.32	1.00	15.32
71598-T6A-003	SPACERL.RR.BUMPER SIDE	1	19.10	25	14.32	1.00	15.32
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
72841-SH3-315	OILSHEET	1	40.70	25	30.52	2.14	32.66
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
	<b>SUM PARTS:</b>				<b>5,157.88</b>	<b>361.05</b>	<b>5,518.93</b>
BOSUN	0760 SUNDRIES	1	20.00		20.00	1.40	21.40
BOJSE	0760 BODY JOINT SEALANT.	1	80.00		80.00	5.60	85.60
BOBC	EXT-YBH BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00

WD 2/12

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

**SERVICE PRE-INVOICE**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

**Customer:** WZE011 / EQ INSURANCE  
**Chassis No:** JHMRC1890GC207564  
**License No:** SLK452D  
**Mileage:** 61777  
**Engine No:** K24W72013339

**Document No:** SVO19012923  
**Printed By:** ARYCHUA  
**Order Date:** 27. February 2019  
**Order Time:** 4:10:22 PM  
**Service Advisor:** ARY CHUA WAI NGEE

BML02I	0760 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	100.00	100.00	7.00	107.00
BA02R	0760 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	130.00	130.00	9.10	139.10
BP00R	EXT-YBH APPLY BODY UNDERSIDE COATING (N).	1	180.00	180.00	12.60	192.60
BKOT00R	0760 REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	220.00	220.00	15.40	235.40
BMF00D	0760 RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	280.00	280.00	19.60	299.60
BMI03D	0760 REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	300.00	300.00	21.00	321.00
BG02D	0760 REMOVE & INSTALL RR. WINDSCREEN. (N)	1	300.00	300.00	21.00	321.00
BOMISC1	0760 RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM(N)	1	320.00	320.00	22.40	342.40
BOMISC1	0760 REMOVE & INSTALL REVERSE CAMERA & CALIBRATION(N)	1	320.00	320.00	22.40	342.40
BKTG02R	0760 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	380.00	380.00	26.60	406.60
BP06R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2,500.00	2,500.00	175.00	2,675.00
BKRP22M	0760 CUT RR FLOOR PANEL,RR END PANEL ETC... STRAIGHTEN ALIGN RR CHASSIS & RENEW DAMAGE PARTS.	1	3,920.00	3,920.00	274.40	4,194.40

**SUM LABOUR:** 9,150.00 640.50 9,790.50  
**TOTAL SGD** 14,307.88 1,001.55 15,309.43

**Total Payable (SGD) 15,309.43**

GST Amount is calculated from individual line(s)