INS. CASE OWNER.	Rennou	cc 3/ M/h 19	00 3 +03	, real/	DAC:
Sheleyer	lese	DOI	SNMENT OF	Date / Time :	26/2/91
Pre-assign / CCU /	FIE TONG	1710 C		Registered in Merin	en TIVIL
Insured Vehicle No.	hall how t	ordala h Wander	Claim No.		
Name of Insured	10111 - 11011 X	acris a. Bloshi	Books Policy No.	12	
Insured Tel No.	3	HP: 2001240	Make / Mode	(A)	
Excess Sec II :SS		D.O.A : 191119	Piace of Acci	dent:	
Is driver the owner?		Nature of Accident	Fallen Lemma	0	
If NO, Driver Nam Driver Tel N		(V/L: (ES) NO)	Of GIA REPO		GIA REPORT: YES NO Final? Yes / No
7402408	J →				÷
INSRS: WSP: Tel: Liability: RMKS:	INSRS WSP: Tel: Liabilit RMKS		INSRS: WSP: Tel: Liability: RMKS:		INSRS: WSP: Tel: Liability: RMKS:
Date/Time	e e e colt	ruenlamly	2.2 - 111		
28/2	2402/628 COLO	(Thopasolanian	136 P 1874-15141	Non-Reporting ltr (1s	
₩~	V 101501402	116(4)	TWO COUNTY HILL	Non-Reporting ltr (2n Non-Reporting ltr (Fi	
	NAM SULLEGE V			Notification ltr (if nor Call OI:	APTINITIES AND THE PARTY OF THE
				After call itr to Cit	SHAIR CU-02-14
				Documentation Che	ck List: Handler Typist
				Notification ltr (if nor	s-pickup)
				After call lir to Cit;	
				Authorisation To Act	
				Final Repair Bill	
				Car Rental Invoice:	
				Towing Invoice	
				LTA / GIA :	
				Medical Bill:	
				PIR:	
				Mandate/Reject Inst	truction:
				LOD Payment Breakdow	- F
PRELIMINARY ADVICE	Date/Time:	Sent By:		Post-Repair Photos:	
	1-11-11-1			Others:	
FINALIZATION	Date/Time:	Confirm with:		Confirm by: 1654.	
THE RESERVE OF THE PARTY OF THE	\$\$1,818-50 (2 days) Reduction:	9, %		Email Cull
FINAL SETTLEMENT	Date/Time: (3-04-79	Confirm with 195mins.		Email Call	
Final Liability:		/ Assessed) BOLA S/N No.:	37	If NO or B 28, Ass.	Lin:
Repair Cost: wilds	\$\$2,111.65 \$\$.455.60 (REAL ENDED TO:	001	5W
Loss of Rental (LOR): Loss of Use (LOU):	S\$ (\$ x	# days) > +113-40 days)		[C)[0]	-lilian
Loss of Income (LOI):		4 days)		P P	1X/18/19
LOR only LOU only	promotion (company)	OR + LOI Tick only	one]		
GIA/LTA Search	S\$1-49				
Medical	5\$ -		to a Charle		mal/Reject/Private Settle
Dishursement: Legal Cost	SS T	(e.g. Tow/ Indepe	ndent)	2) Report Format:	*310
Total:	85 2313-14	Global Sum SS:		3) Survey fee:	730
FINAL PAYMENT	Date/Time: 13-06-19	Confirm with: APSINITE		Email - Call	
Payce 1:	5\$3,TI3.T4 +		TO SERVICES PIE TO		
Payer 3. (Strike ITNA.)	SS	Name 2:	The Parties of the Pa		
Payer 3: (Stelke (CNA))	5\$	Name 51	***************************************		

ASS. REC. BY:	
Kenneth	ASSIGNMENT
From: Date:	
Estimated Cost:	Veh No: S110 5408 J Yr Regn: 01, 1
OD TP IWS I TP RES I OD RES I EVA I INV I MY	Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi) Prime Mover /
To Inspect Vehicle No:	Truck / Traller or
at Workshop m/s Trans Cab	Make: Toy Privs c.c 175
01	Colour M.P.White / Red AC: Insured / Std / NI / NJ
Insured:	Sp.Reading 10058 T/Radio; Insured / Std / NI / N.
Policy No.	Eng/No:
Claims No.	CNO: JTD KB 31=4.0030.79
Sum Insured: Excess:	Gen, Cond. Good / Fair / Poor / Burnt
(Client's Record)	Sleering: Inorger/ Jammed / Leaked / Burnt or
Make of Veh:	Brake: Inorder / Jammed / Leaked / Burnt or
	Modi: NII / S/RIm / STD A/RIm or
(Pollo Contill)	Tyre Size: F: 185 165R 15
(Policy Condition)	R:
Permark: The veh had commenced its repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
	TOYO/YOKO or
Bar, or Market Value:	Eron! Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 9 mm R/Bal C
GIA / PR Seen: Consistent?: Yes or No	UBal. 9 mm UBal S
Est. Repairs: OZ days Res.: Yes or No	DOA 28/2/19 DOI 26/2/19
Lum Sum: 13/ % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS	
- Vehicle: IN CO.	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	. Body Structure affected due to collision.
Fix poss To	
01973.50	
(0m + 10 mm) + 1	
(RED) + 19,324.76 91%	
Distriction File Date to 1	
Onta/Tane, File Pass to? : Prell. Report	Days Of Repair:
: Freil, Report	Days Of Repair: Resurvey No. of Trip: Superv Ener.
: Freil, Report : Final Report	Resurvey No. of Trip: Survey Fee:
: Freil. Report : Final Report	Resurvey No. of Trip: Survey Fee:
: Prell, Report : Final Report Outs/Time, File Return to? Add Fee	Resurvey No. of Trip: Survey Fee: Transportation: Site Insp (\$) _ 5 - RS _ Si
Eport Format :	Resurvey No. of Trip: Survey Fee: Transportation: Site Insp (\$) _5 -RS _SI Interview (\$) Factors
Duts/Time, File Return to?	Resurvey No. of Trip: Survey Fee: Transportation: Site Insp (\$) _ 5 - RS _ Si

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Our Ref

: AAD1902-193

Your Ref

: FBN9710C

Date

: 09.April 2019

AIG ASIA PACIFIC INSURANCE

Dear Sir/Madam,

ACCIDENT INVOLVING SHD5408J AND FBN9710C ON 24/02/19 10:50 PM ALONG CAVENAGH ROAD TOWARDS BUKIT TIMAH ROAD

It appears that the above accident was caused by your insured's negligence. We, therefore seeking compensation from you for our financial loss as itemized below:-

1	Cost of Repair (inclusive of 7% GST)	\$	2.111.65
2.	Loss of Rental for 4 days @ \$ 113-40 per day	5	453.60
3.	Loss of Income for 4 days @ \$ 50 per day	5	200.00
4.	LTA Search Fee	5	7.49
5.	Survey Fee	S	0.00
	Total	\$	2 772 74

We enclose a copy of the following documents for your consideration :-

GIA report lodged by our driver

Rental rate and mileage records

Certificate of Insurance

Authorization To Act

Original final repair bill

LTA Search Fee

Kindly let us have the discharge voucher within the next 14 days, failing which we shall proceed to hand over the conduct of this matter to our solicitors without further reference to you.

Yours Faithfully

Trans-Cab Services Pte Ltd

Jasmine Tan

General Manager

Tel No.: 6603 1250 (DID)

Note: Please email any further correspondence to claims@transcab.com.sg (6603 1259)

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD 5408J

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer:

Date of Registration:

PART

AAD1902-193

Not Nothania Resurry B& paint

81973.50

SHD 5408J

JTDKB3FU003079151

TOYOTA

PRIUS

24.2.2019

AIG

25/1/2019

LIST

			\$	6,201.43
		25%	\$	8,268.57 2,067.14
22	1 TAILLAMP UPPER LH		\$	√L 557,90
21	1 TAILLAMP LOWER LH		\$	Ph 548.40
20	1 REAR BUMPER SIDE LH		\$	Mgens 232.00
19	1 REAR BUMPER SIDE RH		\$	Sn 232.00
18	1 TAILLAMP UPPER RH		\$	£ 557.90
17	1 TAILLAMP LOWER RH		\$	√ 548.40
16	1 REAR END PANEL		\$	N 602.10
15	1 REAR TAILGATE WEATHERSTRIP		\$	∫L 365.20
14	1 PANEL ASSY, BACK DOOR TRIM, UPPER		5	55 51.20
13	1 BOARD ASSY, BACK DOOR TRIM		\$	Pm 254.40
12	1 GARNISH, BACK DOOR SIDE, RH		\$	امر 93.60
11	1 GARNISH, BACK DOOR SIDE, LH		\$	€m 93.60
10	1 COVER, REAR COMBINATION LAMP, RH		\$	Sh 54.70
9	1 COVER, REAR COMBINATION LAMP, RH		\$	Su 54.70
8	1 REAR TAILGATE OUTER GARNISH		\$	رام 905.10
7	1 REAR TAILGATE		5	N 1,547.27
6	1 REAR BUMPER SIDE RETAINER RH		5	Sh 112.70
5	1 REAR BUMPER SIDE RETAINER LH		5	In 112.70
4	1 REAR BUMPER UNDER COVER (BLACK)		5	By 552.60
3	1 REAR BUMPER TOWING COVER		\$	Sm 14.70
2	1 REAR BUMPER RE-INFORCEMENT		\$	A 318.80

Specical Nett

Trans-cab Auto Services Pte Ltd

AAD1902-193

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5408J

				241
2	1SET	REAR BUMPER CLIP	\$	Na 22.00 L
3	2	REAR WINDSCREEN SELANT	\$	22 80.00 J
4	1	WINDSCREEN MOULDING	\$	100.00
5	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00
6	1	REAR TAILGATE TOYOTA LOGO	\$	~~ 47.00 } X
7	1	REAR TAILGATE WORDING 'PRIUS'	\$	~~ 52.90
8	1	REAR TAILGATE WORDING 'HYBRID'	\$	مر 53.50
9	1	REAR TAILGATE STICKER 'TRANS-CAB'	5	امر 80.00
10	1	REAR TAILGATE STICKER '6555-3333'	\$	~~ 80.00
11	1	REAR BUMPER PROTECTOR	\$	100.00
		TOTAL	\$	1,315.40
		TOTAL PARTS	\$	7,516.83
		LABOUR		
		Putty And Spray Painting Of The Affected Portion.	\$	3,000.00 28
		Panel Beating, Knocking And Straightening The		
		Necessary Portion, Remove And Renewal Of Parts,		
		Adjust And Realign The Same	\$	3,000.00 200
		To Rust-Proofing Of The Affected Areas.	\$	an 170.00 X
		To reinstall rear bumper parking sensor.	\$	170.00 501
		To transfer of Tailgate fittings, attachments and		
		perform water seepage test.	\$	1~170.00 X
		To transfer of Rear Bumper fittings, attachments and		
		perform water seepage test.	\$	↑ 170.00 Å
		To repair and realign rear exhaust pipe.	\$	5 170.00 X
		To drop rear exhaust box, renew the same, to repair		-
		and realign centre exhaust pipe.	\$	170.00 X

Trans-cab Auto Services Pte Ltd

AAD1902-193

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5408J

(PART-BY-PART) Repair Days	2day	
Over All Total	\$ 21,298.26	
TOTAL	\$ 7,580.00	
To check steering geometry and computer wheel alignment	\$ ^∼ 220.00 .	X
water seepage test.	\$ ار 170.00 ب	<
To transfer of rear windscreen fittings and conduct		
perform water seepage test.	\$ ル _{へ 170.00})	(
To transfer of rear end panel fittings, attachment and		



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	venicle
Owner ID Type:	Company
Owner ID: Vehicle Details	3878K
Vehicle No.:	SHD5408J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	25 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2B98460
Chassis No.	JTDKB3FU003079151
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	25 Jan 2019
First Registration Date:	25 Jan 2019
Transfer Count:	0
Actual ARF Paid:	\$14,247.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Jan 2027
PARF Rebate Amount:	\$10,685.00
Intended COE Rebate Details	
COE Expiry Date:	24 Jan 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$20.838.00
COE Rebate Amount:	\$16.670.00
Total Rebate Amount: Message	\$27.355.00
Please note that the 8-year COE for this vehicle cannot to	be further renewed. The vehicle must be de-registered upon COE expiry or when the

vehicle reaches its statutory lifespan (if applicable), whichever is earlier. The information contained herein is correct as at 25 Feb 2019

OK

Asher Sng (LKKAuto)

From:

Asher Sng (LKKAuto)

Sent: To: Tuesday, 7 May 2019 9:50 AM NUR_FADZLY@HOTMAIL.COM

Subject:

ACCIDENT INVOLVING FBN 9710C AND SHD 5408J ON 24/02/2019

Our Ref: CC3/AIG19003703/Kea3

07 MAY 2019

MOHAMMAD NUR FADZLY BIN ISKANDAR ZULKARNAIN

Dear Sir/Madam,

ACCIDENT INVOLVING FBN 9710C AND SHD 5408J ON 24/02/2019

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Asher

Case Handler DID: 6841 6051 FAX: 6741 4108

Email: Ashersng@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd

(Motor Claims Dept)

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Authorization To Act

We, Trans-cab Services Pte Ltd of Company Registration No. 200303878K hereby authorize Trans-cab Auto Services Pte Ltd to act on behalf to claim for all losses incurred for the accident involving SHD5408J and FBN9710C along CAVENAGH ROAD TOWARDS BUKIT TIMAH ROAD on 24/02/19 10:50 PM.

In addition, we also hereby authorize the above payment to be made in favour of Trans-cab Auto Services Pte Ltd upon settlement.

Dated this 9 (day) of April 2019

Yours Faithfully Trans-Cab Services Pte Ltd

Jasmine Tan General Manager

RELEASE VOUCHER (AIG Asia Pacific - Express Third Party Claim)

"We/I, TRANS-CAB AUTO SERVICES PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$2,111.65 (Repair Cost), S\$653.60 (Loss of Use/Rental), S\$7.49 (Disbursement) for vehicle no. SHD 5408J that was damaged pursuant to the accident which occurred on 24/02/2019 (date) along CAVENAGH ROAD TOWARDS BUKIT TIMAH ROAD (location) involving vehicle no/s FBN 9710C.

This is pursuant to the inspection conducted on 26/02/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner <u>TRANS-CAB SERVICES PTE LTD</u> ("the third party claimant") of vehicle no. <u>SHD 5408J</u> make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SHD (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this (day) of 06	(month) 20_ [4] (year)
(LKK) KM	(29 4609)
Signed by appointed surveyor	Signed by "the workshop" (with chop)

Trans-Cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel: 6287 6666 Fax: 6287 7764

Co. Reg. No.: 201019626G GST Reg. No.: 201019626G

Tax Invoice / Debit Note

TO:

AIG ASIA PACIFIC INSURANCE PTE LTD

78 Shenton Way

#07-16 CHARTIS Building

079120 Singapore

ATTENTION:

INVOICE NO.

: INV1903-364

DATE

: 31. March 2019

REFERENCE NO : AAD1902-193 TERMS

DUE DATE

: Net 30 Days : 30. April 2019

PAGE : 1

NO.	CODE	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
L.	6050101	REPAIR-SHD5408J;DOA 24.02.19(PART-BY-PART-19)	1	2,111.65	2,111.65

Total SGD Excl. GST: 1,973.50

7% GST:

138.15

**** TWO THOUSAND ONE HUNDRED ELEVEN AND SIXTY FIVE SGD ONLY ****

Total SGD Incl. GST:

2,111.65

¹⁾ All cheques should be crossed and made payable to "Trans-Cab Auto Services Pte Ltd"

²⁾ Please quote our Invoice Number during payment.

³⁾ We reserve the right to charge interest @ 1.5% per month on overdue invoice.

⁴⁾ Any dispute as to the accuracy, charges etc of this invoice must be communicated within 10 days from the date hereof failing which it shall be deemed to have been unconditionally accepted.

Trans-Cab Services Pte Ltd No. 2 Ang Mo Kio Street 63 Tel No.; 6287 6666 Fax No. 6281 1400 Co./GST Reg. No. 200303878K 09 April, 2019 To Whom It May Concern

Dear Sir / Madam,

Accident on 24/02/19 10:50 PM at CAVENAGH ROAD TOWARDS BUKIT TIMAH ROAD

- We refer to the above-mentioned accident and wish to inform that Trans-Cab Services Pte Ltd is the
 registered owner of the taxi bearing vehicle registration no. SHD5408J. The taxi was hired to CHIN KUM
 HOONG MICHAEL a registered hirer-operator of Trans-Cab Services Pte Ltd at the time of occurrence of
 the aforementioned accident at a rental rate \$113.4 per day (inclusive of GST).
- Please be advised that the Taxi is insured with AXA INSURANCE PTE LTD on a third party basis at the material time of the accident.
- Please liaise with us directly for any settlement of claims in respect of the said accident.

Yours faithfully,

Jasmine Tan General Manager

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

24-02-2019

Dear Sir/Madam,

Please be informed that the taxi was undergo accident repair in the workshop as follow:

Date In	Date Out	Vehicle No.	
Accident No.	AAD1902-193	Accident Da	te 24-02-2019
2/25/2019 08:30	2/27/2019 20:00	SHD5408J	
3/6/2019 15:00	3/6/2019 16:40	SHD5408J	

Yours Faithfully,

Trans-Cab Services Pte Ltd

Jasmine Tan

General Manager

2/25/2010

> Back to OneMotoring

Vehicle Insurance Particulars Result

Vehicle No.	Incident Date/Time	Insurance Company Name
SJP1018R	23 Feb 2019 / 19:00:00	ALLIED WORLD ASSURANCE COMPANY, LTD
		(SINGAPORE BRANCH)
FBL8771T	24 Feb 2019 / 03:45:00	GREAT AMERICAN INSURANCE COMPANY
FBN9710C	24 Feb 2019 / 22:50:00	AIG ASIA PACIFIC INSURANCE PTE. LTD.
SLT6945L	24 Feb 2019 / 11:00:00	EQ INSURANCE COMPANY LTD
SJS9061X	22 Feb 2019 / 17:50:00	NTUC INCOME INS CO-OP LTD

Print OK Save as PDF

Merimen e-Claims

No results.

...CLAIM SUBFOLDER...(Pending for Survey Report) Express

Case	Notified	Est Submitted	Ad) Assigned	Ad	ij Rpt	Adj:	Submitted	Ins Auth'ed	Stat	US		
Main	28 Feb 2019 Edit Reg		26 Feb 2019 00:00 Edit Adj Rpt	100	\$1,973.50 Edit Estimates	1000	,973.50 ew Rpt		Rep	Pending for Survey Report Cancel Case		
	Main	R	eference		Claim Deta	ails		Documents		1	Show All	
CLAIM SU	BFOLDER DE	ETAILS					[Created	by adjuster]				
insured:	МОНАММ	AD NUR FADZLY	BIN ISKANDAR Z	ULKA	ARNAIN, ID: S	8807	1541					
Main Claimant:	TRANS-C	AB SERVICES PT	ELTD, Co. Reg. N	io.: 2	00303878K							
Vehicle Re No.:	SHD540	SHD5408J Date of Loss: 24/02/2019 22:00 - :59 [30 Days From LTA Reg Date (Man Yr)]										
Claim Type	e: TP / 5986132444SG Policy/Cover Note No.: 1900004782											
Vehicle Re No. (Insured):		FBN9710C			Policy No (Claiman		VPX/P1680520					
					Excess:							
Repairer:		reference by the format and the format and the first of the format and the first of	te Ltd () No 2 Ang		the foreign that the second of	miles in the second	and the second second second second second					
Handling Insurer:	WZ.Taniği		e Pte. Ltd. (Expres	is) -	Tel: 65-6419-30	000	. [Handled b	y Tan, Bennie-W	Z - 6419	9 1718]	Bennie-	
Claimant's Insurer:			Q) - Tel: 6338 7288									
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-35	561 [Handled	by K	ENNETH KO	NG] [Final R	pt due	08/03	/2019]	
ASSOCIA	TED MAIL RE	CEIVED						Viev	IIA.v	Compos	ie Case Mi	
There are	no mail for this	case.										
	CIATED TAS										Complet	

Merimen e-Claims Page 1 of 2

Claim Documents

*SHD5408J (5986132444SG) [FBN9710C] TP TRANS-CAB SERVICES PTE LTD

Feb 24 2019 10:00PM [MOHAMMAD NUR FADZLY BIN ISKANDAR ZULKARNAIN] Trans-cab Auto Services Pte Ltd

Let	ters/Corresponder	nces	1 per	page 🔻	V
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	0	Edit	
Ass	essment Reports		1 per	page 🔻	V
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Name and Address of the Address of t	Thumbnail	Print
1	28/02/19 10:39	Accident Statement From:SC - Reg. No: FBN9710C, Claimant: MCHAMMAD NUR FADZLY BIN ISKANDAR ZULKARNAIN	0	Load HTM	
Pho	otos/Images		3 per	page V	2
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	-
1	07/05/19 09:51	General View	0	Load JPG	V
2	07/05/19 09:51	General View	0	Load JPG	3
3	07/05/19 09:51	General View	0	Load JPG	V
4	07/05/19 09:51	General View	0	Load JPG	V
5	07/05/19 09:51	General View	0	Load JPG	S
6	07/05/19 09:51	General View	0	Load 3PG	V
7	07/05/19 09:51	General View	0	Load JPG	V
В	07/05/19 09:51	General View	0	Load 3PG	V
9	07/05/19 09:51	General View	0	Load JPG	₩
10	07/05/19 09:51	Odometer Reading	0	Load JPG	V
11	07/05/19 09:51	Chassis Number	0	Load JPG	V
12	07/05/19 09:52	Reinspection Photo	0	Load JPG	[2]
13	07/05/19 09:52	Reinspection Photo	0	Load JPG	V
14	07/05/19 09:52	Reinspection Photo	0	Load JPG	Ø
15	07/05/19 09:52	Reinspection Photo	0	Load 3PG	V
Doc	umentation		1 per	page 🔽	Z
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnall	-
1	27/02/19 16:31	TP ESTIMATE - MARKED	0	Load PDF	-
2	27/02/19 16:31	TP GIA REPORT	0	Load PDF	
3	07/05/19 09:51	LETTER TO OI	0	Load PDF	
4	01/07/19 09:08	WORKSHOP INVOICE	0	Load PDF	
5	01/07/19 09:08	AUTHORISATION TO ACT FORM	0	Load PDF	
6	01/07/19 09:08	Release Voucher	0	Load PDF	
2	01/07/19 09:08	RENTAL RECEIPT	0	Load PDF	
8	01/07/19 09:08	RENTAL MILEAGE	0	Load PDF	
9	01/07/19 09:08	LTA SEARCH	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print

Merimen e-Claims Page 2 of 2

There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	· ·

And of the Park and the Control of the Control		COLLEGE	And in case of the last	Ph 3.6	CHIDA	IEN/OB
NOTE: TO	-	COMPI	Dec 1 Dec 1 1	HV	SHIP	J = Y (1 2
NOIE. IO		COMIL			301	

LKK Auto Consultants Pte Ltd

TEAM		
I CANIV		

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	FBN9710C (Insd veh)			Model:	Model:		TOYOTA PRIUS 1.8 (A)	
	SHD54	D5408J (TP veh)						
Date of Accident:	24/02/2019							
						,		
Global Sum Settlen	nent :	[] Yes		[X] No				
Repair Estimate		:\$		260.61	1			
Final Repair Cost			: \$	2,1	11.65			
Loss of Use			: \$	2	00.00	4	.00 day	s at \$50.00 per day
Rental (if any)			: \$	4	53.60	4	day	5
LTA / GIA Search F	ee		: \$		7.49			
Others:			: \$		0.00			
			: \$					
Final Settlement Su	m		: \$	2,7	72.74			
pelow)	1-4			Combination	O'LLOW-COLD !		100	2010
A) For Non GIA R	egistere	d Workshop:		Agreed Li	ability		_100	(%)
								(%) OLA Scenario No:
B) For GIA Regis	tered Wo	orkshop:		BOLA Ap	plicabl	e: Yes/	No B	OLA Scenario No:
B) For GIA Regist	tered Wo	orkshop: (%)	chain	BOLA Ap	plicabl	e: Yes/ ity (*):_	No B	OLA Scenario No:
* Assessed Lia	tered Wo	orkshop: (%)	chain	BOLA Ap	plicabl	e: Yes/ ity (*):_	No B	OLA Scenario No:
B) For GIA Regist BOLA Liability:	tered Wo	orkshop: (%)	chain	BOLA Ap	plicabl	e: Yes/ ity (*):_	No B	OLA Scenario No:
B) For GIA Regist BOLA Liability: * Assessed Lia	tered Wo	orkshop: (%)	chain	BOLA Ap	plicabl	e: Yes/ ity (*):_	No B	OLA Scenario No:
B) For GIA Regist BOLA Liability: * Assessed Lia Remarks	tered Wo	orkshop: (%) e filled anly far		BOLA Ap	plicabl	e: Yes/ ity (*):_	No B	OLA Scenario No:
B) For GIA Regist BOLA Liability: * Assessed Lia	bility to be	e filled only for		BOLA Ap	Liabili Liabili	e: Yes/ ity (*):_	No B	OLA Scenario No:
B) For GIA Regist BOLA Liability: * Assessed Lia Remarks Payment Instruction 1) Trans-cab Aut	bility to be	e filled only for		BOLA App Assessed collisions and	Liabili Liabili	e: Yes/ ity (*):_	No B	OLA Scenario No:(%) OLA does not apply.
B) For GIA Regist BOLA Liability: * Assessed Lia Remarks Payment Instruction 1) Trans-cab Auture 2)	bility to be	e filled only for		BOLA App Assessed collisions and	Liabili Liabili	e: Yes/ ity (*):_	No B	OLA Scenario No:(%) OLA does not apply.
B) For GIA Regist BOLA Liability: * Assessed Lia Remarks Payment Instruction	bility to be	e filled only for		Assessed collisions and	Liabili Liabili	e: Yes/ ity (*):_	No B	OLA Scenario No:(%) OLA does not apply.

Please attach all the supporting documents to the form. (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)

Date

LKK Auto Consultants Pte Ltd (Co Reg No. 199607 198R)

51 Ubi Ave 1 #01-25. Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/AIG19003703/KEA3Q2

Date:

01/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1900004782

Claimant Vehicle

SHD5408J

Insured Vehicle No :

FBN9710C

No: Date of Loss:

24/02/2019

Nature of Claim:

TP.

Claim No: 5986132444SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHD5408J

Make & Model:

TOYOTA PRIUS, 1.8 (A)

Engine No:

2ZR2B98460

Reg. Date: Colour

25/01/2019 (Man. Year: 2018) Metallic White/Red

Chassis No: Odometer

JTDKB3FU003079151 10058 km

Engine Capacity:

1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size:

195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Front Right Side: Goodyear 9 mm Goodyear 9 mm Rear Left Side: Rear Right Side: Goodyear 9 mm Goodyear 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		7,616.83	1,443.50	6,173.33	81.05
Miscellaneous Items		0.00	0.00	0.00	
Labour		7,580.00	530.00	7,050.00	93.01
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	15,196.83	1,973.50	13,223.33	87.01
	+ GST 7.00/7.00% (S\$)	1,063.78	138.15	925.63	87.01
	Nett Amount (S\$)	16,260.61	2,111.65	14,148.96	87.01
	+ Loss of Use (4.0 x S	\$\$50.00/day) (S\$)	200.00		
	+ Car Rental (4.0 x S	\$113.40/day) (S\$)	453.60		
	+ Doo	/Search Fee (S\$)	7.49		
		Nett Liability (S\$)	2,772.74		

INSPECTION

Date of Assignment:

26/02/2019

Date Inspected:

26/02/2019

Inspected At:

Trans-cab Auto Services Pte Ltd

No 2 Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair:

2.0 days

Adjuster Report Page 2 of 4

Adjuster: KENNETH KONG Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	458.60 FL	*458.60 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	318.80 FL	*318.80 FL
3	1		*REAR BUMPER TOWING COVER	Serviceable	14.70 FL	*-FL
4	1		*REAR BUMPER UNDER COVER (BLACK)	Bent	552.60 FL	*552.60 FL
5	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	112.70 FL	*-FL
6	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	112.70 FL	*-FL
7	1		*REAR TAILGATE	Repair	1,547.27 FL	*-FL
8	1		*REAR TAILGATE OUTER GARNISH	Serviceable	905.10 FL	*-FL
9	1		*COVER ,REAR COMBINATION LAMP ,RH	Serviceable	54.70 FL	*- FL
10	1		*COVER ,REAR COMBINATION LAMP ,RH	Serviceable	54.70 FL	*-FL
11	1		*GARNISH ,BACK DOOR SIDE LH	Serviceable	93.60 FL	*-FL
12	1		*GARNISH ,BACK DOOR SIDE RH	Serviceable	93.60 FL	*-FL
13	1		*BOARD ASSY ,BACK DOOR TRIM	Serviceable	254.40 FL	*- FI.
14	1		*PANEL ASSY ,BACK DOOR TRIM ,UPPER	Serviceable	51.20 FL	*-FL
15	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	365.20 FL	*-FL
16	1		*REAR END PANEL	Repair	602.10 FL	*-FL
17	1		*TAILLAMP LOWER RH	Serviceable	548.40 FL	*-FL
18	1		*TAILLAMP OUTER RH	Serviceable	557.90 FL	*-FL
19	1		*REAR BUMPER SIDE RH	Serviceable	232.00 FL	*-FL
20	1		*REAR BUMPER SIDE LH	Serviceable	232.00 FL	*232.00 FL
21	1		*TAILLAMP LOWER LH	Serviceable	548.40 FL	*-FL
22	1		*TAILLAMP UPPER LH	Serviceable	557.90 FL	*-FL
23	1		*SET PARKING AID	Shorted	700.00 FS	*250:00 FS
24	1		*SET REAR BUMPER CLIP	Necessary	22.00 FS	*22.00 FS
25	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*-FS
26	1		*WINDSCREEN MOULDING	Not Necessary	100.00FS	*-FS
27	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*-FS
28	1		*REAR TAILGATE TOYOTA LOGO	Not Necessary	47.00 FS	*- FS
29	1		*REAR TAILGATE WORDING PRIUS	Not Necessary	52.90 FS	*-F8
30	1		*REAR TAILGATE WORDING HYBRID	Not Necessary	53.50 FS	*-F8
31	1		*REAR TAILGATE STICKER TRANS-CAB	Not Necessary	80.00 FS	*-FS
32	1		*REAR TAILGATE STICKER 6555-3333	Not Necessary	80.00FS	*-F8
33	1		*REAR BUMPER PROTECTOR	Not Necessary	100.00FS	*-FS
F=Fra	nchise p	art S=SpcN	lett. L=ListItemDisc		22-0-2020-0-2020	NEWSTA UNICESSA
				Sub Total (S\$)	9,683.97	1,834.00
			- List Item Discount on L Item	ns 25.00/25.00% (S\$)	2,067.14	390.50
				Total Parts (S\$)	7,616.83	1,443.50

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	280.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	3,000.00	200.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
5	TO TRANSFER OF TAILGATE FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
7	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
8	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
9	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
10	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170,00	0.00
11	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
	Gross Labour	Cost (S\$)	7,580.00	530.00
	Report was unsubmitted during	his print-out.		

< END OF ESTIMATES >