

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5408J**AAD1902-193***Not Authorised**Resurvey B&Paint**81973.50*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 5408J

JTDKB3FU003079151

TOYOTA

PRIUS

24.2.2019

AIG

25/1/2019

PART**LIST**

1	1 REAR BUMPER	\$	CM 458.60	✓
2	1 REAR BUMPER RE-INFORCEMENT	\$	B 318.80	✓
3	1 REAR BUMPER TOWING COVER	\$	Sn 14.70	X
4	1 REAR BUMPER UNDER COVER (BLACK)	\$	B 552.60	✓
5	1 REAR BUMPER SIDE RETAINER LH	\$	Sn 112.70	X
6	1 REAR BUMPER SIDE RETAINER RH	\$	Sn 112.70	X
7	1 REAR TAILGATE	\$	R 1,547.27	} X
8	1 REAR TAILGATE OUTER GARNISH	\$	Sn 905.10	
9	1 COVER, REAR COMBINATION LAMP, RH	\$	Sn 54.70	
10	1 COVER, REAR COMBINATION LAMP, RH	\$	Sn 54.70	
11	1 GARNISH, BACK DOOR SIDE, LH	\$	Sn 93.60	
12	1 GARNISH, BACK DOOR SIDE, RH	\$	Sn 93.60	
13	1 BOARD ASSY, BACK DOOR TRIM	\$	Sn 254.40	
14	1 PANEL ASSY, BACK DOOR TRIM, UPPER	\$	Sn 51.20	
15	1 REAR TAILGATE WEATHERSTRIP	\$	Sn 365.20	
16	1 REAR END PANEL	\$	R 602.10	
17	1 TAILLAMP LOWER RH	\$	Sn 548.40	} X
18	1 TAILLAMP UPPER RH	\$	Sn 557.90	
19	1 REAR BUMPER SIDE RH	\$	Sn 232.00	
20	1 REAR BUMPER SIDE LH	\$	mg 232.00	
21	1 TAILLAMP LOWER LH	\$	Sn 548.40	X
22	1 TAILLAMP UPPER LH	\$	Sn 557.90	X
		\$	8,268.57	
		25% \$	2,067.14	
		\$	6,201.43	

Special Nett

1 1SET PARKING AID

\$ *Short 700.00 250.00*

Trans-cab Auto Services Pte Ltd**AAD1902-193**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5408J

2	1SET REAR BUMPER CLIP	\$	na	22.00	✓
3	2 REAR WINDSCREEN SELANT	\$	na	80.00	} X
4	1 WINDSCREEN MOULDING	\$	na	100.00	
5	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
6	1 REAR TAILGATE TOYOTA LOGO	\$	na	47.00	
7	1 REAR TAILGATE WORDING 'PRIUS'	\$	na	52.90	
8	1 REAR TAILGATE WORDING 'HYBRID'	\$	na	53.50	
9	1 REAR TAILGATE STICKER 'TRANS-CAB'	\$	na	80.00	}
10	1 REAR TAILGATE STICKER '6555-3333'	\$	na	80.00	
11	1 REAR BUMPER PROTECTOR	\$	na	100.00	

TOTAL \$ 1,315.40**TOTAL PARTS \$ 7,516.83****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	2801
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	2001
To Rust-Proofing Of The Affected Areas.	\$	na 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	501
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	na 170.00	X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	na 170.00	X
To repair and realign rear exhaust pipe.	\$	na 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1902-193**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5408J

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00 X
To check steering geometry and computer wheel alignment	\$	220.00 X
TOTAL	\$	7,580.00

Over All Total	\$	21,298.26
-----------------------	-----------	------------------

(PART-BY-PART) Repair Days**10-DAYS***2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: