

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5810K

AAD1902-212

*Not Authorized
Limp & Flood*

Vehicle No.:	SHC 5810K
Chassis No.:	VF1ABL15AUC281649
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	24.2.2019
Third Party Insurer :	AXA
Date of Registration :	19/6/2015

PART

LIST

1	1	BUMPER COVER FRT	\$	Tn	1,259.42	✓
2	1	BUMPER SPOILER FRT	\$	Diy	181.75	✓
3	1	BUMPER ABSORBER FRT	\$	Tn	394.68	✓
4	1	BUMPER RETAINER FRT LH	\$	Diy	151.41	✓
5	1	BUMPER SUPPORT FRT	\$	Sn	123.88	X
6	1	BUMPER RETAINER FRT RH	\$	CM	150.77	✓
7	1	BUMPER SUPPORT FRT	\$	CM	123.88	✓
8	1	BUMPER UNDERTRAY FRT	\$	CM	472.83	✓
9	1	BUMPER GRILLE LOWER FRT	\$	CM	266.80	✓
10	1	BUMPER FOG LAMP GRILLE LH	\$	Sn	207.21	X
11	1	BUMPER FOG LAMP GRILLE RH	\$	diy	207.21	✓
12	1	BUMPER BEAM FRT	\$	R	914.08	✓
13	1	TOW COVER FRT	\$	diy	28.61	✓
14	1	RADIATOR GRILLE	\$	CM	1,707.78	✓
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	na	225.36	✓
16	1	RADIATOR GRILLE FRAME	\$	CM	1,353.75	✓
17	1	FRAME FULL SUPPORT PANEL	\$	CM	615.90	✓
18	1	FRAME FULL SUPPORT BRACKET	\$	R	89.79	} X
19	1	FRONT BRACE PANEL	\$	R	177.22	
20	1	HORN	\$	Sn	314.17	
21	1	HORN BRACKET	\$	R	40.45	
22	1	HEADLAMP LH	\$	Sn	1,184.43	
23	1	HEADLAMP HARNESS	\$	Sn	928.29	
24	1	HEADLAMP PANEL FRT LH	\$	R	152.15	
25	1	BONNET	\$	R	1,941.63	
26	1	BONNET INSULATOR	\$	Sn	405.73	
27	1	BONNET STRUT LH	\$	Sn	88.61	
28	1	BONNET STRUT RH	\$	Sn	88.61	
29	1	BONNET HINGE LH	\$	R	348.31	

Trans-cab Auto Services Pte Ltd

AAD1902-212

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5810K

30	1	BONNET HINGE RH	\$	R	348.31
31	1	BONNET LOCK	\$	R	305.48
32	1	BONNET CABLE	\$	Sn	119.19
33	1	BONNET CABLE COVER	\$	Sn	161.03
34	1	BONNET SEAL OUTER	\$	Sn	92.36
35	1	BONNET SEAL INNER	\$	Sn	157.28
36	1	FENDER PANEL FRT LH	\$	R	783.83
37	1	WHEELARCH FRT LH	\$	Sn	278.84
38	1	FENDER BRACKET LOWER LH	\$	Sn	15.79
39	1	FENDER INSULATOR LH	\$	Sn	130.84
40	1	FENDER PANEL INNER FRT LH	\$	R	1,693.77
41	1	FENDER PANEL REINFORCEMENT FRT LH	\$	R	1,096.22
42	1	WHEEL HOUSING PANEL FRT LH	\$	R	5,173.47
43	1	TURBO DUCT	\$	Sn	1,027.80
44	1	A/C HEATER VALVE	\$	Sn	484.50
45	1	SUBFRAME OUTER FRT	\$	Sn	2,652.45
46	1	SUBFRAME BRACKET OUTER LH	\$	R Sn	92.36
47	1	SUBFRAME BRACKET OUTER RH	\$	R	92.36
48	1	ENGINE UNDERTRAY	\$	Sn	564.98
49	1	A/C CONDENSER	\$	Sn	2,020.37
50	1	A/C CONDENSER GARNISH LH UPPER	\$	Sn	39.67
51	1	A/C CONDENSER GARNISH RH UPPER	\$	Sn	39.67
52	1	A/C CONDENSER GARNISH LH	\$	Sn	58.81
53	1	A/C CONDENSER GARNISH RH	\$	Sn	59.60
54	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	Sn	208.39
55	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	Sn	658.72
74	1	A/C PIPE COMPRESSOR	\$	Sn	334.29
75	1	A/C PIPE	\$	Sn	658.72
76	1	A/C COMRPESSOR	\$	Sn	2,684.61
77	1	AIR COOLER	\$	Sn	792.60
78	1	AIR INTERCOOLER HOSE (LONG)	\$	Sn	1,014.13
79	1	AIR INTERCOOLER HOSE (Short)	\$	Sn	375.14
80	1	TRANSMISSION COOLER	\$	Sn	1,219.30
81	1	TRANSMISSION COOLER PAD	\$	Sn	17.96
82	1	RADIATOR	\$	Sn	1,202.20
83	2	RADIATOR STUD UPPER	\$	Sn	14.41
84	2	RADIATOR BUSH UPPER	\$	Sn	50.12
85	2	RADIATOR MTG LOWER	\$	Sn	55.85

X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5810K

AAD1902-212

86	1	RADIATOR FAN COWLING	\$	820.54	} X
87	1	RADIATOR FAN MOTOR LH	\$	967.36	
88	1	RADIATOR FAN MOTOR RH	\$	1,479.46	
89	1	RADIATOR TANK	\$	324.62	
90	1	RADIATOR HOSE UPPER	\$	240.56	
91	1	RADIATOR HOSE LOWER	\$	491.18	
92	1	RADIATOR TANK HOSE	\$	61.18	

TOTAL	\$	45,305.01
10%	\$	4,530.50
	\$	40,774.51

Special Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	52.00	} X
2	1SET	BUMPER CLIP FRT	\$	66.00	
3	1	BUMPER BRACKET CLIP FRT LH	\$	12.00	
4	1	BUMPER SUPPORT CLIP FRT LH	\$	10.50	
5	1	BUMPER BRACKET CLIP FRT RH	\$	12.00	
6	1	BUMPER SUPPORT CLIP FRT RH	\$	10.50	
7	1	TOW COVER FRT	\$	14.50	
8	1SET	RADAIATOR GRILLE SCREW	\$	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	69.00	
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00	
11	2	FRAME FULL SUPPORT PANEL NUT	\$	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	30.00	
13	1	Windscreen moulding	\$	100.00	
14	1	FRONT NUMBER PLATE WITH HOLDER	\$	200.00	

TOTAL	\$	682.50
TOTAL PARTS	\$	41,457.01

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 4,000.00 *5501*

Towing Fees.

\$ 120.00 *501*

Trans-cab Auto Services Pte Ltd

AAD1902-212

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5810K

To apply paint protection system (PPS) maintain and enhancement	\$	<i>nn</i> 380.00 <i>X</i>
Putty and spray painting of the affected portion.	\$	4,000.00 <i>6601</i>
To rust-proofing of the affected areas.	\$	<i>nn</i> 170.00 <i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<i>nn</i> 380.00 <i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00 <i>X</i>
To lift-up engine with gear box and refit.	\$	<i>nn</i> 440.00 <i>X</i>
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	<i>nn</i> 440.00 <i>X</i>
To remove and refit air bag system and reset.	\$	<i>nn</i> 480.00 <i>X</i>
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	<i>nn</i> 380.00 <i>X</i>
To vacuum, replace, refix and recharge air condenser	\$	380.00 <i>1001</i>
To replace, refix and top up coolant for radiator	\$	170.00 <i>501</i>

Trans-cab Auto Services Pte Ltd

AAD1902-212

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5810K

To vacuum, replace, refix and recharge Air Intercooler	\$	170.00 <i>501</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>na</i> 170.00 <i>X</i>
To Transfer Of Bonnet Fittings, Attachments And Perform Water Seepage Test.	\$	<i>na</i> 170.00 <i>X</i>
To Transfer Of Door Fittings, Attachments And Perform Water Seepage Test.	\$	<i>na</i> 170.00 <i>X</i>
TOTAL	\$	13,000.00
Over All Total	\$	54,457.01

Repair Days (Lump Sum)

~~20 days~~

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: