

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5810K

AAD1902-212

*Not Authorized
Limp & Flood*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5810K

VF1ABL15AUC281649

RENAULT

LATITUDE

24.2.2019

AXA

19/6/2015

PART**LIST**

QTY	PART	UNIT	PRICE	REMARKS
1	BUMPER COVER FRT	\$	Tn 1,259.42	✓
2	BUMPER SPOILER FRT	\$	Diy 181.75	✓
3	BUMPER ABSORBER FRT	\$	Tn 394.68	✓
4	BUMPER RETAINER FRT LH	\$	Diy 151.41	✓
5	BUMPER SUPPORT FRT	\$	Sn 123.88	X
6	BUMPER RETAINER FRT RH	\$	CM 150.77	✓
7	BUMPER SUPPORT FRT	\$	CM 123.88	✓
8	BUMPER UNDERTRAY FRT	\$	CM 472.83	✓
9	BUMPER GRILLE LOWER FRT	\$	CM 266.80	✓
10	BUMPER FOG LAMP GRILLE LH	\$	Sn 207.21	X
11	BUMPER FOG LAMP GRILLE RH	\$	diy 207.21	✓
12	BUMPER BEAM FRT	\$	R 914.08	✓
13	TOW COVER FRT	\$	diy 28.61	✓
14	RADIATOR GRILLE	\$	CM 1,707.78	✓
15	RADIATOR GRILLE BADGE 'RENAULT'	\$	na 225.36	✓
16	RADIATOR GRILLE FRAME	\$	CM 1,353.75	✓
17	FRAME FULL SUPPORT PANEL	\$	CM 615.90	✓
18	FRAME FULL SUPPORT BRACKET	\$	R 89.79	} X
19	FRONT BRACE PANEL	\$	R 177.22	
20	HORN	\$	Sn 314.17	
21	HORN BRACKET	\$	R 40.45	
22	HEADLAMP LH	\$	Sn 1,184.43	
23	HEADLAMP HARNESS	\$	Sn 928.29	
24	HEADLAMP PANEL FRT LH	\$	R 152.15	
25	BONNET	\$	R 1,941.63	
26	BONNET INSULATOR	\$	Sn 405.73	
27	BONNET STRUT LH	\$	Sn 88.61	
28	BONNET STRUT RH	\$	Sn 88.61	
29	BONNET HINGE LH	\$	R 348.31	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5810K

AAD1902-212

30	1	BONNET HINGE RH	\$	R	348.31
31	1	BONNET LOCK	\$	R	305.48
32	1	BONNET CABLE	\$	Sn	119.19
33	1	BONNET CABLE COVER	\$	Sn	161.03
34	1	BONNET SEAL OUTER	\$	Sn	92.36
35	1	BONNET SEAL INNER	\$	Sn	157.28
36	1	FENDER PANEL FRT LH	\$	R	783.83
37	1	WHEELARCH FRT LH	\$	Sn	278.84
38	1	FENDER BRACKET LOWER LH	\$	Sn	15.79
39	1	FENDER INSULATOR LH	\$	Sn	130.84
40	1	FENDER PANEL INNER FRT LH	\$	R	1,693.77
41	1	FENDER PANEL REINFORCEMENT FRT LH	\$	R	1,096.22
42	1	WHEEL HOUSING PANEL FRT LH	\$	R	5,173.47
43	1	TURBO DUCT	\$	Sn	1,027.80
44	1	A/C HEATER VALVE	\$	Sn	484.50
45	1	SUBFRAME OUTER FRT	\$	Sn	2,652.45
46	1	SUBFRAME BRACKET OUTER LH	\$	R Sn	92.36
47	1	SUBFRAME BRACKET OUTER RH	\$	R	92.36
48	1	ENGINE UNDERTRAY	\$	Sn	564.98
49	1	A/C CONDENSER	\$	Sn	2,020.37
50	1	A/C CONDENSER GARNISH LH UPPER	\$	Sn	39.67
51	1	A/C CONDENSER GARNISH RH UPPER	\$	Sn	39.67
52	1	A/C CONDENSER GARNISH LH	\$	Sn	58.81
53	1	A/C CONDENSER GARNISH RH	\$	Sn	59.60
54	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	Sn	208.39
55	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	Sn	658.72
74	1	A/C PIPE COMPRESSOR	\$	Sn	334.29
75	1	A/C PIPE	\$	Sn	658.72
76	1	A/C COMRPESSOR	\$	Sn	2,684.61
77	1	AIR COOLER	\$	Sn	792.60
78	1	AIR INTERCOOLER HOSE (LONG)	\$	Sn	1,014.13
79	1	AIR INTERCOOLER HOSE (Short)	\$	Sn	375.14
80	1	TRANSMISSION COOLER	\$	Sn	1,219.30
81	1	TRANSMISSION COOLER PAD	\$	Sn	17.96
82	1	RADIATOR	\$	Sn	1,202.20
83	2	RADIATOR STUD UPPER	\$	Sn	14.41
84	2	RADIATOR BUSH UPPER	\$	Sn	50.12
85	2	RADIATOR MTG LOWER	\$	Sn	55.85

X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5810K

AAD1902-212

86	1	RADIATOR FAN COWLING	\$	Sn	820.54	}
87	1	RADIATOR FAN MOTOR LH	\$	Sn	967.36	
88	1	RADIATOR FAN MOTOR RH	\$	Sn	1,479.46	
89	1	RADIATOR TANK	\$	Sn	324.62	
90	1	RADIATOR HOSE UPPER	\$	Sn	240.56	
91	1	RADIATOR HOSE LOWER	\$	Sn	491.18	
92	1	RADIATOR TANK HOSE	\$	Sn	61.18	

TOTAL	\$	45,305.01
10%	\$	4,530.50
	\$	40,774.51

Special Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	na	52.00	}
2	1SET	BUMPER CLIP FRT	\$	na	66.00	
3	1	BUMPER BRACKET CLIP FRT LH	\$	na	12.00	
4	1	BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	
5	1	BUMPER BRACKET CLIP FRT RH	\$	na	12.00	
6	1	BUMPER SUPPORT CLIP FRT RH	\$	na	10.50	
7	1	TOW COVER FRT	\$	na	14.50	
8	1SET	RADAIATOR GRILLE SCREW	\$	na	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	na	69.00	
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	
11	2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	
13	1	Windscreen moulding	\$	na	100.00	
14	1	FRONT NUMBER PLATE WITH HOLDER	\$	mis	200.00	

TOTAL	\$	682.50
TOTAL PARTS	\$	41,457.01

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 4,000.00

5501

Towing Fees.

\$

120.00

501

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5810K**AAD1902-212**

To apply paint protection system (PPS) maintain and enhancement	\$	<i>nn</i> 380.00 <i>X</i>
Putty and spray painting of the affected portion.	\$	4,000.00 <i>6601</i>
To rust-proofing of the affected areas.	\$	<i>nn</i> 170.00 <i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<i>nn</i> 380.00 <i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00 <i>X</i>
To lift-up engine with gear box and refit.	\$	<i>nn</i> 440.00 <i>X</i>
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	<i>nn</i> 440.00 <i>X</i>
To remove and refit air bag system and reset.	\$	<i>nn</i> 480.00 <i>X</i>
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	<i>nn</i> 380.00 <i>X</i>
To vacuum, replace, refix and recharge air condenser	\$	380.00 <i>1001</i>
To replace, refix and top up coolant for radiator	\$	170.00 <i>501</i>

Trans-cab Auto Services Pte Ltd

AAD1902-212

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5810K

To vacuum, replace, refix and recharge Air Intercooler	\$	170.00 <i>501</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>na</i> 170.00 <i>X</i>
To Transfer Of Bonnet Fittings, Attachments And Perform Water Seepage Test.	\$	<i>na</i> 170.00 <i>X</i>
To Transfer Of Door Fittings, Attachments And Perform Water Seepage Test.	\$	<i>na</i> 170.00 <i>X</i>

TOTAL \$ 13,000.00

Over All Total \$ 54,457.01

Repair Days (Lump Sum) ~~20~~ days
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: