



CROWN ASIA BUS BUILDER PTE. LTD. (UEN:201023449R)

44 Sungei Kadut Avenue Singapore 729667
 Tel: (65) 6469 3319, Fax: (65) 6902 6758
 GST ID No : 201023449R

Repair Estimate

No. : QT-000031

ERGO INSURANCE PTE LTD

5 TEMASEK BLVD
 SINGAPORE 038985

Your Ref. :
 Our D/O No. :
 Terms : C.O.D.
 Date : 19-03-2019
 Page : 1 of 2

TEL :

FAX :

Item	Tax Code	Description	Qty	UOM	U/ Price	Disc.	Total
						S\$	S\$

ZR

Traffic accident on 14/02/2019 involving PC4444X and XD9837M along SLE (Lentor) highway

Parts Required:

1.	ZR	REAR RIGHT TAIL LAMP	1.00		960.00		960.00
2.	ZR	REAR RIGHT BATTERY COMPARTMENT DOOR ASSY	1.00	BUC ✓	2,800.00	1800	2,800.00
3.	ZR	REAR RIGHT COMPARTMENT DOOR LOCK ASSY	1.00	mc ✓	180.00		180.00
4.	ZR	REAR CORNER BUMPER	1.00	Repair x	3,700.00		3,700.00
		SubTotal					7,640.00
5.	ZR	LESS 10% TRADE DISCOUNT	1.00		\$ 2,940.00	-764.00	-764.00
					-10%		

Labour Charges:

6.	ZR	LABOUR CHARGES	1.00		\$ 2,646.00	2,900.00	2,900.00
		1. TO PUTTY AND SPRAY ON REAR RIGHT HAND SIDE AREA, BATTERY COMPARTMENT DOOR, BODY AND ALL AFFECTED ACCIDENT PARTS					1200
7.	ZR	LABOUR CHARGES	1.00		150.00		80 150.00
		TO CHECK THE WIRING OF TAIL LAMP, BATTERY SIDE AND ALL ACCIDENT SIDE THAT MIGHT AFFECTED					
8.	ZR	LABOUR CHARGES	1.00		3,400.00		3,400.00
		3. TO FIBER, KNOCK AND STRAIGHTEN ALL NECESSARY PARTS INCLUDING REPAIRING AND CHANGING OF ALL DAMAGED APRTS AND ALIGN SAME.					1300
		- REAR BODY, REAR UPPER PARTS, COMPARTMENT AREA ETC (3 AFFECTED PARTS)					
					TOTAL: \$ 5,026.00		\$2,380.00
					-20%		
					\$ 4,020.80		

NOTE: THIS ESTIMATE IS BASED ON VISIBLE DAMAGE ONLY. SHOULD ANY HIDDEN PARTS AND/OR LABOUR CHARGES REQUIRED

L/S \$4,000