



CROWN ASIA BUS BUILDER PTE. LTD. (UEN:201023449R)

44 Sungei Kadut Avenue Singapore 729667
 Tel: (65) 6469 3319, Fax: (65) 6902 6758
 GST ID No : 201023449R

Repair Estimate

No. : QT-000031

ERGO INSURANCE PTE LTD
 5 TEMASEK BLVD
 SINGAPORE 038985

Your Ref. :
 Our D/O No. :
 Terms : C.O.D.
 Date : 19-03-2019
 Page : 1 of 2

TEL : FAX :

Item	Tax Code	Description	Qty	UOM	U/ Price S\$	Disc.	Total S\$
------	----------	-------------	-----	-----	-----------------	-------	--------------

ZR

Traffic accident on 14/02/2019 involving PC4444X and XD9837M along SLE (Lentor) highway

Parts Required:

1.	ZR	REAR RIGHT TAIL LAMP	1.00		960.00		960.00
2.	ZR	REAR RIGHT BATTERY COMPARTMENT DOOR ASSY	1.00	BUC ✓	2,800.00	1800	2,800.00
3.	ZR	REAR RIGHT COMPARTMENT DOOR LOCK ASSY	1.00	me ✓	180.00		180.00
4.	ZR	REAR CORNER BUMPER	1.00	Repair x	3,700.00		3,700.00
		SubTotal					7,640.00
5.	ZR	LESS 10% TRADE DISCOUNT	1.00		-764.00		-764.00

Labour Charges:

6.	ZR	LABOUR CHARGES 1. TO PUTTY AND SPRAY ON REAR RIGHT HAND SIDE AREA, BATTERY COMPARTMENT DOOR, BODY AND ALL AFFECTED ACCIDENT PARTS	1.00		2,900.00		2,900.00 1200
7.	ZR	LABOUR CHARGES TO CHECK THE WIRING OF TAIL LAMP, BATTERY SIDE AND ALL ACCIDENT SIDE THAT MIGHT AFFECTED	1.00		150.00		80 150.00
8.	ZR	LABOUR CHARGES 3. TO FIBER, KNOCK AND STRAIGHTEN ALL NECESSARY PARTS INCLUDING REPAIRING AND CHANGING OF ALL DAMAGED APRTS AND ALIGN SAME. - REAR BODY, REAR UPPER PARTS, COMPARTMENT AREA ETC (3 AFFECTED PARTS)	1.00		3,400.00		3,400.00 1300

NOTE: THIS ESTIMATE IS BASED ON VISIBLE DAMAGE ONLY. SHOULD ANY HIDDEN PARTS AND/OR LABOUR CHARGES REQUIRED



CROWN ASIA BUS BUILDER PTE. LTD. (UEN:201023449R)

44 Sungei Kadut Avenue Singapore 729667
Tel: (65) 6469 3319, Fax: (65) 6902 6758
GST ID No : 201023449R

Repair Estimate

No. : QT-000031

ERGO INSURANCE PTE LTD	
5 TEMASEK BLVD	
SINGAPORE 038985	
TEL :	FAX :

Your Ref. :
 Our D/O No. :
 Terms : C.O.D.
 Date : 19-03-2019
 Page : 2 of 2

Item	Tax Code	Description	Qty	UOM	U/ Price S\$	Disc.	Total S\$
------	----------	-------------	-----	-----	-----------------	-------	--------------

DURING WORKS IN PROGRESS, IT WILL BE NOTIFIED ACCORDINGLY.

PRICE QUOTED IS SUBJECTED TO 7% GST

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Handwritten:
 Hwee Jie - LKK
 20/3/19
 L/S 5 days.
 [Signature]

SINGAPORE DOLLAR THIRTEEN THOUSAND THREE HUNDRED TWENTY SIX ONLY

Sub Total (Excluding GST)	13,326.00
GST payable @ 7% on 0.00	0.00
Total (Inclusive of GST)	13,326.00

- Notes :
1. All cheques should be crossed and made payable to CROWN ASIA BUS BUILDER PTE. LTD.
 2. Goods sold are neither returnable nor refundable. Otherwise a cancellation fee of 20% on purchase price will be imposed.

GST Summary

Amount(S\$)

Tax(S\$)

Authorised Signature

