

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SKU1087C/1902029

27th February 2019

The Manager
Motor Claim Department
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

Date Of Accident : 23th February 2019
Location : Along PIE towards Sims Ave
Third Party Claim Vehicle No : SMC 999 Z
Repair Cost For Vehicle No : SKU 1087 C (BMW 520i)

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Rear boot cover	1	1,642.45	\$ 1,642.45
2	Rear boot cover emblem(logo)	1	71.25	\$ 71.25
3	Rear boot cover emblem (520i)	1	64.10	\$ 64.10
4	Rear boot reflector RH	1	360.25	\$ 360.25
5	Rear end panel	1	817.30	\$ 817.30
6	Rear end panel inner garnish	1	15.55	\$ 15.55
7	Rear end panel inner garnish clips	1set	50.00	\$ 50.00
8	Rear bumper fascia	1	1,563.25	\$ 1,563.25
9	Rear bumper clips	1set	50.00	\$ 50.00
10	Rear bumper reinforcement	1	772.05	\$ 772.05
11	Rear bumper sensor	2	236.85	\$ 473.70
12	Rear bumper moulding(centre)	1	171.50	\$ 171.50
13	Rear bumper moulding L&R	2	128.65	\$ 257.30
14	Rear bumper towing cover	1	47.60	\$ 47.60
15	Rear bumper sponge <i>inner sensor</i>	1	61.55	\$ 61.55
16	Rear bumper bracket L&R	2	192.15	\$ 384.30
17	Rear bumper under cover	1	60.45	\$ 60.45
18	Rear bumper under cover clips	1set	50.00	\$ 50.00
19	Rear end panel sealer (s/nett)	1	80.00	\$ 80.00
				\$ 6,992.60

(52)

28/2

Not Allowed
hkh
4/5 \$5298.81
4dy.
28/2/19
The above amount.

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SKU1087C/1902029

27th February 2019

Balance b/f

\$ 6,992.60

Labour Charges :-

Amounts

Cut out, renew, knocking & welding rear boot cover, rear end panel, remove & install all damage parts, straighten & re-align body

\$ 1,080.00 800

Remove & install rear bumper sensor

\$ 100.00 50

Spray painting on damage parts

\$ 1,280.00 800

Tuff-kote on damage parts

\$ 80.00 60

Check all lighting after repairs

\$ 60.00 30

Labour Charge

\$ 2,600.00

Total Amount

\$ 9,592.60

1742

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-3746.12

52
3858.81

5298.81

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SKU1087C/1902029

13th March 2019

The Manager
Motor Claim Department
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

Date Of Accident : 23th February 2019
Location : Along PIE towards Sims Ave
Third Party Claim Vehicle No : SMC 999 Z
Repair Cost For Vehicle No : SKU 1087 C (BMW 520i)

Supplementary of Parts

<u>No.</u>	<u>Particulars</u>	<u>Qty</u>	<u>Price</u>	<u>Amounts</u>
1	Rear bumper reinforcement adaptor	Che 1	92.62	\$ 92.62
2	Rear under cover RH	Che 1	72.30	\$ 72.30
				<u>\$ 164.92</u>

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.