

7/30/2002

ASS. REC. BY:

REF: CS/SM019003755/Asden

Special Instruction:

Surveyor: Adnan
Munim

ASSIGNMENT (Office)

From (Person):

Thelma Choo

of

SMO

Date/Time:

27/2/19

Estimated Cost:

Bill to:

OD / TP / AWS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SJX 9937T

Insured:

YP7343J

at Workshop n/s:

New tpck Teck

Tel:

67479241

of

Ikaki Bkt Ave 6 # 01-43

Policy No:

D18MTHCVE 001895

Claim No:

CMTD190114

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A.

27/2/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

28/2/19

Date/Time:

5:17pm 28/2/19

Person Contacted:

Sukyji

Vehicle IN/OUT

0

Date/Time

Action/Instruction (✓) Estimate

SJX 9937T - CC7/A19.12017545 / Cp53p1

20A: 6/9/12

YP 7343J - X

04/03/19

@ 09:27 a.m. revert pending estimate from repair to Thelma Choo via munim

REF SMO

INSURANCE

Date: 28/02/2019

Estimated Year: 2008

On: WS / TR / RES / OD / RES / EVA / HM / MV

Registered Vehicle No: SJX9937T

at Work Shop: New Hock Teck

at: 1 Kaki Bkt Ave 6 # 01-43

Insured: _____

Policy No: _____

Claim No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. of Market Value: _____

IDAC Accident Report: Consistent? Yes or No

GIA / PRT Seen: Consistent? Yes or No

Est. Repair: days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{1wp}

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Sub No: SJX9937T. a Page 2008 May

Type: Car / B/Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Jazz

Color: Blue. AC Insured / STD / NI / NA

Sp Reading: 261249. (Photo Insured / STD / NI / NA)

Eng No: _____

Ch No: JHMGD18508S211164

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Normal / Jammed / Leaked / Burnt or

Brake: Normal / Jammed / Leaked / Burnt or

Mod: Nil / STD A/Rim or

Tyre Size: F: 195/50R15
R: 195/50R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SHML / TOYO / YOKO or Continental.

Front R/Bal: 06 mm
L/Bal: 06 mm

Rear R/Bal: 06 mm
L/Bal: 06 mm

D.O.A. 28/02/19

Survey held at NHT.

Des. of Damages: Frt / Rear / O/S / N/S / UC / Rooftop or

The UC / Chassis frame / Body Structure affected due to collision.



MV: 46K
PV: 35.2K
Nett: 10.8K

(Depreciation \$5K)

RECEIVED 26 MAR 2019

26/03/19 Confirmed HS \$10k @ 10 days with Adrian.
(P 13,829.80 Red - 58%)

Date/Time, File Pass to: 26/03/19
 : Profi. Report
 : Final Report
 Date/Time, File Return to: Typ. x

Days Of Repair: 10
Resurvey No. of Trip: 2

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Adv (\$)
 Weekend (\$)

Survey Fee: 450
 Transportation: 10
 Photo: _____
 Other: _____
 Total: 460

Report Format: _____
Lump Sum / LB: 10k 45

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Feb 2019		27 Feb 2019 16:53 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	MING MOVERS PTE LTD , Co. Reg. No.: 199408790C								
Main Claimant:	CHEW KIAN CHOON								
Vehicle Reg. No.:	SJX9937T	Date of Loss:	27/02/2019 09:00 - :59						
Claim Type:	TP / CMTD1901114	Policy/Cover Note No.:	D18MTHCVE001895 (Comprehensive)						
Vehicle Reg. No. (Insured):	YP7343J	Policy No. (Claimant):							
		Excess:							
Repairer:	New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 9241								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/03/2019]								
Driver/Custodian (Insured):	ONG LAI BENG (), NRIC: S70307351, Tel: +6591405022 Email:								
Adj Asg. Remarks:	- NO TP SAS SUBMITTED								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***SJX9937T (CMTD1901114)
[YP7343J]**

TP
CHEW KIAN CHOON
Feb 27 2019 9:00AM
[MING MOVERS PTE LTD]
New Hock Teck Motor Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **04/03/2019 09:27 AM**.
To thelma.choo@sompo.com.sg
CC sur@lkkauto.com
Subject **SJX9937T (CMTD1901114) [YP7343J] TP**

Dear Thelma,

Please be informed that we have inspected the vehicle SJX 9937T on 28/02/2019.

We are pending estimate from repairer.

Thank you.
Best Regards,
Shirley Hiew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY




There are no documents.

Post FREE Ad to Sell Your Used Items!
 Have preloved items cluttering around your house?
 Sell it on Marketplace. Posting an advertisement is FREE!

Price Range
 Depreciation
 > 10 year(s)
 Vehicle Type

Used Car Comparison

--- Comparing 2 Vehicles ---

<p>Honda Fit 1.3A G (COE till 05/2028)</p>  <p>MONSTER</p> <p><input type="button" value="Add to Shortlist"/></p>	<p>Honda Jazz 1.5A L Skyroof (New 10-yr COE)</p>  <p><input type="button" value="Add to Shortlist"/></p>	<p></p> <p>NO IMAGE AVAILABLE</p> <p>Use search bar above to select another car to compare.</p>	<p></p> <p>NO IMAGE AV</p> <p>Use search bar above to se to compare.</p>
---	--	--	---

CAR DETAILS				
Price	\$48,000	\$43,800	-	-
Instalment	N.A.	N.A.	-	-
Registration Date	30-May-2008	09-Dec-2008	-	-
Manufactured	2008	2008	-	-
Mileage	108,000 km	98,515 km	-	-
Transmission	Auto	Auto	-	-
Engine Cap	1,339 cc	1,497 cc	-	-
Road Tax	\$649 /yr	\$752 /yr	-	-
Power	73.0 kW (97 bhp)	88.0 kW (118 bhp)	-	-
Curb Weight	1,010 kg	1,115 kg	-	-
Features	Fully Stock 1.3L I-VTEC Engine Combined With A Responsive, Quiet And Smooth 5 Speed CVT Auto Transmission Producing Up To 97 Bhp. SRS Airbags, ABS.	Powerful 1.5 I-VTEC Engine, 5 Speed Auto With Paddle Shifters, Full Panoramic Glass Roof, Retractable Side Mirrors, Digital Climatic Aircon Control.	-	-
Accessories	1 Owner Unit With Genuine Low Mileage, In Car Camera, Navigation, Factory Sound System.	16" S/Rims, Factory Fitted HID Headlamps, Fully Integrated Audio Systems With Steering Controls, Original RS Bodykit, Skyroof, Knockdown Rear Seats.	-	-
Description	Honda's Signature Compact And Nimble VTEC Hatchback In Factory Black Exterior And Red On Black Leather Upholstery. Buy With A Peace Of Mind. Always Parked Under Shelter. Regularly Serviced At Reputable Honda Workshop. Loan Available. All Trade In Accepted. Viewings Strictly By Appointment Only. Call Now, This Baby Could Be Yours Next!	10 Years New COE. Price Exclde GST 7%. Easy Maintained Car. Regularly Serviced And Maintained By Owner. Very Rare 1.5L With Huge Skyroof. Super High Spec Model With Paddle Shift And Climate Control Aircon. Super Low Mileage Done. Low Depreciation! Hurry Up, Call Us Now Before It's Gone.	-	-
COE	\$38,192	-	-	-
OMV	\$11,514	\$21,533	-	-
ARF	\$5,543	\$21,533	-	-
Depreciation	\$5,190 /yr	\$4,380 /yr	-	-
No. of Owners	1	4	-	-
Type of Vehicle	Hatchback	Hatchback	-	-
Category	COE Car, Consignment Car	COE Car, Low Mileage Car	-	-
Availability	Available	Available	-	-

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 5302Z

Vehicle Details

Vehicle No.: SJX9937T
Vehicle to be Exported: No
Intended Deregistration Date: 27 Feb 2019
Vehicle Make: HONDA
Vehicle Model: JAZZ 1.4A
Primary Colour: Black
Manufacturing Year: 2008
Engine No.: L13A55000502
Chassis No.: JHMGD18508S211164
Maximum Power Output: 60.0 kW (80 bhp)
Open Market Value: \$14,772.00
Original Registration Date: 12 May 2008
First Registration Date: 12 May 2008
Transfer Count: 1
Actual ARF Paid: \$14,772.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 11 May 2028
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
PQP Paid: \$38,192.00
COE Rebate Amount: \$35,154.00
Total Rebate Amount: \$35,154.00

The information contained herein is correct as at 27 Feb 2019

OK

MSME19027501 / SME Motor Plo Ltd - Kaki Bukit
 ENTRY DATE & TIME 27/02/2019 17:49
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/02/2019 17:49
Date Of Accident	27/02/2019 09:05
Exact Location Of Accident	UPP CHANGI RD EAST (OPP UPP CHANGI MRT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJX9937T
Insured/Policyholder	
Name Of Registered Owner	CHEW KIAN CHOON
NRIC No	S1825302Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91733884
Alternative Phone No	OFFICE-91733884
Vehicle Particulars	
Manufacturer	HONDA
Model	JAZZ
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5095519962-01
Cover Note Number	
Driver	
Name of Driver	ONG HOCK LAM
NRIC No	S0834335G
Date Of Birth	16/10/1942
Occupation	INDOOR
Date Of Driving Pass	04/01/1960
Driving Experience	59 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-81136862
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address 10 FLORA ROAD #05-05
 Postcode 509729
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - FATHER-IN-LAW
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : LIM SAI GUET
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS DRIVING STRAIGHT ALONG UPPER CHANGI ROAD EAST (OPP UPPER CHANGI MRT AT THIRD LANE OF 5 LANES). ALL VEHICLES IN FRONT OF ME STOPPED DUE TO TRAFFIC LIGHT WAS RED, I FOLLOWED SUIT. SUDDENLY, I FELT A HUGE IMPACT. VEHICLE B COLLIDED ONTO REAR PORTION OF MY VEHICLE AND CAUSED DAMAGES. DUE TO THE HUGE IMPACT, MY VEHICLE SURGED FORWARD AND STOPPED AT THE YELLOW BOX. BOTH OF US ALIGHTED. VEHICLE B ADMITTED HIS FAULT AND APOLOGISED TO ME. AFTER THE INCIDENT, MY PASSENGER AND I FELT DISCOMFORT.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YP7343J
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name ONG HOCK LAM

Approximate Age

Injuries Sustain

Injured person in which vehicle? SJX9937T

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 2

Name LIM SAI GUET

Approximate Age

Injuries Sustain

Injured person in which vehicle? SJX9937T

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this {form} and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature


Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving straight along upper Changi Rd East (opposite upper Changi MRT) at 3rd lane of 5 lanes.

All vehicles in front of me stopped due to the traffic light was red, I followed suite. Suddenly, I felt a huge impact. Veh "B" collided onto rear portion of my vehicle and caused damages.

Due to the huge impact, my vehicle surged forward and stopped at the yellow box.

Both of us alrighted, Veh "B" admitted his fault and apologised with me.

After the incident, I & my passenger feel discomfort.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

27/02/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

JHMGD18508S211164

TP Sampo.
Shirley.

nett: 10k

Accident date: 27/02/2019

Estimated repair cost for vehicle no: SJX9937T HONDA JAZZ 1.4 A '08

CHASSIS: JHMGD18508S211164

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Distorted.</i>		\$820.30 ✓
2	2	Rear Boot Lid Hinge <i>NE new</i>	\$48.90	\$97.80 X
3	2	Rear Boot Lid Shock Absorber <i>Bent</i>	\$184.90	\$369.80 ✓
4	1	Rear Boot Lid Emblem Logo <i>new</i>		\$38.10 ✓
5	1	Rear Boot Lid Jazz Logo <i>new</i>		\$38.00 ✓
6	1	Rear Boot Lid Number Plate <i>Bent.</i>		\$50.00 ✓
7	2	Rear Boot Lid Number Plate Lamp <i>all new</i>	\$48.20	\$96.40 X
8	1	Rear Boot Lid Centre Moulding <i>cracked</i>		\$120.60 ✓
9	6	Rear Boot Lid Centre Moulding Clip <i>new</i>	\$6.50	\$39.00 ✓ 20
10	1	Rear Boot Lid Inner Lock <i>Tarned</i>		\$232.10 ✓
11	1	Rear Boot Lid Inner Rubber <i>lit</i>		\$128.10 ✓
12	1	Rear Boot Lid Inner Trim Board <i>Deformed</i>		\$296.70 ✓
13	1	Rear Boot Lid Wiper Link <i>new</i>		\$175.90 ✓
14	1	Rear Boot Lid Wiper Cover <i>cut</i>		\$45.00 ✓
15	1	Rear Boot Lid Wiper Arm <i>Broken</i>		\$86.00 ✓
16	1	Rear Boot Lid Wiper Motor <i>Damaged</i>		\$328.50 ✓
17	1	Rear Boot Lid Windscreen <i>Shattered</i>		\$1,256.20 250.50
18	1	Rear Boot Lid Windscreen Seal <i>new</i>		\$136.20 ✓
19	1	Rear Boot Lid Brake Lamp <i>new</i>		\$248.00 X
20	1	Rear Boot Lid Top Spoiler (Special Nett) <i>cracked</i>		\$850.00 650 (sw)
21	2	Rear Tail Lamp <i>Cracked</i>	\$296.50	\$593.00 ✓
22	4	Rear Tail Lamp Clip <i>new</i>	\$8.00	\$32.00 ✓
23	2	Rear Tail Lamp Panel <i>Distorted.</i>	\$191.70	\$383.40 ✓
24	1	Rear Bumper <i>Distorted</i>		\$494.60 ✓
25	8	Rear Bumper Clip <i>new</i>	\$6.50	\$52.00 30
26	2	Rear Bumper Side Retainer <i>new</i>	\$28.70	\$57.40 ✓
27	1	Rear Bumper Towing Cover <i>Deformed</i>		\$28.00 ✓
28	2	Rear Bumper Mud Shield <i>RH Dehd</i>	\$94.80	\$189.60 94.80
29	8	Rear Bumper Mud Shield Clip <i>new</i>	\$6.50	\$52.00 10

30	1	Rear Bumper Reverse Sensor (Special Nett)	Damaged	\$350.00	200(SN)
31	1	Rear End Panel	Dished	\$365.30	✓
32	1	Rear End Panel Top Garnish	Deland	\$140.20	✓
33	2	Rear Fender	Replaced	\$682.20	\$1,364.40 ✓
34	2	Rear Fender Glass	Paint	\$288.00	\$576.00 +
35	2	Rear Fender Air Duct	Paint	\$38.00	\$76.00 +
36	2	Rear Fender Inner Panel	Repair	\$633.00	\$1,266.00 *
37	2	Rear Fender Top Trim Board	Deformed	\$293.60	\$587.20 ✓
38	2	Rear Fender Inner Trim Board	Deland	\$339.80	\$679.60 ✓
39	16	Rear Fender Inner Trim Board Clip	new	\$6.50	\$104.00 60.
40	1	Rear Spare Tyre Panel	Repair	\$737.40	*
41	1	Rear Spare Tyre Panel Top Cover	Deformed	\$260.40	✓
42	1	Rear Spare Tyre Panel Top Sponge	New	\$206.00	*
43	1	Rear Spare Tyre Panel Insulation Pad.	New	\$450.00	* 200(SN)
44	2	Rear Spare Tyre Side Panel	Repair	\$151.20	\$302.40 +
45	1	Rear Chassis	Repair	\$460.30	*
46	1	Rear Exhaust	?	\$586.50	*
47	1	Rear Centre Exhaust	NP	\$562.40	+
48	1	Rear Exhaust Aluminium Cover	new	\$95.00	+
49	2	Rear Exhaust Mounting	✓	\$38.20	\$76.00 +
50	1	Rear Bootlid Windscreen Solar Film	New 305 250 (SN)		
				Subtotal :-	\$16,579.80

8640.20

6912.16 S.N 1300

Labour charges

To remove & refit cushion & trim board	\$280.00 60
To remove & refit rear windscreen	\$120.00 ✓
Gum	\$50.00 ✓
To remove & refit rear LH & RH fender glass	\$200.00 120
Gum	\$100.00 60
To remove & refit reverse sensor	\$100.00 50
To remove & refit rear & centre exhaust	\$380.00 80
To check wiring	\$120.00 30
Towing fee	4320 \$150.00 50
Tuff kote	\$150.00 100
Panel beating	\$3,200.00 1900
Spray painting	\$2,400.00 1700

4320

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Subtotal :- \$7,250.00

Total:- \$23,829.80

total: 12532.16

1/5 70K

10 Days.

10K
10 days

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19003755/ASD3N2

Date: 17/04/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTHCVE001895
Claimant Vehicle No :	SJX9937T	Insured Vehicle No :	YP7343J
Date of Loss:	27/02/2019	Nature of Claim:	TP
		Claim No:	CMTD1901114

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJX9937T	Engine No:	L13A55000502
Make & Model:	HONDA JAZZ, 1.4 (A)	Chassis No:	JHMGD18508S211164
Reg. Date:	12/05/2008 (Man. Year: 2008)	Odometer:	261249 km
Colour:	Black		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R15	Rear Tyre Size:	195/50 R15
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	16,879.80	8,212.16	8,667.64	51.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,250.00	4,320.00	2,930.00	40.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,129.80	12,532.16	11,597.64	48.06
Approved Total (Overridden) (S\$)		10,000.00		
(S\$)	24,129.80	10,000.00	14,129.80	58.56
+ GST 7.00/7.00% (S\$)	1,689.09	700.00	989.09	58.56
Nett Amount (S\$)	25,818.89	10,700.00	15,118.89	58.56

INSPECTION

Date of Assignment:	27/02/2019	
Date Inspected:	28/02/2019	Inspected At:
		New Hock Teck Motor Pte Ltd (HQ)
		1 Kaki Bukit Ave 6, Blk C #01-43
		Autobay@Kaki Bukit
		Singapore 417883

Estimated Period of Repair: 10.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 16 Apr 2019)
Parts: 144	HONDA JAZZ 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJX9937T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Distorted	820.30 F	*820.30 FL
2	2		*REAR BOOT LID HINGE	Not Necessary	97.80 F	*- FL
3	2		*REAR BOOT LID SHOCK ABSORBER	Bent	369.80 F	*369.80 FL
4	1		*REAR BOOT LID EMBLEM LOGO	Necessary	38.10 F	*38.10 FL
5	1		*REAR BOOT LID JAZZ LOGO	Necessary	38.00 F	*38.00 FL
6	1		*REAR BOOT LID NUMBER PLATE	Bent	50.00 F	*50.00 FL
7	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	96.40 F	*- FL
8	1		*REAR BOOT LID CENTRE MOULDING	Cracked	120.60 F	*120.60 FL
9	1		*REAR BOOT LID CENTRE MOULDING CLIP	Necessary	39.00 F	*20.00 FL
			(6 PCS)			
10	1		*REAR BOOT LID INNER LOCK	Jammed	232.10 F	*232.10 FL
11	1		*REAR BOOT LID INNER RUBBER	Cut	128.10 F	*128.10 FL
12	1		*REAR BOOT LID INNER TRIM BOARD	Deformed	296.70 F	*296.70 FL
13	1		*REAR BOOT LID WIPER LINK	Not Necessary	175.90 F	*- FL
14	1		*REAR BOOT LID WIPER COVER	Cut	45.00 F	*45.00 FL
15	1		*REAR BOOT LID WIPER ARM	Broken	86.00 F	*86.00 FL
16	1		*REAR BOOT LID WIPER MOTOR	Damaged	328.50 F	*328.50 FL
17	1		*REAR BOOT LID WINDSCREEN	Shattered	1,256.20 F	*750.50 FL
18	1		*REAR BOOT LID WINDSCREEN SEAL	Necessary	136.20 F	*136.20 FL
19	1		*REAR BOOT LID BRAKE LAMP	Not Necessary	248.00 F	*- FL
20	1		*REAR BOOT LID TOP SPOILER	Cracked	850.00 FS	*650.00 FS
21	2		*REAR TAIL LAMP	Cracked	593.00 F	*593.00 FL
22	4		*REAR TAIL LAMP CLIP	Necessary	32.00 F	*32.00 FL
23	2		*REAR TAIL LAMP PANEL	Dented	383.40 F	*383.40 FL
24	1		*REAR BUMPER	Distorted	494.60 F	*494.60 FL
25	8		*REAR BUMPER CLIP	Necessary	52.00 F	*30.00 FL
26	2		*REAR BUMPER SIDE RETAINER	Necessary	57.40 F	*57.40 FL
27	1		*REAR BUMPER TOWING COVER	Deformed	28.00 F	*28.00 FL
28	1		*REAR BUMPER MUD SHIELD	O/S Deformed	189.60 F	*94.80 FL
29	8		*REAR BUMPER MUD SHIELD CLIP	Necessary	52.00 F	*10.00 FL
30	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
31	1		*REAR END PANEL	Distorted	365.30 F	*365.30 FL
32	1		*REAR END PANEL TOP GARNISH	Deformed	140.20 F	*140.20 FL
33	2		*REAR FENDER	Buckled	1,364.40 F	*1,364.40 FL
34	2		*REAR FENDER GLASS	Not Necessary	576.00 F	*- FL
35	2		*REAR FENDER AIR DUCT	Not Necessary	76.00 F	*- FL
36	2		*REAR FENDER INNER PANEL	Repair	1,266.00 F	*- FL
37	2		*REAR FENDER TOP TRIM BOARD	Deformed	587.20 F	*587.20 FL
38	2		*REAR FENDER INNER TRIM BOARD	Deformed	679.60 F	*679.60 FL
39	16		*REAR FENDER INNER TRIM BOARD CLIP	Necessary	104.00 F	*60.00 FL
40	1		*REAR SPARE TYRE PANEL	Repair	737.40 F	*- FL
41	1		*REAR SPARE TYRE PANEL TOP COVER	Deformed	260.40 F	*260.40 FL
42	1		*REAR SPARE TYRE PANEL TOP SPONGE	Not Necessary	206.00 F	*- FL
43	1		*REAR SPARE TYRE PANEL INSULATION PAD	Necessary	450.00 FS	*200.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
44	2		*REAR SPARE TYRE SIDE PANEL	Repair	302.40 F	*- FL	
45	1		*REAR CHASSIS	Repair	460.30 F	*- FL	
46	1		*REAR EXHAUST	Not Necessary	586.50 F	*- FL	
47	1		*REAR CENTRE EXHAUST	Not Necessary	562.40 F	*- FL	
48	1		*REAR EXHAUST ALUMINIUM COVER	Not Necessary	95.00 F	*- FL	
49	2		*REAR EXHAUST MOUNTING	Not Necessary	76.00 F	*- FL	
50	1		*REAR BOOTLID WINDSCREEN SOLAR FILM	Necessary	300.00 FS	*250.00 FS	
					Sub Total (S\$)	16,879.80	9,940.20
					- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	1,728.04
					Total Parts (S\$)	16,879.80	8,212.16

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT CUSHION & TRIM BOARD	New	280.00	60.00
2	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
3	GUM	New	50.00	50.00
4	TO REMOVE & REFIT REAR LH & RH FENDER GLASS	New	200.00	120.00
5	GUM	New	100.00	60.00
6	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
7	TO REMOVE & REFIT REAR & CENTRE EXHAUST	New	380.00	80.00
8	TO CHECK WIRING	New	120.00	30.00
9	TOWING FEE	New	150.00	50.00
10	TUFF KOTE	New	150.00	100.00
11	PANEL BEATING	New	3,200.00	1,900.00
12	SPRAY PAINTING	New	2,400.00	1,700.00
Gross Labour Cost (\$\$)			7,250.00	4,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >