

Adrian

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 8 days Res.: Yes or No
 Lum Sum: 30 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLQ8030D Yr Regn: 2017 / July
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mit Attrage c.c. 1193

Colour: Blue A/C: Insured / Std / Nil / NA

Sp. Reading: 35544 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: MMBSTA13A1H006331

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Normal / Jammed / Leaked / Burnt or _____

Brake: Normal / Jammed / Leaked / Burnt or _____

Modl: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 185/55R15

R: 185/55R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YORK or _____

Front: _____ Rear: _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 28/02/19

Survey held at: M6 Solution

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP FWD.</u>
	<u>140 → 5,600 (RED) → 10,464.15 65%</u>
	<u>MV :</u>
	<u>PV :</u>
	<u>Nett :</u>

Date/Time, File Pass to?	Date/Time, File Return to?	Part Prices Check:		Survey Fee:	Date:					
1)	2)	IN	OUT	Basic & Add.	<table border="1"> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> </table>					
3)	4)			___ S + RS, ___ SI						
5)	6)			Photos						
Prel. Report:				Others						
Final Report:				TOTAL						

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: FWD	DATE	: 28/02/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SLQ8030D		
MODEL	: MITSUBISHI ATTRAGE 1.2		MMB5TA13 AHH 006331
CHASSIS NO			Asher
<u>ACCIDENT DETAILS</u>	DATE : 27-Feb-19		
	TIME : 10:30HRS		
THIRD PARTY REQUESTOR / CONTACT	: JACK LI		

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOTLID <i>Painted</i>	1	\$ 950.50	\$ 950.50
2	BOOTLID LOGO <i>new</i>	1	\$ 62.20	\$ 62.20
3	BOOTLID EMBLEM"ATTRAGE" <i>new</i>	1	\$ 63.00	\$ 63.00
4	BOOTLID EMBLEM"MIVEC TECHNOLOGY" <i>new</i>	1	\$ 63.00	\$ 63.00
5	BOOTLID EMBLEM"C&C" <i>new</i>	1	\$ 63.00	\$ 63.00
6	BOOTLID TOP LOCK <i>Damaged</i>	1	\$ 228.40	\$ 228.40
7	BOOTLID CATCH <i>new</i>	1	\$ 103.00	\$ 103.00
8	BOOTLID HINGE <i>new new</i>	2	\$ 123.20	\$ 246.40
9	BOOTLID KEYLESS ANTENNA <i>cracked</i>	1	\$ 233.20	\$ 233.20
10	BOOTLID BUZZER <i>new</i>	1	\$ 203.40	\$ 203.40
11	BOOTLID WEATHERSTRIP <i>cut</i>	1	\$ 192.00	\$ 192.00
12	BOOTLID SENSOR LOCK <i>new</i>	1	\$ 203.40	\$ 203.40
13	BOOTLID OUTER GARNISH <i>new</i>	1	\$ 220.00	\$ 220.00
14	REAR BUMPER <i>Painted</i>	1	\$ 822.30	\$ 822.30
15	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 72.50	\$ 145.00
16	REAR BUMPER AIR VENT <i>new cracked</i>	1	\$ 89.00	\$ 89.00
17	REAR BUMPER AIR VENT COVER <i>new cracked</i>	1	\$ 133.00	\$ 133.00
18	REAR BUMPER REFLECTOR <i>cracked</i>	2	\$ 63.00	\$ 126.00

828
✓
✓
✓
✓
✓
+
+
69
+87
-
+
✓
708
56
✓
✓
✓

19	REAR NUMBER PLATE LAMP(SET) <i>new</i>	1	\$ 133.80	\$ 133.80	+
20	TAILLAMP <i>cracked</i>	2	\$ 463.20	\$ 926.40 <i>590</i>	+
21	TAILLAMP PANEL <i>Repair</i>	2	\$ 174.00	\$ 348.00	+
22	REAR FENDER <i>Repair</i>	2	\$ 680.00	\$ 1,360.00	+
23	REAR FENDER INNER TRIM <i>new</i>	2	\$ 310.20	\$ 620.40	+
24	REAR END PANEL <i>vented</i>	1	\$ 566.30	\$ 566.30	✓
25	REAR END PANEL TOP GARNISH <i>rebrand</i>	1	\$ 174.00	\$ 174.00	-
26	REAR FLOOR PANEL <i>Repair</i>	1	\$ 960.80	\$ 960.80	+
27	REAR FLOOR PANEL TOP BOARD <i>toin</i>	1	\$ 233.90	\$ 233.90	✓
28	EXHAUST PIPE	1	\$ 810.00	\$ 810.00	+
29	EXHAUST PIPE MOUNTING <i>new</i>	4	\$ 62.30	\$ 249.20	+
30	EXHAUST PIPE INSULATOR	1	\$ 233.90	\$ 233.90	+

4331.8
389862

TOTAL PRICE \$ 10,763.50
LESS 10% \$ 1,076.35
SUB TOTAL PRICE \$ 9,687.15

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	BOOTLID OUTER GARNISH CLIP (SET) <i>new</i>	1	\$ 25.00	\$ 25.00	+
3	BOOTLID STICKER <i>new</i>	1	\$ 50.00	\$ 50.00 <i>30</i>	+
4	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 22.00	\$ 22.00	✓
5	TAILLAMP CLIP (SET) <i>new</i>	1	\$ 20.00	\$ 20.00	-
6	TAILLAMP PANEL SEALANT <i>new</i>	1	\$ 20.00	\$ 20.00	+
7	REAR WINDSCREEN SEALANT <i>new</i>	1	\$ 120.00	\$ 120.00	+
8	REAR WINDSCREEN INNER SEAL	1	\$ 100.00	\$ 100.00	+
9	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 20.00	\$ 20.00 <i>10</i>	+
10	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 120.00	\$ 120.00 <i>60</i>	+
11	REAR FLOOR PANEL INSULATION SEAL <i>new</i>	1	\$ 120.00	\$ 120.00	+
12	REVERSE CAMERA <i>new</i>	1	\$ 380.00	\$ 380.00	+
13	REVERSE SENSOR <i>new</i>	1	\$ 220.00	\$ 220.00 <i>200</i>	+

342

TOTAL \$ 1,267.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,000.00 <i>1300</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,000.00 <i>1300</i>	
3	TUFF COAT	\$ 150.00 <i>50</i>	
4	WIRING CHECK	\$ 150.00 <i>30</i>	

5	TO REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$	120.00	50	
6	TO REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$	150.00	50	
7	TO REMOVE AND REFIX EXHAUSE PIPE	\$	320.00	X	
8	TO REMOVE AND REFIX REAR WINDSCREEN	\$	100.00	X	
9	CONDUCT WATER LEAKAGE TEST	\$	120.00	X	
TOTAL			\$5,110.00		

2780

ESTIMATE REPORT

TOTAL PARTS COST : \$ 10,954.15
 TOTAL LABOUR COST : \$ 5,110.00
 TOTAL REPAIR COST : \$ 16,064.15

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :
 NO OF DAYS :

Adrian Lj
 L/C 28/02/19
 08 Days.

Total: 702062
 L/S: 5.6K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	28 Feb 2019 13:56	Cim Veh Model Changed	(204773) MITSUBISHI ATTRAGE 1.2 CVT (A).	[A] HOW MEI KWAN
2	28 Feb 2019 13:56	Cim Created	Reg No: SLQ8030D. Acct Date: 2019/02/27. Claim Type: TP. Insurer: FWD Singapore Pte. Ltd. (HQ). TP Insurer: FWD Singapore Pte. Ltd. (HQ). Workshop: Mg Solution Pte Ltd - Kaki Bukit (HQ)	[A] HOW MEI KWAN
3	28 Feb 2019 13:56	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ); RR Region: FWD - Ext Auto Adj Assignment. Suggested Adj. : VICOM Ltd.	[A] HOW MEI KWAN
4	28 Feb 2019 13:56	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/03/11	[A] HOW MEI KWAN
5	28 Feb 2019 13:56	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] HOW MEI KWAN
6	28 Feb 2019 13:56	Label Added	(20005):Direct Settlement .	[A] HOW MEI KWAN
7	28 Feb 2019 13:56	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] HOW MEI KWAN
8	28 Feb 2019 16:04	Cim Registration Modified	Pol No:->PNPV2018-00007330.	[I] Clara Li Zi Rong
9	29 Apr 2019 17:11	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/03/11	[A] Asher Sng Rong Yi
10	31 May 2019 10:38	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
11	31 May 2019 10:38	Cim Dtl Modified	JPJ Reg. Date: -> 2017/07/24.	[A] JOANNE LEE KHANG MIN
12	31 May 2019 10:38	Cim Details Notified		[A] JOANNE LEE KHANG MIN
13	13 Jun 2019 12:26	Adj Mandate Request	Cur.Req:6492.00:LIABILITY: 100% B:27 OI REAR ENDED TP QUANTUM: (a) COR w/GS T: \$5,992.00 + (b) LOU : \$500.00 (10days x \$50) Total: a+b = \$6,237.45 PLEASE REV ERT WITH YOUR APPROVAL / MANDATE / INSTRUCTIONS, IF ANY.	[A] Asher Sng Rong Yi

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2130424	29/04/2019 17:11	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLQ8030D	SJT7564U	10.70

Print Received Message

This mail is associated with :

***SLQ8030D (1201900005507)**
[SJT7564U]

TP
MUHAMMAD AIZAL BIN MD AMIN
Feb 27 2019 10:00AM
[Jereen Neo Wei Fang]
Mg Solution Pte Ltd - Kaki Bukit

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 28/06/2019 09:17 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$6492.00) - SLQ8030D - Claim Handler: Josey Loh

Approved:6492.00.

MG SOLUTION PTE LTD
23 Kaki Bukit Ave 4 (South Wing) #02-03B
Vicom Inspection Centre, Singapore 415933
Tel: 6243 1373 Fax: 6243 1376
GST Reg. No. : 201427944N

MOTOR CLAIM DISCHARGE

INSURED: MUHAMMAD AIZAL BIN MD AMIN
CAR/LORRY/CYCLE: REG NO: SLQ 8030D POLICY NO:
ACCIDENT CLAIM NO:

I / We confirm that I / we have taken delivery of Car / Lorry / Motor Cycle

Registered No. SLQ 8030D from the repairers,
Messrs MG SOLUTION PTE LTD

And that all repairs necessary as a result of an accident in which the said vehicle was involved on or
about the 27 day of 02 20..... 19 have been completed to my / our satisfaction, and that
I / we have no further claim on the above company in Respect thereof.

Date: Signature: 

Co's Stamp: NRIC No:

27/02/2019 - FR I
03/03/2019 - Sunday
Vehicle In - 27/02/2019
Vehicle Out - 08/03/2019
Lok - 10 days + \$200
= \$ 2,000



MG SOLUTION PTE LTD

23 Kaki Bukit Ave 4, AAS Kaki Bukit Centre #02-03 Singapore 415933

Tel: 6243 1373 Fax: 6243 1376

(GST Reg. No. 201427944N)

Date : 26/04/2019
Your Ref : SJT7564U
To : **FWD INSURANCE PTE LTD**
Attn : Motor Claims Department

Dear Sir/Mdm,

**RE: ACCIDENT INVOLVING VEHICLE SLQ8030D & SJT7564U ON 27/02/2019 AT
ALONG PIE TOWARDS CHANGI BEFORE STEVENS ROAD EXIT.**

We refer to the above matter.

Attached copies of the following for your kind perusal:

- 1) Proforma Bill No.198134 @ S\$5,992.00 (Inclusive Of 7% GST)
- 2) Loss of Use @ S\$2,000.00 (10 Days x S\$200)
- 3) LTA Search @ SSNIL
- 4) Authorisation to Act
- 5) GIA Report

Hope the above is in order and kindly let us have your confirmation soon.

Tax invoice will be issue upon amount finalized.

Thank You.

Yours faithfully,



Sharon Chia

HP: 9188 6931

E-mail: mg3solution@gmail.com

LETTER OF AUTHORITY

Name : MUHAMMAD AIZAL BIN MD-AWIN

Address : BLK 21 TEBAN GARDENS ROAD
#28-119 SINGAPORE 60021

Contact No : _____

TO: FWD INSURANCE PTE LTD

Dear Sirs,

ACCIDENT INVOLVING SLQ8030D AND SJT7564U ON 27/02/2019
AT/ALONG PIE TOWARDS CHANGI BEFORE STEVEN'S ROAD EXIT

I/We, MUHAMMAD AIZAL BIN MD-AWIN, am/are the registered owner of
motor car no. SLQ3080D

Please note that I have assigned all compensations monies due to me/us in the above said accident
to **M/S MG SOLUTION PTE LTD**.

I/We, hereby authorize you to release all compensation monies pertaining to the above-mentioned
accident to **M/S MG SOLUTION PTE LTD** and forward your settlement cheque to **M/S MG SOLUTION
PTE LTD** whom I had authorized to collect the said compensation monies.

Thank you

x 

Signature of Claimant



Witness By

RELEASE

Claim Reference:	1201900005507
Surveyor's Reference:	CC4/FWD19003759/Aea3
TP Reference:	SLQ 8030D

We, **MG SOLUTION PTE LTD** ("Workshop") hereby agree and confirm that we are authorized by the owner ("Claimant") of motor vehicle **SLQ 8030D** ("Vehicle") to accept the sum of **\$6,492.00**, being the amount claimed for **\$5,992.00** (repair costs), **\$500.00** (loss of rental/ use), **\$ -** (loss of income), **\$ -** (disbursement) as compensation for the loss of or damage to the Vehicle, as a result of an accident ("Accident") which occurred on **27/02/2019** (date of accident) at / along **PIE TWDS CHANGI B4 STEVEN RD EXIT** (location) involving vehicle no/s. **SLQ 8030D** and **SJT 7564U**.

This is pursuant to the inspection conducted on **28/02/2019** (date) at the Workshop.

We confirm that this acceptance is in full and final settlement of all claims arising from the damage to the Vehicle (whether now or hereafter to become manifest), to the intent that FWD Singapore Pte. Ltd. and all other persons, in particular the driver of **SJT 7564U** be absolutely and finally exonerated and discharged from all claims of every nature and kind whatsoever which have been made or which may be made in respect of this Accident.

We also declare that we are authorized by the Claimant to receive the above compensation and we have full authority to make the claim as set out above and to settle the matter on behalf of the Claimant in any manner we deem fit.

This settlement is reached on a without prejudice and without admission of liability basis. As such, this Release is not to be construed as an admission of liability on the part of FWD Singapore Pte Ltd, their policyholder and / or authorised driver and shall not be used as evidence in any claims and / or action which may be lodged by any of them.

Dated this 09 day of 07 2019

CLAIMANT



[Signed by the "Workshop" with Co. Stamp]

For and on behalf of the "Claimant"



LWP

[FWD's appointed surveyor with Co. Stamp]

For and on behalf of FWD Singapore Pte. Ltd.

Provided always that this discharge of my claim for damages relating to the damage to my vehicle shall not prejudice or affect my further claim for general and special damages for my personal injuries sustained in the same accident.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Mar 2019 Edit Reg		27 Feb 2019 00:00 Edit Adj Rpt	\$5,600.00 Edit Estimates	\$5,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Jereen Neo Wei Fang , ID: S9408902F								
Main Claimant:	MUHAMMAD AIZAL BIN MD AMIN , ID: S8323947F								
Vehicle Reg. No.:	SLQ8030D	Date of Loss:	27/02/2019 10:00 - :59 [19 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1201900005507	Policy/Cover Note No.:	PNPV2018-00007330 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJT7564U	Policy No. (Claimant):	PNPV2018-00009002						
Repairer:	Mg Solution Pte Ltd - Kaki Bukit (HQ) 25 Kaki Bukit Road 4 #04-01, 41800 Kaki Bukit - Tel:								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]								
Claimant's Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 11/03/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> FWD_SG (28/06/2019): Alert - Adj Mandate Approved (\$6492.00) - SLQ8030D - Claim Handler: Josey Loh FWD_SG (14/06/2019): Alert - Adj Mandate Maintained - SLQ8030D - Claim Handler: Josey Loh 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLQ8030D (1201900005507)
[SJT7564U]
TP
MUHAMMAD AIZAL BIN MD AMIN
Feb 27 2019 10:00AM
[Jereen Neo Wei Fang]
Mg Solution Pte Ltd - Kaki Bukit

Upload Documents			Upload Photos			Compose New Letter			View View in Browser			
Letters/Correspondences										1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print				
1	(Draft)	Third Party Express Settlement - Payment Breakdown						Edit				
Assessment Reports										1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print				
1	29/04/19 17:11	Adjuster Immediate Advice						Load HTM				
Photos/Images										3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print				
1	09/04/19 23:04	General View						Load JPG	<input checked="" type="checkbox"/>			
2	09/04/19 23:04	General View						Load JPG	<input checked="" type="checkbox"/>			
3	09/04/19 23:04	General View						Load JPG	<input checked="" type="checkbox"/>			
4	09/04/19 23:04	General View						Load JPG	<input checked="" type="checkbox"/>			
5	09/04/19 23:04	General View						Load JPG	<input checked="" type="checkbox"/>			
6	09/04/19 23:04	General View						Load JPG	<input checked="" type="checkbox"/>			
7	09/04/19 23:04	General View						Load JPG	<input checked="" type="checkbox"/>			
8	09/04/19 23:04	General View						Load JPG	<input checked="" type="checkbox"/>			
9	09/04/19 23:04	General View						Load JPG	<input checked="" type="checkbox"/>			
10	09/04/19 23:04	General View						Load JPG	<input checked="" type="checkbox"/>			
11	09/04/19 23:04	General View						Load JPG	<input checked="" type="checkbox"/>			
12	09/04/19 23:04	General View						Load JPG	<input checked="" type="checkbox"/>			
13	09/04/19 23:04	General View						Load JPG	<input checked="" type="checkbox"/>			
14	09/04/19 23:04	General View						Load JPG	<input checked="" type="checkbox"/>			
15	09/04/19 23:04	General View						Load JPG	<input checked="" type="checkbox"/>			
16	09/04/19 23:04	General View						Load JPG	<input checked="" type="checkbox"/>			
17	09/04/19 23:04	General View						Load JPG	<input checked="" type="checkbox"/>			
18	09/04/19 23:04	General View						Load JPG	<input checked="" type="checkbox"/>			
19	09/04/19 23:04	General View						Load JPG	<input checked="" type="checkbox"/>			
20	09/04/19 23:04	General View						Load JPG	<input checked="" type="checkbox"/>			
21	09/04/19 23:04	General View						Load JPG	<input checked="" type="checkbox"/>			
22	09/04/19 23:04	General View						Load JPG	<input checked="" type="checkbox"/>			
23	09/04/19 23:04	General View						Load JPG	<input checked="" type="checkbox"/>			
24	09/04/19 23:04	General View						Load JPG	<input checked="" type="checkbox"/>			
25	09/04/19 23:04	General View						Load JPG	<input checked="" type="checkbox"/>			
26	09/04/19 23:04	General View						Load JPG	<input checked="" type="checkbox"/>			
27	09/04/19 23:04	General View						Load JPG	<input checked="" type="checkbox"/>			
28	09/04/19 23:04	General View						Load JPG	<input checked="" type="checkbox"/>			
29	09/04/19 23:04	General View						Load JPG	<input checked="" type="checkbox"/>			
30	09/04/19 23:04	General View						Load JPG	<input checked="" type="checkbox"/>			

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
32	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
33	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
34	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
35	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
36	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
37	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
38	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
39	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
40	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
41	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
42	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
43	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
44	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
45	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
46	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
47	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
48	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
49	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
50	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
51	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
52	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
53	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
54	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
55	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
56	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
57	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
58	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
59	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
60	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
61	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
62	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
63	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
64	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
65	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
66	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
67	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
68	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
69	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
70	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
71	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
72	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
73	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
74	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
75	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
76	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
77	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
78	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
79	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>
80	09/04/19 23:04	Reinspection Photo		<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/02/19 13:56	ACKNOWLEDGEMENT EMAIL TO FWD DD 28.02.2019	Load PDF	
2	28/02/19 13:56	NOTIFICATION FROM WORKSHOP +TP GIA REPORT	Load PDF	
3	29/04/19 17:11	TP ESTIMATE MARKED	Load PDF	
4	25/06/19 09:56	LOD	Load PDF	
5	16/07/19 14:01	WORKSHOP INVOICE	Load PDF	
6	16/07/19 14:01	Release Voucher	Load PDF	
7	16/07/19 14:01	AUTHORISATION TO ACT FORM	Load PDF	
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	04/03/19 18:58	OI GIA	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SJT7564U (Insd veh)	Model:	MITSUBISHI ATTRAGE 1.2 CVT (A)
	SLQ8030D (TP veh)		
Date of Accident:	27/02/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	17,188.64	
Final Repair Cost	:	\$	5,992.00	
Loss of Use	:	\$	500.00	10.00 days at \$50.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	0.00	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	6,492.00	
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)				
A) For Non GIA Registered Workshop:		Agreed Liability ____ 100 ____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	Mg Solution Pte Ltd	:	\$ 6,492.00
2)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

16 Jul
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19003759/AEA3Q2
Date: 18/07/2019

REFERENCE

Handling Insurer:	FWD Singapore Pte. Ltd.	Policy No:	PNPV2018-00007330
Claimant Vehicle No :	SLQ8030D	Insured Vehicle No :	SJT7564U
Date of Loss:	27/02/2019	Nature of Claim:	TP
			Claim No: 1201900005507

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ8030D	Engine No:	3A92UGB5929
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AHH006331
Reg. Date:	24/07/2017 (Man. Year: 2017)	Odometer:	35544 km
Colour:	Blue		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,954.15	4,240.62	6,713.53	61.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,110.00	2,780.00	2,330.00	45.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,064.15	7,020.62	9,043.53	56.30
Approved Total (Overridden) (S\$)		5,600.00		
	(S\$)	16,064.15	5,600.00	10,464.15
	+ GST 7.00/7.00% (S\$)	1,124.49	392.00	732.49
	Nett Amount (S\$)	17,188.64	5,992.00	11,196.64
	+ Loss of Use (10.0 x S\$50.00/day) (S\$)		500.00	
		Nett Liability (S\$)	6,492.00	

INSPECTION

Date of Assignment:	27/02/2019	
Date Inspected:	28/02/2019	Inspected At: Mg Solution Pte Ltd - Kaki Bukit (HQ) 25 Kaki Bukit Road 4 #04-01 Singapore 41800
Estimated Period of Repair:	8.0 days	

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 31 May 2019)	
Parts:	N/A	mitsubishi attrage 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ8030D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	950.50 FL	*828.00 FL
2	1		*BOOTLID LOGO	Necessary	62.20 FL	*62.20 FL
3	1		*BOOTLID EMBLEM ATTRAGE	Necessary	63.00 FL	*63.00 FL
4	1		*BOOTLID EMBLEM MIVEC TECHNOLOGY	Necessary	63.00 FL	*63.00 FL
5	1		*BOOTLID EMBLEM C&C	Necessary	63.00 FL	*63.00 FL
6	1		*BOOTLID TOP LOCK	Damaged	228.40 FL	*228.40 FL
7	1		*BOOTLID CATCH	Not Necessary	103.00 FL	*- FL
8	2		*BOOTLID HINGE	Not Necessary	246.40 FL	*- FL
9	1		*BOOTLID KEYLESS ANTENNA	Cracked	233.20 FL	*69.00 FL
10	1		*BOOTLID BUZZER	Not Necessary	203.40 FL	*87.00 FL
11	1		*BOOTLID WEATHERSTRIP	Cut	192.00 FL	*192.00 FL
12	1		*BOOTLID SENSOR LOCK	Not Necessary	203.40 FL	*- FL
13	1		*BOOTLID OUTER GARNISH	Not Necessary	220.00 FL	*- FL
14	1		*REAR BUMPER	Deformed	822.30 FL	*708.00 FL
15	2		*REAR BUMPER SIDE RETAINER	Necessary	145.00 FL	*56.00 FL
16	1		*REAR BUMPER AIR VENT	Cracked	89.00 FL	*89.00 FL
17	1		*REAR BUMPER AIR VENT COVER	Cracked	133.00 FL	*133.00 FL
18	2		*REAR BUMPER REFLECTOR	Cracked	126.00 FL	*126.00 FL
19	1		*SET REAR NUMBER PLATE LAMP	Not Necessary	133.80 FL	*- FL
20	2		*TAILLAMP	Cracked	926.40 FL	*590.00 FL
21	2		*TAILLAMP PANEL	Repair	348.00 FL	*- FL
22	2		*REAR FENDER	Repair	1,360.00 FL	*- FL
23	2		*REAR FENDER INNER TRIM	Not Necessary	620.40 FL	*- FL
24	1		*REAR END PANEL	Dented	566.30 FL	*566.30 FL
25	1		*REAR END PANEL TOP GARNISH	Deformed	174.00 FL	*174.00 FL
26	1		*REAR FLOOR PANEL	Repair	960.80 FL	*- FL
27	1		*REAR FLOOR PANEL TOP BOARD	Torn	233.90 FL	*233.90 FL
28	1		*EXHAUST PIPE	Not Necessary	810.00 FL	*- FL
29	4		*EXHAUST PIPE MOUNTING	Not Necessary	249.20 FL	*- FL
30	1		*EXHAUST PIPE INSULATOR	Not Necessary	233.90 FL	*- FL
31	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
32	1		*SET BOOTLID OUTER GARNISH CLIP	Not Necessary	25.00 FS	*- FS
33	1		*BOOTLID STICKER	Necessary	50.00 FS	*30.00 FS
34	1		*SET REAR BUMPER CLIP	Necessary	22.00 FS	*22.00 FS
35	1		*SET TAILLAMP CLIP	Necessary	20.00 FS	*20.00 FS
36	1		*TAILLAMP PANEL SEALANT	Not Necessary	20.00 FS	*- FS
37	1		*REAR WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
38	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	100.00 FS	*- FS
39	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*10.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
40	1		*REAR END PANEL INSULATION SEAL	Necessary	120.00 FS	*60.00 FS	
41	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	120.00 FS	*- FS	
42	1		*REVERSE CAMERA	Not Necessary	380.00 FS	*- FS	
43	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS	
					Sub Total (S\$)	12,030.50	4,673.80
					- List Item Discount on L Items 10.00/10.00% (S\$)	1,076.35	433.18
					Total Parts (S\$)	10,954.15	4,240.62

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	2,000.00	1,300.00
2	TO SPRAY PAINT AFFECTED AREA	New	2,000.00	1,300.00
3	TUFF COAT	New	150.00	50.00
4	WIRING CHECK	New	150.00	30.00
5	TO REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	120.00	50.00
6	TO REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	150.00	50.00
7	TO REMOVE AND REFIX EXHAUST PIPE	New	320.00	0.00
8	TO REMOVE AND REFIX REAR WINDSCREEN	New	100.00	0.00
9	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
Gross Labour Cost (S\$)			5,110.00	2,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >