

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

| | | | |
|---------------------------------|--------------------------|----------|--------------------|
| TO | : FWD | DATE | : 28/02/2019 |
| ATTENTION | : MOTOR CLAIMS DEPT | JOB TYPE | : T/P CLAIM |
| ESTIMATE REPORT | : | | |
| <u>VEHICLE DETAILS</u> | | | |
| VEHICLE NO | : SLQ8030D | | |
| MODEL | : MITSUBISHI ATTRAGE 1.2 | | MMB5TA13AHH 006331 |
| CHASSIS NO | | | Asher |
| <u>ACCIDENT DETAILS</u> | | DATE | : 27-Feb-19 |
| | | TIME | : 10:30HRS |
| THIRD PARTY REQUESTOR / CONTACT | : JACK LI | | |

CLAIM DETAIL : PARTS

| S/N | DESCRIPTION | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |
|-----|---|-----|-----------------|----------------------|
| 1 | BOOTLID <i>Painted.</i> | 1 | \$ 950.50 | \$ 950.50 |
| 2 | BOOTLID LOGO <i>new</i> | 1 | \$ 62.20 | \$ 62.20 |
| 3 | BOOTLID EMBLEM"ATTRAGE" <i>new</i> | 1 | \$ 63.00 | \$ 63.00 |
| 4 | BOOTLID EMBLEM"MIVEC TECHNOLOGY" <i>new</i> | 1 | \$ 63.00 | \$ 63.00 |
| 5 | BOOTLID EMBLEM"C&C" <i>new</i> | 1 | \$ 63.00 | \$ 63.00 |
| 6 | BOOTLID TOP LOCK <i>Damaged.</i> | 1 | \$ 228.40 | \$ 228.40 |
| 7 | BOOTLID CATCH <i>new</i> | 1 | \$ 103.00 | \$ 103.00 |
| 8 | BOOTLID HINGE <i>new</i> | 2 | \$ 123.20 | \$ 246.40 |
| 9 | BOOTLID KEYLESS ANTENNA <i>cracked</i> | 1 | \$ 233.20 | \$ 233.20 |
| 10 | BOOTLID BUZZER <i>new</i> | 1 | \$ 203.40 | \$ 203.40 |
| 11 | BOOTLID WEATHERSTRIP <i>cut</i> | 1 | \$ 192.00 | \$ 192.00 |
| 12 | BOOTLID SENSOR LOCK <i>new</i> | 1 | \$ 203.40 | \$ 203.40 |
| 13 | BOOTLID OUTER GARNISH <i>new</i> | 1 | \$ 220.00 | \$ 220.00 |
| 14 | REAR BUMPER <i>Painted</i> | 1 | \$ 822.30 | \$ 822.30 |
| 15 | REAR BUMPER SIDE RETAINER <i>new</i> | 2 | \$ 72.50 | \$ 145.00 |
| 16 | REAR BUMPER AIR VENT <i>new cracked</i> | 1 | \$ 89.00 | \$ 89.00 |
| 17 | REAR BUMPER AIR VENT COVER <i>new cracked</i> | 1 | \$ 133.00 | \$ 133.00 |
| 18 | REAR BUMPER REFLECTOR <i>cracked</i> | 2 | \$ 63.00 | \$ 126.00 |

828
 ✓
 ✓
 ✓
 ✓
 ✓
 ✓
 +
 +
 69
 +87
 -
 +
 ✓
 708
 56
 ✓
 ✓
 ✓

| | | | | | |
|----|--|---|-----------|---------------------------------|---|
| 19 | REAR NUMBER PLATE LAMP(SET) <i>new</i> | 1 | \$ 133.80 | \$ 133.80 | + |
| 20 | TAILLAMP <i>cracked</i> | 2 | \$ 463.20 | \$ 926.40 <i>590</i> | + |
| 21 | TAILLAMP PANEL <i>Repair</i> | 2 | \$ 174.00 | \$ 348.00 | + |
| 22 | REAR FENDER <i>Repair Repair</i> | 2 | \$ 680.00 | \$ 1,360.00 | + |
| 23 | REAR FENDER INNER TRIM <i>new</i> | 2 | \$ 310.20 | \$ 620.40 | + |
| 24 | REAR END PANEL <i>dented</i> | 1 | \$ 566.30 | \$ 566.30 | ✓ |
| 25 | REAR END PANEL TOP GARNISH <i>behind</i> | 1 | \$ 174.00 | \$ 174.00 | - |
| 26 | REAR FLOOR PANEL <i>Repair</i> | 1 | \$ 960.80 | \$ 960.80 | + |
| 27 | REAR FLOOR PANEL TOP BOARD <i>torn</i> | 1 | \$ 233.90 | \$ 233.90 | ✓ |
| 28 | EXHAUST PIPE | 1 | \$ 810.00 | \$ 810.00 | + |
| 29 | EXHAUST PIPE MOUNTING <i>new</i> | 4 | \$ 62.30 | \$ 249.20 | + |
| 30 | EXHAUST PIPE INSULATOR | 1 | \$ 233.90 | \$ 233.90 | + |

4331.8 TOTAL PRICE \$ 10,763.50
 3898.62 LESS 10% \$ 1,076.35
 SUB TOTAL PRICE \$ 9,687.15

SPECIAL NETT ITEMS

| S/N | DESCRIPTION | QTY | UNIT LIST PRICE | TOTAL S/NETT | |
|-----|---|-----|-----------------|---------------------------------|---|
| 1 | REAR NUMBER PLATE <i>new</i> | 1 | \$ 50.00 | \$ 50.00 | + |
| 2 | BOOTLID OUTER GARNISH CLIP (SET) <i>new</i> | 1 | \$ 25.00 | \$ 25.00 | + |
| 3 | BOOTLID STICKER <i>new</i> | 1 | \$ 50.00 | \$ 50.00 <i>30</i> | + |
| 4 | REAR BUMPER CLIP (SET) <i>new</i> | 1 | \$ 22.00 | \$ 22.00 | ✓ |
| 5 | TAILLAMP CLIP (SET) <i>new</i> | 1 | \$ 20.00 | \$ 20.00 | - |
| 6 | TAILLAMP PANEL SEALANT <i>new</i> | 1 | \$ 20.00 | \$ 20.00 | + |
| 7 | REAR WINDSCREEN SEALANT <i>new</i> | 1 | \$ 120.00 | \$ 120.00 | x |
| 8 | REAR WINDSCREEN INNER SEAL | 1 | \$ 100.00 | \$ 100.00 | + |
| 9 | REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i> | 1 | \$ 20.00 | \$ 20.00 <i>10</i> | + |
| 10 | REAR END PANEL INSULATION SEAL <i>new</i> | 1 | \$ 120.00 | \$ 120.00 <i>60</i> | + |
| 11 | REAR FLOOR PANEL INSULATION SEAL <i>new</i> | 1 | \$ 120.00 | \$ 120.00 | + |
| 12 | REVERSE CAMERA <i>new</i> | 1 | \$ 380.00 | \$ 380.00 | + |
| 13 | REVERSE SENSOR <i>new</i> | 1 | \$ 220.00 | \$ 220.00 <i>200</i> | + |

342 TOTAL \$ 1,267.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

| | | | | |
|---|--|-------------|-----------------|--|
| 1 | PANEL BEATING, REMOVAL AND REPLACING PARTS | \$ 2,000.00 | 1300 | |
| 2 | TO SPRAY PAINT AFFECTED AREA | \$ 2,000.00 | 1300 | |
| 3 | TUFF COAT | \$ 150.00 | 50 | |
| 4 | WIRING CHECK | \$ 150.00 | 30 | |

| | | | | |
|---|---|-----------|----|--|
| 5 | TO REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING | \$ 120.00 | 50 | |
| 6 | TO REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING | \$ 150.00 | 50 | |
| 7 | TO REMOVE AND REFIX EXHAUSE PIPE | \$ 320.00 | X | |
| 8 | TO REMOVE AND REFIX REAR WINDSCREEN | \$ 100.00 | X | |
| 9 | CONDUCT WATER LEAKAGE TEST | \$ 120.00 | X | |

TOTAL

\$5,110.00

2780

ESTIMATE REPORT

TOTAL PARTS COST : \$ 10,954.15
 TOTAL LABOUR COST : \$ 5,110.00
 TOTAL REPAIR COST : \$ 16,064.15

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :
 NO OF DAYS :

Adrian Lj
 2/c 28/02/19

Total: 7020.62
 4/s: 5.61K.

08 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: