

CC 3, CTI 1900 3766, K1 203m

LKK:
IDAC:

INS. CASE OWNER:

ASSIGNMENT

DOE:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II : SS

Is driver the owner?

(YES) NO

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup):

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time: 05/03/19

Sent By: QB

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

L9 S\$ 3,100.00 (4 days) Reduction: 51 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

% 100% (Agreed / Assessed) BOLA S/N No.: 1a

If NO or B 28, Ass. Lia:

Repair Cost:

(w/ GST) S\$ 3,377.00

(OI TOWING, TP VIDEO IN)

Loss of Rental (LOR):

S\$ 602.34 (6 days) X \$100.39

Loss of Use (LOU):

S\$ - (\$ x days)

Loss of Income (LOI):

S\$ - (\$ x days)

LOR only ☒ LOU only ☐LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

S\$ 7.45

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 3,926.79

Global Sum S\$: -

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$ 3,926.79

Name 1:

PREMIER AUTOMOTIVE SERVICES PTE LTD

Payee 2 (Strike if N/A):

S\$ -

Name 2:

-

Payee 3 (Strike if N/A):

S\$ -

Name 3:

-



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/CTH19003766/K1ea3

Date: 05.03.2019

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHD 1262M

We refer to the above matter.


Please be informed that we had conducted the inspection of the above mentioned vehicle on 27.02.2019 at the premises of M/s Premier Automotive Services Pte Ltd - Changi and have the following to report:-

Workshop Estimate Amount	: S\$	6,393.30
Revised Estimate Amount	: S\$	2,561.00
"Check" Items Amount	: S\$	1,116.00
Total (Including Check Items)	: S\$	3,677.00

Market Value	: S\$	-	(est.)
LTA Reimbursement Value	: S\$	-	(est.)
Nett Value	: S\$	-	(est.)

Description of Damage:

The vehicle sustained damages at the
Front O/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4.0 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	02 Sep 2015 / 07:51:23	Receipt No.:	AACCK001-AX239-150902-000013
Asset Type:	Vehicle	Transaction Amount:	\$69,850.00
Asset ID:	SHD1262M	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20150902075123968750		

Vehicle No.:	SHD1262M
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	02 Sep 2015
Original Registration Date:	02 Sep 2015
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414MF5621944
Engine No.:	D4FDEH313607
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2015
Open Market Value:	\$21,659.00
Minimum PARF Benefit:	\$13,402.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	02 Sep 2015 07:51:23
COE No.:	2015090201003466H
COE Expiry Date:	01 Sep 2023
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$47,373.00
Lifespan Expiry Date:	01 Sep 2023

Text size + -

Enquire Transaction History

Transaction History Details

Log Date/Time:	02 Sep 2015 / 07:51:23	Receipt No.:	AACCK001-AX239-150902-000013
Asset Type:	Vehicle	Transaction Amount:	\$69,850.00
Asset ID:	SHD1262M	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20150902075123968750		

Vehicle No.:	SHD1262M
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	02 Sep 2015
Original Registration Date:	02 Sep 2015
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414MF5621944
Engine No.:	D4FDEH313607
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2015
Open Market Value:	\$21,669.00
Minimum PARF Benefit:	\$13,402.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	02 Sep 2015 07:51:23
COE No.:	2015090201003466H
COE Expiry Date:	01 Sep 2023
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$47,373.00
Lifespan Expiry Date:	01 Sep 2023

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5107202885-001394

Cover : Third Party

- | | |
|---|---------------------------|
| 1. Index mark and Registration Number of Vehicle | : SHD1262M |
| Chassis Number | : KNAGM414MF5621944 |
| 2. Name of Policyholder | : PREMIER TAXIS PTE. LTD. |
| 3. Effective Date of Insurance | : 01 Feb 2019 |
| 4. Expiry Date of Insurance | : 31 Jan 2020 |
| 5. Persons or Classes of Persons entitled to drive* | |
| (a) The Policyholder. | |
| (b) Any licensed taxi driver driving on the Policyholder's order or with his/her permission. | |
| Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. | |
| 6. Limitations as to Use* | |
| (a) Use as a Taxi. | |
| (b) Use for social domestic and pleasure purposes. | |

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
- (b) Use whilst drawing a trailer except the towing (Other than for reward) of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third- Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION I)	: N/A
EXCESS (SECTION II)	: S\$3,500
INSURE WITH COE	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : HL SUNTEK INSURANCE BROKERS PTE LTD (00000690672)
Date of Issue : 01 Feb 2019 09:37 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:



Authorised Officer



Chief Executive

PREMIER TAXIS	HIRER / RELIEF / SUPER RELIEF
VEHICLE NO.	SHD1262M
CONTACT NO.	8876 2717
NEW MAILING ADDRESS (if any)	

REPUBLIC OF SINGAPORE

Service Number: S6926693B

Name: CHIA KOK CHUAN

Birth Date: 28 Aug 1969

Issue Date: 03 Nov 2014

002355982J

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S6926693B



Name

CHIA KOK CHUAN

Race

CHINESE

Date of birth

28-08-1969

Sex

M

Country of birth

SINGAPORE

S6926693B

Land Transport & Authority



VOCATIONAL LICENCE

Licence No. S6926693B

Name CHIA KOK CHUAN

Issue Date: 20/4/2016

Please visit www.lta.gov.sg to check the status of this vocational licence

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

		EFFECTIVE DATE
Class 3	Motor cars <= 2000 kg with <= 7 passengers, exclusive of the driver; and motor tractors/vehicles <= 2500 kg	25 Sep 2014
Class 4	Heavy motor cars and motor tractors > 2500 kg	03 Mar 2015



NRIC No. S6926693B



Date of issue

17-01-2013

APT BLK 636A SENJA ROAD #10-311
SINGAPORE 671636

S6926693B

11/05/2015

S6926693B

S/No 9000217494

NP 428A



This card is not transferable and is the property of the Land Transport Authority (LTA). It must be surrendered to the LTA on request. If found please return to LTA, 10 Sin Ming Drive, Singapore 575701.

Type Description

02 TAXI VL

Issue Date

20/04/2016



PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

27-Feb-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1262 M

1 pc	o/s head lamp	X	\$	1,028.00
1 pc	Front o/s fog lamp cover	X	\$	66.00
1 pc	Front o/s bumper protector	X <i>repair</i>	\$	51.00
1 pc	Front bumper emblem	/	\$	44.00
1 pc	Front bumper	/	\$	531.00
2 pcs	Front bumper n/s & o/s side retainer @\$16.00	<i>n/s x o/s /</i>	\$	32.00
1 pc	Front o/s fender	/	\$	384.00
1 pc	Front o/s fender inner shield	/	\$	120.00
1 pc	Front o/s lower arm	/	\$	439.00
1 pc	Front o/s shock absorber	?	\$	330.00
1 pc	Front o/s ball joint	?	\$	59.00
1 pc	Front o/s tie rod end	?	\$	61.00
1 pc	Front o/s knuckle bearing	?	\$	157.00
1 pc	Front o/s stabilizer link	?	\$	86.00
1 pc	Front o/s knuckle arm	?	\$	547.00
1 pc	Front o/s rim	X	\$	246.00
1 pc	Front o/s wheel cover	/	\$	116.00
			\$	4,297.00
			Less 10%	\$ 429.70
			\$	3,867.30

S/NETT

1 set	Front o/s fender inner shield clips	/	\$	28.00
1 set	Front bumper clips	/	\$	48.00
1 pc	Front o/s fender sticker	X	\$	30.00
1 pc	Tyre	X	\$	200.00

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1262 M

Towing Fee	\$	50.00	/
To check wiring on headlamp	\$	80.00	X
Sundry	\$	50.00	20
To check wheel alignment	\$	80.00	60
To dismantle and replace front o/s undercarriage	\$	250.00	80
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	X
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.	\$	400.00	
To putty and spray painting on front bumper, front o/s fender	\$	500.00	360
To apply rustproofing on the repaired and replaced panels.	\$	180.00	30
	\$	6,393.30	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

К. /на 1uck/

27/2/19 1040h.

4 Days

L/s

After Repairing the

Let's Auto Consultants hence notify the Subscribers of the following:

- To be used only for the purpose of pending
- To be used as a control during recovery
- To be used as a control during recovery
- To be used as a control during recovery
- No file or data should be deleted on a "no-fault" basis
- Support for the system should be provided on a "no-fault" basis

is subject to final approval with the relevant authority.

Acknowledged by Repairer

Signature:

Date:

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG: 200707743D GST REG: 200707743D

27-Feb-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1262 M

1 pc	o/s head lamp	X	see	\$	1,028.00
1 pc	Front o/s fog lamp cover	X	see	\$	66.00
1 pc	Front o/s bumper protector	X	repair	\$	51.00
1 pc	Front bumper emblem	-	see	\$	44.00
1 pc	Front bumper	-	see	\$	531.00
2 pcs	Front bumper n/s & o/s side retainer	@\$16.00	n/s X o/s -	\$	32.00
1 pc	Front o/s fender	-	see	\$	384.00
1 pc	Front o/s fender inner shield	-	see	\$	120.00
1 pc	Front o/s lower arm	-	see	\$	439.00
1 pc	Front o/s shock absorber	-	see	\$	330.00
1 pc	Front o/s ball joint	X	see	\$	59.00
1 pc	Front o/s tie rod end	X	see	\$	61.00
1 pc	Front o/s knuckle bearing	X	see	\$	157.00
1 pc	Front o/s stabilizer link	-	see	\$	86.00
1 pc	Front o/s knuckle arm	X	see	\$	547.00
1 pc	Front o/s rim	X	see	\$	246.00
1 pc	Front o/s wheel cover	-	hanged	\$	116.00
				\$	4,297.00
				Less 10%	\$ 429.70
					\$ 3,867.30

S/NETT

1 set	Front o/s fender inner shield clips	-	see	\$	28.00
1 set	Front bumper clips	-	see	\$	48.00
1 pc	Front o/s fender sticker	X	see	\$	30.00
1 pc	Tyre	X	see	\$	200.00

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1262 M

Towing Fee	\$ 50.00 /
To check wiring on headlamp	\$ 80.00 + 27
Sundry <i>new</i>	\$ 50.00 20
To check wheel alignment	\$ 80.00 60
To dismantle and replace front o/s undercarriage	\$ 250.00 80
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 x 4
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.	\$ 850.00 400
To putty and spray painting on front bumper, front o/s fender	\$ 500.00 360
To apply rustproofing on the repaired and replaced panels.	\$ 180.00 30
	<u>\$ 6,393.30</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

7392.30

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Ka/ha 100%

27/2/19 1040h.

4 Days

L/s

After Repair photo

7/3/19

chd 4/5 \$3100 / 4/12

By signing this estimate, hence notify the repairer of the following:

- I have read and understood the estimate.
- The repairer has advised me of the extent of the damage and the estimated cost of repair.
- The repairer has advised me of the estimated time for completion of the repair.
- The repairer has advised me of the estimated cost of the repair.
- The repairer has advised me of the estimated cost of the repair.
- The repairer has advised me of the estimated cost of the repair.

Acknowledged by Repairer

Signature: _____

Date: _____

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

27-Feb-19

SUPPLEMENTARY ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1262 M

1 pc	Front o/s drive shaft @ \$971.00	✓	Int	\$	971.00
1 pc	Front o/s insulator assy strut @ \$105.00	✓	Int	\$	105.00
1 pc	Front o/s strut bearing @ \$34.00	✓	Int	\$	34.00
				\$	1,110.00
				Less 10%	\$ 111.00
				\$	999.00

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT
INCLUDE ANY UNFORESEEN DAMAGES.





Victory Recovery (Business Reg No.: 53096358B)

65 Teban Gardens Rd #23-617, Singapore 600065.

Mobile: 9618 0311 Fax: 6267 8996

CASH /
W.O. No. 99225

TOW JOB WORKS ORDER

M Premier Taxi Svc Date 27/2/19
Car Make/Model Kia Vehicle No. SHD 1262 M
M'ship/NRIC No./Card No. _____ Contact No. _____
Time - Rec'd 8 20 Arrived 8 50 Completed 9 40
Amount Charge S\$ _____ Tow Truck No YN 3661
Destination (from) Senja Rd (to) 23 May (LI)
Remark (if any) ERP \$2

Tow Driver's Signature _____ Member's Signature 2nd

- | | | |
|---|--|--|
| ☐ Change Tyres & Towing | ☐ Using King Dolley | ☐ Use Car Carrier |
| ☐ Basement / Multi Carpark | ☐ Low Spoiler / Low Oil Sump | ☐ Release Brake / Shaft |
| ☐ Causeway / 2nd Link | ☒ Accident / Over-turn | ☐ Loaded |

Note : The owner or his representative is required to follow along to the towing destination, failing which the tow operator shall not be liable for any alleged damages to the car nor missing items from the same. Vehicle is towed at owner's risk. The tow operator accepts no responsibility for any damages to the owner's vehicle whilst being towed.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI19003766/K1ha3n2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 27-09-2019		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMG 8762R	Veh. Inspected	SHD 1262M	
Policy No.	DMPCSN3014301800	Coverage (\$)	0.00	
Claim No.	SNM19D201003C02/2	Excess (\$)	0.00	
Assign From		Assign Date	27/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KNAGM414MF5621944	Colour	SILVER	
Odometer	363494	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	ACHILLES	6 mm	
L/H Front Tyre	205/65 R16	ACHILLES	6 mm	
R/H Rear Tyre	205/65 R16	ACHILLES	6 mm	
L/H Rear Tyre	205/65 R16	ACHILLES	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/02/2019	Inspection Date	27/02/2019	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1262M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	O/S HEAD LAMP	SERVICEABLE	1,028.00	-
1	FRONT O/S FOG LAMP COVER	SERVICEABLE	66.00	-
1	FRONT O/S BUMPER PROTECTOR	TO REPAIR SEE LABOUR	51.00	-
1	FRONT BUMPER EMBLEM	NECESSARY	44.00	44.00
1	FRONT BUMPER	DEFORMED	531.00	531.00
2	FRONT BUMPER N/S & O/S SIDE RETAINER @\$16.00	O/S CRACKED / N/S SERVICEABLE	32.00	16.00
1	FRONT O/S FENDER	DENTED	384.00	384.00
1	FRONT O/S FENDER INNER SHIELD	TORN	120.00	120.00
1	FRONT O/S LOWER ARM	BENT	439.00	439.00
1	FRONT O/S SHOCK ABSORBER	BENT	330.00	330.00
1	FRONT O/S BALL JOINT	SERVICEABLE	59.00	-
1	FRONT O/S TIE ROD END	SERVICEABLE	61.00	-
1	FRONT O/S KNUCKLE BEARING	SERVICEABLE	157.00	-
1	FRONT O/S STABILIZER LINK	BENT	86.00	86.00
1	FRONT O/S KNUCKLE ARM	SERVICEABLE	547.00	-
1	FRONT O/S RIM	SERVICEABLE	246.00	-
1	FRONT O/S WHEEL COVER	GRAZED	116.00	116.00
1	FRONT O/S DRIVE SHAFT (ADDITIONAL)	BENT	971.00	971.00
1	FRONT O/S INSULATOR ASSY STRUT (ADDITIONAL)	BENT	105.00	105.00
1	FRONT O/S STRUT BEARING (ADDITIONAL)	BENT	34.00	34.00
	LESS 10% DISCOUNT		-540.70	-317.60
			4,866.30	2,858.40
SPECIAL NETT ITEMS				
1	SET FRONT O/S FENDER INNER SHIELD CLIPS (SN)	NECESSARY	28.00	28.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	FRONT O/S FENDER STICKER (SN)	NOT NECESSARY	30.00	-
1	TYRE (SN)	SERVICEABLE	200.00	-
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			356.00	96.00

Report Ref No. CC3/CTI19003766/K1ha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TOWING FEE.		50.00	50.00
	TO CHECK WIRING ON HEADLAMP.	NOT NECESSARY	80.00	-
	TO CHECK WHEEL ALIGNMENT.		80.00	60.00
	TO DISMANTLE AND REPLACE FRONT O/S UNDERCARRIAGE.		250.00	80.00
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS, INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE SAME, ETC. INCLUSIVE OF THE REPAIR OF FRONT O/S BUMPER PROTECTOR.		850.00	400.00
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER, FRONT O/S FENDER.		500.00	360.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		180.00	30.00
			2,170.00	980.00
	GRAND TOTAL		7,392.30	3,934.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,100.00

Report Ref No. CC3/CT19003766/K1ha3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.