

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

27-Feb-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1262 M

		\$	1,028.00
1 pc	o/s head lamp X	\$	66.00
1 pc	Front o/s fog lamp cover X	\$	51.00
1 pc	Front o/s bumper protector X repair	\$	44.00
1 pc	Front bumper emblem	\$	531.00
1 pc	Front bumper	\$	32.00
2 pcs	Front bumper n/s & o/s side retainer @\$16.00 n/s x o/s	\$	384.00
1 pc	Front o/s fender	\$	120.00
1 pc	Front o/s fender inner shield	\$	439.00
1 pc	Front o/s lower arm	\$	330.00
1 pc	Front o/s shock absorber ?	\$	59.00
1 pc	Front o/s ball joint ?	\$	61.00
1 pc	Front o/s tie rod end ?	\$	157.00
1 pc	Front o/s knuckle bearing ?	\$	86.00
1 pc	Front o/s stabilizer link ?	\$	547.00
1 pc	Front o/s knuckle arm ?	\$	246.00
1 pc	Front o/s rim X	\$	116.00
1 pc	Front o/s wheel cover	\$	4,297.00
		\$	429.70
	Less 10%	\$	3,867.30

S/NETT

1 set	Front o/s fender inner shield clips	\$	28.00
1 set	Front bumper clips	\$	48.00
1 pc	Front o/s fender sticker X	\$	30.00
1 pc	Tyre X	\$	200.00

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1262 M

Towing Fee	\$ 50.00	/
To check wiring on headlamp	\$ 80.00	X
Sundry	\$ 50.00	20
To check wheel alignment	\$ 80.00	60
To dismantle and replace front o/s undercarriage	\$ 250.00	80
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00	X
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.	\$ 850.00	400
To putty and spray painting on front bumper, front o/s fender	\$ 500.00	360
To apply rustproofing on the repaired and replaced panels.	\$ 180.00	30
	<u>\$ 6,393.30</u>	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

1 Call / 1 UCA
 27/2/19 1040h.
 4 Days
 L/s
 After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



Victory Recovery (Business Reg No.: 53096358B)
65 Teban Gardens Rd #23-617, Singapore 600065.
Mobile: 9618 0311 Fax: 6267 8996

CASH /
W.O. No. 99225

TOW JOB WORKS ORDER

M Premier Taxi Svc Date 27/2/19
Car Make/Model Kia Vehicle No. SHD 1262M
M'ship/NRIC No./Card No. _____ Contact No. _____
Time - Rec'd 8 20 Arrived 8 50 Completed 9 40
Amount Charge S\$ _____ Tow Truck No YH 3661
Destination (from) Senja Rd (to) 23 Changi (CL)
Remark (if any) ERP \$2
Tow Driver's Signature _____ Member's Signature 2nd

- | | | |
|---|--|--|
| <input type="checkbox"/> Change Tyres & Towing | <input type="checkbox"/> Using King Dolley | <input type="checkbox"/> Use Car Carrier |
| <input type="checkbox"/> Basement / Multi Carpark | <input type="checkbox"/> Low Spoiler / Low Oil Sump | <input type="checkbox"/> Release Brake / Shaft |
| <input type="checkbox"/> Causeway / 2nd Link | <input checked="" type="checkbox"/> Accident / Over-turn | <input type="checkbox"/> Loaded |

Note : The owner or his representative is required to follow along to the towing destination, failing which the tow operator shall not be liable for any alleged damages to the car nor missing items from the same. Vehicle is towed at owner's risk. The tow operator accepts no responsibility for any damages to the owner's vehicle whilst being towed.