

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 1713U

DATE 27/2/2019 11:00

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille /			\$ 1,110.10
	Front Bumper Cover X-Hpr /			\$ 1,052.20
	Front Bumper Bracket Top (LH/RH) X	\$	22.40	\$ 44.80
	Front Bumper Bracket (LH/RH) X	\$	24.60	\$ 49.20
	1090 /			\$ 39.50
	SUB TOTAL			\$ 2,256.30
	LESS 20%			\$ 451.26
	DISCOUNTED TOTAL			\$ 1,805.04
	Labour Charge			
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 300.00
	TOTAL LABOUR			\$ 700.00
	ESTIMATE TOTAL			\$ 2,505.04
<p>Kahar (UCC)</p> <p>27/2/19 1400h</p> <p>2h</p> <p>P/P</p> <p>Adh Rep p 44</p> <div data-bbox="925 1428 1396 1806"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary items must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> </div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				