



320 UBI ROAD 3 SINGAPORE 408649

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TPVehicle No. : YP6263MMake & Model : HINO FD7JLMA-HASYear of Manufacture : 2016Chassis No. : FD7JLM11583Ins Company : AXAEngine No. : J07ETP14155

Excess : _____

Policy No. : _____

Date of Accident : 08-Jan-19Time of Accident : 17:00

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimates**Case Owner : JOHARI /CK

Signature : _____

Parts (a) Cost / List Price Items \$5,000.00Plus/Less 10% \$500.00Total of Cost / List \$5,500.00

(b) Nett Price Items _____

Less _____

Total of Nett Item _____

(c) Special Nett Items _____

Total Parts Cost (Appendix A) _____**Labour (Appendix B)** _____**Total Repair Cost** \$5,500.00

Contact No
6848 5726 - Jasmine Chng
Ubi_cr@sparkcarcare.com

The above total will be subjected to 7% G.S.T.

Name of Surveyor : _____

Company : _____

Survey conducted on : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Rd S(579701)
Tel: 6383362/63837102 Fax: 62815767

9228 5918 zu Johari

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

PAGE 1

COST / LIST

VEHICLE NO.: **YP6263M**
MAKE: **HINO FD7JLMA-HAS**
MODEL:
YEAR OF MAKE: **2016**
CHASSIS NO.: **FD7JLM11583**

S/N	Parts Description	PART NUMBER	Qty	Remarks	
				COST	LIST
1	TO SUPPLY & REPLACE (01) TAILGATE				
2	ALUMINIUM PLATFORM				
3					
4					
5	TO SUPPLY LABOUR TO RE-ALIGN TAILGATE	(Labar) /		\$5,000	
7					
8	TO SUPPLY & REWRAP REAR CARGO BOX	(Labar) Repair			
9					
10	MARK UP ON COST 10%			\$500	
11					
12	TOTAL:			\$5,500.00	
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					
24					
25					
26					
27					
28					
29					
30					

Star (LKK) with inspection 21/3/19 5.30pm
8372 8813 5 days
P/P
R- before spray

VEHICLE NO.: **YP6263M**