

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLM5677D/1902031

28th February 2019

The Manager
Motor Claim Department
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Acknowledged
date
1/3/19
Took photo before repair.
4 days.
P/O # 3324.91

Date of Accident : 12th February 2019
Location : Along Sixth Avenue Towards Holland Road
Third Party Claim Vehicle No : SJP 3663 R
Repair Cost For Vehicle No : SLM 5677 D Nissan X-Trail

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Rear boot cover (net)	1	4200.00	\$ 4200.00 X
2	Rear boot cover emblem (X-Trail) (net)	1	101.30	\$ 101.30 ✓
3	Rear boot cover emblem (logo) (net)	1	73.60	\$ 73.60 ✓
4	Rear windscreen moulding (net)	1	98.00	\$ 98.00 X
5	Rear bumper fascia (net)	1	660.50	\$ 660.50 ✓
6	Rear bumper clips (net)	1 set	26.00	\$ 26.00 ✓
7	Rear bumper bracket L&RH (net)	2	174.80	\$ 349.60 ✓
8	Rear bumper sponge (net)	1	162.40	\$ 162.40 X
9	Rear bumper side retainer L&RH (net)	2	52.60	\$ 105.20 ✓
10	Rear end panel (net)	1	554.70	\$ 554.70 X
Rear bumper reinforcement. Ref -				\$
Less			10%	\$
				\$
11	Rear bumper sensor (s/net) 4200	1	380.00	\$ 380.00 250
12	Rear windscreen sealant (s/net)	1	80.00	\$ 80.00 X
13	Rear end panel sealer (s/net)	1	80.00	\$ 80.00 X
				\$ 2,836.17

P-1549.90
102
1394.91

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLM5677D/1902031

28th February 2019

Balance b/f \$2,836.17

Labour Charges :-

	<u>Amounts</u>
Cut out, renew, knocking & welding rear boot cover, rear end panel, remove & install all damage parts, straighten & re-align body	\$ 980.00 800
Remove & install rear windscreen glass	17 \$ 140.00 X
Remove & refix rear bumper sensor	\$ 80.00 50
Tuff-kote on damage parts	11 \$ 80.00 X
Spray painting on damage parts	\$ 1,280.00 800
Check all lighting after repairs	\$ 35.00 30
Labour Charge	\$ 2,595.00
Total Amount	\$ 1 1680

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

3324.91

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLM5677D/1902031

28th February 2019

The Manager
Motor Claim Department
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

Date of Accident : 12th February 2019
Location : Along Sixth Avenue Towards Holland Road
Third Party Claim Vehicle No : SJP 3663 R
Repair Cost For Vehicle No : SLM 5677 D Nissan X-Trail

Supplementary Supply of Parts

<u>No.</u>	<u>Particulars</u>	<u>Qty</u>	<u>Price</u>	<u>Amounts</u>
1	Rear bumper reinforcement	<i>Ref</i> 1	583.30	\$ 583.30 ✓
				\$ 583.30
		Less	10%	\$ 58.33
				<u>\$ 524.97</u>

GST will be reflected in the final bills.