

2000000

ASS. REC. BY:

RIFF CS/CTI 19003785/Kg d3/9

Action/Instruction:

Surveyed

ASSIGNMENT (Office)

Meimen

Ong chin kiat

of CTI

Date/Time: 28/1/19 @ 1:46pm

Estimated Cost:

Bill to

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CG

To Inspect Vehicle No:

GBF 96022

Insured:

SJL 8180D

at Workshop info:

Tong Luck Auto

Tel:

62500088

of

160 Sim Ming Drive # 07-01

Policy No:

DMPCS N12272618066

Claim No:

SNM19D 200397 C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/01/2019

11319

I.L.O.D. Performance:

CA / REV / REP. / REV 24 HRS

Date/Time:

2:17pm 28/1/19

Person Contacted:

Cendy

Vehicle: INJ / OHT

Date/Time	Action/Instruction
	(✓) Estimate
	GBF 96022 - CCG / AIG 19001366 / Acc 3
	SJL 8180D - X
2/4	58070.50 Confirmed by email (Ref to 5037250, 38%)

REF: CTI

ASSIGNMENT

From: Date: 01/03/19

Yr No: GBF 96022 Yr Regn: 05 17
Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GBF 96022
at Workshop no: Tong Luck
of: 160 Sin Ming Drive #07-01

Truck / Trailer or
Make: Mercedes Vito CC: 1598
Colour: Red A/C: Insured / Std / Nil / NA
Sp Reading: 64895 T/Fade: Insured / Std / Nil / NA
Eng/No:
ChNo: WDF 44760323272799

Insured:
Policy No: 37787


Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inoperative / Jammed / Leaked / Burnt or
Brake: Inoperative / Jammed / Leaked / Burnt or

Claims No:
Sum Insured:
(Client's Record)

Modi: Nil / S/Rim / STD A/Rim or
Tyrn Size: F: Yokohama 205/65R16
R: Michelin

Make of Veh:

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Bal. or Market Value:

Front: R/Bal: 9 mm L/Bal: 9 mm D.O.A: 2/1/1/19
Rear: R/Bal: 9 mm L/Bal: 9 mm D.O.A: 1/3/1/9

IDAC Accident Report: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: 06 days Rea: Yes or No

Lum Sum: 13.1 % 3 Val: Yes or No

Survey held at:
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
& 1st

CA / REV / REP. / 24 HRS (wp)

Vehicle: IN / OUT

Date: Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

RECEIVED 08 APR 2019

Case/Time: File Pass to/

: Prol. Report
 : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Date/Time: File Return to/

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech Insp (\$)
 Wheeland (\$)

Interpretation:

Report Format:

MER-7P

Lump Sum (L.B.): (\$)

8070.50

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Feb 2019		28 Feb 2019 13:46 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	TEO EE TONG, ID: S7146415F								
Main Claimant:	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD., Co. Reg. No.: 199803778Z								
Vehicle Reg. No.:	GBF9602Z	Date of Loss:	21/01/2019 08:00 - :59 [20 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D200397C02	Policy/Cover Note No.:	DMPCSN12272618066 (Comprehensive) Coverage: 12/12/2018 - 11/12/2019						
Vehicle Reg. No. (Insured):	SJL8180D	Policy No. (Claimant):	999995580						
		Excess:	S\$0.00						
Repairer:	Tong Luck Auto Pte Ltd (HQ) 160 Sin Ming Drive, #07-01 Sin Ming AutoCity, 575722 Sin Ming - Tel: 6250 0088								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 11/03/2019]								
Driver/Custodian (Insured):	TEO EE TONG (47 / Male) , NRIC: S7146415F Email:								
Adj Asp. Remarks:	please assign Kenneth kong for SJE. thank you								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/01/2019 20:36
Date Of Accident	21/01/2019 08:00
Exact Location Of Accident	WEST COAST HIGHWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF9602Z
Insured/Policyholder	
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.
Co Reg No	199803778Z
Email Address	FAIZAL.MOHAMED@DAIMLER.COM
Mobile Phone No	
Alternative Phone No	OFFICE-68498118

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	VITO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995580
Cover Note Number	N.A.

Driver

Name of Driver	ALKHANSA' BINTE AHZAMSHAH
NRIC No	S9708098D
Date Of Birth	04/03/1997
Occupation	INDOOR
Date Of Driving Pass	29/12/2017
Driving Experience	1 YEAR AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-83991403
Fax Number	
Contact Number	OFFICE-83991403
EMail Address	NOEMAIL

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	FM8673R
Vehicle Make/Model/Colour	SUZUKI/VS400GLR
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SGJ6748B
Vehicle Make/Model/Colour	NISSAN/LATIO 1.5L T_
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

ACCIDENT STATEMENT (2000 characters)

I was travelling on west coast highway towards Jalan Buroh. I was at third lane when this motorbike FM8673R tried to do illegal left turn. When this vehicle SGJ6748B jammed braked, I managed to react to brake on time when vehicle SJL8180D couldn't braked on time and hit my rear portion of my vehicle and my vehicle move forward and hit the rear of the front vehicle. Damages to my car were in the front and back portion. No injuries were involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MUHAMMAD FIRZA BIN IDERIS

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

28 January 2019 at 4:57 PM

Date/Time:

28 January 2019 at 4:57 PM



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SJL8180D/SGJ6748B/FM8673R

CLAIM TYPE : THIRD PARTY

TP INS. CO. : CHINA TAIPING INSURANCE (SINGAPORE) PTE

ACCIDENT DATE : 21/01/2019

TP VEH REG NO : SJL8180D

ESTIMATE

NO : QUOT201902-000076(00)

DATE : 27/02/2019

POLICY NO : 999995580

VEH REG NO : GBF9602Z

MAKE/MODEL : MERCEDES BENZ VITO 109
CDI MT LONG

CHASSIS NO : R9MA503C016413

ENGINE NO : WDF44760323272799

REG. DATE : 2017

Not Authorised
U1 Long B?
Return After Paint

below

Estimate Repair Cost to Vehicle No : GBF9602Z

Description	Quantity	Unit Price	Amount
		SG	SG
LIST PRICE			
1 Support panel	1	380.00	R 380.00 TX
2 Support panel top garnish	1	92.00	92.00 TX
3 Support panel top garnish clips	10	9.00	90.00 TX
4 Headlamp assy - LH/RH	2	685.00	1,370.00 L
5 Front bumper	1	750.00	Bu 750.00 ✓
6 Front bumper centre logo	1	135.00	CM 135.00 ✓
7 Front bumper reinforcement	1	595.00	Bu 595.00 ✓
8 Front bumper side retainer - RH	1	45.00	bu 45.00 X
9 Front bumper clips	15	9.00	bu 135.00 ✓
10 Front fender - RH	1	695.00	N-C (Bu) 695.00 X
11 Front fender inner shield - RH	1	158.00	bu 158.00 X
12 Front fender inner shield clips	10	9.00	bu 90.00 X
13 Tailgate	1	2,250.00	Bu 2,250.00 ✓
14 Tailgate lock	1	250.00	bu 250.00 ✓
15 Tailgate trimboard clips	8	9.00	bu 72.00 ✓
16 Tailgate centre logo	1	45.00	bu 45.00 ✓
17 Rear end panel (outer)	1	290.00	R 290.00 TX
18 Rear bumper	1	1,240.00	Bu 1,240.00 ✓
19 Rear bumper reflector - RH	1	38.00	bu 38.00 ✓
			8,720.00
			Less 10%
			872.00
			7,848.00
SPECIAL NET			
20 Front number plate	1	40.00	Bu 40.00 ✓
21 Rear windscreen sealant	1	60.00	bu 60.00 40.00
22 Tailgate '70km/h' sticker	1	25.00	bu 25.00 15.00
23 Rear bumper sensor	1	350.00	CM 350.00 200.00
24 Rear number plate	1	40.00	bu 40.00 X
25 Air-con gas	1	55.00	bu 55.00 TX
			570.00
LABOUR			
26 To remove and refit rear windscreen glass	1	150.00	150.00 120.00
27 To check and rectify wiring system	1	80.00	80.00 40.00

LTA Auto Consultants hence notify the Repairer of the following:

- To remove before/after every painting
- To display damaged part(s) during recovery
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No direct modification is allowed
- Supplementary items must be recovered and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature: _____
Date: _____



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SJL8180D/SGJ6748B/FM8673R

CLAIM TYPE : THIRD PARTY

TP INS. CO. : CHINA TAIPING INSURANCE (SINGAPORE) PTE

ACCIDENT DATE : 21/01/2019

TP VEH REG NO : SJL8180D

ESTIMATE

NO : QUOT201902-000076(00)

DATE : 27/02/2019

POLICY NO : 999995580

VEH REG NO : **GBF9602Z**

MAKE/MODEL : MERCEDES BENZ VITO 109
CDI MT LONG

CHASSIS NO : R9MA503C016413

ENGINE NO : WDF44760323272799

REG. DATE : 2017

Estimate Repair Cost to Vehicle No : GBF9602Z

Description	Quantity	Unit Price	Amount
		S\$	S\$
28 To transfer damaged tailgate interior mechanism to new tailgate	1	160.00	160.00
29 To remove and refix air-con condenser, pipes and radiator assy	1	120.00	120.00
30 To panel beat and straighten front chassis frame, RH front fender inner panel, rear floorboard panel, rear chassis frame, to cut and weld rear end panel including replacement of parts and align where necessary, to refit and adjust the same	1	1,500.00	1,500.00
31 To putty and spray same on affected areas	1	1,000.00	1,000.00
32 To apply rust proofing on repaired and replaced panels	1	180.00	180.00
33 To supply art work and paste logos and letterings on tailgate and RH front fender (3M)	1	(Bill) 1,500.00	1,500.00
			4,690.00
		TOTAL	S\$ 13,108.00
		ADD GST @ 7%	917.56
		GRAND TOTAL	S\$ 14,025.56

SINGAPORE DOLLAR FOURTEEN THOUSAND TWENTY-FIVE AND CENTS FIFTY-SIX ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SJL8180D/SGJ6748B/FM8673R

CLAIM TYPE : THIRD PARTY

TP INS. CO. : CHINA TAIPING INSURANCE (SINGAPORE) PTE

ACCIDENT DATE : 21/01/2019

TP VEH REG NO : SJL8180D

ESTIMATE

NO : QUOT201902-000076(00)

DATE : 27/02/2019

POLICY NO : 999995580

VEH REG NO : GBF9602Z

MAKE/MODEL : MERCEDES BENZ VITO 109
CDI MT LONG

CHASSIS NO : R9MA503C016413

ENGINE NO : WDF44760323272799

REG. DATE : 2017

Not Notarised

tt loop 8?

Return After Paint

1/3/19 @ 1100 hrs.

6 days

Estimate Repair Cost to Vehicle No : GBF9602Z

Description	Quantity	Unit Price	Amount
		S\$	S\$
LIST PRICE			
1 Support-panel	1	380.00	380.00
2 Support-panel-top-garnish	1	92.00	92.00
3 Support-panel-top-garnish-clips	10	9.00	90.00
4 Headlamp assy - LH/BHf	2	685.00	1,370.00
5 Front bumper	1	750.00	750.00
6 Front bumper centre logo	1	135.00	135.00
7 Front bumper reinforcement	1	595.00	595.00
8 Front bumper-side-retainer-RH	1	45.00	45.00
9 Front bumper clips	15	9.00	135.00
10 Front-fender-RH	1	695.00	695.00
11 Front-fender-inner-shield-RH	1	158.00	158.00
12 Front-fender-inner-shield-clips	10	9.00	90.00
13 Tailgate	1	2,250.00	2,250.00
14 Tailgate lock	1	250.00	250.00
15 Tailgate trimboard clips	8	9.00	72.00
16 Tailgate centre logo	1	45.00	45.00
17 Rear-end-panel-(outer)	1	290.00	290.00
18 Rear bumper	1	1,240.00	1,240.00
19 Rear bumper reflector - RH	1	38.00	38.00
			8,720.00
		Less 10%	872.00
			7,848.00
SPECIAL NET			
20 Front number plate	1	40.00	40.00
21 Rear windscreen sealant	1	60.00	60.00
22 Tailgate '70km/h' sticker	1	25.00	25.00
23 Rear bumper sensor	1	350.00	350.00
24 Rear-number-plate	1	40.00	40.00
25 Air-con-gas	1	55.00	55.00
			570.00
LABOUR			
26 To remove and refit rear windscreen glass	1	150.00	150.00
27 To check and rectify wiring system	1	80.00	80.00

6,195.00
-10%
619.50

5,575.50

1201
401



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD
1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118 FAX :
ATTN : ACCOUNTS DEPT

YOUR REF NO : SJL8180D/SGJ6748B/FM8673R
CLAIM TYPE : THIRD PARTY
TP INS. CO. : CHINA TAIPING INSURANCE (SINGAPORE) PTE
ACCIDENT DATE : 21/01/2019
TP VEH REG NO : SJL8180D

ESTIMATE

NO : QUOT201902-000076(00)
DATE : 27/02/2019
POLICY NO : 999995580
VEH REG NO : GBF9602Z
MAKE/MODEL : MERCEDES BENZ VITO 109
CDI MT LONG
CHASSIS NO : R9MA503C016413
ENGINE NO : WDF44760323272799
REG. DATE : 2017

Estimate Repair Cost to Vehicle No : GBF9602Z

Description	Quantity	Unit Price	Amount
		S\$	S\$
28 To transfer damaged tailgate interior mechanism to new tailgate	1	160.00	160.00
29 To remove and refix air-con-condenser, pipes and radiator-assy	1	120.00	120.00
30 To panel beat and straighten front chassis frame, RH front fender inner panel, rear floorboard panel, rear chassis frame, to cut and weld rear end panel including replacement of parts and align where necessary, to refit and adjust the same	1	1,500.00	1,500.00
31 To putty and spray same on affected areas	1	1,000.00	1,000.00
32 To apply rust proofing on repaired and replaced panels (end panel)	1	180.00	180.00
33 To supply art work and paste logos and letterings on tailgate and RH front fender (3M)	1	1,500.00	1,500.00
			4,690.00
		TOTAL	S\$ 13,108.00
		ADD GST @ 7%	917.56
		GRAND TOTAL	S\$ 14,025.56

SINGAPORE DOLLAR FOURTEEN THOUSAND TWENTY-FIVE AND CENTS FIFTY-SIX ONLY

~~8,140.50~~ 8070.50
 7% 569.83

 8,710.33.

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

JE-GRAPHICS PTE LTD

48 Toh Guan Road East
#08-123 EnterpriseHub
Singapore 608586
Tel: 6316-7246 Fax: 6316-7248
E-MAIL: sales@jegraphics.com.sg
GST REG NO.: 200504725D
CO REG NO.: 200504725D

TO: TONG LUCK AUTO PTE LTD

TAX INVOICE : 20191153

DATE : 12/03/2019
P/O :
D/O :
TERMS : CASH
SALESMAN CODE : YN
PAGE NO. : 001

ATTN : Terence Tan
TEL/FAX : 9623 5378

NO.	DESCRIPTION	QTY UOM	UNIT-PRICE	AMOUNT
			SGD	SGD
	To supply art work & paste sticker & lettering on tailgate (3M)	1 UNIT	680.00	680.00

Vehicle No: GBF96022

SUB-TOTAL 680.00

ADD 7.00% GST 47.60
TOTAL 727.60

SINGAPORE DOLLARS: SEVEN HUNDRED TWENTY-SEVEN & CENTS SIXTY ONLY

Cheque should be crossed and made payable to JE-GRAPHICS PTE LTD. 1.5% interest shall be charged for all overdue invoices. Discrepancies if any, should be verified within 7 days from date hereof. Deposit are not refundable & transferable.

JE-GRAPHICS PTE LT

E. & O.E

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Feb 2019		28 Feb 2019 13:46 Edit Adj Rpt	S\$8,070.50 Edit Estimates	S\$8,070.50 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	TEO EE TONG, ID: S7146415F								
Main Claimant:	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD., Co. Reg. No.: 199803778Z								
Vehicle Reg. No.:	GBF9602Z	Date of Loss:	21/01/2019 08:00 - :59 [20 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D200397C02	Policy/Cover Note No.:	DMPCSN12272618066 (Comprehensive) Coverage: 12/12/2018 - 11/12/2019						
Vehicle Reg. No. (Insured):	SJL8180D	Policy No. (Claimant):	999995580						
		Excess:	S\$0.00						
Repairer:	Tong Luck Auto Pte Ltd (HQ) 160 Sin Ming Drive, #07-01 Sin Ming AutoCity, 575722 Sin Ming - Tel: 6250 0088								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 11/03/2019]								
Driver/Custodian (Insured):	TEO EE TONG (47 / Male) , NRIC: S7146415F Email:								
Adj Asg. Remarks:	please assign Kenneth kong for SJE. thank you								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBF9602Z (SNM19D200397C02)
[SJL8180D]

TP

DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.

Jan 21 2019 8:00AM

[TEO EE TONG]

Tong Luck Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter			View	View in Browser
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	29/01/19 20:49	Accident Statement	 Load HTM	
2	06/02/19 05:03	Addendum Sheet	 Load JPG	<input checked="" type="checkbox"/>
3	06/02/19 05:06	Accident Statement Addm. #1	 Load HTM	
4	27/02/19 10:44	Addendum Sheet	 Load TIF	
5	27/02/19 10:47	Accident Statement Addm. #2	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
2	08/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
3	08/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
4	08/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
5	08/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
6	08/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
7	08/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
8	08/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
9	08/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
10	08/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
11	08/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
12	08/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
13	08/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
14	08/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
15	08/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
16	08/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
17	08/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
18	08/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
19	08/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
20	08/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
21	08/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
22	08/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
23	08/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
24	08/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
25	08/04/19 10:17	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
26	08/04/19 10:17	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
27	08/04/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
28	08/04/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
29	08/04/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	08/04/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
31	08/04/19 10:21	Reinspection Photo		<input checked="" type="checkbox"/>
32	08/04/19 10:21	Reinspection Photo		<input checked="" type="checkbox"/>
33	08/04/19 10:21	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/02/19 13:32	PRS email		<input type="checkbox"/>
2	28/02/19 13:32	insd gia report		<input type="checkbox"/>

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	29/01/19 20:49	Accident Statement		<input type="checkbox"/>
2	06/02/19 05:03	Addendum Sheet		<input checked="" type="checkbox"/>
3	06/02/19 05:06	Accident Statement Addm. #1		<input type="checkbox"/>
4	27/02/19 10:44	Addendum Sheet		<input type="checkbox"/>
5	27/02/19 10:47	Accident Statement Addm. #2		<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	06/02/19 05:03	Accident Photo		<input checked="" type="checkbox"/>
2	06/02/19 05:03	Accident Photo		<input checked="" type="checkbox"/>
3	06/02/19 05:03	Accident Photo		<input checked="" type="checkbox"/>
4	06/02/19 05:03	Accident Photo		<input checked="" type="checkbox"/>
5	06/02/19 05:03	Accident Photo		<input checked="" type="checkbox"/>
6	06/02/19 05:03	Accident Photo		<input checked="" type="checkbox"/>
7	06/02/19 05:03	Accident Photo		<input checked="" type="checkbox"/>
8	06/02/19 05:03	Accident Photo		<input checked="" type="checkbox"/>
9	06/02/19 05:03	Accident Photo		<input checked="" type="checkbox"/>
10	06/02/19 05:03	Accident Photo		<input checked="" type="checkbox"/>
11	06/02/19 05:03	Accident Photo		<input checked="" type="checkbox"/>
12	06/02/19 05:03	Accident Photo		<input checked="" type="checkbox"/>
13	06/02/19 05:03	Accident Photo		<input checked="" type="checkbox"/>
14	06/02/19 05:03	Accident Photo		<input checked="" type="checkbox"/>
15	06/02/19 05:03	Accident Photo		<input checked="" type="checkbox"/>
16	06/02/19 05:03	Accident Photo		<input checked="" type="checkbox"/>
17	06/02/19 05:03	Accident Photo		<input checked="" type="checkbox"/>
18	06/02/19 05:03	Accident Photo		<input checked="" type="checkbox"/>
19	06/02/19 05:03	Driving License		<input checked="" type="checkbox"/>
20	06/02/19 05:03	Driving License		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	29/01/19 20:46	Sketch Plan		<input checked="" type="checkbox"/>
2	29/01/19 20:46	Common Statement		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)



Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119003788/KQD3Q2

Date: 10/04/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN12272618066
 Claimant Vehicle No: GBF9602Z Insured Vehicle No: SJL8180D
 Date of Loss: 21/01/2019 Nature of Claim: TP Claim No: SNM19D200397C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF9602Z**
 Make & Model: MERCEDES-BENZ VITO 109, 1.6 CDI LONG (M) Engine No: R9MA503C016413
 Reg. Date: 02/05/2017 (Man. Year: 2017) Chassis No: WDF44760323272799
 Colour: Red Odometer: 44695 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R16 Rear Tyre Size: 205/65 R16
 Front Left Side: Yokohama 9 mm Rear Left Side: Michelin 9 mm
 Front Right Side: Yokohama 9 mm Rear Right Side: Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,418.00	5,870.50	2,547.50	30.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,690.00	2,200.00	2,490.00	53.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,108.00	8,070.50	5,037.50	38.43
+ GST 7.00/7.00% (S\$)	917.56	564.94	352.62	38.43
Nett Amount (S\$)	14,025.56	8,635.44	5,390.12	38.43

INSPECTION

Date of Assignment: 28/02/2019
 Date Inspected: 01/03/2019 Inspected At: Tong Luck Auto Pte Ltd (HQ)
 160 Sin Ming Drive, #07-01 Sin Ming
 AutoCity
 Singapore 575722
 Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 10 Apr 2019)	
Parts:	N/A	MERCEDES-BENZ VITO 109 1.6 CDI LONG (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF9602Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUPPORT PANEL	Repair	380.00 FL	*- FL
2	1		*SUPPORT PANEL TOP GARNISH	Serviceable	92.00 FL	*- FL
3	10		*SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	90.00 FL	*- FL
4	1		*HEADLAMP ASSY -LH/RH	N/S Cracked	1,370.00 FL	*685.00 FL
5	1		*FRONT BUMPER	Bent	750.00 FL	*750.00 FL
6	1		*FRONT BUMPER CENTRE LOGO	Cracked	135.00 FL	*135.00 FL
7	1		*FRONT BUMPER REINFORCEMENT	Buckled	595.00 FL	*595.00 FL
8	1		*FRONT BUMPER SIDE RETAINER -RH	Serviceable	45.00 FL	*- FL
9	15		*FRONT BUMPER CLIPS	Necessary	135.00 FL	*135.00 FL
10	1		*FRONT FENDER -RH (BENT)	Not Consistent With The Impact	695.00 FL	*- FL
11	1		*FRONT FENDER INNER SHIELD -RH	Serviceable	158.00 FL	*- FL
12	10		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	90.00 FL	*- FL
13	1		*TAILGATE	Bent	2,250.00 FL	*2,250.00 FL
14	1		*TAILGATE LOCK	Dented	250.00 FL	*250.00 FL
15	8		*TAILGATE TRIMBOARD CLIPS	Necessary	72.00 FL	*72.00 FL
16	1		*TAILGATE CENTRE LOGO	Necessary	45.00 FL	*45.00 FL
17	1		*REAR END PANEL (OUTER)	Repair	290.00 FL	*- FL
18	1		*REAR BUMPER	Buckled	1,240.00 FL	*1,240.00 FL
19	1		*REAR BUMPER REFLECTOR-RH	Missing	38.00 FL	*38.00 FL
20	1		*FRONT NUMBER PLATE	Bent	40.00 FS	*40.00 FS
21	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
22	1		*TAILGATE 70KM/H STICKER	Necessary	25.00 FS	*15.00 FS
23	1		*REAR BUMPER SENSOR	Cracked	350.00 FS	*200.00 FS
24	1		*REAR NUMBER PLATE	Serviceable	40.00 FS	*- FS
25	1		*AIR-CON GAS	Not Necessary	55.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,290.00	6,490.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	872.00	619.50
Total Parts (\$\$)	8,418.00	5,870.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	150.00	120.00
2	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	40.00
3	TO TRANSFER DAMAGED TAILGATE INTERIOR MECHANISM TO NEW TAILGATE	New	160.00	60.00
4	TO REMOVE AND REFIX AIR-CON CONDENSER ,PIPES AND RADIATOR ASSY	New	120.00	0.00
5	TO PANEL BEAT AND STRAIGHTEN FRONT CHASSIS FRAME ,RH FRONT FENDER INNER PANEL,REAR FLOORBOARD PANEL,REAR CHASSIS FRAME ,TO CUT AND WELD REAR END PANEL INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY ,TO REFIT AND ADJUST THE SAME	New	1,500.00	700.00
6	TO PUTTY AND SPRAY SAME ON AFFECTED AREAS	New	1,000.00	600.00
7	TO APPLY RUST PROOFING ON REPAIRED AND REPLACED PANELS	New	180.00	0.00
8	TO SUPPLY ART WORK AND PASTE LOGOS AND LETTERING ON TAILGATE AND RH FRONT FENDER (3M)	New	1,500.00	680.00
Gross Labour Cost (S\$)			4,690.00	2,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >