

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Elaine Cheong

Date: 04 Mar 2019

**Preliminary Advice**

Vehicle No	: SKE418Y	Accident Date	: 18/02/2019
Make	: NISSAN GTR	Policy No.	: DMPCSN1817761800
Assignment Date	: 28/02/2019	Excess	: S\$3,000.00
Date of Inspection	: 01/03/2019	Est. Duration of Repair	: 28.00
Inspection At	: NGEE SENG AUTO WORKS (HQ) BLOCK 3022A, UBI ROAD 1, #01-50 SINGAPORE 408716		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	218,527.72
Revised Amount	:S\$	155,056.24
Check Items (Estimated)	:S\$	14,671.08
Total	:S\$	169,727.32

Lump Sum Repair (Estimated)	:S\$	135,800.00
-----------------------------	------	------------

Brake System	: In Order
Steering System	: In Order
Tyre Condition (Front)	: 6/6 mm
Tyre Condition (Rear)	: 6/6 mm

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	175,000.00
COE / PARF Rebate	:S\$	35,378.00
Salvage Value	:S\$	
Margin for Repair	:S\$	139,622.00

**Remarks**

( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( ) Other comments :