

Address 54 KEW DRIVE
 Postcode 467976
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
 Weather Conditions RAINING
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? YES
 Foreign Vehicle Registration Number JMY7253 (PRIVATE CAR)
 Number of vehicles (including own vehicle) Involved in the accident 3
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 POLICE STATION NAME [OTHER] TRAFIK KULAIJAYA
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number UNKNOWN
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number JMY7253
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please Refer to Statement

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

SIABMC Sketchplanform 1/2

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

I WAS TRAVELLING ALONG MELAKA TOWARDS SINGAPORE AT THE HIGHWAY, I WAS ON THE SECOND LANE FROM THE LEFT, WHEN SUDDENLY VEH B FROM THE EXTREME LEFT LANE CUT INTO MY LANE AND HIT ONTO MY VEH LEFT FRONT PORTION, MY VEH LOST CONTROL SPIN TO THE RIGHT SIDE AND HIT ONTO THE ROAD BARRIER, THEN COME TO A STOP FACING AGAINST THE TRAFFIC, AFTER THE IMPACT MY VEH CANNOT BE DRIVEN AND I ALIGHTED FROM MY VEH, STAND ON THE ROAD SIDE MAKE MY CALL. AFTER 15 MIN LATER, ANOTHER VEH C (BEARING NO JMY7253) COME FROM THE FIRST LANE AND HIT ONTO MY VEH FRONT PORTION.



POLIS DIRAJA MALAYSIA

REPOT POLIS

Balai : TRAFIK KULAIJAYA
 Daerah : KULAIJAYA
 Kontinjen : JOHOR
 No Repot : TRAFIK KULAIJAYA/001564/19
 Tarikh : 18/02/2019
 Waktu : 0739 AM
 Bahasa Diterima : B. Malaysia

Pegawai Penyiasat : R123905

Butir-butir Penerima Repot

Nama : MOHD ALIEF BIN SAMAT
 Butir-butir Jurubahasa (Jika Ada)

No Personel : R193588

Pangkat : KONST/P

Nama : ---

No K/P (Baru) : ---

No Polis/Tentera : ---

No Paspot : ---

Bahasa Asal : ---

Alamat : ---

Butir-butir Pengadu

Nama : FU CHEN LOK

No K/P (Baru) : ---

No Polis/Tentera : ---

No Paspot : E6107493E

No Sijil Beranak : ---

Jantina : Lelaki

Tarikh Lahir : 18/03/1987

Umur : 31 tahun 11 bulan

Keturunan : Cina

Warganegara : Singapore

Pekerjaan : SWASTA

Alamat Tempat Tinggal : 54 KEW DRIVE, SINGAPORE, 467976

Alamat Ibu/Bapa : ---

Alamat Pejabat : ---

No Tel (Rumah) : ---

No Tel (Pejabat) : ---

No Tel (HP) : 6598230937

Pengadu Menyatakan:-

PADA 18/02/2019 JAM LEBIH KURANG 0450HRS SAYA MEMANDU BERSEORANGAN M/KAR NO. SKE418Y JENIS NISSAN DARI MELAKA HENDAK KE SINGAPURA. PADA KETIKA ITU, SEMASA BERADA DI LORONG KIRI KM 19.7 LEBUHRAYA UTARA-SELATAN(S) DALAM KEADAAN HUJAN LEBAT TIBA-TIBA M/KAR SAYA HILANG KAWALAN DISEBABKAN JALAN LICIN MENYEBABKAN M/KAR SAYA HILANG KAWALAN LALU TERLANGGAR BESI PEMBAHAGI KANAN JALAN DAN BERPUSING. PADA MASA YANG SAMA DATANG SEBUAH M/KAR NO. JMY7253 JENIS P/SAGA DARI ARAH BELAKANG TELAH TERLANGGAR BAHAGIAN DEPAN KIRI M/KAR SAYA. SAYA TIDAK CEDERA. KEROSAKAN M/KAR SAYA BAHAGIAN DEPAN BUMPER, PANEL, CERMIN BESAR, BONET, TANGKI AIR/AIRCOND, MUDGUARD, TAYAR/ARM/RIM, SENSOR, CERMIN BESAR DAN LAIN-LAIN KEROSAKAN BELUM PASTI. SAYA BUAT LAPORAN UNTUK RUJUKAN PIHAK INSURAN DAN PIHAK YANG BERKENAAN. SEKIAN LAPORAN SAYA.

Tandatangan Pengadu:

Tandatangan Jurubahasa (Jika ada):

Tandatangan Penerima Repot:

ID Pencetak | Tarikh @ Masa Cetak

: A7027689 | 18/02/2019 08:17:06 AM

SALINAN YANG DISAHKAN BENAR
 (HANYA UNTUK TUNTUTAN SIVIL)

KRSPTD IPD KULAI JOHOR

<http://10.1.1.199/prs/coffice/viewpol155real.asp?type=printedsalinan&salinan=ya&jenissalina...> 18-Feb-19

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE No.

DMPCSN1817761800

Engine No : VR38006991A
Chassis No: R35004855

1. Index Mark and Registration
Number of Vehicle

SKE418Y

2. Name of Policy Holder

FU CHEN LOK

3. Effective date of the Commencement of Insurance for
the purposes of the Regulations, Ordinance or Enactment

6 JUNE 2018

4. Date of Expiry of Insurance

5 JUNE 2019

5. Persons or Classes of Persons entitled to drive *

NAMED DRIVERS EX SECT. I S\$3,000.00
ADDITIONAL EX OTHER THAN NAMED DRIVERS: S\$6,000.00
EX ON WINDSCREEN S\$350.00

AS PER NAMED DRIVER(S) STATED BELOW.

PROVIDED THAT THE PERSON DRIVING IS PERMITTED IN ACCORDANCE WITH THE LICENSING OR OTHER LAWS OR
REGULATIONS TO DRIVE THE MOTOR VEHICLE OR HAS BEEN SO PERMITTED AND IS NOT DISQUALIFIED BY ORDER OF A
COURT OF LAW OR BY REASON OF ANY ENACTMENT OR REGULATION IN THAT BEHALF FROM DRIVING THE MOTOR VEHICLE.

THE INSURED,
FU WAI KONG.

FU QIAN LI DRIVING ONLY

6. Limitations as to use: *

USE FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES AND FOR THE POLICYHOLDER'S BUSINESS.
THE POLICY DOES NOT COVER USE FOR HIRE OR REWARD TUITION DRIVING TEST RACING RACE-MAKING, RELIABILITY
TRIAL, SPEED-TESTING, THE CARRIAGE OF GOODS OTHER THAN SAMPLES IN CONNECTION WITH ANY TRADE OR BUSINESS
OR USE FOR ANY PURPOSE IN CONNECTION WITH THE MOTOR TRADE.

HIRE PURCHASE CO. : SWEE SENG CREDIT PTE LTD AS HP OWNER

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the
provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the
Road Transport Act, 1987 (Malaysia).
Please see reverse



Authorised Officer

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Authorised Signatory

Countersigned By:

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Tel: 6389 6111

Fax: 6225 3592

Website: www.sg.cntaiping.com



NGEE SENG AUTO

REGISTRATION NO:

Blk. 3022A, Ubi Road 1, #01-50, Singa
ALL TYPES OF MOTOR REPAIRS SERVICES, SPRA

電話

x: 6743 9006

CHINA TAI PING INSURANCE (SINGAPORE) PTE LTD
3, Anson Road #16-00
Springleaf Tower
Singapore 079909

Estimate

RE: VEHICLE NO. SKE 418 Y NISSAN GTR

Qty	Description
1	FRONT BUMPER
1	FRONT BUMPER SPONGE } Missing
1	FRONT BUMPER SPOILER } Missing
2	FRONT BUMPER SIDE LAMP RH/LH
2	FRONT BUMPER SIDE RETAINER RH/LH
2	FRONT BUMPER SIDE BRACKET RH/LH } Missing
1	FRONT BUMPER BEAM
1	FRONT BUMPER REINFORCEMENT
2	FRONT BUMPER REINFORCEMENT BRACKET Missing
2	FRONT FENDER RH/LH Dished
2	FRONT FENDER INNER SHIELD (FRONT) torn
2	FRONT FENDER INNER SHIELD (REAR) torn
1	FRONT SUPPORT PANEL
1	FRONT SUPPORT PANEL GARNISH } Dished
2	FRONT HEADLAMP RH/LH Smashed
2	FRONT HEADLAMP BRACKET missing
2	ROCKER PANEL GARNISH RH/LH LH Dished
2	FRONT LOWER ARM
2	FRONT KNUCKLE ARM } LH Dished, RH ?
2	FRONT KNUCKLE ARM BEARING
2	FRONT UPPER ARM
1	FRONT CROSS MEMBER Bent
1	FRONT STEERING RACK & PINION Dished
2	FRONT DRIVSHAFT RH/LH LH Dished
1	FRONT STABILISER BAR LH Dished
2	FRONT STABILISER BAR LINK LH Bent, RH ?
2	FRONT SHOCK ABSORBER LH Bent, RH ?
1	FRONT OIL COOLEN Dished
1	RADIATOR Dished
1	RADIATOR FAN } Dished
1	AIR CON FAN
1	AIR CON CONDENSER Bent
1	FRONT CALIPER Bent cut
1	FRONT OIL COOLEN BRACKET Bent
1	FRONT OIL COOLEN HOSE IN ?
1	FRONT OIL COOLEN HOSE OUT ?
1	FRONT ENGINE LOWER COVER REAR } torn
1	FRONT ENGINE LOWER COVER FRONT

SUB TOTAL
LESS 10%
TOTAL (1)

6,990.3 +
580.2 +
4,500. +
550. +
390. +
370. +
360.5 +
2,650.5 +
424. +
5,971. +
662.6 +
709. +
5,980.8 +
1,680. +
7,901. +
1,800. +
8,350.

20

145,776.24 +
930. +
8,350. +
155,056.24

check
2,860. +
3,160.2 +
950.5 +
1,050. +
680.5 +
3,800. +
1,950. +
1,850. +
16,301.2

x
90. %
14,671.08 *



NGEE SENG AUTO WORKS 誼盛摩哆

REGISTRATION NO: 52791500M

Blk. 3022A, Ubi Road 1, #01-50, Singapore 408716. Tel: 6841 2276 Fax: 6743 9006

ALL TYPES OF MOTOR REPAIRS SERVICES, SPRAY PAINTING & INSURANCE CLAIMS.

CHINA TAI PING INSURANCE (SINGAPORE) PTE LTD

3, Anson Road #16-00
Springleaf Tower
Singapore 079909

Estimate Repair Bill :ES19001

Date :21/02/2019
Ref No :SKE 418 Y
Policy No. :DMPCSN 1817761800
Page :02

RE: VEHICLE NO. SKE 418 Y NISSAN GTR

Qty	Description	Unit Price	AMOUNT
1	FRONT DOOR <i>Dented</i>		\$6,990.30 ✓
1	FRONT DOOR MOULDING <i>new</i>		\$760.00 ✓
1	FRONT GRILLE <i>smashed</i>		\$882.00 ✓
1	FRONT GRILLE CHROME <i>smashed</i>		\$1,678.00 ✓
1	FRONT GRILLE HOUSEING <i>smashed</i>		\$932.00 ✓
1	FRONT GRILLE LOGO <i>new</i>		\$180.00 ✓
1	FRONT BUMPER LOWER GRILLE <i>Dented</i>		\$970.00 ✓
1	FRONT BUMPER CLIPS (SET) <i>new</i>		\$150.00 ✓
1	FRONT FENDER INNER SHIELD (SET) <i>new</i>		\$110.00 ✓
1	FRONT BUMPER RUBBER <i>missing</i>		\$260.50 ✓
2	FRONT FENDER LOGO (GTR) RH/LH <i>new</i>	\$280.00	\$560.00 ✓
1	FRONT BUMPER LOWER LIP <i>missing</i>		\$6,231.00 ✓
1	FRONT BONNET <i>Dented</i>		\$5,600.00 ✓
2	FRONT BONNET HINGE RH/LH <i>Best</i>	\$655.00	\$1,310.00 ✓
2	FRONT BONNET HINGE COVER RH/LH <i>missing</i>	\$260.30	\$520.60 ✓
2	FRONT BONNET LOCK RH/LH <i>Best</i>	\$280.00	\$560.00 ✓
1	FRONT BONNET INSULATION RH/LH <i>new</i>		\$878.00 ✓
1	FRONT DOOR LOCK <i>new</i>		\$760.60 ✓
1	ROCKER PANEL <i>Repair</i>		\$1,950.40 ✓
3	TOP UP BONNET SENSOR <i>missing</i>	\$586.00	\$1,758.00 ✓
2	FRONT FENDER AIR DUCT <i>Dented</i>	\$398.80	\$797.60 ✓
2	TURBO COOLER <i>missing</i>	\$6,505.00	\$1,301.00 ✓
1	FRONT WINDSCREEN <i>cracked</i>		\$4,500.00 ✓
2	FRONT CHASSIS <i>Repair</i>	\$5,985.00	\$11,970.00 ✓
1	FRONT AIR CON PIPE (IN) <i>Best</i>		\$975.00 ✓
1	FRONT AIR CON PIPE (OUT) <i>Best</i>		\$860.00 ✓
1	REAR BUMPER <i>torn</i>		\$6,990.00 ✓
1	REAR BUMPER LOWER LIP <i>Repair</i>		\$3,282.50 ✓
4	SPORT RIM <i>3 pieces cut</i>	\$4,000.00	\$16,000.00 12000 ✓
1	FRONT BUMPER LED LAMP (SET) <i>missing</i>		\$3,600.00 ✓
1	REAR TAILLAMP <i>new</i>		\$2,480.50 ✓

SUB TOTAL
LESS 10%
TOTAL (2)

\$85,798.00
\$8,579.80
\$77,218.20



NGEE SENG AUTO WORKS 誼盛摩哆

REGISTRATION NO: 52791500M

Blk. 3022A, Ubi Road 1, #01-50, Singapore 408716. Tel: 6841 2276 Fax: 6743 9006

ALL TYPES OF MOTOR REPAIRS SERVICES, SPRAY PAINTING & INSURANCE CLAIMS.

CHINA TAI PING INSURANCE (SINGAPORE) PTE LTD

3, Anson Road #16-00

Springleaf Tower

Singapore 079909

Estimate Repair Bill :ES19001

Date :21/02/2019

Ref No :SKE 418 Y

Policy No. :DMPCSN 1817761800

Page :03

RE: VEHICLE NO. SKE 418 Y NISSAN GTR

Qty	Description	Unit Price	AMOUNT
	SPECIAL NETT ITEM		
2	FRONT / REAR NUMBER PLATE <i>Front Missing</i>	\$50.00	\$100.00 50
4	TYRE <i>1 piece</i>	\$1,500.00	\$6,000.00 800
2	FRONT / REAR WINDSCREEN SEALANT / SEAL <i>per</i>	\$120.00	\$240.00 80
TOTAL (3)			<u>\$6,340.00</u>

LABOUR

TO TOWING

~~\$200.00~~ 150

TO REMOVE & REFIX FRONT WINDSCREEN

~~\$400.00~~ 120

TO REMOVE & REFIX FRONT DOOR COMPONENT

~~\$300.00~~ 80

TO REMOVE & REFIX RIM, TYRE & BALANCING

~~\$350.00~~ 150

TO CONDUCT COMPUTERISED WHEEL ALIGNMENT

~~\$400.00~~ 80

TO CHECK & RECTIFY WIRING SYSTEM, RESET COMPUTER

~~\$800.00~~ 300

TO REMOVE & REFIX FRONT UNDERCARRIAGE

~~\$3,800.00~~ 1200

TO CARRY OUT CHASSIS ALIGN RH/LH

~~\$600.00~~ 350

TO RUST PROOF AFFECTED AREAS

~~\$300.00~~ 120

TO SETTING AIR BAG SYSTEM

~~\$1,200.00~~ x

TO REMOVE DASHBOARD / AIR BAG

~~\$1,500.00~~ x

TO REMOVE & REFIX ENGINE

~~\$2,500.00~~ 1000

TO PANEL BEATING

~~\$6,000.00~~ 3000

TO SPRAY PAINTING

~~\$4,000.00~~ 1800

LABOUR CHARGES

\$22,350.00

TOTAL SPARE PARTS & LABOUR CHARGES

\$218,527.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
2/s 01/03/19
28 Days
Not Authorised Excess \$3000



NGEE SENG AUTO WORKS 誼盛摩哆

REGISTRATION NO: 52791500M

Blk. 3022A, Ubi Road 1, #01-50, Singapore 408716. Tel: 6841 2276 Fax: 6743 9006

ALL TYPES OF MOTOR REPAIRS SERVICES, SPRAY PAINTING & INSURANCE CLAIMS.

CHINA TAI PING INSURANCE (SINGAPORE) PTE LTD

3, Anson Road #16-00

Springleaf Tower

Singapore 079909

Estimate Repair Bill :ES19001

Date :21/02/2019

Ref No :SKE 418 Y

Policy No. :DMPCSN 1817761800

Page :01

RE: VEHICLE NO. SKE 418 Y NISSAN GTR

Qty	Description	Unit Price	AMOUNT
1	FRONT BUMPER		\$6,990.30 ✓
1	FRONT BUMPER SPONGE } Missing		\$580.20 ✓
1	FRONT BUMPER SPOILER		\$4,500.00 ✓
2	FRONT BUMPER SIDE LAMP RH/LH	\$275.00	\$550.00 ✓
2	FRONT BUMPER SIDE RETAINER RH/LH	\$195.00	\$390.00 ✓
2	FRONT BUMPER SIDE BRACKET RH/LH } Missing	\$185.00	\$370.00 ✓
1	FRONT BUMPER BEAM		\$360.50 ✓
1	FRONT BUMPER REINFORCEMENT		\$2,650.50 ✓
2	FRONT BUMPER REINFORCEMENT BRACKET Missing	\$212.00	\$424.00 ✓
2	FRONT FENDER RH/LH Dished	\$2,985.50	\$5,971.00 ✓
2	FRONT FENDER INNER SHIELD (FRONT) torn	\$331.30	\$662.60 ✓
2	FRONT FENDER INNER SHIELD (REAR) torn	\$354.50	\$709.00 ✓
1	FRONT SUPPORT PANEL		\$5,980.80 ✓
1	FRONT SUPPORT PANEL GARNISH } Dished		\$1,680.00 ✓
2	FRONT HEADLAMP RH/LH Smashed	\$3,950.50	\$7,901.00 ✓
2	FRONT HEADLAMP BRACKET missing	\$165.00	\$330.00 ✓
2	ROCKER PANEL GARNISH RH/LH } LH Dished	\$1,982.00	\$3,964.00 1582
2	FRONT LOWER ARM	\$2,860.00	\$5,720.00 2860
2	FRONT KNUCKLE ARM	\$3,160.20	\$6,320.40 3160.20
2	FRONT KNUCKLE ARM BEARING } LH Dished, RH RH	\$950.50	\$1,901.00 950.50
2	FRONT UPPER ARM	\$1,050.00	\$2,100.00 1050
1	FRONT CROSS MEMBER Bent		\$6,120.00 ✓
1	FRONT STEERING RACK & PINION Dished		\$9,211.00 ✓
2	FRONT DRIVSHAFT RH/LH LH Dished	\$4,591.00	\$9,182.00 4591
1	FRONT STABILISER BAR LH Dished		\$2,510.50 ✓
2	FRONT STABILISER BAR LINK LH Bent, RH Bent	\$680.50	\$1,361.00 680.50
2	FRONT SHOCK ABSORBER LH Bent, RH Bent	\$3,800.00	\$7,600.00 3800
1	FRONT OIL COOLEN Dished		\$8,200.00 ✓
1	RADIATOR Dished		\$3,480.00 ✓
1	RADIATOR FAN } Dished		\$1,160.00 ✓
1	AIR CON FAN		\$1,238.00 ✓
1	AIR CON CONDENSER Bent		\$3,346.00 ✓
1	FRONT CALIPER RH cut		\$4,120.00 ✓
1	FRONT OIL COOLEN BRACKET Bent		\$678.00 ✓
1	FRONT OIL COOLEN HOSE IN Bent		\$1,950.00 ✓
1	FRONT OIL COOLEN HOSE OUT Bent		\$1,850.00 ✓
1	FRONT ENGINE LOWER COVER REAR } torn		\$1,750.00 ✓
1	FRONT ENGINE LOWER COVER FRONT		\$1,320.00 ✓
SUB TOTAL			\$125,132.80
LESS 10%			\$12,513.28
TOTAL (1)			\$112,619.52



NGEE SENG AUTO WORKS 誼盛摩哆

REGISTRATION NO: 52791500M

Bld. 3022A, Ubi Road 1, #01-50, Singapore 408716. Tel: 6841 2276 Fax: 6743 9006

ALL TYPES OF MOTOR REPAIRS SERVICES, SPRAY PAINTING & INSURANCE CLAIMS.

CHINA TAI PING INSURANCE (SINGAPORE) PTE LTD

3, Anson Road #16-00

Springleaf Tower

Singapore 079909

Estimate Repair Bill :ES19001

Date :21/02/2019

Ref No :SKE 418 Y

Policy No. :DMPCSN 1817761800

Page :02

RE: VEHICLE NO. SKE 418 Y NISSAN GTR

Qty	Description	Unit Price	AMOUNT
1	FRONT DOOR <i>Painted</i>		\$6,990.30 ✓
1	FRONT DOOR MOULDING <i>new</i>		\$760.00 ✓
1	FRONT GRILLE <i>scratched</i>		\$882.00 ✓
1	FRONT GRILLE CHROME <i>scratched</i>		\$1,678.00 ✓
1	FRONT GRILLE HOUSEING <i>scratched</i>		\$932.00 ✓
1	FRONT GRILLE LOGO <i>new</i>		\$180.00 ✓
1	FRONT BUMPER LOWER GRILLE <i>Painted</i>		\$970.00 ✓
1	FRONT BUMPER CLIPS (SET) <i>new</i>		\$150.00 ✓
1	FRONT FENDER INNER SHIELD (SET) <i>new</i>		\$110.00 ✓
1	FRONT BUMPER RUBBER <i>missing</i>		\$260.50 ✓
2	FRONT FENDER LOGO (GTR) RH/LH <i>new</i>	\$280.00	\$560.00 ✓
1	FRONT BUMPER LOWER LIP <i>missing</i>		\$6,231.00 ✓
1	FRONT BONNET <i>Dented</i>		\$5,600.00 ✓
2	FRONT BONNET HINGE RH/LH <i>Best</i>	\$655.00	\$1,310.00 ✓
2	FRONT BONNET HINGE COVER RH/LH <i>missing</i>	\$260.30	\$520.60 ✓
2	FRONT BONNET LOCK RH/LH <i>Best</i>	\$280.00	\$560.00 ✓
1	FRONT BONNET INSULATION RH/LH <i>new</i>		\$878.00 ✓
1	FRONT DOOR LOCK <i>new</i>		\$760.60 ✓
1	ROCKER PANEL <i>Repairs</i>		\$1,950.40 ✓
3	TOP UP BONNET SENSOR <i>missing</i>	\$586.00	\$1,758.00 ✓
2	FRONT FENDER AIR DUCT <i>Painted</i>	\$398.80	\$797.60 ✓
2	TURBO COOLER <i>missing</i>	\$6,505.00	\$1,301.00 ✓
1	FRONT WINDSCREEN <i>cracked</i>		\$4,500.00 ✓
2	FRONT CHASSIS <i>Repairs</i>	\$5,985.00	\$11,970.00 ✓
1	FRONT AIR CON PIPE (IN) <i>Best</i>		\$975.00 ✓
1	FRONT AIR CON PIPE (OUT) <i>Best</i>		\$860.00 ✓
1	REAR BUMPER <i>torn</i>		\$6,990.00 ✓
1	REAR BUMPER LOWER LIP <i>Repairs</i>		\$3,282.50 ✓
4	SPORT RIM <i>3 pieces cut</i>	\$4,000.00	\$16,000.00 12000 ✓
1	FRONT BUMPER LED LAMP (SET) <i>missing</i>		\$3,600.00 ✓
1	REAR TAILLAMP <i>new</i>		\$2,480.50 ✓

165773.6

149196.24

SUB TOTAL

\$85,798.00

LESS 10%

\$8,579.80

TOTAL (2)

\$77,218.20



NGEE SENG AUTO WORKS 誼盛摩哆

REGISTRATION NO: 52791500M

Blk. 3022A, Ubi Road 1, #01-50, Singapore 408716. Tel: 6841 2276 Fax: 6743 9006

ALL TYPES OF MOTOR REPAIRS SERVICES, SPRAY PAINTING & INSURANCE CLAIMS.

CHINA TAI PING INSURANCE (SINGAPORE) PTE LTD

3, Anson Road #16-00

Springleaf Tower

Singapore 079909

Estimate Repair Bill :E519001

Date :21/02/2019

Ref No :SKE 418 Y

Policy No. :DMPCSN 1817761800

Page :03

RE: VEHICLE NO. SKE 418 Y NISSAN GTR

Qty	Description	Unit Price	AMOUNT
	SPECIAL NETT ITEM		
2	FRONT / REAR NUMBER PLATE <i>Front missing</i>	\$50.00	\$100.00 50
4	TYRE <i>1 piece pun</i>	\$1,500.00	\$6,000.00 800
2	FRONT / REAR WINDSCREEN SEALANT / SEAL <i>per</i>	\$120.00	\$240.00 80
TOTAL (3)			<u>\$6,340.00</u>

930

LABOUR

TO TOWING

TO REMOVE & REFIX FRONT WINDSCREEN

TO REMOVE & REFIX FRONT DOOR COMPONENT

TO REMOVE & REFIX RIM, TYRE & BALANCING

TO CONDUCT COMPUTERISED WHEEL ALIGNMENT

TO CHECK & RECTIFY WIRING SYSTEM, RESET COMPUTER

TO REMOVE & REFIX FRONT UNDERCARRIAGE

TO CARRY OUT CHASSIS ALIGN RH/LH

TO RUST PROOF AFFECTED AREAS

TO SETTING AIR BAG SYSTEM

TO REMOVE DASHBOARD / AIR BAG

TO REMOVE & REFIX ENGINE

TO PANEL BEATING

TO SPRAY PAINTING

~~\$200.00~~ 150

~~\$400.00~~ 120

~~\$300.00~~ 80

~~\$350.00~~ 150

~~\$400.00~~ 80

~~\$800.00~~ 300

~~\$3,800.00~~ 1200

~~\$600.00~~ 350

~~\$300.00~~ 120

~~\$1,200.00~~ *

~~\$1,500.00~~ *

~~\$2,500.00~~ 1000

~~\$6,000.00~~ 3000

~~\$4,000.00~~ 1800

8350

LABOUR CHARGES

\$22,350.00

TOTAL SPARE PARTS & LABOUR CHARGES

\$218,527.72

total: 158476.24

L/S: 12010

Adnan Lij

L/S 01/03/19

28 days