

730012007

ASS. REC. BY:

REF: CS/EQI19003791/Usd3

Special Instruction:

SAVING/NOT

From (Person):

Joel Goh

ASSIGNMENT (Office)

of EQI

Bill to:

Date/Time:

28/2/19 @ 2.11pm

Estimated Cost:

OD/TP/WS/TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SKF 9503U

Insured:

at Workshop m/s

SME Motor

Tel:

6747 6106

of

11kaki Bkt Ave 6 # 02-15 Autobay

Policy No:

DMPPHQ18-005228

Claim No:

DM19HO 00568

Excess:

\$300.00 (50% waiver)

Sum Insured:

D.O.A. 26/2/19

Make of Veh:

(Client's Record)

01/03/2019

H.O.D. Endorsement:

CA If in order

REV / REP. / REV 24 HRS

Vehicle IN/OUT

Date/Time:

2.15pm @ 28/2/19

Person Contacted:

pei ying

Date/Time Action/Instruction (✓) Estimate

SKF 9503U - CC1/EQI19003696/11/13

D.O.A. 26/2/19

01/03/19 @ 14:12 p.m. revised PA to Joel Goh via memo

01/03/19 @ 14:22 p.m. mandate requested authorisation report to

Joel Goh via memo.

01/03/19 @ 14:41 p.m. mandate approved by ~~TEA~~ Joel Goh via memo

authorisation report to Jacob (Superior) via email

WYNDHAM

Marcy

REF: EQ1

ASSIGNMENT

From

Date: 1/3/19

Estimated Cost:

OD? TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SKF 95034

at Workshop m/s

SME MOTOR

of

1 Kaki Blk Ave 6 # 02-15

Insured:

Policy No.:

Claims No.:

Sum Insured:

Excess:

\$ 300.00
(50% waiver)

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

61k.

IDAC Accident Rpt:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

5 days
15% %

Res: Yes or No

Lum Sum:

3 Val: Yes or No

CA if in order
REV / REP. / 24 HRS

AF7U

Vehicle: IN / OUT

Date:

Person Contacted:

net 9228

Veh No: SKF 95034

Yr Regn: 7/12

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi CA / A4

C.C. 1798

Colour:

Black

A/C Insured / Std / NI / NA

Sp Reading:

97003

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAUZZZ8KXDA065040

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/50R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

continued

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

26/2/19

D.O.I.

1/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

LL

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

47A 51772 3yrs. 4ml. Dep
workshop 25th P/P
No second hand part.

RECEIVED 27 MAR 2019

26/3/19

confirmed final p/s 8981.60 with AH ying
(F1160.50 Red - 11%)

27/3/2019

Date/Time, File Pass to?

27/3/19

1) Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.B.E: (\$ 8,981.60

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee:

230

Transportation

1) S + RS (\$)

2) Photo

3) Other

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. days (\$

☐

Weekend (\$

REF: EQ1

Jacod B. Sme Motor
ang @ Sme Motor.com.sg

ASSIGNMENT

From:

Date: 1/3/19

Estimated Cost:

Veh No:

SKF 95034

Yr Regn:

7, 12

To Inspect Vehicle No:

SKF 95034

at Workshop n/s

SME MOTOR

at 1 Kaki Blk Ave 6 # 02-15

Insured:

Policy No.:

Claims No.:

Sum Insured:


Excess:

\$ 300.00
(50% waiver)

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Est. or Market Value:

61k.

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Scan:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val: Yes or No

if in order
CA / REV / REP. / 24 HRS

AFFU

Vehicle: INT/OUT

Date:

Person Contacted:

net 9228

Type: M. Car / M. Cycle / Bus / Van / Lorry / Trail / Prime Mover /

Truck / Trailer or

Make:

Audi A4

C.O.

Colour:

Black

AC: Insured / Std / NI / NA

Sp. Roading:

97003

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WANTZ228KXDA065040

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Ins. / Jammed / Leaked / Burnt or

Brake: Ins. / Jammed / Leaked / Burnt or

Mod: Nil / WRM / STD A/Rim or

Tyre Size:

P: 225/50R17
R:

BS / DUN / EXNOVA / QY / PS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

continued

Front

6

mm

Rear

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

1/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 51772 3yrs. 4mths. Dep
monthly asly P/P

Date/Time, File Path to?



: Prel. Report

1)

Date/Time, File Return to?



: Final Report

2)

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Insp (\$



: Weekend (\$

Report Format:

Lump Sum / L.B.E. (\$

Days Of Repair:

Resurvey No. of Trip:

iSurvey Fee:

Transportation

) 3.10. 01

) Photos

) Others

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Feb 2019 Sendback Est	27 Feb 2019 11:47 S\$9,270.60	28 Feb 2019 14:11 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	WONG PUI KWANG ROLAND, ID: S8238871J, Tel: +6591912103, Email: NOEMAIL			
Vehicle Reg. No.:	SKF9503U	Date of Loss:	26/02/2019 07:00 - :59 [79 Months and 7 Days From LTA Reg Date (Man Yr)]	
Claim Type:	OD / DM19HO00568	Policy/Cover Note No.:	DMPPHQ18-005228 (Comprehensive)	
		Excess:	S\$300.00	
Repairer:	SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, 417883 Eunos - Tel: 6747 6106 (6 Lines)			
Handling Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433 ... [Handled by Joel Goh]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 11/03/2019]			
Driver/Custodian:	WONG PUI KWANG ROLAND (36 / Male) , NRIC: S8238871J, Tel: +6591912103 Email: NOEMAIL			
Adj Asg. Remarks:	EXCESS: \$300.00 (50% WAIVER) SURVEY AND AUTHORISE IF IN ORDER			

ASSOCIATED MAIL RECEIVED

View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 5 March 2019 10:08 AM
To: 'Sebastian Kong'; 'Jacob Ang'
Cc: SUR; Admin-D (LKKAuto)
Subject: RE: ***SPAM*** SKF 9503U OD (EQI) DOA 26/02/2019

Dear All,

As instructed by our client, please proceed at repair cost not exceeding \$9,000.00 (inclusive supplementary) to repair the insured vehicle

SKF 9503U (Excess \$ 300/-) on part by part basis.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sebastian Kong [mailto:sebastian@smemotor.com.sg]
Sent: Tuesday, 5 March 2019 10:02 AM
To: ShirleyHiew@lkkauto.com; admin-d@lkkauto.com
Cc: sur@lkkauto.com; Jacob Ang <jacob.ang@smemotor.com.sg>
Subject: Fw: ***SPAM*** SKF 9503U OD (EQI) DOA 26/02/2019

Hi Shirley,

Please kindly assist

Best Regards

Sebastian
SME MOTOR PTE LTD
1 Kaki Bukit Ave 6
Blk D, #02-15/16/17/18
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 6747 6106 (6 lines)
Fax: 6744 2368

From: Jacob Ang
Sent: Monday, March 4, 2019 1:07 PM
To: Shirley Hiew (LKK Auto)
Cc: SUR
Subject: Re: ***SPAM*** SKF 9503U OD (EQI) DOA 26/02/2019

Hi Shirley,

We are able to undertake the repair at limit \$9000 (before GST and Excess) on part by part basis.
Please kindly advise authorisation.

Best Regards

Jacob Ang
SME MOTOR PTE LTD
1 Kaki Bukit Ave 6
Blk D, #02-15/16/17/18
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 6747 6106 (6 lines)
Fax: 6744 2368

From: Shirley Hiew (LKK Auto)
Sent: Monday, March 4, 2019 11:43 AM
To: jacob.ang@smemotor.com.sg
Cc: SUR
Subject: ***SPAM*** SKF 9503U OD (EQI) DOA 26/02/2019

Dear Sir/Madam,

Kindly check the repair cost limit whether you are able to repair the vehicle not exceeding \$ 9,000.00 on part by part basis.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SKF9503U (DM19H000568)

OD

Feb 26 2019 7:00AM

[WONG PUI KWANG ROLAND]

SME Motor Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From EQ Insurance Company Ltd (HQ) (EQI_HQ), sent on 06/03/2019 09:04 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$9000.00) - SKF9503U - Claim Handler: Joel Goh

Approved:9000.00.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

SKF9503U (DM19H000568)

OD

Feb 26 2019 7:00AM

[WONG PUI KWANG ROLAND]

SME Motor Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From EQ Insurance Company Ltd (HQ) (EQI_HQ), sent on 01/03/2019 14:41 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$8963.60) - SKF9503U - Claim Handler: Joel Goh

Approved:8963.60.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: EQ Insurance Company Ltd
5 Maxwell Road, #17-00 Tower Block
MND Complex
Singapore 069110

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joel Goh

Date: 06 Mar 2019

Preliminary Advice

Vehicle No	: SKF9503U	Accident Date	: 26/02/2019
Make	: AUDI A4	Policy No.	: DMPPHQ18-005228
Assignment Date	: 28/02/2019	Excess	: S\$300.00
Date of Inspection	: 01/03/2019	Est. Duration of Repair	: 5 days
Inspection At	: SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit Singapore 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,892.10 (inclusive supplementary \$ 621.50)
Revised Amount	:S\$	6,257.60 (inclusive supplementary \$ 621.50)
Check Items (Estimated)	:S\$	3,327.50
Total	:S\$	9,585.10

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	61,000.00
COE / PARF Rebate	:S\$	51,772.00
Salvage Value	:S\$	
Margin for Repair	:S\$	9,228.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Kindly inform the supplementary amount is \$ 621.50. Repairer able to undertake the repair cost not exceeding \$ 9,000.00 on part by part basis.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: EQ Insurance Company Ltd
5 Maxwell Road, #17-00 Tower Block
MND Complex
Singapore 069110

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joel Goh

Date: 01 Mar 2019

Preliminary Advice

Vehicle No	: SKF9503U	Accident Date	: 26/02/2019
Make	: AUDI A4	Policy No.	: DMPPHQ18-005228
Assignment Date	: 28/02/2019	Excess	: S\$300.00
Date of Inspection	: 01/03/2019	Est. Duration of Repair	: 5 days
Inspection At	: SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit Singapore 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,270.60
Revised Amount	:S\$	5,636.10
Check Items (Estimated)	:S\$	3,327.50
Total	:S\$	8,963.60

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	61,000.00
COE / PARF Rebate	:S\$	51,772.00
Salvage Value	:S\$	
Margin for Repair	:S\$	9,228.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : REPAIRER ASKING REPAIR ON PART BY PART BASIS DUE TO NO SECOND HAND PART.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/02/2019 16:57
Date Of Accident	26/02/2019 07:30
Exact Location Of Accident	KPE BEFORE PIE EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKF9503U
Insured/Policyholder	
Name Of Registered Owner	WONG PUI KWANG ROLAND
NRIC No	S8238871J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91912103
Alternative Phone No	OFFICE-91912103

Vehicle Particulars

Manufacturer	AUDI
Model	A4-1.8 TFSI (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPPHQ18-005228
Cover Note Number	

Driver


Name of Driver	WONG PUI KWANG ROLAND
NRIC No	S8238871J
Date Of Birth	26/11/1982
Occupation	INDOOR
Date Of Driving Pass	14/06/2001
Driving Experience	17 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91912103
Fax Number	
Contact Number	OFFICE-91912103
Email Address	NOEMAIL

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Vehicle B suddenly jam brake. I can't stop in time and rear ended vehicle B.

why

DECLARATION

I/We declare the foregoing particulars are true in every respect.

why
Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

3/1/2019

PARF/COE Rebate Enquiry

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8871J
Vehicle Details	
Vehicle No.:	SKF9503U
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Mar 2019
Vehicle Make:	AUDI
Vehicle Model:	A4 1.8 TFSI MU (NAVIGATION & XENON)
Primary Colour:	Black
Manufacturing Year:	2012
Engine No.:	CJE019226
Chassis No.:	WAUZZZ8KXDA065040
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$36,504.00
Original Registration Date:	19 Jul 2012
First Registration Date:	19 Jul 2012
Transfer Count:	2
Actual ARF Paid:	\$36,504.00 <i>if 152</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Jul 2022
PARF Rebate Amount:	\$23,727.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jul 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$83,000.00
COE Rebate Amount:	\$28,045.00
Total Rebate Amount:	\$51,772.00

The information contained herein is correct as at 01 Mar 2019

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8871J
Vehicle Details	
Vehicle No.:	SKF9503U
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Mar 2019
Vehicle Make:	AUDI
Vehicle Model:	A4 1.8 TFSI MU (NAVIGATION & XENON)
Primary Colour:	Black
Manufacturing Year:	2012
Engine No.:	CJE019226
Chassis No.:	WAUZZZ8KXDA065040
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$36,504.00
Original Registration Date:	19 Jul 2012
First Registration Date:	19 Jul 2012
Transfer Count:	2
Actual ARF Paid:	\$36,504.00 <i>if 252</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Jul 2022
PARF Rebate Amount:	\$23,727.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jul 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$83,000.00
COE Rebate Amount:	\$28,045.00
Total Rebate Amount:	\$51,772.00

The information contained herein is correct as at 01 Mar 2019

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



6303 6303

Wide selection of Inchcape Certified Pre-owned LEXUS & TOYOTA Other Makes & Model available

Free Tyre & Service Credits up to \$3,000

Interest Rate 1.99%

Extended Warranty 1yr



Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2017 Toyota Camry 2.0A at \$102,800



Beautiful Condition
 StarAd

Aut
 An Inspiration

click here to view
 our **PRISTINE**
 at

Browse by Category

Sort by Date Posted

6 vehicles

audi a4

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
Search Selection	audi a4		Any	Any	2012	Any	Any	
	Audi A4 1.8 TFSI MU		\$64,800	\$13,080 /yr	21-Sep-2012	1,798 cc	24,000 km	
Lowest Mileage. Rarely Driven Highest Specs Model. Perfect Car To Renew COE. Immaculate Condition With Back Seats Rarely Used. Fu By Agent. High Loans Up To 80% With Lowest Interest Rate...								
Posted: 28-Feb-2019 Tags: 2012 Audi A4, 2012 audi a4, Audi A4, audi a4, Audi, A4, a4, Used Audi								
	Audi A4 1.8A TFSI MU Attraction Plus		\$61,000	\$11,510 /yr	16-Nov-2012	1,798 cc	88,000 km	
Full Accessories, Rare Attraction Plus Spec From Agent. Low Mileage. Never Tracked, Accident Free, Never Modded, Ceramic Paint Prote Always Parked In Basement Carpark. Well Taken Care.								
Posted: 28-Feb-2019 Tags: 2012 Audi A4, 2012 audi a4, Audi A4, audi a4, Audi, A4, a4, Used Audi								
	Audi A4 1.8A TFSI MU		\$62,800	\$12,440 /yr	29-Sep-2012	1,798 cc	132,000 km	
High COE And High OMV Unit! \$1221.00 x 43 Months. Audi RS4 Bodykit. Pre-Loved And Well Maintain By Car Enthusiast. Almost New Ty Pads. Flexible Loan Packages Available. Accident Free, Buy W...								
Car Buyers Automotive Pte Ltd								
Posted: 15-Feb-2019 Tags: 2012 Audi A4, 2012 audi a4, Audi A4, audi a4, Audi, A4, a4, Used Audi								
	Audi A4 1.8 TFSI MU		\$69,000	\$13,910 /yr	24-Oct-2012	1,798 cc	89,000 km	
1 Owner Only. Full Agent Serviced Record. Supreme Condition. Trade In Available. Viewing By Appointment.								
360 VR Cars								
Posted: 09-Feb-2019 Tags: 2012 Audi A4, 2012 audi a4, Audi A4, audi a4, Audi, A4, a4, Used Audi								
	Audi brings added efficiency to the A4 The Audi A4 2.0 TFSI, with its innovative 'B-cycle process', aims to deliver a balanced combination of performance and added efficiency. Read this article							
	Audi A4 1.8A TFSI MU Attraction		\$68,800	\$15,310 /yr	19-Jun-2012	1,798 cc	105,000 km	
Single Owner N Well Maintained, Face Lifted Model, Agent Unit, Serviced Regularly At Workshop, Original Factory Condition, Accident Fr /STA Evaluation Welcome, Optional Warranty Can Be ...								
Compare Motoring								

Repairer Estimates

Page 1 of 3

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883
 Tel: 6747 6106 (8 Lines) Fax: 6744 2368
 Email: service@smemotor.com.sg Website: www.smemotor.com.sg
 Co. & GST Reg. No: 201119451E

INSURER:

EQ Insurance Company Ltd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	19/EQ/OD-124 (02)
Policy No:	DMPPHQ18-005228	Date of Loss:	28/02/2019
Vehicle Reg. No.:	SKF9503U	Driveable?	
Driver Age/Info:	36 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	WONG PUI KWANG ROLAND	Contact No:	+6591912103
Driver:	WONG PUI KWANG ROLAND		

Make/Model: AUDI A4, 1.8 TFSI (A)

Vehicle Reg. Date: 19/07/2012

Vehicle Colour: BLACK
 Engine No: CJE019226
 Odometer: 0 KM

Chassis No: WAUZZZ8KXDA065040

Paint Type:
 Total Loss? NO
 Est. Duration of Repair (day) 7

not Authorized
2442
Excess After 50% \$300
11/3/19 S-Lang

Description of Accident/Loss: VEHICLE B SUDDENLY JAM BRAKE. I CAN'T STOP IN TIME AND REAR ENDED VEHICLE B.
 Remarks: VEHICLE IN.
 Present Location: SME MOTOR PTE LTD (KAKI BUKIT)

COST OF CLAIMS

Parts	Amount
Miscellaneous Items	7,695.60
Labour	45.00
Paintwork Labour	1,530.00
Towing	0.00
	0.00
Gross Total (\$\$)	9,270.60
+ GST 7.00% (\$\$)	648.94
Nett Amount (\$\$)	9,919.54

This claim is handled by: CHIA PEI YING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Feb 2019)
 Parts: 143 AUDI A4 1.8 TFSI (A) (Catalogue: Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)

Print Code: SME Motor Pte Ltd/SKF9503U/27/02/2019 11:47

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BONNET <i>DD/Buc</i>	0.00	0.00	*1,100.00 F
2	1		*FRT BONNET LOCK <i>7u1</i>	0.00	0.00	*120.00 F
3	1		*FRT BONNET LOCK CATCH <i>24</i>	0.00	0.00	*110.00 F
4	1		*FRT GRILLE ASSY <i>370</i>	0.00	0.00	*550.00 F
5	4		*FRT GRILLE CLIP <i>2u</i>	0.00	0.00	*12.00 F
6	1		*FRT BUMPER <i>D.S</i>	0.00	0.00	*850.00 F
7	2		*FRT BUMPER RETAINER <i>17</i>	0.00	0.00	*70.00 F
8	10		*FRT BUMPER CLIP <i>12u</i>	0.00	0.00	*30.00 F
9	2		*FRT BUMPER FOG LAMP GARNISH <i>M.S</i>	0.00	0.00	*140.00 F
10	1		*FRT BUMPER INNER SPONGE <i>11u</i>	0.00	0.00	*75.00 F
11	1		*FRT BUMPER REINFORCEMENT <i>1u</i>	0.00	0.00	*330.00 F
12	2		*HEADLAMP <i>015 cm + 17c</i>	0.00	0.00	*1,720.00 F
13	2		*HEADLAMP LOWER BRACKET <i>015 cm + 17c</i>	0.00	0.00	*160.00 F
14	1		*HEADLAMP SUPPORT PANEL	0.00	0.00	*480.00 F
15	1		*AIRCON CONDENSER <i>3u/1u</i>	0.00	0.00	*460.00 F
16	1		*RADIATOR <i>3u/1u</i>	0.00	0.00	*380.00 F
17	2		*AIRCON SIDE DEFLECTOR	0.00	0.00	*80.00 F
18	1		*HEADLAMP SUPPORT TOP GARNISH <i>De</i>	0.00	0.00	*100.00 F
19	6		*HEADLAMP SUPPORT TOP GARNISH CLIP <i>015</i>	0.00	0.00	*24.00 F
20	1		*RH HEADLAMP NOOZLE	0.00	0.00	*145.00 F
21	1		*RH HEADLAMP NOOZLE COVER	0.00	0.00	*60.00 F

F=Franchise part.

Sub Total (\$\$) 6,996.00
 + Margin on L,N Items 10.00% (\$\$) 699.60
 Total Parts (\$\$) 7,695.60

SME Motor Pte Ltd/SKF9503U/27/02/2019 11:47. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

2pc for by interior bracket \$150 x 2 3u ✓
2pc RH by interior bracket top holder \$15. M.S ✓
for bumper low grille \$90 1u ✓
grille base \$160 1u ✓

REPAIR DETAILS**Reference**

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 27 Feb 2019)

Parts: 143

AUDI A4 1.8 TFSI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: SME Motor Pte Ltd/SKF9503U/27/02/2019 11:47

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BONNET <i>DD/Sec</i>	0.00	0.00	*1,100.00 F
2	1		*FRT BONNET LOCK <i>Tu</i>	0.00	0.00	*120.00 F
3	1		*FRT BONNET LOCK CATCH <i>RY</i>	0.00	0.00	*110.00 F
4	1		*FRT GRILLE ASSY <i>370</i>	0.00	0.00	*550.00 F
5	4		*FRT GRILLE CLIP <i>2u</i>	0.00	0.00	*12.00 F
6	1		*FRT BUMPER <i>D.S</i>	0.00	0.00	*850.00 F
7	2		*FRT BUMPER RETAINER <i>17</i>	0.00	0.00	*70.00 F
8	10		*FRT BUMPER CLIP <i>1u</i>	0.00	0.00	*30.00 F
9	2		*FRT BUMPER FOG LAMP GARNISH <i>M.S</i>	0.00	0.00	*140.00 F
10	1		*FRT BUMPER INNER SPONGE <i>71.1</i>	0.00	0.00	*75.00 F
11	1		*FRT BUMPER REINFORCEMENT <i>1u</i>	0.00	0.00	*330.00 F
12	2		*HEADLAMP	0.00	0.00	*1,720.00 F ?
13	2		*HEADLAMP LOWER BRACKET	0.00	0.00	*160.00 F ?
14	1		*HEADLAMP SUPPORT PANEL	0.00	0.00	*480.00 F ?
15	1		*AIRCON CONDENSER <i>3u/1u</i>	0.00	0.00	*480.00 F
16	1		*RADIATOR	0.00	0.00	*380.00 F ?
17	2		*AIRCON SIDE DEFLECTOR	0.00	0.00	*80.00 F ?
18	1		*HEADLAMP SUPPORT TOP GARNISH <i>De</i>	0.00	0.00	*100.00 F
19	6		*HEADLAMP SUPPORT TOP GARNISH CLIP <i>n.c</i>	0.00	0.00	*24.00 F
20	1		*RH HEADLAMP NOOZLE	0.00	0.00	*145.00 F ?
21	1		*RH HEADLAMP NOOZLE COVER	0.00	0.00	*60.00 F ?

F=Franchise part.

Sub Total (\$)	6,996.00
+ Margin on L,N Items 10.00% (\$)	699.60
Total Parts (\$)	7,695.60

SME Motor Pte Ltd/SKF9503U/27/02/2019 11:47. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Repairer Estimates

Page 3 of 3

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	NUMBER PLATE	25.00
2	1	RADIATOR COOLANT	20.00
Sub Total (S\$)			45.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	WIRE CHECKING	New	30.00
2	REMOVE & REFIX AIRCON AND GAS	New	100.00
3	LABOUR CHARGE	New	700.00
4	SPRAY PAINTING	New	700.00
Gross Labour Cost (S\$)			1,530.00

SME Motor Pte Ltd/SKF9503U/27/02/2019 11:47. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Like Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883

Tel: 6747 6106 (6 Lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

INSURER: EQ Insurance Company Ltd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	19/EQ/OD-124 (02)
Policy No:	DMPPHQ18-005228	Date of Loss:	26/02/2019
Vehicle Reg. No.:	SKF9503U	Driveable?	
Driver Age/Info:	36 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	WONG PUI KWANG ROLAND	Contact No:	+6591912103
Driver:	WONG PUI KWANG ROLAND		

Make/Model:	AUDI A4, 1.8 TFSI (A)	Vehicle Reg. Date:	19/07/2012
Vehicle Colour:	BLACK	Chassis No:	WAUZZZ8KXDA065040
Engine No:	CJE019226		
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	7

not Authorized
KKK
Excess After 50% 4300
11/3/19 S-Ling

Description of Accident/Loss	VEHICLE B SUDDENLY JAM BRAKE. I CAN'T STOP IN TIME AND REAR ENDED VEHICLE B.
Remarks:	VEHICLE IN.
Present Location:	SME MOTOR PTE LTD (KAKI BUKIT)

COST OF CLAIMS

Parts	7,695.60
Miscellaneous Items	45.00
Labour	1,530.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	9,270.60
+ GST 7.00% (\$\$)	648.94
Nett Amount (\$\$)	9,919.54

LKIA to Consumers hence notify the insurer of the following:

- To insure before blue spray painting
- To insure before repair (parts) during resurvey
- Both items are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No repair/painting/repairs is allowed
- Survey report must be submitted and is subject to final approval from Insurance Company

Acknowledged by Repairer: _____
 Signature: _____
 Date: _____

This claim is handled by: CHIA PEI YING

10142.10

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Feb 2019)

Parts: 143 AUDI A4 1.8 TFSI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: SME Motor Pte Ltd/SKF9503U/27/02/2019 11:47

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BONNET <i>DD/3uc</i>	0.00	0.00	*1,100.00 F
2	1		*FRT BONNET LOCK <i>7u1</i>	0.00	0.00	*120.00 F
3	1		*FRT BONNET LOCK CATCH <i>2u1</i>	0.00	0.00	*110.00 F
4	1		*FRT GRILLE ASSY <i>3u0</i>	0.00	0.00	*550.00 F
5	4		*FRT GRILLE CLIP <i>2u1</i>	0.00	0.00	*12.00 F
6	1		*FRT BUMPER <i>D.S</i>	0.00	0.00	*850.00 F
7	2		*FRT BUMPER RETAINER <i>2u1</i>	0.00	0.00	*70.00 F
8	10		*FRT BUMPER CLIP <i>2u1</i>	0.00	0.00	*30.00 F
9	2		*FRT BUMPER FOG LAMP GARNISH <i>2u1</i>	0.00	0.00	*140.00 F
10	1		*FRT BUMPER INNER SPONGE <i>7u1</i>	0.00	0.00	*75.00 F
11	1		*FRT BUMPER REINFORCEMENT <i>But But</i>	0.00	0.00	*330.00 F
12	2		*HEADLAMP <i>2u1</i>	0.00	0.00	*1,720.00 F
13	2		*HEADLAMP LOWER BRACKET <i>2u1</i>	0.00	0.00	*160.00 F
14	1		*HEADLAMP SUPPORT PANEL <i>2u1</i>	0.00	0.00	*480.00 F
15	1		*AIRCON CONDENSER <i>But/2u1</i>	0.00	0.00	*460.00 F
16	1		*RADIATOR <i>But/2u1</i>	0.00	0.00	*380.00 F
17	2		*AIRCON SIDE DEFLECTOR <i>2u1</i>	0.00	0.00	*80.00 F
18	1		*HEADLAMP SUPPORT TOP GARNISH <i>De</i>	0.00	0.00	*100.00 F
19	6		*HEADLAMP SUPPORT TOP GARNISH CLIP <i>2u1</i>	0.00	0.00	*24.00 F
20	1		*RH HEADLAMP NOOZLE <i>2u1</i>	0.00	0.00	*145.00 F
21	1		*RH HEADLAMP NOOZLE COVER <i>2u1</i>	0.00	0.00	*60.00 F

F=Franchise part.

Sub Total (\$\$) 6,996.00
+ Margin on L,N Items 10.00% (\$\$) 699.60

Total Parts (\$\$) 7,695.60

SME Motor Pte Ltd/SKF9503U/27/02/2019 11:47. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

2-6806
102
7486.60

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	NUMBER PLATE	25.00 <i>sent</i>
2	1	RADIATOR COOLANT	20.00 <i>sent</i>
Sub Total (S\$)			45.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	WIRE CHECKING	New	30.00 <i>20</i>
2	REMOVE & REFIX AIRCON AND GAS	New	100.00 ✓
3	LABOUR CHARGE	New	700.00 <i>580</i>
4	SPRAY PAINTING	New	700.00 <i>600</i>
Gross Labour Cost (S\$)			1,530.00

SME Motor Pte Ltd/SKF9503U/27/02/2019 11:47. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

1570

SME MOTOR PTE LTD**1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883****Tel: 6747 6106 (6 Lines) Fax: 6744 2368****Email: service@smemotor.com.sg Website: www.smemotor.com.sg****Co. & GST Reg. No: 201119451E****(SUPPLEMENTARY)****INSURER: EQ Insurance Company Ltd (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	19/EQ/OD-124 (02)
Policy No:	DMPPHQ18-005228	Date of Loss:	26/02/2019
Vehicle Reg. No.:	SKF9503U	Driveable?	
Driver Age/Info:	36 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	WONG PUI KWANG ROLAND	Contact No:	+6591912103
Driver:	WONG PUI KWANG ROLAND		

Make/Model:	AUDI A4, 1.8 TFSI (A)	Vehicle Reg. Date:	19/07/2012
Vehicle Colour:	BLACK		
Engine No:	CJE019226	Chassis No:	WAUZZZ8KXDA065040
Odometer:	0 KM		

Paint Type:

Total Loss? **NO**

Est. Duration of Repair (day) **7**

Description of Accident/Loss: **VEHICLE B SUDDENLY JAM BRAKE. I CAN'T STOP IN TIME AND REAR ENDED VEHICLE B.**

Present Location: **SME MOTOR PTE LTD (KAKI BUKIT)**

COST OF CLAIMS**Amount**

Parts	621.50
Miscellaneous items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (S\$)	621.50
+ GST 7.00% (S\$)	43.51
Nett Amount (S\$)	665.01
+ Previous Estimates (S\$)	9,919.54
Claim Total (S\$)	10,584.55

Generated using *Merimen e-Claims Internet Estimation & Adjusting System*

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 05 Mar 2019)**Parts:** 143 AUDI A4 1.8 TFSI (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** SME Motor Pte Ltd/SKF9503U/05/03/2019 14:43**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	2		*FRONT BUMPER REINFORCEMENT BRACKET <i>Surf/tn</i>	0.00	0.00	*300.00 F
2	1	<i>ADJ</i>	*RH BUMPER REINFORCEMENT BRACKET TOP HOLDER <i>ms</i>	0.00	0.00	*15.00 F
3	1		*FRONT BUMPER LOWER GRILLE <i>cm</i>	0.00	0.00	*90.00 F
4	1		*GRILLE BASE <i>cm</i>	0.00	0.00	*160.00 F

F=Franchise part.

Sub Total (S\$) 565.00

+ Margin on L,N Items 10.00% (S\$) 56.50

Total Parts (S\$) 621.50

SME Motor Pte Ltd/SKF9503U/05/03/2019 14:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 REPROGRAMME AIRBAG & HEADLIGHT

250.00

150

Sub Total (S\$)

250.00

Estimates on Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Parts 6806 ✓
f104 7486-60 ✓
SN 295 195
LC 1300 1300
8981.60
26/3/19
9081-60

26/09/2019

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

SME Motor Pte Ltd/SKF9503U/05/03/2019 14:43. Not valid without Reference section.

Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403
TOYOTA / LEXUS / MITSUBISHI / FORD / WINDSCREEN / CHEVROLET /

DAIHATSU / KIA / SUZUKI / HONDA

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

MLS: SME MOTOR PTE LTD

1 KAKI BUKIT AVE 6

#02-15/16/17/18 AUTOBAY @ KAKI BUKIT

SINGAPORE 417883

SKF9503U

GARY

NO: DLI9214960

PAGE 1

DATE 11-03-2019

A/C CODE LDSN446

TERMS CR

P.O NO: SKF9503U

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
Our D/O No: DDO9022895					
1 V8K0 823 029 H	BONNET	VA-19	1	1,100.00	1,100.00
2 V8K0 823 509 G	BONNET LOCK	VB-1	1	120.00	120.00
3 V8T0 823 480	CATCH HOOK LID	VB0-18	1	110.00	110.00
4 V8K0 807 065 C GRU	FRT BUMPER	VBA-20	1	850.00	850.00
5 V8K0 807 681 K 01C	FRT FOGLAMP COVER LH	VB14-5	1	70.00	70.00
6 V8K0 807 550 E	FR SPONGE	VA-19	1	75.00	75.00
7 V8K0 807 113 D	FR REINFORCEMENT	VA-15	1	330.00	330.00
8 V8T0 260 403 F	A/C CONDENSER	VBA-16T	1	460.00	460.00
9 V8K0 807 081 B 9B9	BUMPER TOP CVR	VBA-38	1	100.00	100.00
Our D/O No: DDO9022896					
1 V8K0 853 651 E 1QP	FRT GRILLE	DDS	1	550.00	550.00
2 V8K0 807 682 K 01C	FRT FOGLAMP COVER RH	VBA49-15	1	70.00	70.00
Our D/O No: DDO9022897					
1 V8K0 941 044 D-M	HEADLAMP RH(711307024093)	VA-3	1	860.00	860.00
2 V8K0 805 607 B	HEADLAMP BKT LH	VB5-9	1	80.00	80.00
3 V8K0 805 608 B	HEADLAMP BKT RH	DDS	1	80.00	80.00
4 V8K0 121 251 AJ	RADIATOR	VBA28-TOP	1	380.00	380.00
5 V8K0 807 133 D	FR BKT LH	VB6-13	1	150.00	150.00
6 V8K0 807 134 D	REINF BKT RH	DDS	1	150.00	150.00
7 V8K0 807 333 B	FRT BUMPER REINFORMENT BKT SUPPORT	VBA-85	2	15.00	30.00
8 V8K0 807 683	FRT BUMPER LOWER GRILLE	DDS	1	90.00	90.00

Print / MT / 11/03/2019 9:51:46 AM



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Feb 2019 Sendback Est	27 Feb 2019 11:47 S\$9,270.60	28 Feb 2019 14:11 Edit Adj Rpt	S\$8,981.60 Edit Estimates	S\$8,981.60 View Rpt		Pending for Survey Report Cancel Case
Supp #1	05 Mar 2019 14:22	05 Mar 2019 14:43 S\$621.50	05 Mar 2019 14:43			(Combined)	Combined with Main Uncombine Suppl.
Supp #2	26 Mar 2019 12:17	26 Mar 2019 12:18 S\$250.00	26 Mar 2019 12:18			(Combined)	Combined with Main Uncombine Suppl.

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	WONG PUI KWANG ROLAND , ID: S8238871J, Tel: +6591912103, Email: NOEMAIL		
Vehicle Reg. No.:	SKF9503U	Date of Loss:	26/02/2019 07:00 - :59 [79 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / DM19HO00568	Policy/Cover Note No.:	DMPPHQ18-005228 (Comprehensive)
		Excess:	S\$300.00
Repairer:	SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, 417883 Eunos - Tel: 6747 6106 (6 Lines)		
Handling Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433 ... [Handled by Joel Goh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 11/03/2019]		
Driver/Custodian:	WONG PUI KWANG ROLAND (36 / Male), NRIC: S8238871J, Tel: +6591912103 Email: NOEMAIL		
Adj Asg. Remarks:	EXCESS: \$300.00 (50% WAIVER) SURVEY AND AUTHORISE IF IN ORDER		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- EQI_HQ (06/03/2019): Alert - Adj Mandate Approved (S\$9000.00) - SKF9503U - Claim Handler: Joel Goh
- EQI_HQ (01/03/2019): Alert - Adj Mandate Approved (S\$8963.60) - SKF9503U - Claim Handler: Joel Goh

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

SKF9503U (DM19H000568)
OD
Feb 26 2019 7:00AM
[WONG PUI KWANG ROLAND]
SME Motor Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)

Assessment Reports

			1 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	27/02/19 11:47	Repairer Estimates	 Load HTM	
2	05/03/19 14:43	Repairer Estimates Suppl. #1	 Load HTM	
3	26/03/19 12:18	Repairer Estimates Suppl. #2	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/03/19 14:20	Adjuster Immediate Advice	 Load HTM	
2	06/03/19 08:57	Adjuster Immediate Advice	 Load HTM	

Photos/Images

			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/03/19 09:00	General View	 Load JPG	☒
2	06/03/19 09:00	General View	 Load JPG	☒
3	06/03/19 09:00	General View	 Load JPG	☒
4	06/03/19 09:00	General View	 Load JPG	☒
5	06/03/19 09:00	General View	 Load JPG	☒
6	06/03/19 09:00	General View	 Load JPG	☒
7	06/03/19 09:00	General View	 Load JPG	☒
8	06/03/19 09:00	General View	 Load JPG	☒
9	06/03/19 09:00	General View	 Load JPG	☒
10	06/03/19 09:00	General View	 Load JPG	☒
11	06/03/19 09:00	General View	 Load JPG	☒
12	06/03/19 09:00	General View	 Load JPG	☒
13	06/03/19 09:00	General View	 Load JPG	☒
14	06/03/19 09:00	General View	 Load JPG	☒
15	06/03/19 09:00	General View	 Load JPG	☒
16	06/03/19 09:00	General View	 Load JPG	☒
17	06/03/19 09:00	General View	 Load JPG	☒
18	06/03/19 09:00	General View	 Load JPG	☒
19	06/03/19 09:00	General View	 Load JPG	☒
20	06/03/19 09:00	General View	 Load JPG	☒
21	06/03/19 09:00	General View	 Load JPG	☒
22	06/03/19 09:00	General View	 Load JPG	☒
23	06/03/19 09:00	General View	 Load JPG	☒
24	06/03/19 09:00	General View	 Load JPG	☒
25	06/03/19 09:00	General View	 Load JPG	☒
26	06/03/19 09:00	General View	 Load JPG	☒
27	06/03/19 09:00	General View	 Load JPG	☒
28	06/03/19 09:00	General View	 Load JPG	☒
29	06/03/19 09:00	General View	 Load JPG	☒

Assessment Reports			1 per page ▼	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
30	06/03/19 09:00	General View	 Load JPG	☒
31	06/03/19 09:00	General View	 Load JPG	☒
32	06/03/19 09:00	General View	 Load JPG	☒
33	06/03/19 09:00	General View	 Load JPG	☒
34	06/03/19 09:00	General View	 Load JPG	☒
35	06/03/19 09:00	General View	 Load JPG	☒
36	06/03/19 09:00	General View	 Load JPG	☒
37	06/03/19 09:00	General View	 Load JPG	☒
38	06/03/19 09:00	General View	 Load JPG	☒
39	06/03/19 09:00	General View	 Load JPG	☒
40	06/03/19 09:00	General View	 Load JPG	☒
41	06/03/19 09:00	General View	 Load JPG	☒
42	06/03/19 09:00	General View	 Load JPG	☒
43	06/03/19 09:00	General View	 Load JPG	☒
44	06/03/19 09:00	General View	 Load JPG	☒
45	06/03/19 09:00	General View	 Load JPG	☒
46	06/03/19 09:01	General View	 Load JPG	☒
47	06/03/19 09:01	General View	 Load JPG	☒
48	06/03/19 09:01	General View	 Load JPG	☒
49	06/03/19 09:01	General View	 Load JPG	☒
50	06/03/19 09:01	General View	 Load JPG	☒
51	06/03/19 09:01	General View	 Load JPG	☒
52	06/03/19 09:01	General View	 Load JPG	☒
53	06/03/19 09:01	General View	 Load JPG	☒
54	06/03/19 09:01	General View	 Load JPG	☒
55	06/03/19 09:01	Chassis Number	 Load JPG	☒
56	06/03/19 09:01	General View	 Load JPG	☒
57	06/03/19 09:01	Odometer Reading	 Load JPG	☒
58	06/03/19 09:01	General View	 Load JPG	☒
59	06/03/19 09:01	General View	 Load JPG	☒
60	06/03/19 09:01	General View	 Load JPG	☒
61	06/03/19 09:01	General View	 Load JPG	☒
62	06/03/19 09:01	General View	 Load JPG	☒
63	06/03/19 09:01	General View	 Load JPG	☒
64	06/03/19 09:01	General View	 Load JPG	☒
65	06/03/19 09:01	General View	 Load JPG	☒
66	06/03/19 09:01	General View	 Load JPG	☒
67	06/03/19 09:01	General View	 Load JPG	☒
68	06/03/19 09:01	General View	 Load JPG	☒
69	06/03/19 09:01	Reinspection Photo	 Load JPG	☒
70	06/03/19 09:01	Reinspection Photo	 Load JPG	☒
71	06/03/19 09:01	Reinspection Photo	 Load JPG	☒
72	06/03/19 09:01	Reinspection Photo	 Load JPG	☒
73	06/03/19 09:01	Reinspection Photo	 Load JPG	☒
74	06/03/19 09:01	Reinspection Photo	 Load JPG	☒
75	06/03/19 09:01	Reinspection Photo	 Load JPG	☒
76	06/03/19 09:01	Reinspection Photo	 Load JPG	☒
77	06/03/19 09:01	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
78	06/03/19 09:01	Reinspection Photo	 Load JPG	☒
79	06/03/19 09:01	Reinspection Photo	 Load JPG	☒
80	06/03/19 09:01	Reinspection Photo	 Load JPG	☒
81	06/03/19 09:01	Reinspection Photo	 Load JPG	☒
82	06/03/19 09:01	Reinspection Photo	 Load JPG	☒
83	06/03/19 09:01	Reinspection Photo	 Load JPG	☒
84	06/03/19 09:01	Reinspection Photo	 Load JPG	☒
85	06/03/19 09:01	Reinspection Photo	 Load JPG	☒
86	06/03/19 09:01	Reinspection Photo	 Load JPG	☒
87	06/03/19 09:01	Reinspection Photo	 Load JPG	☒
88	06/03/19 09:01	Reinspection Photo	 Load JPG	☒
89	06/03/19 09:01	Reinspection Photo	 Load JPG	☒
90	06/03/19 09:01	Reinspection Photo	 Load JPG	☒
91	06/03/19 09:01	Reinspection Photo	 Load JPG	☒
92	06/03/19 09:01	Reinspection Photo	 Load JPG	☒
93	06/03/19 09:01	Reinspection Photo	 Load JPG	☒
94	06/03/19 09:01	Reinspection Photo	 Load JPG	☒
95	06/03/19 09:01	Reinspection Photo	 Load JPG	☒
96	06/03/19 09:01	Reinspection Photo	 Load JPG	☒
97	06/03/19 09:01	Reinspection Photo	 Load JPG	☒
98	06/03/19 09:01	Reinspection Photo	 Load JPG	☒
99	06/03/19 09:01	Reinspection Photo	 Load JPG	☒
100	06/03/19 09:01	Reinspection Photo	 Load JPG	☒
101	27/03/19 09:48	Reinspection Photo	 Load JPG	☒
102	27/03/19 09:48	Reinspection Photo	 Load JPG	☒
103	27/03/19 09:48	Reinspection Photo	 Load JPG	☒
104	27/03/19 09:48	Reinspection Photo	 Load JPG	☒
105	27/03/19 09:48	Reinspection Photo	 Load JPG	☒
106	27/03/19 09:48	Reinspection Photo	 Load JPG	☒
107	27/03/19 09:48	Reinspection Photo	 Load JPG	☒
108	27/03/19 09:48	Reinspection Photo	 Load JPG	☒
109	27/03/19 09:48	Reinspection Photo	 Load JPG	☒
110	27/03/19 09:48	Reinspection Photo	 Load JPG	☒
111	27/03/19 09:48	Reinspection Photo	 Load JPG	☒
112	27/03/19 09:48	Reinspection Photo	 Load JPG	☒
113	27/03/19 09:48	Reinspection Photo	 Load JPG	☒
114	27/03/19 09:48	Reinspection Photo	 Load JPG	☒
115	27/03/19 09:48	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	27/02/19 11:48	E-filed GIA report	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/03/19 14:11	ESTIMATE.pdf	 Load PDF	
2	27/03/19 09:49	ESTIMATE & SUPPLEMENTARY MARKED.pdf	 Load PDF	
3	03/04/19 14:59	PARTS INVOICE	 Load PDF	
4	03/04/19 14:59	SUPPLEMENTARY	 Load PDF	

Linked Accident Report Documents

View View in Browser ▼

Assessment Reports

1 per page ▼



No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print
1	26/02/19 17:07	Accident Statement	1	Load HTM	

Photos/Images

3 per page ▼



No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print
1	26/02/19 17:03	Accident Photo	1	Load JPG	☒
2	26/02/19 17:03	Accident Photo	1	Load JPG	☒
3	26/02/19 17:03	Accident Photo	1	Load JPG	☒
4	26/02/19 17:03	Accident Photo	1	Load JPG	☒
5	26/02/19 17:03	Accident Photo	1	Load JPG	☒
6	26/02/19 17:03	Accident Photo	1	Load JPG	☒
7	26/02/19 17:03	Accident Photo	1	Load JPG	☒
8	26/02/19 17:03	Accident Photo	1	Load JPG	☒
9	26/02/19 17:04	Accident Photo	1	Load JPG	☒
10	26/02/19 17:04	Accident Photo	1	Load JPG	☒
11	26/02/19 17:04	Accident Photo	1	Load JPG	☒

Documentation

1 per page ▼



No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print
1	26/02/19 17:03	Sketch Plan	1	Load TIF	
2	26/02/19 17:03	Sketch Plan #2	1	Load TIF	
3	26/02/19 17:03	Sketch Plan #3	1	Load TIF	
4	26/02/19 17:03	Sketch Plan #4	1	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

EQ Insurance Company Ltd
5 Maxwell Road, #17-00 Tower Block, MND Complex
Singapore 069110

Our File No: CS/EQ19003791/USD3S2

Date: 03/04/2019

REFERENCE

Insured/Claimant: WONG PUI KWANG ROLAND Policy No: DMPPHQ18-005228
Date of Loss: 26/02/2019 Nature of Claim: OD Claim No: DM19HO00568

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKF9503U**
Make & Model: AUDI A4, 1.8 TFSI (A) Engine No: CJE019226
Reg. Date: 19/07/2012 (Man. Year: 2012) Chassis No: WAUZZZ8KXDA065040
Colour: Black Odometer: 97003 km
Engine Capacity: 1798 cc
Market Value/New Car Price: S\$61,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50R17 Rear Tyre Size: 225/50R17
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,317.10	7,486.60	830.50	9.99
Miscellaneous Items	295.00	195.00	100.00	33.90
Labour	1,530.00	1,300.00	230.00	15.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,142.10	8,981.60	1,160.50	11.44
- Excess (S\$)	0.00	300.00	-300.00	
(S\$)	10,142.10	8,681.60	1,460.50	14.40
+ GST 7.00/7.00% (S\$)	709.95	607.71	102.24	14.40
Nett Amount (S\$)	10,852.05	9,289.31	1,562.74	14.40

INSPECTION

Date of Assignment: 28/02/2019 Present Location: SME Motor Pte Ltd (Kaki Bukit)
SME Motor Pte Ltd (Kaki Bukit)
Date Inspected: 01/03/2019 Inspected At: 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit
Singapore 417883
Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Apr 2019)
Parts:	143	AUDI A4 1.8 TFSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKF9503U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET (WCP)	Dented / Buckled	1,100.00 F	*1,100.00 F
2	1		*FRT BONNET LOCK (WCP)	Twisted	120.00 F	*120.00 F
3	1		*FRT BONNET LOCK CATCH (WCP)	Bent	110.00 F	*110.00 F
4	1		*FRT GRILLE ASSY (WCP)	Broken	550.00 F	*550.00 F
5	4		*FRT GRILLE CLIP (WCP)	Necessary	12.00 F	*12.00 F
6	1		*FRT BUMPER (WCP)	Distorted	850.00 F	*850.00 F
7	2		*FRT BUMPER RETAINER (WCP)	Not Necessary	70.00 F	*- F
8	10		*FRT BUMPER CLIP (WCP)	Necessary	30.00 F	*30.00 F
9	2		*FRT BUMPER FOG LAMP GARNISH (WCP)	Missing	140.00 F	*140.00 F
10	1		*FRT BUMPER INNER SPONGE (WCP)	Torn	75.00 F	*75.00 F
11	1		*FRT BUMPER REINFORCEMENT (WCP)	Bent	330.00 F	*330.00 F
12	2		*HEADLAMP (WCP)	Cracked	1,720.00 F	*1,720.00 F
13	2		*HEADLAMP LOWER BRACKET (WCP)	Cracked	160.00 F	*160.00 F
14	1		*HEADLAMP SUPPORT PANEL (WCP)	Repair	480.00 F	*- F
15	1		*AIRCON CONDENSER (WCP)	Bent / Punctured	460.00 F	*460.00 F
16	1		*RADIATOR (WCP)	Bent / Punctured	380.00 F	*380.00 F
17	2		*AIRCON SIDE DEFLECTOR (WCP)	Torn	80.00 F	*80.00 F
18	1		*HEADLAMP SUPPORT TOP GARNISH (WCP)	Deformed	100.00 F	*100.00 F
19	6		*HEADLAMP SUPPORT TOP GARNISH CLIP (WCP)	Necessary	24.00 F	*24.00 F
20	1		*RH HEADLAMP NOOZLE (WCP)	Not Necessary	145.00 F	*- F
21	1		*RH HEADLAMP NOOZLE COVER (WCP)	Not Necessary	60.00 F	*- F
Supplementary #1						
22	2		*FRONT BUMPER REINFORCEMENT BRACKET (WCP)	Bent / Twisted	300.00 F	*300.00 F
23	1		*RH BUMPER REINFORCEMENT BRACKET TOP HOLDER (WCP)	Missing	15.00 F	*15.00 F
24	1		*FRONT BUMPER LOWER GRILLE (WCP)	Cracked	90.00 F	*90.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
25	1		*GRILLE BASE (WCP)	Cracked	160.00 F	*160.00 F
			F=Franchise part.			
					Sub Total (S\$)	7,561.00 6,806.00
					+ Margin on L,N Items 10.00/10.00% (S\$)	756.10 680.60
					Total Parts (S\$)	8,317.10 7,486.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	NUMBER PLATE (BENT)	25.00	25.00
2	1	RADIATOR COOLANT (NECESSARY)	20.00	20.00
Supplementary #2				
3	1	REPROGRAMME AIRBAG & HEADLIGHT	250.00	150.00
Sub Total (S\$)			295.00	195.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	30.00	20.00
2	REMOVE & REFIX AIRCON AND GAS	New	100.00	100.00
3	LABOUR CHARGE	New	700.00	580.00
4	SPRAY PAINTING	New	700.00	600.00
Gross Labour Cost (S\$)			1,530.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >