

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: EQ Insurance Company Ltd
5 Maxwell Road, #17-00 Tower Block
MND Complex
Singapore 069110

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joel Goh

Date: 06 Mar 2019

Preliminary Advice

Vehicle No	: SKF9503U	Accident Date	: 26/02/2019
Make	: AUDI A4	Policy No.	: DMPPHQ18-005228
Assignment Date	: 28/02/2019	Excess	: S\$300.00
Date of Inspection	: 01/03/2019	Est. Duration of Repair	: 5 days
Inspection At	: SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit Singapore 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,892.10 (inclusive supplementary \$ 621.50)
Revised Amount	:S\$	6,257.60 (inclusive supplementary \$ 621.50)
Check Items (Estimated)	:S\$	3,327.50
Total	:S\$	9,585.10

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	61,000.00
COE / PARF Rebate	:S\$	51,772.00
Salvage Value	:S\$	
Margin for Repair	:S\$	9,228.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Kindly inform the supplementary amount is \$ 621.50. Repairer able to undertake the repair cost not exceeding \$ 9,000.00 on part by part basis.