

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)  
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: EQ Insurance Company Ltd  
5 Maxwell Road,#17-00 Tower Block  
MND Complex  
Singapore 069110

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Joel Goh

Date: 01 Mar 2019

## Preliminary Advice

Vehicle No	: SKF9503U	Accident Date	: 26/02/2019
Make	: AUDI A4	Policy No.	: DMPPHQ18-005228
Assignment Date	: 28/02/2019	Excess	: S\$300.00
Date of Inspection	: 01/03/2019	Est. Duration of Repair	: 5 days
Inspection At	: SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit Singapore 417883		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,270.60
Revised Amount	:S\$	5,636.10
Check Items (Estimated)	:S\$	3,327.50
Total	:S\$	8,963.60
Lump Sum Repair		:S\$

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	61,000.00
COE / PARF Rebate	:S\$	51,772.00
Salvage Value	:S\$	
Margin for Repair	:S\$	9,228.00

### Remarks

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.  
Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : REPAIRER ASKING REPAIR ON PART BY PART BASIS DUE TO NO SECOND  
HAND PART.