

7/0.3/2002

ASS. REC. BY:

REF:

CS/CTI/19003792/Utd3

n2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Chung Boon Sen

of

CTI

Date/Time:

28/2/19 @ 201pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY7CS

To Inspect Vehicle No:

SJT 6307C

Insured:

SKX 1841B

at Workshop m/s

Tan lim 10 for

Tel:

68885151

of

1 Defu lane 6

Policy No:

DMPCSN11643471802

Claim No:

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A.

22/02/2019

CA / REV / REP. / REV 24 HRS

11/3/19

H.O.D. Endorsement:

Date/Time:

2:47pm @ 28/2/19

Person Contacted:

Caymen

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJT 6307C - XS 3/CTI/180138 28/d3

DUA: 28/7/18

SKX 1841B-X

Surveyor

Warranty

REF: CH

## ASSIGNMENT

From:

Date:

1/3/19

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SJT 6307C

at Workshop m/s

Tan Lim

of

1 Defu Lane 6

Insured:

Policy No.:

Claims No.:

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Morning

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

26k.

ID No. Accident Rpt:

Consistent? : Yes or No

CA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJT 6307C

Yr Regn:

10, 09

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make:

Toyota Estima Aeras 2362

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

133855

T/Radio: Insured / Std / NI / NA

Eng/No:

ACR50 0093052

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

22/2/19

D.O.A.

1/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 18526

4/5 \$ 7100

net 7474

1/3/19

confirmed 4/5 \$ 7100 with Cayman. (Red: 4212.25; 37%)

RECEIVED 6 MAR 2019

Date/Time, File Pass to?

6/3 Typist

Date/Time, File Return to?



Preli. Report



Final Report

Days Of Repair:

7

Resurvey No. of Trip:

—

Survey Fee:

Transportation

) \$ RS \$

) Photos

) Other

TOTAL

220

2)

Add Fee:



Site Insp (\$)



Interview (\$)



Tech Invs (\$)



Weekend (\$)

Report Format:

TP

Lump Sum / L.B.T. (\$)

7100

## Nivitha (LKK Auto)

---

**From:** Shu Pei (LKKAuto) <shupeil@lkkauto.com>  
**Sent:** Thursday, 28 February 2019 2:01 PM  
**To:** assignments  
**Subject:** FW: Third party survey - SJT6307C Your insured: SKX1841B DOA: 22.02.2019

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Thursday, 28 February 2019 2:00 PM  
**To:** Caymen <caymen@tlmotor.com.sg>  
**Cc:** 'Wei Shong' <wei.shong@tlmotor.com.sg>; Admin A <admin-a@lkkauto.com>  
**Subject:** RE: Third party survey - SJT6307C Your insured: SKX1841B DOA: 22.02.2019

Without prejudice

Dear Caymen,

We appoint LKK.

Dear LKK,

Pls pri.

Regards,

**Chong Boon Sen**

Claims Executive

Claims

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: [boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** Caymen [<mailto:caymen@tlmotor.com.sg>]  
**Sent:** Thursday, 28 February, 2019 1:51 PM

**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

**Cc:** 'Wei Shong' <wei.shong@tlmotor.com.sg>

**Subject:** RE: Third party survey - SJT6307C Your insured: SKX1841B DOA: 22.02.2019

Dear Boon Sen,

We would like to choose Adrian Ling for the survey.

Please arrange survey asap as vehicle grounded since 27.02.2019.

Thank you.

Regards,



**Caymen**  
caymen@tlmotor.com.sg

O. +65 6858 5151  
F. +65 6858 0877

**Tan Lim Motor Pte L**  
1 Defu Lane 6  
Singapore 539365  
<http://www.tlmotor.com.sg>

**Confidentiality Notice:** This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan L Pte Ltd. Any use of the information (including, but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place ar programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

---

**From:** Chong Boon Sen [mailto:boonsen.chong@sg.cntaiping.com]

**Sent:** 28, Feb, 2019 1:39 PM

**To:** Caymen <caymen@tlmotor.com.sg>

**Cc:** 'Wei Shong' <wei.shong@tlmotor.com.sg>

**Subject:** RE: Third party survey - SJT6307C Your insured: SKX1841B DOA: 22.02.2019

#### Without Prejudice

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,  
**Chong Boon Sen**  
Claims Executive  
Claims

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #16-00 Springleaf Tower  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 63896171  
Fax: 62247175  
Email: [boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** Caymen [<mailto:caymen@tlmotor.com.sg>]  
**Sent:** Thursday, 28 February, 2019 1:31 PM  
**To:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>  
**Cc:** 'Wei Shong' <[wei.shong@tlmotor.com.sg](mailto:wei.shong@tlmotor.com.sg)>  
**Subject:** FW: Third party survey - SJT6307C Your insured: SKX1841B DOA: 22.02.2019

Dear Officer,

Please help to arrange survey asap.

Thank you.

Regards,



**Caymen**  
[caymen@tlmotor.com.sg](mailto:caymen@tlmotor.com.sg)

O. +65 6858 5151  
F. +65 6858 0877

**Tan Lim Motor Pte L**  
1 Defu Lane 6  
Singapore 539365  
<http://www.tlmotor.com.sg>

**Confidentiality Notice:** This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan L Pte Ltd. Any use of the information (including, but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place anti-virus programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

---

**From:** Caymen [<mailto:caymen@tlmotor.com.sg>]  
**Sent:** 28, Feb, 2019 9:30 AM  
**To:** 'claimsdept@sg.cntaiping.com' <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>; 'Irene Tay' <[irene.tay@sg.cntaiping.com](mailto:irene.tay@sg.cntaiping.com)>  
**Cc:** 'Wei Shong' <[wei.shong@tlmotor.com.sg](mailto:wei.shong@tlmotor.com.sg)>  
**Subject:** FW: Third party survey - SJT6307C Your insured: SKX1841B DOA: 22.02.2019

Dear Sir/Mdm,

Please help to arrange survey asap as our vehicle is in our premises.

Thank you.

Regards,



**Caymen**  
[caymen@tlmotor.com.sg](mailto:caymen@tlmotor.com.sg)

O. +65 6858 5151  
F. +65 6858 0877

**Tan Lim Motor Pte L**  
1 Defu Lane 6  
Singapore 539365  
<http://www.tlmotor.com.sg>

**Confidentiality Notice:** This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan L Pte Ltd. Any use of the information (including, but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place all programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

**From:** Caymen [<mailto:caymen@tlmotor.com.sg>]

**Sent:** 27, Feb, 2019 11:54 AM

**To:** 'claimsdept@sg.cntaiping.com' <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>; 'Joel Goh' <[joel.goh@sg.cntaiping.com](mailto:joel.goh@sg.cntaiping.com)>

**Cc:** 'Wei Shong' <[wei.shong@tlmotor.com.sg](mailto:wei.shong@tlmotor.com.sg)>; 'sam@tlmotor.com.sg' <[sam@tlmotor.com.sg](mailto:sam@tlmotor.com.sg)>

**Subject:** Third party survey - SJT6307C Your insured: SKX1841B DOA: 22.02.2019

Your Ref: SKX1841B

Our Ref: SJT6307C

DOA: 22.02.2019

Without Prejudice

Dear All,

We refer to the above matter.

We enclose the following documents for your attention:-

- a. Copy of our client's SAS report and damaged photos; - resend once ready
- b. Copy of the estimated cost of repair. – resend once ready

Pursuant to paragraph 2.3 of Pre-Action Protocol for NIMA Cases, please let us have a **list of 10 motor surveyors** for our selection and please let us know within **2 working days** whether you would like to conduct a pre-repair survey of our client's vehicle. If we do not hear from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

In the event that you request for post repair inspection pursuant to paragraph 4.1 under the NIMA Protocol, you must compensate our client for the loss of use of his/her vehicle for the day that the inspection is conducted.

In addition, please confirm in writing whether you are agreeable to direct settle with us at 100% liability for this case.

**Please arrange survey asap as vehicle was grounded at our premises.**

Thank you.

Regards,



**Caymen**  
[caymen@tlmotor.com.sg](mailto:caymen@tlmotor.com.sg)

O. +65 6858 5151  
F. +65 6858 0877

**Tan Lim Motor Pte L**  
1 Defu Lane 6  
Singapore 539365  
<http://www.tlmotor.com.sg>

**Confidentiality Notice:** This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan L Pte Ltd. Any use of the information (including, but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place anti-virus programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	4263F
<b>Vehicle Details</b>	
Vehicle No.:	SJT6307C
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	ESTIMA AERAS 2.4 A
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	2AZC612765
Chassis No.:	ACR500093052
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$34,697.00
Original Registration Date:	23 Oct 2009
First Registration Date:	23 Oct 2009
Transfer Count:	2
Actual ARF Paid:	\$34,697.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Oct 2019
PARF Rebate Amount:	\$17,348.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	22 Oct 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$18,109.00
COE Rebate Amount:	\$1,178.00
<b>Total Rebate Amount:</b>	<b>\$18,526.00</b>

The information contained herein is correct as at 27 Feb 2019

OK





## DON'T FALL FOR HER ONLINE PURCHASE SCAM

CLICK TO FIND OUT MORE AT [www.scamalert.sg](http://www.scamalert.sg)



SINGAPORE  
POLICE FORCE



TOTE  
2000



SINGAPORE  
POLICE FORCE







Submit

Advanced  
Search

Home » Used Cars » A1 Motoring Pte Ltd » Toyota Estima 3.5A Aeras

### Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

### Car Rental

For Private &  
Commercial Vehicles  
Rental From  
**\$50/Day**



## Empower My Community

What do you want  
design to do for  
you? Find out more  
from 4 to 17 March  
2019.

Compare

## Toyota Estima 3.5A Aeras

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

### Car Details

Price **\$29,888**

Depreciation

Reg Date 23-Jul-2009

(4mths 21days COE left)

Manufactured 2009

Mileage

Transmission Auto

Engine Cap 3,456 cc

Road Tax \$3,100 /yr

Power 206.0 kW (276 bhp)

View specs of the Toyota Estima (2006-2010)

Curb Weight 1,860 kg

### Features

Powered By 3.5L V6 DOHC Engine, 6 Speed Auto Transmission, Cruise Control, Twin Powered Sliding Door, Keyless Entry.

### Accessories

7 Seater, DVD Player, Sound System With Twin Headrest Monitor, 19 Inch Sports Rim.

### Description

OMV At \$44604. High Value For Body. Balloon Scheme Available.

COE \$17,501

OMV \$44,604

ARF \$44,604

Dereg Value \$22,988 as of today (change)

No. of Owners 2

Type of Veh MPV

Category PARF Car

Availability Available

Add to Shortlist

Add to Compare

Add a Note

Posted on: 12-Jan-2019 | Last Updated on: 25-Feb-2019

Tags: Toyota Estima, toyota estima, 2009 Toyota Estima, 2009 toyota estima, Toyota, Estima, estima, Used Toyota

### Upfront Payment

» more Financial info

Transfer Fee \$25

Down Payment \$8,966 (change)

Maximum 70% Loan

1st Instalment \$5,282



### Seller Information

#### Company

**A1 Motoring Pte Ltd**

» dealer's pricelist

» 14 vehs sold | 11 vehs available

#### Address

48 Toh Guan Road East #01-116

Search cars nearby this location

#### Location

Enterprise Hub

#### Contact Person(s)

Roy 87999711

Steve 81820249

Lee 93678860

### Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

#### Vehicle Evaluation

Find out the market value for your car. Get a free Car Valuation.

#### Free Valuation



AVIVA

15% off now, promo code: CAR15

Get a quote

## Post an Advertisement

Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

## Classic Promo! Best Deal! Fast Selling! Hurry Down Now!

Flexible Loan. Trade In Are  
Welcome. 100% Deposit Refund  
For Unapproved Loan.  
Classic Credit StarAdVALUE FOR MONEY  
VALUE FOR TIME  
A PEACE OF MIND

HOTLINE: 6741 9997

view our cars

Browse by Category

« Back ( 1 2 3 ) Next »






Sort by Date Posted

20 results/page

46 vehicles

Toyota Estima

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Estima		Any	Any	2009	Any	Any	Any	Available
	Toyota Estima	Toyota Estima 2.4A X (New 10-yr COE)	\$71,800	\$7,170 /yr	27-Mar-2009	2,362 cc	-	MPV	Available
2.68% P.A Lowest Interest At \$988 Monthly For Toyota Estima. \$0 Admin Fees For All GV Purchase. 2 Years Warranty For Engine And Gearbox With STA Evaluation Graded. Add Ons Available.									
2.68%P.A Low Interest@GV Finance. \$0 Admin Fees. \$4800 Downpayment Monthly \$988									
GV Credit Pte Ltd									
Posted: 01-Mar-2019 Tags: 2009 Toyota Estima, 2009 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used Toyota									
	Toyota Estima	Toyota Estima 2.4A X (New 5-yr COE)	\$54,800	\$10,950 /yr	27-Feb-2009	2,362 cc	-	MPV	Available
2.68% Per Annum Lowest Interest At \$988 Monthly For Toyota Estima. \$0 Admin Fees For All GV Purchase. 2 Years Warranty For Engine And Gearbox With STA Evaluation Graded. Add-Ons Available.									
2.68%P.A Low Interest@Gv Finance. \$0 Admin Fees. \$4800 Downpayment Monthly \$988									
GV Credit Pte Ltd									
Posted: 01-Mar-2019 Tags: 2009 Toyota Estima, 2009 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used Toyota									
	Toyota Estima	Toyota Estima Hybrid 2.4A X (COE till 01/2029)	\$66,800	\$6,750 /yr	20-Jan-2009	2,362 cc	135,000 km	MPV	Available
Fuel Type: Petrol-Electric									
TRD Sport Suspensions With 19 Inch Alloy Wheels! Well Maintained By Previous Owner And Car In Perfect Condition! Please Arrange For Viewing As Car Is Not In Showroom.									
Posted: 01-Mar-2019 Tags: 2009 Toyota Estima, 2009 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used Toyota									
	Toyota Estima	Toyota Estima 2.4A Aeras (New 10-yr COE)	\$73,800	\$7,370 /yr	16-Sep-2009	2,362 cc	-	MPV	Available
100% Loan Subjected To Approval. Reliable And Efficient MPV On The Road. New Leather Seats, New Paintwork (Buyer Able To Choose Colour). Steering Newly Wrapped, 100% Accident Free! Great For The Next ...									
QiFei Auto Pte Ltd									
Posted: 28-Feb-2019 Tags: 2009 Toyota Estima, 2009 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used Toyota									
Is your COE expiring? Let us help you renew it!									
Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.									
	Toyota Estima	Toyota Estima 2.4A Aeras S (New 10-yr COE)	\$79,800	\$7,970 /yr	01-Sep-2009	2,362 cc	-	MPV	Available
2015 Facelift. Like Driving A 2015 Estima. New Paintwork, Low Mileage. Engine Oil/Mounting/Steering Rack/Balance Shaft/Bearing All Serviced. Act Now. Best Quality Estima In Market. Mthly From \$900 So ...									
Posted: 28-Feb-2019 Tags: 2009 Toyota Estima, 2009 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used Toyota									

Compare



陳林摩哆私人有限公司  
TAN LIM MOTOR PTE LTD

CTP Insured's Veh No : SKX1841B  
Date of Accident : 22 February 2019

51 Defu Lane 10 Singapore 539216  
Tel : 68585151 ( 24 Hours ) Fax : 68580877

GST Regn. No. : M2-8922054-2

Mr Lim Hsiao Wei, Cliff

Date : 27 February 2019

Estimate To Repair SJT6307C - Toyota Estima Aeras 2.4A  
Chassis No : ACR500093052

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	tailgate lid <i>BodG</i>	\$ 1,520.00
02	1 pc	tailgate lid Estima badge <i>neu</i>	\$ 47.00
03	1 pc	tailgate lid Aeras badge <i>neu</i>	\$ 55.00
04	1 pc	tailgate lid centre logo badge <i>neu</i>	\$ 75.00
05	1 pc	tailgate lid weatherstrip <i>twi</i>	\$ 358.80
06	1 pc	tailgate lid outer garnish <i>11</i>	\$ 217.70
07	1 pc	tailgate lid lock top <i>DD/twi</i>	\$ 425.00
08	1 pc	tailgate lid lock latch bottom <i>11</i>	\$ 40.00
09	1 pc	tailgate lid inner trim board <i>de/twin</i>	\$ 476.90
10	2 ps	tailgate lid rubber stopper @ \$18.50 <i>11</i>	\$ 37.00
11	2 ps	tailgate lid side catch @ \$50.00 <i>11</i>	\$ 100.00
12	2 ps	tailgate lid side catch latch @ \$50.00 <i>11</i>	\$ 100.00
13	1 pc	tailgate lid inner closing handle <i>11</i>	\$ 38.50
14	1 pc	tailgate lid outer opening sensor - switch <i>11</i>	\$ 146.00
15	1 pc	tailgate lid lock cover <i>11</i>	\$ 62.50
16	2 ps	rear licence plate lamps @ \$55.00 <i>11</i>	\$ 110.00
17	1 pc	rear windscreen glass weatherstrip seal with clips <i>neu</i>	\$ 100.00
18	1 pc	rear end panel outer <i>B-dg</i>	\$ 660.00
19	1 pc	rear end panel inner top trim <i>twi/de</i>	\$ 256.00
20	1 pc	rear end panel inner bottom trim <i>twi/de</i>	\$ 185.00
21	2 pc	rear fender inner trim @ \$798.80 <i>de/cu</i>	\$ 1,597.60
22	1 pc	n/s rear fender air vent <i>11</i>	\$ 143.10
23	1 pc	rear luggage floor panel <i>crump/3u1</i>	\$ 774.90
24	1 pc	rear bumper <i>D.S</i>	\$ 585.00
25	2 ps	rear bumper tow cover @ \$29.50 <i>n/s twi</i>	\$ 59.00
26	2 ps	rear bumper parking sensor @ \$378.00 <i>shud</i>	\$ 756.00
27	2 pc	rear bumper reflectors @ \$56.90 <i>11</i>	\$ 113.80
28	2 ps	rear bumper end dust covers @ \$94.85 <i>11</i>	\$ 189.70
29	2 ps	rear bumper side retainers @ \$54.70 <i>34</i>	\$ 109.40
30	2 ps	rear bumper side holders @ \$38.40 <i>34</i>	\$ 76.80
31	12 ps	rear bumper fastener clips @ \$4.30 <i>neu</i>	\$ 51.60
32	2 ps	rear bumper inner sponge @ \$69.20 <i>n/s cu</i>	\$ 138.40
33	1 pc	rear bumper inner remote sensor <i>Dye</i>	\$ 417.30
Less 25 %			\$ 10,023.00
			\$ 2,505.75
			\$ 7,517.25
<u>SPECIAL NETT ITEMS</u>			
34	1 pc	rear licence plate <i>11</i>	\$ 45.00
35	1 pc	rear windscreen glass sealant <i>neu</i>	\$ 40.00

01/3-2KK MARCOS.

not Adm  
2/2/19

1/3/19

the ph. After rep.

7 day.

4/5 \$7100

1810

40



陳林摩哆私人有限公司  
TAN LIM MOTOR PTE LTD

CTP Insured's Veh No : SKX1841B  
Date of Accident : 22 February 2019

51 Defu Lane 10 Singapore 539216  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
GST Regn. No. : M2-8922054-2

Mr Lim Hsiao Wei, Cliff

Date : 27 February 2019

Estimate To Repair SJT6307C - Toyota Estima Aeras 2.4A

Chassis No : ACR500093052

S/No	Quantity	Description	Amount
<b>SPECIAL NETT ITEMS</b>			
36	1 pc	rear windscreen inner sponge seal <i>all</i>	\$ 30.00
37	1 pc	rear windscreen glass sealant <i>all</i>	\$ 80.00
38	1 pc	rear luggage floor insulator <i>17</i>	\$ 160.00
39	1 pc	back-up camera len <i>17</i>	\$ 0.00
			\$ 355.00
<b>LABOUR &amp; MISC. CHARGES</b>			
01		To rust-proofing of the affected areas.	\$ 120.00
02		To reinstall of rear bumper parking sensor and simulator test.	\$ 100.00
03		To check electrical lighting concerned.	\$ 60.00
04		To remove and refit rear windscreen glass.	\$ 120.00
05		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 180.00
06		To remove and refit back-up camera len and simulator test	\$ 80.00
07		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 80.00
08		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,500.00
09		Putty and spray painting of the affected portion.	\$ 1,200.00
			\$ 3,440.00
		<b>Total</b>	\$ 11,312.25

L&P Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To do the damaged part(s) during resurvey
- Extra items are subject to confirmation
- Third party are resurvey on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

89224  
7138

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19003792/UTD3N2

Date: 06/03/2019

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SJT6307C	Insured Vehicle No :	SKX1841B
Date of Loss:	22/02/2019	Nature of Claim:	TP
		Claim No:	N/A

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT6307C	Engine No:	2AZC612765
Make & Model:	TOYOTA ESTIMA, 2.4 (A)	Chassis No:	ACR500093052
Reg. Date:	23/10/2009 (Man. Year: 2009)	Odometer:	133855 km
Colour:	Black		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/55R17	Rear Tyre Size:	215/55R17
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,872.25	6,212.50	1,659.75	21.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,440.00	2,710.00	730.00	21.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>11,312.25</b>	<b>8,922.50</b>	<b>2,389.75</b>	<b>21.13</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>7,100.00</b>		
<b>(\$\$)</b>	<b>11,312.25</b>	<b>7,100.00</b>	<b>4,212.25</b>	<b>37.24</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>791.86</b>	<b>497.00</b>	<b>294.86</b>	<b>37.24</b>
<b>Nett Amount (\$\$)</b>	<b>12,104.11</b>	<b>7,597.00</b>	<b>4,507.11</b>	<b>37.24</b>

### INSPECTION

Date of Assignment:	01/03/2019		
Date Inspected:	01/03/2019	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	7.0 days		

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 06 Mar 2019)
<b>Parts:</b>	M1-MPV	TOYOTA ESTIMA 2.4 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJT6307C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE LID	Badly Dented	1,520.00 FL	*1,520.00 FL
2	1		*TAILGATE LID ESTIMA BADGE	Necessary	47.00 FL	*47.00 FL
3	1		*TAILGATE LID AERAS BADGE	Necessary	55.00 FL	*55.00 FL
4	1		*TAILGATE LID CENTRE LOGO BADGE	Necessary	75.00 FL	*75.00 FL
5	1		*TAILGATE LID WEATHERSTRIP	Twisted	358.80 FL	*358.80 FL
6	1		*TAILGATE LID OUTER GARNISH	Not Necessary	217.70 FL	*- FL
7	1		*TAILGATE LID LOCK TOP	Dented/Twisted	425.00 FL	*425.00 FL
8	1		*TAILGATE LID LOCK LATCH EMBLEM	Not Necessary	40.00 FL	*- FL
9	1		*TAILGATE LID INNER TRIM BOARD	Deformed/Torn	476.90 FL	*476.90 FL
10	2		*TAILGATE LID RUBBER STOPPER	Not Necessary	37.00 FL	*- FL
11	2		*TAILGATE LID SIDE CATCH	Not Necessary	100.00 FL	*- FL
12	2		*TAILGATE LID SIDE CATCH LATCH	Not Necessary	100.00 FL	*- FL
13	1		*TAILGATE LID INNER CLOSING HANDLE	Not Necessary	38.50 FL	*- FL
14	1		*TAILGATE LID OUTER OPENING SENSOR-SWITCH	Not Necessary	146.00 FL	*- FL
15	1		*TAILGATE LID LOCK COVER	Not Necessary	62.50 FL	*- FL
16	2		*REAR LICENCE PLATE LAMPS	Not Necessary	110.00 FL	*- FL
17	1		*REAR WINDSCREEN GLASS WEATHERSTRIP SEAL WITH CLIPS	Necessary	100.00 FL	*100.00 FL
18	1		*REAR END PANEL OUTER	Badly Dented	660.00 FL	*660.00 FL
19	1		*REAR END PANEL INNER TOP TRIM	Deformed/Twisted	256.00 FL	*256.00 FL
20	1		*REAR END PANEL INNER BOTTOM TRIM	Deformed/Twisted	185.00 FL	*185.00 FL
21	2		*REAR FENDER INNER TRIM	Deformed/Cracked	1,597.60 FL	*1,597.60 FL
22	1		*N/S REAR FENDER AIR VENT	Not Necessary	143.10 FL	*- FL
23	1		*REAR LUGGAGE FLOOR PANEL	Crumpled/Buckled	774.90 FL	*774.90 FL
24	1		*REAR BUMPER	Distorted	585.00 FL	*585.00 FL
25	1		*REAR BUMPER TOW COVER	N/s Twisted	59.00 FL	*29.50 FL
26	2		*REAR BUMPER END DUST COVERS	Not Necessary	189.70 FL	*- FL
27	2		*REAR BUMPER REFLECTORS	Not Necessary	113.80 FL	*- FL
28	2		*REAR BUMPER SIDE RETAINERS	Bent	109.40 FL	*109.40 FL
29	2		*REAR BUMPER SIDE HOLDERS	Bent	76.80 FL	*76.80 FL
30	12		*REAR BUMPER FASTENER CLIPS	Necessary	51.60 FL	*51.60 FL
31	1		*REAR BUMPER INNER SPONGE	N/s Cracked	138.40 FL	*69.20 FL
32	1		*REAR BUMPER INNER REMOTE SENSOR	Damaged	417.30 FL	*417.30 FL
33	2		*REAR BUMPER PARKING SENSOR	Shorted	567.00 FS	*200.00 FS
34	1		*REAR LICENCE PLATE	Not Necessary	45.00 FS	*- FS
35	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
36	1		*REAR WINDSCREEN INNER SPONGE SEAL	Necessary	30.00 FS	*30.00 FS
37	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
38	1		*REAR LUGGAGE FLOOR INSULATOR	Not Necessary	160.00 FS	*- FS
39	1		*BACK-UP CAMERA LEN (NPA)	Not Necessary	0.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 10,189.00 8,180.00

Report was unsubmitted during this print-out.



No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 25.00/25.00% (S\$)					2,316.75	1,967.50
Total Parts (S\$)					7,872.25	6,212.50
Report was unsubmitted during this print-out.						



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RUST-PROOFING OF THE AFFECTED AREAS	New	120.00	60.00
2	TO REINSTALL OF REAR BUMPER PARKING SENSOR AND SIMULATOR TEST	New	100.00	50.00
3	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	30.00
4	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	120.00	120.00
5	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMMINGS,GARNISH AND OTHER,TO ENABLE REPAIR	New	180.00	80.00
6	TO REMOVE AND REFIT BACK-UP CAMERA LEN AND SIMULATOR TEST	New	80.00	30.00
7	TO TRANSFER OF TAILGATE FITTINGS, FIXTURE AND PERFORM WATERSEEPAGE TEST	New	80.00	60.00
8	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	1,500.00	1,200.00
9	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,200.00	1,080.00
<b>Gross Labour Cost (S\$)</b>			<b>3,440.00</b>	<b>2,710.00</b>

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;