

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHC 988P (Supplementary)

DATE : 1.03.2019

MAKE :

TEL : 6542 5119

MODEL : MERCEDES BENZ VIANO

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Fan Blower <i>distorted n/s</i>			\$ 580.00 ✓
	Radiator Fan Protector Grill <i>broken n/s</i>			\$ 184.00 ✓
	Radiator Fan Cowling <i>replaced</i>		764.00	\$ 450.00 X
	SUB TOTAL		687.60	\$ 1,214.00
	LESS 10%			\$ 121.40
	DISCOUNTED TOTAL			\$ 1,092.60
	<i>01/03/2019</i> <i>[Signature]</i> <i>2 KK Auto</i> <i>[Signature]</i>			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.