

TRANS-CAB AUTO SERVICES PTE LTD

NO.58 DEFU LANE 1 SINGAPORE 539498
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
 SHD118D - AXA

Andrea

NOT Authored

11 Sep @ 4650h

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD 118D - Andrea
 JTDER12W203000034*
 TOYOTA
 WISH 1.8 BI-FUEL
 17.05.2013
AXA

PART**LIST**

1	1	Rear Bumper	\$	R 487.80 ✓
2	1	Rear Bumper Side Retainer RH	\$	D 57.30 ✓
3	1	Rear Bumper Side Retainer LH	\$	D 57.30 ✓
4	1	Rear Bumper Bracket RH	\$	R 90.00 ✓
5	1	Rear Bumper Bracket LH	\$	R 90.00 ✓
6	1	Rear Bumper Stay RH	\$	D 20.00 ✓
7	1	Rear Bumper Stay LH	\$	D 20.00 ✓
8	1	Rear Bumper Reflectors RH	\$	S 55.00 X
9	1	Rear Bumper Reflectors LH	\$	S 55.00 X
10	1	Rear End Panel Outer	\$	R 519.80 ✓
11	1	Rear End Panel Inner Trim	\$	mg D 219.87 ✓
12	1	Tailgate Lid	\$	R 1,233.70 ✓
13	1	Tailgate Lid Centre 'TOYOTA' Logo Badge	\$	N 68.00 ✓
14	1	Tailgate Lid Lock - Top	\$	D 388.80 ✓
15	1	Tailgate Lid Lock - Bottom	\$	R 32.83 X
16	1	Tailgate Lid Inner Trim Board	\$	B 258.28 ✓
17	1	Tailgate Lid Weatherstrip	\$	D/C 286.90 ✓
18	1	Tailgate Lid Outer Chrome Garnish	\$	C 214.50 ✓
19	1	Tailgate Lid Switcher Opener	\$	m 96.00 ✓
20	1	Rear Lamp LH	\$	mg 496.43 ✓
21	1	Rear Lamp Inner Panel LH	\$	R 540.00 X
22	1	Rear Fender LH	\$	R 1,013.60 X
23	1	Rear Fender RH	\$	R 1,013.60 X

TOTAL	\$	7,314.71
25%	\$	1,828.68
	\$	5,486.03

Specical Nett

1 Set Rear Bumper Fastener Clip

\$

N 30.00 ✓

TRANS-CAB AUTO SERVICES PTE LTD

NO.58 DEFU LANE 1 SINGAPORE 539498

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHD118D - AXA**Andrea**

1 Set Rear Bumper Parking Sensor	\$	Del 300.00 ^{220SN}
4 Rear End Panel Inner Trim Clip	\$	NR 30.00 ✓
1 Rear End Panel Sealant	\$	NR 80.00 30SN
1 CNG Sticker	\$	NR 15.00 ✓
1 Tailgate Sticker 'Trans-cab'	\$	NR 30.00 ✓
1 Tailgate Sticker 'Trans-link'	\$	NR 30.00 ✓
1 Tailgate Sticker '6555-3333'	\$	NR 30.00 ✓
1 Tailgate Lid Inner Trim Board Clip	\$	NR 18.00 ✓
1 Rear Windscreen Sealant	\$	NR 80.00 40SN
1 Rear Windscreen Inner Sponge Seal	\$	NR 60.00 30SN
1 CNG Board Cover	\$	SN 120.00 X
1 Rear Number Plate	\$	Del 80.00 25SN

TOTAL	\$	903.00
-------	----	---------------

TOTAL PARTS	\$	6,389.03
--------------------	-----------	-----------------

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,500.00 ⁷²⁰
To Rust-Proofing Of The Affected Areas.	\$	200.00 60
To Check Electrical Lighting Concerned.	\$	100.00 20
To Reinstall Rear Bumper Parking Sensor.	\$	150.00 50
To Remove And Refit Interior Fittings, Trimings, Garnish, Fittings And Other, To Enable Repair.	\$	250.00 60
Putty And Spray Painting Of The Affected Portion	\$	1,800.00 ⁷²⁰
To Remove And Replace Corporate Sticker	\$	NR 150.00 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.58 DEFU LANE 1 SINGAPORE 539498
TEL NO.6287 6666 FAX NO.6366 8862
CO/GST REG NO.201019626G
SHD118D - AXA

Andrea

To Transfer Of Tailgate Fittings, Attachments And Perform Water Seepage Test.	\$	150.00 60%
To Remove And Refit Rear W/ screen Glass To Facilitate Bodywork Repair.	\$	150.00 120%
To Reseal Sealant On Gap	\$	100.00 30%
Towing Fee	\$	nn 100.00 X
TOTAL	\$	<u>5,650.00</u>

Over All Total \$ 12,039.03

Total Repair Days ~~10~~ Days
5 days