

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VGS Singapore, 247, 159934 Singapore

HO SUM LIM
1 HARVEY CRESCENT
Singapore, 489363
Singapore

Steve CLKK) wil Prejudice
83228813 *1/3/19 1:45pm*
3 days
P/P
Res before spray

VGS Singapore
247
Alexandra Road
159934 Singapore

Phone No. +65 6305 7299
Fax No. +65 6474 3643
E-Mail service@vw.com.sg

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV022880
Quote No. SER/QUO/1900430
QuoteDate 28/02/19
Salesperson Steve Hung
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Golf 1.0 TSI 81 kW Trendline	30,291	Kong Charmaine
License No.	VIN	Initial Registration	Sales Advisor
SLV3544U	WVWZZZAUZJW084512	28/12/17	Steve Hung
Engine Code	Labor Type	Engine No.	Model Code
	1T	CHZ 580382	BQ12AZ

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR <i>840</i>	3	Labor		<i>840</i> 2,520.00
P B&P ALEX PAINT	SPRAY PAINT <i>800</i>	3	Labor		<i>800</i> 2,400.00
P B&P NUMBER PLATE	B&P NUMBER PLATE -NETT	1	pcs		80.00 ✓
P B&P SENSOR	SUPPLY & INSTALL REVERSE SE	1	Pieces		? 400.00 ✓
P B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un		480.00 ✓
	COMPULSORY TO DO AFTER AC				
P B&P MECH	CHECK WIRE HARNESS, ECU, S	1	Time Un		280.00 ✓
	Nett				
	Sum Labor				6,160.00
P 5G0807305D	BUMPER REINFORCEMENT ?	1	Pieces		680.69
	Use Predecessor 5G0807305B				
P 5G6807393	BUMPER BRACKET LH ?	1	Pieces		41.96
P 5G6807393A	BUMPER GUIDE LH ?	1	Pieces		41.96
P 5G6807394	BUMPER BRACKET RH ?	1	Pieces		41.96
P 5G6807394A	BUMPER GUIDE RH ?	1	Pieces		41.96
P 5G6807417BQGRU	REAR BUMPER COVER / <i>00</i>	1	Pieces		1,046.26
P 5G6807863C	STRIP ?	1	Pieces		96.26
	Sum Item				1,991.05

Payments to:

- BBN: - Acc.-No.:

VGS Singapore, 247, 159934 Singapore

HO SUM LIM
1 HARVEY CRESCENT
Singapore, 489363
Singapore

VGS Singapore
247
Alexandra Road
159934 Singapore

Phone No. +65 6305 7299
Fax No. +65 6474 3643
E-Mail service@vw.com.sg

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV022880
Quote No. SER/QUO/1900430
QuoteDate 28/02/19
Salesperson Steve Hung
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description
Volkswagen Passeng	Golf 1.0 TSI 81 kW Trendline
License No.	VIN
SLV3544U	WVWZZZAUZJW084512
Engine Code	Labor Type
	1T

Mileage
30,291
Initial Registration
28/12/17
Engine No.
CHZ 580382

Service Advisor
Kong Charmaine
Sales Advisor
Steve Hung
Model Code
BQ12AZ

Sum Labor	6,160.00
Sum Item	1,991.05
Total SGD	8,151.05
7% GST	8,151.05 570.57
Total SGD Incl. GST	8,721.62

Explanations

P = Proportionately Charged

Payment Terms No Credit

Payments to: - BBN: - Acc.-No..: