

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP /0250/2019/KS
Date : 25-Feb-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured Veh No :

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms June Tey Su Min
Address : 30 Eastwood Rd
Singapore 486365
Telephone : (HP) +65 96833811
Type of Claim : Third Party Claims
Policy No. :
Vehicle No : **SKB 1508 E**
Model Code : Audi A1 SB 1.4 TFSI S-Tronic
Model / Year : May-12
Engine No : CAXA93994
Chassis No : WAUZZZ8X4CB226485
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 25-Feb-19
Place of Accident : Junction Of Macpherson Rd & Genting Lane

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKB 1508 E

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
2	To remove and transfer aircon condenser, radiator, additional radiator, electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system.	S/N \$ 1,000.00	?
3	To dismantle front bumper rhs front fender and bonnet. Renew front lock carrier and align to position. Renew front bumper, rhs front fender, bonnet and headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 4,500.00	17.50
4	To remove rhs front door panel trim. Dismantle and reinstall rhs wing mirror assy.	S/N \$ 300.00	✓
5	To respray front bumper, rhs front fender, bonnet and rhs front door.	\$ 2,400.00	2200
6	To dismantle and reinstall front suspension assy. Inspect for damages and renew accordingly.	S/N \$ 2,400.00	?
7	To renew rhs front rim and tyre. Carry out wheel alignment.	S/N \$ 280.00	✓
8	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 11,432.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SKB 1508 E

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>distorted</i>	\$ 1,582.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 224.00	+
3	FRONT BUMPER CLOSING ELEMENT <i>crushed</i>	\$ 152.00	✓
4	RADIATOR GRILLE ?	\$ 894.00	?
5	"CAUTION" STICKER ?	\$ 13.00	?
6	FOAM FILLER PIECE <i>crushed</i>	\$ 107.00	✓
7	REINFORCEMENT BEAM <i>new</i>	\$ 630.00	+
8	FRONT BUMPER AIR GUIDE GRILLE RH <i>missing</i>	\$ 192.00	✓
9	FRONT FENDER RH <i>distorted</i>	\$ 809.00	✓
10	FRONT FENDER ATTACHMENT PARTS ?	\$ 39.00	?
11	FRONT FENDER BRACKET RH - FRONT <i>But</i>	\$ 54.00	✓
12	FRONT FENDER BRACKET RH - CENTER <i>new</i>	\$ 11.00	✓
13	FRONT FENDER BRACE RH <i>But</i>	\$ 49.00	✓
14	FRONT FENDER CLOSING ELEMENT RH ?	\$ 23.00	?
15	WHEEL HOUSING LINER <i>torn</i>	\$ 158.00	✓
16	WHEEL HOUSING ATTACHMENT PARTS ?	\$ 36.00	?
17	HEADLIGHT RH <i>crushed</i>	\$ 1,792.00	✓
18	HEADLIGHT MOUNTING RH <i>crushed</i>	\$ 96.00	✓
19	HEADLIGHT DISCHARGE LAMP <i>new</i>	\$ 398.00	+
20	HEADLIGHT CONTROL UNIT RH <i>new</i>	\$ 1,051.00	+
SUB-TOTAL SPARE PARTS		\$ 8,310.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SKB 1508 E

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	HEADLIGHT POWER MODULE RH <i>new</i>	\$ 356.00	+
22	LIFT CYLINDER RH ?	\$ 128.00	?
23	LIFT CYLINDER HOSE RH <i>new snapped</i>	\$ 78.00	+
24	WASH WATER RESERVOIR <i>Dischd</i>	\$ 197.00	—
25	WASH WATER RESERVOIR SEAL <i>new</i>	\$ 8.00	—
26	BONNET <i>Dented</i>	\$ 2,063.00	—
27	BONNET ATTACHMENT PARTS ?	\$ 126.00	?
28	BONNET COVER LH / RH <i>new</i>	\$ 58.00	+
29	BONNET EDGE PROTECTION <i>new</i>	\$ 36.00	—
30	BONNET CATCH HOOK <i>new</i>	\$ 60.00	+
31	BONNET LOCK BAR	\$ 90.00	+
32	AIR COND STICKER <i>new</i>	\$ 35.00	—
33	LOCK CARRIER ?	\$ 936.00	?
34	HORN RH <i>new</i>	\$ 206.00	—
35	HALOGEN FOG LAMP <i>missing</i>	\$ 235.00	—
36	ADDITIONAL RADIATOR	\$ 751.00	+
37	RADIATOR	\$ 768.00	+
38	RADIATOR BUSH LOWER	\$ 18.00	+
39	COOLANT ?	\$ 84.00	?
40	A/C CONDENSOR <i>new</i>	\$ 503.00	+
SUB-TOTAL SPARE PARTS		\$ 6,380.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SKB 1508 E

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	ALUMINIUM RIM <i>ok</i>	\$ 528.00	✓
42	RUBBER VALVE <i>ok</i>	\$ 13.00	X
43	SUB-FRAME WITH MOUNTING ?	\$ 970.00	?
44	LOWER ARM RH ?	\$ 262.00	?
45	WHEEL BEARING HOUSING RH ?	\$ 359.00	?
46	LOWER ARM BALL JOINT RH ?	\$ 106.00	?
47	STABILIZER LINK RH ?	\$ 75.00	?
48	DRIVESHAFT RH ?	\$ 1,834.00	?
49	STEERING RACK ?	\$ 3,280.00	?
50	TIE ROD END RH ?	\$ 80.00	?
51	PIRELLI PT 215/45/16 <i>ok</i>	TBC	X
52	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS		\$ 22,497.00	
TOTAL LABOUR CHARGES		\$ 11,432.00	
GRAND TOTAL		\$ 33,929.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: